

RECEIVED MAR 17 1997

LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID (<u>205</u>)
	STATE CODE (<u>12</u>)
	SHRP SECTION CODE (<u>1030</u>)

HIGHWAY RT. NO. (THIS SESSION) US 1

MILEPOST NO. OR LOCATION (THIS SESSION) 1.800

FILENAME W121030.C57 DISK/TAPE ID _____

BEGINNING DATE 1/5 BEGINNING TIME 0:00

ENDING DATE 1/11 ENDING TIME 24:00

COUNT DURATION 7 [] HOURS [☒] DAYS [] MONTHS

WEIGHT SCALE TYPE: PORT. WIM ☒ PERM. WIM _____ OTHER _____

EQUIPMENT MAKE/MODEL # Portable WIM (PAT)

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME FHWA

METHOD OF CALIBRATION AND FREQUENCY Front Axle

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>WDC</u>	PHONE <u>(817) 381-5348</u>
DATE PREPARED <u>FEB 27, 1997</u>	

RECEIVED OCT - 9 1997

LTPP TRAFFIC DATA	STATE ASSIGNED ID (<u>2 0 5</u>)
VEHICLE WEIGHT DATA	STATE CODE (<u>1 2</u>)
TRANSMITTAL FORM	SHRP SECTION CODE (<u>1 0 3 0</u>)

HIGHWAY RT. NO. (THIS SESSION) US 1

MILEPOST NO. OR LOCATION (THIS SESSION) 1.800

FILENAME W121030.I07 DISK/TAPE ID _____

BEGINNING DATE 7/25 BEGINNING TIME 0:00

ENDING DATE 7/31 ENDING TIME 24:00

COUNT DURATION 7 [] HOURS [☒] DAYS [] MONTHS

WEIGHT SCALE TYPE: PORT. WIM ☒ PERM. WIM _____ OTHER _____

EQUIPMENT MAKE/MODEL # Portable WIM (PAT)

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME FHWA

METHOD OF CALIBRATION AND FREQUENCY Front Axle

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>WDC</u>	PHONE <u>(817) 381-5348</u>
DATE PREPARED <u>August 28, 1997</u>	

RECEIVED JUL 25 1997

LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID (<u>205</u>)
	STATE CODE (<u>12</u>)
	SHRP SECTION CODE (<u>1030</u>)

HIGHWAY RT. NO. (THIS SESSION) US 1

MILEPOST NO. OR LOCATION (THIS SESSION) 1.800

FILENAME W121030.G27 DISK/TAPE ID _____

BEGINNING DATE 5/2 BEGINNING TIME 0:00

ENDING DATE 5/8 ENDING TIME 24:00

COUNT DURATION 7 [] HOURS [☒] DAYS [] MONTHS

WEIGHT SCALE TYPE: PORT. WIM ☒ PERM. WIM _____ OTHER _____

EQUIPMENT MAKE/MODEL # Portable WIM (PAT)

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME FHWA

METHOD OF CALIBRATION AND FREQUENCY Front Axle

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>WDC</u>	PHONE <u>(817) 381-5348</u>
DATE PREPARED <u>MAY 27, 1997</u>	