

RECEIVED JAN 20 1997

LTPP TRAFFIC DATA	STATE ASSIGNED ID (<u>1 9 4</u>)
VEHICLE WEIGHT DATA	STATE CODE (<u>1 2</u>)
TRANSMITTAL FORM	SHRP SECTION CODE (<u>3 8 0 4</u>)

HIGHWAY RT. NO. (THIS SESSION) I-75

MILEPOST NO. OR LOCATION (THIS SESSION) 29.384

FILENAME W123804.LT6 DISK/TAPE ID _____

BEGINNING DATE 10/30 BEGINNING TIME 0:00

ENDING DATE 11/5 ENDING TIME 24:00

COUNT DURATION 7 [] HOURS [☒] DAYS [] MONTHS

WEIGHT SCALE TYPE: PORT. WIM ☒ PERM. WIM _____ OTHER _____

EQUIPMENT MAKE/MODEL # Portable WIM (PAT)

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME FHWA

METHOD OF CALIBRATION AND FREQUENCY Front Axle

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>WDC</u>	PHONE <u>(817) 381-5348</u>
DATE PREPARED <u>August 28, 1996</u>	

RECEIVED OCT 16 1996

LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID (<u>1 9 4</u>)
	STATE CODE (<u>1 2</u>)
	SHRP SECTION CODE (<u>3 8 0 4</u>)

HIGHWAY RT. NO. (THIS SESSION) I-75

MILEPOST NO. OR LOCATION (THIS SESSION) 29.384

FILENAME W123804.IR6 DISK/TAPE ID _____

BEGINNING DATE 8/7 BEGINNING TIME 0:00

ENDING DATE 8/13 ENDING TIME 24:00

COUNT DURATION 7 [] HOURS [☒] DAYS [] MONTHS

WEIGHT SCALE TYPE: PORT. WIM ☒ PERM. WIM _____ OTHER _____

EQUIPMENT MAKE/MODEL # Portable WIM (PAT)

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME FHWA

METHOD OF CALIBRATION AND FREQUENCY Front Axle

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>WDC</u>	PHONE <u>(817) 381-5348</u>
DATE PREPARED <u>August 28, 1996</u>	

RECEIVED JUL 17 1996

LTPP TRAFFIC DATA	STATE ASSIGNED ID (<u>1 9 4</u>)
VEHICLE WEIGHT DATA	STATE CODE (<u>1 2</u>)
TRANSMITTAL FORM	SHRP SECTION CODE (<u>3 8 0 4</u>)

HIGHWAY RT. NO. (THIS SESSION) I-75

MILEPOST NO. OR LOCATION (THIS SESSION) 29.384

FILENAME W123804.G36 DISK/TAPE ID _____

BEGINNING DATE 4/21 BEGINNING TIME 0:00

ENDING DATE 4/28 ENDING TIME 24:00

COUNT DURATION 7 [] HOURS [☒] DAYS [] MONTHS

WEIGHT SCALE TYPE: PORT. WIM ☒ PERM. WIM _____ OTHER _____

EQUIPMENT MAKE/MODEL # Portable WIM (PAT)

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME FHWA

METHOD OF CALIBRATION AND FREQUENCY Front Axle

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>WDC</u>	PHONE <u>(817) 381-5348</u>
DATE PREPARED <u>APR 28, 1996</u>	

