

RECEIVED OCT - 9 1997

LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID (<u>1 6 8</u>)
	STATE CODE (<u>1 2</u>)
	SHRP SECTION CODE (<u>4 1 0 8</u>)

HIGHWAY RT. NO. (THIS SESSION) US 98

MILEPOST NO. OR LOCATION (THIS SESSION) 0.961

FILENAME W124108.I97 DISK/TAPE ID _____

BEGINNING DATE 7/9 BEGINNING TIME 0:00

ENDING DATE 7/15 ENDING TIME 24:00

COUNT DURATION 7 [] HOURS [☒] DAYS [] MONTHS

WEIGHT SCALE TYPE: PORT. WIM ☒ PERM. WIM _____ OTHER _____

EQUIPMENT MAKE/MODEL # Portable WIM (PAT)

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME FHWA

METHOD OF CALIBRATION AND FREQUENCY Front Axle

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>WDC</u>	PHONE <u>(817) 381-5348</u>
DATE PREPARED <u>August 28, 1997</u>	

RECEIVED JUL 25 1997

LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID (<u>1 6 8</u>)
	STATE CODE (<u>1 2</u>)
	SHRP SECTION CODE (<u>4 1 0 8</u>)

HIGHWAY RT. NO. (THIS SESSION) US 98

MILEPOST NO. OR LOCATION (THIS SESSION) 0.961

FILENAME W124108.F57 DISK/TAPE ID _____

BEGINNING DATE 4/5 BEGINNING TIME 0:00

ENDING DATE 4/11 ENDING TIME 24:00

COUNT DURATION 7 [] HOURS [☒] DAYS [] MONTHS

WEIGHT SCALE TYPE: PORT. WIM ☒ PERM. WIM _____ OTHER _____

EQUIPMENT MAKE/MODEL # Portable WIM (PAT)

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME FHWA

METHOD OF CALIBRATION AND FREQUENCY Front Axle

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>WDC</u>	PHONE <u>(817) 381-5348</u>
DATE PREPARED <u>MAY 29, 1997</u>	

RECEIVED MAR 17 1997

LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID (<u>1 6 8</u>)
	STATE CODE (<u>1 2</u>)
	SHRP SECTION CODE (<u>4 1 0 8</u>)

HIGHWAY RT. NO. (THIS SESSION) US 98

MILEPOST NO. OR LOCATION (THIS SESSION) 0.961

FILENAME W124108.D17 DISK/TAPE ID _____

BEGINNING DATE 2/1 BEGINNING TIME 0:00

ENDING DATE 2/7 ENDING TIME 24:00

COUNT DURATION 7 [] HOURS [☒] DAYS [] MONTHS

WEIGHT SCALE TYPE: PORT. WIM ☒ PERM. WIM _____ OTHER _____

EQUIPMENT MAKE/MODEL # Portable WIM (PAT)

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME FHWA

METHOD OF CALIBRATION AND FREQUENCY Front Axle

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>WDC</u>	PHONE <u>(817) 381-5348</u>
DATE PREPARED <u>FEB 27, 1997</u>	