

LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID (<u>W 2 9</u>)
	STATE CODE (<u>1 2</u>)
	SHRP SECTION CODE (<u>4 1 0 9</u>)

HIGHWAY RT. NO. (THIS SESSION) US 1MILEPOST NO. OR LOCATION (THIS SESSION) 11.156FILENAME W124109.LD6 DISK/TAPE ID _____BEGINNING DATE 10/14 BEGINNING TIME 0:00ENDING DATE 10/20 ENDING TIME 24:00COUNT DURATION 7 [] HOURS [☒] DAYS [] MONTHSWEIGHT SCALE TYPE: PORT. WIM ☒ PERM. WIM _____ OTHER _____EQUIPMENT MAKE/MODEL # Portable WIM (PAT)SENSOR TYPE PiezoNAME OF SHA CLASSIFICATION SCHEME FHWAMETHOD OF CALIBRATION AND FREQUENCY Front Axle

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>WDC</u>	PHONE <u>(817) 381-5348</u>
DATE PREPARED <u>November 29, 1996</u>	

RECEIVED OCT 16 1996

LTPP TRAFFIC DATA	STATE ASSIGNED ID (<u>W 2 9</u>)
VEHICLE WEIGHT DATA	STATE CODE (<u>1 2</u>)
TRANSMITTAL FORM	SHRP SECTION CODE (<u>4 1 0 9</u>)

HIGHWAY RT. NO. (THIS SESSION) US 1

MILEPOST NO. OR LOCATION (THIS SESSION) 11.156

FILENAME W124109.IQ6 DISK/TAPE ID _____

BEGINNING DATE 7/27 BEGINNING TIME 0:00

ENDING DATE 8/2 ENDING TIME 24:00

COUNT DURATION 7 [] HOURS [☒] DAYS [] MONTHS

WEIGHT SCALE TYPE: PORT. WIM ☒ PERM. WIM _____ OTHER _____

EQUIPMENT MAKE/MODEL # Portable WIM (PAT)

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME FHWA

METHOD OF CALIBRATION AND FREQUENCY Front Axle

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>WDC</u>	PHONE <u>(817) 381-5348</u>
DATE PREPARED <u>August 29, 1996</u>	

RECEIVED JUL 17 1996

LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID (<u>W 2 9</u>)
	STATE CODE (<u>1 2</u>)
	SHRP SECTION CODE (<u>4 1 0 9</u>)

HIGHWAY RT. NO. (THIS SESSION) US 1

MILEPOST NO. OR LOCATION (THIS SESSION) 11.156

FILENAME W124109.F46 DISK/TAPE ID _____

BEGINNING DATE 4/6 BEGINNING TIME 0:00

ENDING DATE 4/10 ENDING TIME 24:00

COUNT DURATION 7 [] HOURS [☒] DAYS [] MONTHS

WEIGHT SCALE TYPE: PORT. WIM ☒ PERM. WIM _____ OTHER _____

EQUIPMENT MAKE/MODEL # Portable WIM (PAT)

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME FHWA

METHOD OF CALIBRATION AND FREQUENCY Front Axle

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>WDC</u>	PHONE <u>(817) 381-5348</u>
DATE PREPARED <u>APR 30, 1996</u>	