

# LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 1000

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{3002}

LOCATION ON US 41 1.3 MI S OF SR 18  
MP# 199.9

TYPE EQUIPMENT  
MODEL #

PERMANENT WIM  
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
01-21-09	1537	Site inspection	Jeff Wourms	317-694-4224	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 1000

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{      }
	*STATE CODE	{18}
	*SHRP SECTION ID	{3002}

LOCATION ON US 41 1.3 MI S OF SR 18  
MP# 199.9

TYPE EQUIPMENT  
MODEL #

PERMANENT WIM  
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
02-10-09	9:45	Reset modem	Donn Klepinger	317-591-5264	N/A

revised November 11, 1999

# LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 1000

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{3002}

LOCATION ON US 41 1.3 MI S OF SR 18  
MP# 199.9

TYPE EQUIPMENT  
MODEL #

PERMANENT WIM  
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
03-06-09	1440	Replaced UPS	Zach Fordice	317-753-5598	N/A

revised November 11, 1999

# LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 1000

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{3002}

LOCATION ON US 41 1.3 MI S OF SR 18  
MP# 199.9

TYPE EQUIPMENT PERMANENT WIM  
MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
04-24-09	1130am	Replaced piezo 1 and 2, respliced all loops	Jeff Wourms	317-694-4224	N/A

revised November 11, 1999

# LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 1000

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{3002}

LOCATION ON US 41 1.3 MI S OF SR 18  
 MP# 199.9

TYPE EQUIPMENT  
 MODEL #

PERMANENT WIM  
 IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
05-11-09	1245pm	Calibrated WIM	Jeff Wourms	317-694-4224	N/A

revised November 11, 1999

STATION 1000

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID { }
	*STATE CODE {18}
	*SHRP SECTION ID {3002}

LOCATION ON US 41 1.3 MI S OF SR 18  
MP# 199.9

TYPE EQUIPMENT  
MODEL #

PERMANENT WIM  
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
05-12-09	0310pm	Repaired phone line	Larry Torrance	317-591-5265	N/A

revised November 11, 1999

# LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 1000

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{      }
	*STATE CODE	{18}
	*SHRP SECTION ID	{3002}

LOCATION ON US 41 1.3 MI S OF SR 18  
MP# 199.9

TYPE EQUIPMENT  
MODEL #

PERMANENT WIM  
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
05-14-09	1210pm	Reset modem and ATR	Richard Martin	317-695-4773	N/A

revised November 11, 1999

STATION 1000

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{      }
	*STATE CODE	{18}
	*SHRP SECTION ID	{3002}

LOCATION ON US 41 1.3 MI S OF SR 18  
MP# 199.9

TYPE EQUIPMENT  
MODEL #

PERMANENT WIM  
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
06-09-09	01:15pm	Reset modem and wim	Jeff Wourms	317-694-4224	N/A

revised November 11, 1999



# LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 1000

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID { }
	*STATE CODE {18}
	*SHRP SECTION ID {3002}

LOCATION ON US 41 1.3 MI S OF SR 18  
MP# 199.9

TYPE EQUIPMENT  
MODEL #

PERMANENT WIM  
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
06-11-09	02:30pm	Reset modem and wim	Zach Fordice	317-753-5598	N/A

revised November 11, 1999