

# LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 1100

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{5518}

LOCATION ON I 65 0.78 MI N OF SR 25  
MP# 175.9

TYPE EQUIPMENT  
MODEL #

PERMANENT WIM  
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
01-23-06	1400	Reset modem.	Jeff Wourms	317-694-4224	N/A

revised November 11, 1999

STATION 1100

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{5518}

LOCATION ON I 65 0.78 MI N OF SR 25  
 MP# 175.9

TYPE EQUIPMENT  
 MODEL #

PERMANENT WIM  
 IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
01-25-06	noon	Replaced modem.	Jeff Wourms	317-694-4224	N/A

revised November 11, 1999