

# LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 2300

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{9020}

LOCATION On I 69 4.2 MI N of SR 18  
MP# 68.3

TYPE EQUIPMENT PERMANENT WIM  
MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
01-21-09	1445	Site Inspection. All loops need resplice, all piezos need replaced	Mike Hemelgarn	317-502-3012	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 2300

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID { }
	*STATE CODE {18}
	*SHRP SECTION ID {9020}

LOCATION On I 69 4.2 MI N of SR 18  
 MP# 68.3

TYPE EQUIPMENT PERMANENT WIM  
 MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
08-06-09	13:15	Repalced piezos 1-8. Respliced all loops.	Mike Hemelgarn	317-502-3012	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 2300

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{      }
	*STATE CODE	{18}
	*SHRP SECTION ID	{9020}

LOCATION      On I 69 4.2 MI N of SR 18  
 MP#          68.3

TYPE EQUIPMENT      PERMANENT WIM  
 MODEL #              IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
09-08-09	5:15pm	Calibrated WIM	Mike Hemelgarn	317-502-3012	N/A

revised November 11, 1999