

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 3600

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{A900}

LOCATION ON I 70 4.3 MI E OF SR 9
MP# 108.0

TYPE EQUIPMENT PERMANENT WIM
MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
01-27-09	11:30am	Site inspection. P1, P4, P8 bad. Loop 5 damaged. All loops needrespliced	Mike Hemelgarn	317-502-3012	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 3600

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID { }
	*STATE CODE {18}
	*SHRP SECTION ID {A900}

LOCATION ON I 70 4.3 MI E OF SR 9
MP# 108.0

TYPE EQUIPMENT PERMANENT WIM
MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
03-20-09	1255	Replace UPS	Larry Torrance	317-591-5265	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 3600

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{A900}

LOCATION ON I 70 4.3 MI E OF SR 9
MP# 108.0

TYPE EQUIPMENT
MODEL #

PERMANENT WIM
IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
04-23-09	02:00pm	Reset WIM and modem	Richard Martin	317-695-4773	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 3600

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{A900}

LOCATION ON I 70 4.3 MI E OF SR 9
MP# 108.0

TYPE EQUIPMENT PERMANENT WIM
MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
05-14-09	10:15am	Reset WIM and modem	Bill Knarr	317-591-5263	N/A

revised November 11, 1999

LTPP HARDWARE / SOFTWARE CHANGES, REPAIRS AND MODIFICATIONS

STATION 3600

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGE AT LTPP TEST LOCATIONS WITH PERMANENT AVC OR WIM	*STATE ASSIGNED ID	{ }
	*STATE CODE	{18}
	*SHRP SECTION ID	{A900}

LOCATION ON I 70 4.3 MI E OF SR 9
MP# 108.0

TYPE EQUIPMENT PERMANENT WIM
MODEL # IRD 1067

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
06-11-09	01:30pm	Reset WIM and modem	Larry Torrance	317-591-5265	N/A

revised November 11, 1999