

SHEET <u>1312</u> LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID [<u>306</u>]
	STATE CODE [<u>26</u>]
	SHRP SECTION ID [<u>3068</u>]

HIGHWAY RT. NO. (THIS SESSION) US 10

MILEPOST NO. OR LOCATION (THIS SESSION) Clare

FILENAME C263068.I13 DISK/TAPE ID _____

BEGINNING DATE 7-1-93 BEGINNING TIME 00:00

ENDING DATE 7-31-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: _____

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

SHEET <u>1372</u> LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID [<u>306</u>]
	STATE CODE [<u>26</u>]
	SHRP SECTION ID [<u>3068</u>]

HIGHWAY RT. NO. (THIS SESSION) US 10

MILEPOST NO. OR LOCATION (THIS SESSION) Clare

FILENAME C263068.J13 DISK/TAPE ID _____

BEGINNING DATE 8-1-93 BEGINNING TIME 00:00

ENDING DATE 8-31-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: _____

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

SHEET 1312 LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID [306]
	STATE CODE [26]
	SHRP SECTION ID [3068]

HIGHWAY RT. NO. (THIS SESSION) 45 10

MILEPOST NO. OR LOCATION (THIS SESSION) Clare

FILENAME C263068.K13 DISK/TAPE ID _____

BEGINNING DATE 9-1-93 BEGINNING TIME 00:00

ENDING DATE 9-30-93 ENDING TIME 23:58

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: _____

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

SHEET 13 12 LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID [306] STATE CODE [26] SHRP SECTION ID [3068]
--	--

HIGHWAY RT. NO. (THIS SESSION) 45 10

MILEPOST NO. OR LOCATION (THIS SESSION) Clare

FILENAME C263068.L13 DISK/TAPE ID _____

BEGINNING DATE 10-1-93 BEGINNING TIME 00:00

ENDING DATE 10-31-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT PAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: FHWA

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

SHEET 13 12
LTPP TRAFFIC DATA
VEHICLE WEIGHT DATA
TRANSMITTAL FORM

STATE ASSIGNED ID [306]
STATE CODE [26]
SHRP SECTION ID [3068]

HIGHWAY RT. NO. (THIS SESSION) 45 10

MILEPOST NO. OR LOCATION (THIS SESSION) Clare

FILENAME C263068.M13 DISK/TAPE ID _____

BEGINNING DATE 11-1-93 BEGINNING TIME 00:00

ENDING DATE 11-30-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: FHWA

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER James Kramer PHONE # 517-322-1736
DATE PREPARED _____

SHEET 18 12 LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID [306]
	STATE CODE [26]
	SHRP SECTION ID [3068]

HIGHWAY RT. NO. (THIS SESSION) US 10 WB

MILEPOST NO. OR LOCATION (THIS SESSION) Clare

FILENAME C263068.N13 DISK/TAPE ID _____

BEGINNING DATE 12-1-93 BEGINNING TIME 00:00

ENDING DATE 12-31-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT PAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: FHWA

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

SHEET 13 LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	*STATE ASSIGNED ID [306] *STATE CODE [26] *SHRP SECTION ID [306B]
--	---

HIGHWAY RT. NO. (THIS SESSION) W/B US-10

MILEPOST NO. OR LOCATION (THIS SESSION) 8 mi west of US-27

FILENAME WZ63068.113 DISK/TAPE ID _____

BEGINNING DATE 1-1-93 BEGINNING TIME 00:00

ENDING DATE 1-31-93 ENDING TIME 24:00

COUNT DURATION 31 [] HOURS [Y] DAYS [] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# GK 6012

SENSOR TYPE Piezo

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>A. Jerome</u>	PHONE # <u>517-322-1716</u>
DATE PREPARED <u>2-1-93</u>	

SHEET 13 LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	*STATE ASSIGNED ID [<u>306</u>] *STATE CODE [<u>26</u>] *SHRP SECTION ID [<u>3060</u>]
--	--

HIGHWAY RT. NO. (THIS SESSION) W/B US-10

MILEPOST NO. OR LOCATION (THIS SESSION) 8mi west of US-27

FILENAME W26306B.E13 DISK/TAPE ID _____

BEGINNING DATE 2-1-93 BEGINNING TIME 00:00

ENDING DATE 2-28-93 ENDING TIME 24:00

COUNT DURATION 28 [] HOURS [X] DAYS [] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# GK 6012

SENSOR TYPE Piezo

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>A. Jerome</u>	PHONE # <u>517-322-1716</u>
DATE PREPARED <u>3-2-93</u>	

SHEET 13 LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	*STATE ASSIGNED ID [<u>306</u>]
	*STATE CODE [<u>26</u>]
	*SHRP SECTION ID [<u>3068</u>]

HIGHWAY RT. NO. (THIS SESSION) _____

MILEPOST NO. OR LOCATION (THIS SESSION) _____

FILENAME W263068.E13. DISK/TAPE ID _____

BEGINNING DATE 3-1-93 BEGINNING TIME 00:00

ENDING DATE 3-31-93 ENDING TIME 24:00

COUNT DURATION 31 [] HOURS [☒] DAYS [] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM ☒ OTHER _____

EQUIPMENT MAKE/MODEL# GK 6000

SENSOR TYPE Piezo

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>A. Jerome</u>	PHONE # _____
DATE PREPARED <u>3-1-93</u>	

SHEET 13 LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	*STATE ASSIGNED ID [<u>306</u>]
	*STATE CODE [<u>26</u>]
	*SHRP SECTION ID [<u>3068</u>]

HIGHWAY RT. NO. (THIS SESSION) US 10

MILEPOST NO. OR LOCATION (THIS SESSION) Clare

FILENAME W263068.FF3 DISK/TAPE ID _____

BEGINNING DATE 4-16-93 BEGINNING TIME 12:00

ENDING DATE 4-30-93 ENDING TIME 23:59

COUNT DURATION 14.5 [] HOURS [X] DAYS [] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM ☒ OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE PIEZO

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER _____	PHONE # _____
DATE PREPARED _____	

<p align="center">SHEET 13</p> <p align="center">LTPP TRAFFIC DATA</p> <p align="center">VEHICLE WEIGHT DATA TRANSMITTAL FORM</p>	<p>*STATE ASSIGNED ID [<u>306</u>]</p> <p>*STATE CODE [<u>26</u>]</p> <p>*SHRP SECTION ID [<u>3068</u>]</p>
---	---

HIGHWAY RT. NO. (THIS SESSION) US 10

MILEPOST NO. OR LOCATION (THIS SESSION) Clare

FILENAME W263068.G13 DISK/TAPE ID _____

BEGINNING DATE 5-1-83 BEGINNING TIME 00:00

ENDING DATE 5-31-83 ENDING TIME 23:59

COUNT DURATION 31 [] HOURS [☒] DAYS [] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM ☒ OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>322-1736</u>
DATE PREPARED _____	

SHEET 13 LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	*STATE ASSIGNED ID [<u>306</u>]
	*STATE CODE [<u>26</u>]
	*SHRP SECTION ID [<u>3068</u>]

HIGHWAY RT. NO. (THIS SESSION) US 10

MILEPOST NO. OR LOCATION (THIS SESSION) CLARE

FILENAME W263068.HB DISK/TAPE ID _____

BEGINNING DATE 6-1-93 BEGINNING TIME 00:00

ENDING DATE 6-30-93 ENDING TIME 23:59

COUNT DURATION 30 [] HOURS [☒] DAYS [] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM ☒ OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517 322 1736</u>
DATE PREPARED _____	

SHEET 13 LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID [<u>306</u>]
	STATE CODE [<u>26</u>]
	SHRP SECTION ID [<u>3068</u>]

HIGHWAY RT. NO. (THIS SESSION) US 10

MILEPOST NO. OR LOCATION (THIS SESSION) Clare

FILENAME Q1263068.I13 DISK/TAPE ID _____

BEGINNING DATE 7-1-93 BEGINNING TIME 00:00

ENDING DATE 7-31-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: _____

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

SHEET 13 LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID [<u>306</u>]
	STATE CODE [<u>26</u>]
	SHRP SECTION ID [<u>3068</u>]

HIGHWAY RT. NO. (THIS SESSION) US 10

MILEPOST NO. OR LOCATION (THIS SESSION) Clare

FILENAME W263068.J13 DISK/TAPE ID _____

BEGINNING DATE 8-1-93 BEGINNING TIME 00:00

ENDING DATE 8-31-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: _____

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

SHEET 13 LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID [<u>306</u>]
	STATE CODE [<u>26</u>]
	SHRP SECTION ID [<u>3068</u>]

HIGHWAY RT. NO. (THIS SESSION) 45 10

MILEPOST NO. OR LOCATION (THIS SESSION) Clare

FILENAME W263068.R13 DISK/TAPE ID _____

BEGINNING DATE 9-1-93 BEGINNING TIME 00:00

ENDING DATE 9-30-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: _____

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

SHEET 13
LTPP TRAFFIC DATA
VEHICLE WEIGHT DATA
TRANSMITTAL FORM

STATE ASSIGNED ID [306]
STATE CODE [26]
SHRP SECTION ID [3068]

HIGHWAY RT. NO. (THIS SESSION) 45 10

MILEPOST NO. OR LOCATION (THIS SESSION) Clare

FILENAME W263068.L13 DISK/TAPE ID _____

BEGINNING DATE 10-1-93 BEGINNING TIME 00:00

ENDING DATE 10-31-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: FNWA

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER James Kramer PHONE # 517-322-1736
DATE PREPARED _____

<p align="center">SHEET 13</p> <p align="center">LTPP TRAFFIC DATA</p> <p align="center">VEHICLE WEIGHT DATA TRANSMITTAL FORM</p>	STATE ASSIGNED ID [<u>306</u>]
	STATE CODE [<u>26</u>]
	SHRP SECTION ID [<u>3068</u>]

HIGHWAY RT. NO. (THIS SESSION) US 10

MILEPOST NO. OR LOCATION (THIS SESSION) Clare

FILENAME W263068.M13 DISK/TAPE ID _____

BEGINNING DATE 10-1-93 BEGINNING TIME 00:00

ENDING DATE 11-30-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [☒] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: FHWA

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

SHEET 13 LTPP TRAFFIC DATA VEHICLE WEIGHT DATA TRANSMITTAL FORM	STATE ASSIGNED ID [<u>306</u>]
	STATE CODE [<u>26</u>]
	SHRP SECTION ID [<u>3068</u>]

HIGHWAY RT. NO. (THIS SESSION) US 10 WB

MILEPOST NO. OR LOCATION (THIS SESSION) Clare

FILENAME W263068.013 DISK/TAPE ID _____

BEGINNING DATE 12-1-93 BEGINNING TIME 00:00

ENDING DATE 12-31-93 ENDING TIME 23:59

COUNT DURATION 1 [] HOURS [] DAYS [X] MONTHS

WEIGHT SCALE TYPE: PORT. WIM _____ PERM. WIM X OTHER _____

EQUIPMENT MAKE/MODEL# PAT DAW 100

SENSOR TYPE Piezo

NAME OF SHA CLASSIFICATION SCHEME: FHWA

METHOD OF CALIBRATION AND FREQUENCY: Auto

COMMENTS _____

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER <u>James Kramer</u>	PHONE # <u>517-322-1736</u>
DATE PREPARED _____	

<p align="center">SHEET 14 LTPP TRAFFIC DATA EQUIPMENT INSTALLATION LOG</p>	STATE ASSIGNED ID [<u>306</u>]
	STATE CODE [<u>26</u>] ?
	SHRP SECTION ID [<u>3068</u>]

LOCATION C/ave DATE OF INSTALLATION 4-16-93

	TYPE	BRAND NAME	SERIAL NUMBER
Control Unit(s) and peripheral equipment			
Control Unit	DAW 100	PAT	HPR 2348
Interface			
Modem	V.3225	UDS	HPR 2328
Loop Amplifiers			
Other <u>Power Supply</u>	DAW 200	PAT	HPR 2341
Sensor(s) / Platform(s)			
GPS Lane Sensor			
Sensor Next Adjacent Lane (1)			
Sensor Next Adjacent Lane (2)			
Sensor Next Adjacent Lane (3)			
Diagonal Sensor			
Offscale Sensor			
Right Platform			
Left Platform			
Other _____			
Software			
Complete Package			
Axle Spacing Algorithm Only			
Other _____			
Loops			
Upstream - Lane 1			
Downstream - Lane 1			
Upstream - Other Lanes			
Downstream - Other Lanes			