

C271016	1/1/93	00:00	7/31/93	24:00	Minn2
W271016	1/1/93	00:00	7/31/93	24:00	Minn2
C274040	1/1/93	00:00	7/31/93	24:00	Minn2
W274040	1/1/93	00:00	7/31/93	24:00	Minn2
C271087	1/1/93	00:00	7/31/93	24:00	Minn2
W271087	1/1/93	00:00	7/31/93	24:00	Minn2
C274054	1/1/93	00:00	7/31/93	24:00	Minn2
W274054	1/1/93	00:00	7/31/93	24:00	Minn2

NAME OF PREPARER: Vicky Sarner  
DATE PREPARED: December 16, 1993

PHONE NO.: 612-296-8526

C271016	8/1/93	00:00	12/31/93	24:00	Minn2
W271016	8/1/93	00:00	12/31/93	24:00	Minn2
C274040	8/1/93	00:00	12/31/93	24:00	Minn2
W274040	8/1/93	00:00	12/31/93	24:00	Minn2
C271087	9/1/93	00:00	12/31/93	24:00	Minn2
W271087	9/1/93	00:00	12/31/93	24:00	Minn2
C274054	9/1/93	00:00	12/31/93	24:00	Minn2
W274054	9/1/93	00:00	12/31/93	24:00	Minn2

NAME OF PREPARER: Vicky Sarner  
DATE PREPARED: March 28, 1994

PHONE NO.: 612-296-8526



**SHEET 14**

**LOG OF CHANGES AT GPS TEST  
LOCATIONS WITH PERM. AVC OR WIM**

\*STATE ASSIGNED ID [ \_1022\_ ]

\*STATE CODE [ 27 ]

\*SHRP SECTION ID [ \_1087 \_ ]

LOCATION TH 13 Eagan, MN TYPE EQUIP. Bending Plate

MP # 101.33 MODEL # IRD

[illegible]

SHEET 14  
LTPP TRAFFIC DATA

LOG OF CHANGES AT GPS TEST  
LOCATIONS WITH PERM. AVC OR WIM

\*STATE ASSIGNED ID [1002]

\*STATE CODE [27]

\*SHRP SECTION ID [1087]

LOCATION TH-13, EAGAN, MN TYPE EQUIP. Bending Plate

MP # 101.33 MODEL # TRD

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
9/20/93		Lane 1, Cell 1 not working.	M. Novak		
9/29/93		Upgraded site software to 7.3.2.	V. Sarnier		
10/20/93		Lane 2 & 4, Cell #4 #7 not working.			
11/8/93		Cell 4 working.			
11/24/93		Cell #7 working. Cell #8 not working.			
11/30/93		Upgraded site software to 7.3.3.			
11/28/93		Cell #7 not working.			

**LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM**

\*SHRP SECTION ID [ 1687 ]

LOCATION	TH 13 Eagan, MN	TYPE EQUIP.	Bending Plate
MP #	101.33	MODEL #	TRD

[illegible]