

RECEIVED OCT 28 1991

SHEET 1  
LTPP TRAFFIC DATA  
SUMMARY TRANSMITTAL FORM

\*STATE ASSIGNED ID 13 L L L 1

\*STATE CODE 28

\*SHRP SECTION ID 130191

3018

STATE OR PROVINCE MS COUNTY TISHOMINGO

HIGHWAY ROUTE NO. US 72 MILEPOST# 11.1

NEAREST CITY/TOWN 3 MI E OF IUKA NEAREST INTERSECTION 5 MI E OF MS25

FUNCTIONAL CLASS 2 NO. LANES EACH DIRECTION 2 TOTAL NO. LANES 4

DIRECTION OF TRAVEL GPS LANE W DATE OPENED TO TRAF. 10-21-84

FIPS COUNTY CODE 141 FHWA STATION IDENTIFICATION NO.

HPMS SAMPLE NO. 711000010000 HPMS SUBDIVISION NO.

TYPE OF PAVEMENT: AC PCC ☒ OTHER

CONTROL OF ACCESS: YES NO ☒ MEDIAN: YES ☒ NO

CURRENT SURROUNDING DEVELOPMENT:  
URBAN SUBURBAN RURAL ☒

HAS INTENSITY OF ROADSIDE DEVELOPMENT INCREASED OVER PAST 10 YEARS?  
YES NO ☒  
IF YES, DESCRIBE CHANGES

NOTE: ATTACH ALL RELATED FORMS AND COUNT DATA AND SUBMIT TO THE  
SHRP REGIONAL OFFICE. ATTACH MAP INDICATING THE LOCATION OF  
EACH TRAFFIC COUNT, VEHICLE CLASSIFICATION COUNT, OR WEIGHT  
STATION RELATIVE TO THIS GPS TEST SECTION.

NAME OF PREPARER PHONE #

DATE PREPARED

RECEIVED OCT 28 1991

<p align="center">SHEET 1</p> <p align="center"><b>LTPP TRAFFIC DATA</b></p> <p align="center"><b>SUMMARY TRANSMITTAL FORM</b></p>	*STATE ASSIGNED ID	131121
	*STATE CODE	1281
	*SHRP SECTION ID	130191
		3018

STATE OR PROVINCE MS COUNTY TISHOMINGO

HIGHWAY ROUTE NO. US 72 MILEPOST# 11.1

NEAREST CITY/TOWN 3MI E OF IUKA NEAREST INTERSECTION 5MI E OF MS25

FUNCTIONAL CLASS 2 NO. LANES EACH DIRECTION 2 TOTAL NO. LANES 4

DIRECTION OF TRAVEL GPS LANE W DATE OPENED TO TRAF. 10-01-84

FIPS COUNTY CODE 141 FHWA STATION IDENTIFICATION NO. \_\_\_\_\_

HPMS SAMPLE NO. 711000010000 HPMS SUBDIVISION NO. \_\_\_\_\_

TYPE OF PAVEMENT: AC \_\_\_\_\_ PCC ✓ OTHER \_\_\_\_\_

CONTROL OF ACCESS: YES \_\_\_\_\_ NO ✓ MEDIAN: YES ✓ NO \_\_\_\_\_

CURRENT SURROUNDING DEVELOPMENT:

URBAN \_\_\_\_\_ SUBURBAN \_\_\_\_\_ RURAL ✓

HAS INTENSITY OF ROADSIDE DEVELOPMENT INCREASED OVER PAST 10 YEARS?

YES \_\_\_\_\_ NO ✓

IF YES, DESCRIBE CHANGES \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**NOTE: ATTACH ALL RELATED FORMS AND COUNT DATA AND SUBMIT TO THE SHRP REGIONAL OFFICE. ATTACH MAP INDICATING THE LOCATION OF EACH TRAFFIC COUNT, VEHICLE CLASSIFICATION COUNT, OR WEIGHT STATION RELATIVE TO THIS GPS TEST SECTION.**

NAME OF PREPARER _____	PHONE # _____
DATE PREPARED _____	

RECEIVED AUG 10 1992

SHEET 11  
LTPP TRAFFIC DATA

VOLUME DATA  
TRANSMITTAL FORM

\*STATE ASSIGNED ID [#018]

\*STATE CODE [28]

\*SHRP SECTION ID [3018]

HIGHWAY RT. NO. (THIS COUNT) US 72 MILEPOST NO. (THIS COUNT) NA

LOCATION (THIS COUNT) Iuka, Tishomingo County

FILENAME V283018.F12 DIST/TAPE ID SHRP No. 1

BEGINNING DATE 4-1-92 BEGINNING TIME 0 hour A.M.

ENDING DATE 6-30-92 ENDING TIME 24 hour P.M.

TYPE OF COUNT: TWO-WAY X ONE-WAY        SPS LANES       

COUNT DURATION 3 [ ] HOURS [ ] DAYS [X] MONTHS

TYPE OF SENSOR        ROAD TUBES X PIEZO CABLE

       PIEZO FILM        LOOPS        OTHER       

EQUIPMENT MANUFACTURER/MODEL # PAT - DAW 100

AXLE CORRECTION FACTOR N/A STANDARD DEV. OF FACTOR N/A

MONTHLY/SEASONAL FACTOR N/A STANDARD DEV. OF FACTOR N/A

DAY-OF-WEEK FACTOR N/A STANDARD DEV. OF FACTOR N/A

OTHER FACTOR N/A STANDARD DEV. OF FACTOR N/A  
SPECIFY       

DISTRIBUTION FACTOR FOR GPS LANE N/A  
(WHEN NOT AVAILABLE FROM ACTUAL COUNT DATA.)

SOURCE OF GPS LANE DISTRIBUTION FACTOR ESTIMATE       

COMMENTS: Day 4-7-92 missing.  
Day 4-23-92, hours 1-9 missing.  
Day 5-14-92, hour 16 missing.

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER Carolyn R. Thornton PHONE # 601-944-9142  
DATE PREPARED 8-1-92

SHEET 11  
LTPP TRAFFIC DATAVOLUME DATA  
TRANSMITTAL FORM

\*STATE ASSIGNED ID [#018]

\*STATE CODE [28]

\*SHRP SECTION ID [3018]

HIGHWAY RT. NO. (THIS COUNT) US 72 MILEPOST NO. (THIS COUNT) NALOCATION (THIS COUNT) Iuka, Tishomingo CountyFILENAME V283018.I12 DIST/TAPE ID SHRP No. 1BEGINNING DATE 7-1-92 BEGINNING TIME 0 hour A.M.ENDING DATE 9-30-92 ENDING TIME 24 hour P.M.TYPE OF COUNT: TWO-WAY X ONE-WAY        SPS LANES       COUNT DURATION 3 [ ] HOURS [ ] DAYS [X] MONTHSTYPE OF SENSOR        ROAD TUBES X PIEZO CABLE       PIEZO FILM        LOOPS        OTHER       EQUIPMENT MANUFACTURER/MODEL # PAT - DAW 100AXLE CORRECTION FACTOR N/A STANDARD DEV. OF FACTOR N/AMONTHLY/SEASONAL FACTOR N/A STANDARD DEV. OF FACTOR N/ADAY-OF-WEEK FACTOR N/A STANDARD DEV. OF FACTOR N/AOTHER FACTOR N/A STANDARD DEV. OF FACTOR N/A  
SPECIFY       DISTRIBUTION FACTOR FOR GPS LANE N/A  
(WHEN NOT AVAILABLE FROM ACTUAL COUNT DATA.)SOURCE OF GPS LANE DISTRIBUTION FACTOR ESTIMATE       COMMENTS: Days 7-22 through 7-24, 7-29, 7-30 missing.

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER Carolyn R. Thornton PHONE # 601-944-9142  
DATE PREPARED 10-22-92

SHEET 11  
LTPP TRAFFIC DATA

VOLUME DATA  
TRANSMITTAL FORM

\*STATE ASSIGNED ID [#018]  
\*STATE CODE [28]  
\*SHRP SECTION ID [3018]

HIGHWAY RT. NO. (THIS COUNT) US 72 MILEPOST NO. (THIS COUNT) NA

LOCATION (THIS COUNT) Iuka, Tishomingo County

FILENAME V283018.L12 DIST/TAPE ID SHRP No. 1

BEGINNING DATE 10-1-92 BEGINNING TIME 0 hour A.M.

ENDING DATE 12-31-92 ENDING TIME 24 hour P.M.

TYPE OF COUNT: TWO-WAY X ONE-WAY        SPS LANES       

COUNT DURATION 3 [ ] HOURS [ ] DAYS [X] MONTHS

TYPE OF SENSOR        ROAD TUBES X PIEZO CABLE

       PIEZO FILM        LOOPS        OTHER       

EQUIPMENT MANUFACTURER/MODEL # PAT - DAW 100

AXLE CORRECTION FACTOR N/A STANDARD DEV. OF FACTOR N/A

MONTHLY/SEASONAL FACTOR N/A STANDARD DEV. OF FACTOR N/A

DAY-OF-WEEK FACTOR N/A STANDARD DEV. OF FACTOR N/A

OTHER FACTOR N/A STANDARD DEV. OF FACTOR N/A

SPECIFY       

DISTRIBUTION FACTOR FOR GPS LANE N/A  
(WHEN NOT AVAILABLE FROM ACTUAL COUNT DATA.)

SOURCE OF GPS LANE DISTRIBUTION FACTOR ESTIMATE       

COMMENTS:       

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER Carolyn R. Thornton PHONE # 601-944-9142  
DATE PREPARED 1-13-93

SHEET 11  
LTPP TRAFFIC DATA

\*STATE ASSIGNED ID [#018]

VOLUME DATA  
TRANSMITTAL FORM

\*STATE CODE [28]

\*SHRP SECTION ID [3019]

HIGHWAY RT. NO. (THIS COUNT) US 72 MILEPOST NO. (THIS COUNT) NALOCATION (THIS COUNT) Iuka, Tishomingo CountyFILENAME V283019.C13 DIST/TAPE ID SHRP No. 1BEGINNING DATE 1-1-93 BEGINNING TIME 0 hour A.M.ENDING DATE 3-31-93 ENDING TIME 24 hour P.M.TYPE OF COUNT: TWO-WAY X ONE-WAY        SPS LANES       COUNT DURATION 80 [ ] HOURS [X] DAYS [ ] MONTHSTYPE OF SENSOR        ROAD TUBES X PIEZO CABLE       PIEZO FILM        LOOPS        OTHER       EQUIPMENT MANUFACTURER/MODEL # PAT - DAW 100AXLE CORRECTION FACTOR N/A STANDARD DEV. OF FACTOR N/AMONTHLY/SEASONAL FACTOR N/A STANDARD DEV. OF FACTOR N/ADAY-OF-WEEK FACTOR N/A STANDARD DEV. OF FACTOR N/AOTHER FACTOR N/A STANDARD DEV. OF FACTOR N/A  
SPECIFY       DISTRIBUTION FACTOR FOR GPS LANE N/A  
(WHEN NOT AVAILABLE FROM ACTUAL COUNT DATA.)SOURCE OF GPS LANE DISTRIBUTION FACTOR ESTIMATE       COMMENTS: Hours 2-23 missing on 3-28-93.

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER Carolyn R. Thornton PHONE # 601-944-9142  
DATE PREPARED 4-15-93

SHEET 11  
LTPP TRAFFIC DATAVOLUME DATA  
TRANSMITTAL FORM

\*STATE ASSIGNED ID [#018]

\*STATE CODE [28]

\*SHRP SECTION ID [3018]

HIGHWAY RT. NO. (THIS COUNT) US 72 MILEPOST NO. (THIS COUNT) NALOCATION (THIS COUNT) Iuka, Tishomingo CountyFILENAME V283018.C13 DIST/TAPE ID SHRP No. 1BEGINNING DATE 1-1-93 BEGINNING TIME 0 hour A.M.ENDING DATE 3-31-93 ENDING TIME 24 hour P.M.TYPE OF COUNT: TWO-WAY X ONE-WAY        SPS LANES       COUNT DURATION 80 [ ] HOURS [X] DAYS [ ] MONTHSTYPE OF SENSOR        ROAD TUBES X PIEZO CABLE       PIEZO FILM        LOOPS        OTHER       EQUIPMENT MANUFACTURER/MODEL # PAT - DAW 100AXLE CORRECTION FACTOR N/A STANDARD DEV. OF FACTOR N/AMONTHLY/SEASONAL FACTOR N/A STANDARD DEV. OF FACTOR N/ADAY-OF-WEEK FACTOR N/A STANDARD DEV. OF FACTOR N/AOTHER FACTOR N/A STANDARD DEV. OF FACTOR N/A  
SPECIFY       DISTRIBUTION FACTOR FOR GPS LANE N/A  
(WHEN NOT AVAILABLE FROM ACTUAL COUNT DATA.)SOURCE OF GPS LANE DISTRIBUTION FACTOR ESTIMATE       COMMENTS: Hours 2-23 missing on 3-28-93.

FILL OUT ONE TRANSMITTAL SHEET FOR EACH DATA FILE SUBMITTED.

NAME OF PREPARER Carolyn R. Thornton PHONE # 601-944-9142  
DATE PREPARED 4-15-93

RECEIVED SEP 20 2000

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATION WITH PERM. AVC OR WIM	*STATE ASSIGNED ID[ 018 ]
	*STATE CODE [ 28 ]
	*SHRP SECTION ID [ 3018/19]

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. PAT

MP # N/A

MODEL# DAW 100

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
August 2, 2000	13:25	Change piezo board.	Johnie Thomas	(601) 359-1502	
August 8, 2000	8:05	Changed mother board.	Johnie Thomas	(601) 359-1502	
August 15, 2000	9:30	Change mother board, and loop board.	Johnie Thomas	(601) 359-1502	



RECEIVED AUG 28 2000

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATION WITH PERM. AVC OR WIM	*STATE ASSIGNED ID[ 018 ]
	*STATE CODE [ 28 ]
	*SHRP SECTION ID [ 3018/19]

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. PAT

MP # N/A

MODEL# DAW 100

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
July 5, 2000	12:00	Replaced the battery.	Johnie Thomas	(601) 359-1502	
July 10, 2000	12:45	Reset fuse of mother board, replace phone jack.	Johnie Thomas	(601) 359-1502	
July 19, 2000	16:35	Replaced the battery.	Johnie Thomas	(601) 359-1502	
July 27, 2000	12:35	Replaced piezo card.	Johnie Thomas	(601) 359-1502	

RECEIVED JUL 24 2000

<p align="center">SHEET 15</p> <p>LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATION WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID[ 018 ]</p> <p>*STATE CODE [ 28 ]</p> <p>*SHRP SECTION ID [ 3018/19]</p>
--	---

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. PAT

MP # N/A

MODEL# DAW 100

[illegible]

RECEIVED MAY 18 2000

<b>SHEET 15</b> <b>LTPP TRAFFIC DATA</b>  <b>LOG OF CHANGES AT GPS TEST</b> <b>LOCATION WITH PERM. AVG OR WIM</b>	<b>*STATE ASSIGNED ID</b> [ 018 ]
	<b>*STATE CODE</b> [ 28 ]
	<b>*SHRP SECTION ID</b> [ 3018/19 ]

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. PAT

MP # N/A

MODEL# DAW 100

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
April 10, 2000	13:57	Changed battery and reset the loops.	Johnie Thomas	(601) 359-1502	
April 26, 2000	12:00	Changed battery.	Johnie Thomas	(601) 359-1502	

RECEIVED MAR 27 2000

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATION WITH PERM. AVC OR WIM	*STATE ASSIGNED ID[ 018 ]
	*STATE CODE [ 28 ]
	*SHRP SECTION ID [ 3018/19]

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. PAT

MP # N/A

MODEL# DAW 100

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
February 8, 2000	8:15	Replaced battery.	Johnie Thomas	(601) 359-1502	
February 15, 2000	13:40	Changed battery.	Johnie Thomas	(601) 359-1502	

RECEIVED JAN 24 2000

SHEET 15 LTPP TRAFFIC DATA	*STATE ASSIGNED ID[ 018 ]
LOG OF CHANGES AT GPS TEST LOCATION WITH PERM. AVC OR WIM	*STATE CODE [ 28 ] *SHRP SECTION ID [ 3018 & 19]

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. PAT

MP # N/A

MODEL# DAW 100

[illegible]

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATION WITH PERM. AVC OR WIM	*STATE ASSIGNED ID[ 018 ]
	*STATE CODE [ 28 ]
	*SHRP SECTION ID [ 3018/19]

LOCATION IUKA, TISHOMINGO COUNTYTYPE EQUIP. PATMP # N/AMODEL# DAW 100

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
November 2, 1999	9:30	Changed battery.	Johnie Thomas	(601) 359-1502	
November 17, 1999	10:40	Changed battery.	Johnie Thomas	(601) 359-1502	

RECEIVED SEP 07 1999

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATION WITH PERM. AVC OR WIM	*STATE ASSIGNED ID[ 018 ]
	*STATE CODE [ 28 ]
	*SHRP SECTION ID [ 3018 & 19]

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. PAT

MP # N/A

MODEL# DAW 100

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
July 1, 1999	15:00	REPLACED BATTERY.	JOHNIE THOMAS	(601) 359-1502	
July 21, 1999	14:55	CHANGED THE MODEM.	JOHNIE THOMAS	(601) 359-1502	
July 27, 1999	14:20	CHANGED THE BATTERY AND LOOP BOARD.	JOHNIE THOMAS	(601) 359-1502	
July 28, 1999	8:30	CHANGE THE BATTERY.	JOHNIE THOMAS	(601) 359-1502	

SHEET 15 LTPP TRAFFIC DATA  LOG OF CHANGES AT GPS TEST LOCATION WITH PERM. AVC OR WIM	*STATE ASSIGNED ID[ 018 ]
	*STATE CODE [ 28 ]
	*SHRP SECTION ID [ 3018&19]

LOCATION IUKA, TISHOMINGO COUNTYTYPE EQUIP. PATMP # N/AMODEL# DAW 100

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
June 2, 1999	12:00	REPLACED BATTERY AND CHANGE THE PIEZO BOARD.	JOHNIE THOMAS	(601) 359-1502	
June 8, 1999	12:45	RESET MODEM.	JOHNIE THOMAS	(601) 359-1502	



## LTPP TRAFFIC DATA

**LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM**

STATE ASSIGNED ID [018]

STATE CODE [28]

SHRP SECTION ID 130 18.

LOCATION TRICA, TISHOMINGO CO. TYPE EQUIP. PAT

MP # NA

MODEL # DAW 100

RECEIVED SEP 11 1998

[illegible]

**LOG OF CHANGES AT GPS TEST  
LOCATIONS WITH PERM. AVC OR WIM**

SHRP SECTION ID [30/8]

RECEIVED JAN 20 1964

RECEIVED JAN 20 1998

MP # NA

TYPE EQUIP. PAT

MODEL # DAW 100

[illegible]

**LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM**

SHRP SECTION ID [3048]

MP # NA

MODEL # DAW 100

RECEIVED OCT 14 1997

[illegible]

**LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM**

SHRP SECTION ID [30/8]

MP # NA

MODEL # DAW 100

[illegible]

RECEIVED APR 19 1996

<b>SHEET 15</b> <b>LTPP TRAFFIC DATA</b> <b>LOG OF CHANGES AT GPS TEST</b> <b>LOCATIONS WITH PERM. AVC OR WIM</b>	STATE ASSIGNED ID [ <u>018</u> ]
	STATE CODE [ <u>28</u> ]
	SHRP SECTION ID [ <u>3018</u> ]

LOCATION Iuka, Tishomingo Co TYPE EQUIP. PAT

MP # NA MODEL # DAW 100

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
8-2-94	16:34	PIEZO ANALYZER BOARD - BURN O.I.T SENT TO FACTORY FOR REPAIR. UNIT OUT OF ORDER, PIEZO BOARD WAS	ALAN D. HATCH	359 7685	N/A
11	11	NOT AVAILABLE (UNIT SHUT DOWN)	11	11	11

RECEIVED OCT 20 1994

<b>SHEET 15</b> <b>LTPP TRAFFIC DATA</b> <b>LOG OF CHANGES AT GPS TEST</b> <b>LOCATIONS WITH PERM. AVC OR WIM</b>	STATE ASSIGNED ID [ <u>018</u> ]
	STATE CODE [ <u>28</u> ]
	SHRP SECTION ID [ <u>3018</u> ]

LOCATION Iuka, Tishomingo Co TYPE EQUIP. PAT

MP # NA MODEL # DAW 100

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
4-20-94	16:44	Loop Analyzer Board Malfunction Installed Good Board Unit Back in Order	ALAN D. Hatch	944 9142	3119
6-14-94	15:30	INSTALLED CHARGED BATTERY UNIT BACK IN ORDER	ALAN D. Hatch	CC	N/A

RECEIVED JUL 20 1994

SHEET 15	*STATE ASSIGNED ID[ 018 ]
LTPP TRAFFIC DATA	
	*STATE CODE [ 28 ]
LOG OF CHANGES AT GPS TEST	
LOCATION WITH PERM. AVC OR WIM	*SHRP SECTION ID [ 3018/19]

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. \_\_\_\_\_ PAT \_\_\_\_\_

MP #	N/A
------	-----

MODEL#                      DAW 100

[illegible]

<b>SHEET 15</b> <b>LTPP TRAFFIC DATA</b>  <b>LOG OF CHANGES AT GPS TEST</b> <b>LOCATION WITH PERM. AVC OR WIM</b>	<b>*STATE ASSIGNED ID[ 018 ]</b>
	<b>*STATE CODE [ 28 ]</b>
	<b>*SHRP SECTION ID [ 3018/19]</b>

LOCATION IUKA, TISHOMINGO COUNTYTYPE EQUIP. PATMP # N/AMODEL# DAW 100

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
May 16, 2000	12:30	Changed the battery.	Johnie Thomas	(601) 359-1502	
May 31, 2000	13:45	Changed the battery.	Johnie Thomas	(601) 359-1502	



RECEIVED APR 24 2000

<b>SHEET 15</b> <b>LTPP TRAFFIC DATA</b>  <b>LOG OF CHANGES AT GPS TEST</b> <b>LOCATION WITH PERM. AVC OR WIM</b>	<b>*STATE ASSIGNED ID[ 018 ]</b>
	<b>*STATE CODE [ 28 ]</b>
	<b>*SHRP SECTION ID [ 3018/19]</b>

LOCATION IUKA, TISHOMINGO COUNTY

TYPE EQUIP. PAT

MP # N/A

MODEL# DAW 100

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE NUMBER	NEW EQUIPMENT SERIAL NUMBER
March 6, 2000	15:40	Replaced the battery.	Johnie Thomas	(601) 359-1502	
March 22, 2000	9:30	Replaced the piezo board, changed the overall sensitivity and front axle.	Johnie Thomas	(601) 359-1502	

RECEIVED JAN 16 1996

**SHEET 15**  
**LTPP TRAFFIC DATA**

**LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM**

STATE ASSIGNED ID [ \_ 018 ]

STATE CODE [ 28 ]

SHRP SECTION ID [3048]

LOCATION Iuka, Tishomingo Co TYPE EQUIP. PAT

MP # NA MODEL # DAW 100

[illegible]

<b>SHEET 15</b> <b>LTPP TRAFFIC DATA</b> <b>LOG OF CHANGES AT GPS TEST</b> <b>LOCATIONS WITH PERM. AVC OR WIM</b>	STATE ASSIGNED ID [ 018 ]
	STATE CODE [ 28 ]
	SHRP SECTION ID [ 3018 ]

LOCATION Iuka, Tishomingo Co TYPE EQUIP. PAT

MP # NA MODEL # DAW 100

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
7-10-95	16:34 PM	MALFUNCTION IN PIEZO ANALYZER BOARD (OVERHEATED). LOOP BOARD LANES 1 AND 2 SIGNAL LOSS.	ALAN D. HATCH	601 359-7685	PIEZO BOARD 772 LOOP BOARD 665
11	11	REPLACED WITH GOOD BOARDS RESET	11	11	11
7-18-95	10:58 AM	MALFUNCTION IN PIEZO ANALYZER BOARD (OVERHEATED). LOOP BOARD LANE 1 SIGNAL LOSS.	11	11	PIEZO BOARD 9300141 LOOP BOARD 590
11	11	REPLACED WITH GOOD BOARDS RESET	11	11	11

SHEET 15

## LTPP TRAFFIC DATA

LOG OF CHANGES AT GPS TEST  
LOCATIONS WITH PERM. AVC OR WIM

STATE ASSIGNED ID [ 018 ]

STATE CODE [ 28 ]

SHRP SECTION ID [ 3018 ]

LOCATION Iuka, Tishomingo Co TYPE EQUIP. PATMP # NA MODEL # DAW 100

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
4-18-95	15:30	CHANGED BATTERY AND COLLECTED DATA UNIT BACK IN ORDER (OK) NOISE IN PHONE LINE (REPAIRED-OK)	ALAN D. HATCH	601 359 7685	NC

RECEIVED AUG - 2 1995