

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P09]
	*STATE CODE	[53]
	*SHRP SECTION ID	[3019]

LOCATION SR 82 TYPE EQUIP. Piezo (Class 1)

MP # 121.20 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
9/00		SITE RE-INSTALLED			9104-1033
10/01/00		<u>Plymouth WIM</u> Was: No answer. Found: GFI tripped; reset (discovered this on 12-19). Discovered system hung up in boot process (on 12-20); cold restart worked.	RICH R		