

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[P6]
	*STATE CODE	[53]
	*SHRP SECTION ID	[6049]

 LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

 MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
12/31/10		No Changes			
12/15/10		<p>HIGHEST IMPACT I-405 Northbound - On I-405 northbound just north of SR 167 there is a collision blocking all lanes. At milepost 4 Note***: webcam at S 5th showed at least 7 cars and maybe one semi involved (9:20am); 2 cars backwards, one sideways, one with no wheels underneath. Alternate route advised. Southbound traffic slowing to look (Tom)</p> <p>HIGHEST IMPACT I-405 Northbound - Update 9:51 AM : On I-405 northbound just north of SR 167 there is a collision blocking all lanes. The current backup is 2 miles. At milepost 4 (traffic bailing to SR 167)</p>			

12/29/10		<p>Two Injured In Hwy. 167 Collision Involving State Trooper Patrol Car Two Lanes Blocked by Crash 11:05 p.m. PST, December 29, 2010 Emergency crews responded late Wednesday night to an accident on State Route 167 involving a Washington State Patrol Trooper. The collision involving the Troopers patrol car and another vehicle occurred around 10:30 p.m. Wednesday night, and it's not clear which driver was injured.</p> <p>WSP Spokesperson Julie Startup said the wreck happened when a WSP trooper was traveling northbound to the scene of an collision. The trooper was traveling in the HOV lane when the a car next to him lost control near S. 212th St. and spun in front of his cruiser. The cruiser t-boned the passenger car.</p> <p>The cruiser's airbags deployed and the trooper sustained minor injuries. He was taken to Valley Hospital to get checked out. The driver of the passenger car sustained serious injuries and was also transported to Valley Hospital.</p> <p>The accident blocked the two left lanes of Highway 167 Northbound just South of South 212th Street just after it happened.</p> <p>A second minor collision occurred a short time later when another trooper was traveling northbound on Hwy.167 in the HOV lane to assist with the first collision. A semi truck bumped a passenger car into the cruiser causing the second crash. No one was injured in that collision. (Tom)</p>			
12/30/10		<p>HIGHEST IMPACT SR 167 Southbound - Update 2:15 PM : On SR 167 southbound at S 180th St (MP 25) there is a collision blocking the 2 right lanes. Fire Assistance, the Incident Response Team, and the State Patrol have arrived on the scene. At milepost 25 (Tom)</p>			

<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [P6)</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [6049]</p>
---	--

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
11/30/10		No Changes			
11/4/10		<p>HIGHEST IMPACT</p> <p>SR 167 Northbound - On SR 167 northbound at 180th St Uxing (mp 24.42) there is a collision blocking all 3 lanes. (3:45pm) At milepost 25 . Traffic getting by on shoulder or taking NB off ramp to South 180th. (Tom)</p>			
11/19/10		<p>HIGHEST IMPACT</p> <p>SR 167 Northbound (2:35pm) - On SR 167 northbound just north of South 180th St there is a collision blocking the 2 right lanes.(6 cars and a flatbed semi; the pickup turned sideways looked like it lost the rear axle) At milepost 25.</p> <p>Fire Assistance, the Incident Response Team, and the State Patrol have arrived on the scene.</p> <p>Two fire trucks arrived at 2:45pm so only one lane open (Tom)</p>			

<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [P6] *STATE CODE [53] *SHRP SECTION ID [6049]</p>
---	---

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
10/31/10		No Changes			
10/14/10		<p>HIGHEST IMPACT SR 167 Northbound - On SR 167 northbound at S 180th St there is a collision blocking the center lane. At milepost 25 (raining; 4:55pm) (Tom)</p>			
10/15/10		<p>HIGHEST IMPACT SR 167 Northbound (3:25pm)- On SR 167 northbound just south of S 180th St there is a collision blocking the right lane. At milepost 25 (Tom)</p>			
10/19/10		<p>HIGHEST IMPACT SR 167 Northbound - On SR 167 northbound just south of I-405 there is a collision blocking the center lane (3pm). At milepost 25 (Tom)</p> <p>HIGHEST IMPACT SR 167 Northbound - Update 3:22 PM : On SR 167 northbound at S 180th St there is a collision blocking the right lane. Medical Aid, Fire Assistance, and the State Patrol have arrived on the scene. At milepost 25</p>			

10/20/10		HIGHEST IMPACT SR 167 Northbound - Update 3:16 PM : On SR 167 northbound at S 180th St there is a collision blocking the right lane. Fire Assistance and the State Patrol have arrived on the scene. At milepost 25 (Tom)			
10/21/10		HIGHEST IMPACT SR 167 Southbound - Update 3:49 PM : On SR 167 southbound just south of I-405 there is a collision blocking the 2 left lanes. Medical Aid, the Incident Response Team, and the State Patrol have arrived on the scene. At milepost 26 (Tom)			
10/25/10		MODERATE IMPACT I-405 Southbound - Monday, Oct. 25 - the morning of Friday, Oct. 29 - The off-ramp from southbound I-405 to north and southbound SR 167 will close nightly from 11 p.m. to 4:30 a.m. for construction work. At milepost 2 (Tom)			
10/29/10		HIGHEST IMPACT SR 167 Northbound - On SR 167 northbound at S 180th St there is a collision blocking the 2 left lanes (1:35pm). Medical Aid has arrived on the scene. At milepost 24.40 (Tom)			

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[P6]
	*STATE CODE	[53]
	*SHRP SECTION ID	[6049]

 LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

 MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
9/30/10		No Changes			
9/14/10		HIGHEST IMPACT SR 167 Northbound - Update 6:53 AM : On SR 167 northbound just south of I-405 there is a disabled vehicle blocking the center lane. At milepost 26 (Tom)			
9/15/10		HIGHEST IMPACT SR 167 Northbound - On SR 167 northbound at S 180th St there is a collision blocking the HOV lane. At milepost 25 (raining; 4:45pm) (Tom)			

<p style="text-align: center;">SHEET 15 LTPP TRAFFIC DATA</p> <p style="text-align: center;">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [P6)</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [6049]</p>
---	--

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
8/31/10		No Changes			
8/3/10		<p>HIGHEST IMPACT I-405 Northbound - Update 7:34 AM : On I-405 northbound just south of 112th Ave SE there is a disabled vehicle blocking the right lane. The current backup is 7 miles. Fire Assistance, the Incident Response Team, and the State Patrol have arrived on the scene. At milepost 9</p> <p>HIGHEST IMPACT I-405 Northbound - Update 8:07 AM : On I-405 northbound at SR167 I/C there is a collision blocking the HOV lane. Medical Aid, Fire Assistance, the Incident Response Team, Tow Assistance, and the State Patrol have arrived on the scene. At milepost 2 (Tom)</p>			
8/6/10		<p>Kent: Southbound SR 167 at 180th St., there is an incident blocking the HOV lane that's causing a visual distraction.</p> <p>UPDATE: Southbound SR 167 @ 180th St, the incident in HOT lane is not impacting SB traffic but there is a 2 mile backup in NB lanes. TIME: 6:50 a.m. (Tom)</p>			

File: 800.12-11-8-12

8/12/10		HIGHEST IMPACT SR 167 Northbound - Update 4:08 PM : On SR 167 northbound at 180th St there is a collision blocking the HOV lane. At milepost 25 (Tom)			
---------	--	---	--	--	--

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[P6]
	*STATE CODE	[53]
	*SHRP SECTION ID	[6049]

 LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

 MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
7/31/10		No Changes			

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[P6]
	*STATE CODE	[53]
	*SHRP SECTION ID	[6049]

 LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

 MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
6/30/10		No Changes			

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[P6)
	*STATE CODE	[53]
	*SHRP SECTION ID	[6049]

 LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

 MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
5/5/10		<p>HIGHEST IMPACT SR 167 Northbound - On SR 167 northbound just south of I-405 I/C there is a collision blocking the (HOV) left lane. Medical Aid, Fire Assistance, and the State Patrol have arrived on the scene (0935). At milepost 26 (Tom)</p> <p>Cleared 9:55 AM : On SR 167 northbound just south of I-405 I/C there is a collision blocking the left lane. Medical Aid, Fire Assistance, the Incident Response Team, and the State Patrol have arrived on the scene.</p>	jh		
5/5/10		<p>HIGHEST IMPACT SR 167 Northbound - On SR 167 northbound at S 180th St there is a collision blocking the center lane (1545). At milepost 25 (Tom)</p>	jh		

4/16/10		<p>Multi-vehicle accident on SR 167 NB at mp 24.43 just North of off ramp to S 180th St; traffic being diverted to 180th ramp. SR 167 SB HOV lane blocked by fire truck (3:50pm) (Tom)</p> <p>HIGHEST IMPACT SR 167 Northbound - SR 167 northbound at S 180th St collision blocking all lanes, verified with camera 4:03 PM - State Patrol on scene At milepost 25</p>			
4/16/10		<p>HIGHEST IMPACT SR 167 Southbound - Update 4:18 PM : SR 167 southbound at S 180th St collision blocking HOV lane, verified with camera 4:04 PM - Fire Dept, State Patrol on scene. At milepost 25 Causing backup on I-405</p> <p>HIGHEST IMPACT SR 167 Northbound - Update 4:11 PM : SR 167 northbound at S 180th St collision blocking all lanes, verified with camera 4:03 PM - Aid, Fire Dept, Incident Response Team, State Patrol on scene. At milepost 25 (Tom)</p>			

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[P6]
	*STATE CODE	[53]
	*SHRP SECTION ID	[6049]

File: 800.12.11.8.12

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
4/5/10		<p>Woman injured in rollover crash dies in hospital Monday, April 5th, 06:23pm</p> <p>A Kent woman was killed Monday afternoon when she lost control of the SUV she was driving and crashed on State Route 167. The crash happened near S. 277th St. at about 5:25 p.m.</p> <p>Troopers said the woman was driving a 1998 Chevy Blazer south into heavy traffic and clipped the back of another vehicle and rolled over.</p> <p>The 36-year-old woman was ejected from the SUV. She was airlifted to Harborview Medical Center where she later died.</p> <p>Her name has not been released.</p> <p>No one else was injured in the crash, and troopers are trying to determine exactly what caused her to lose control.</p> <p>Two southbound lanes and the northbound HOV lane were shut down for the investigation after the crash. (Tom)</p>			

File: 800.12.11.8.12
536049

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [P6]</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [6049]</p>
---	--

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
3/5/10		SR 167 southbound just south of I-405 incident blocking right lane, verified with camera 2:34 PM - Fire Dept on scene (at SB off ramp to S 180 th St(mp 24.43); Boeing fuselage hauler tractor went down SR 167, trailer took ramp). Causing backup on I-405 SB. (Tom)			
3/22/10	1100-1200	Site inspected. Copied log and parameter files. Site looks good! (HN)	HN		
3/23/10		HIGHEST IMPACT SR 167 Northbound - Update 3:47 PM : SR 167 northbound at S 180th St 3 car collision blocking HOV lane and partially blocking left lane, verified with camera 3:44 PM - Aid on scene. At milepost 25 (Tom)			