

File: 800.12.11.8.12

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [P6)</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [6049]</p>
---	--

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
12/31/12		No Changes			
12/3/12		12/3/12 Kent P6 Phone line has been repaired. (HN)			
12/11/12		HIGHEST IMPACT SR 167 Northbound - On SR 167 northbound at S 180th St (MP 24) there is a collision blocking the HOV lane. Last Updated: 12/11/2012 7:41 AM At milepost 24 (Tom)			
12/12/12		HIGHEST IMPACT I-405 Southbound - Update 11:36 AM : On the I-405 southbound off-ramp to SR167 I/C (MP 2) there is a collision blocking the ramp. Medical Aid, Fire Assistance, the Incident Response Team, and the State Patrol have arrived on the scene. Last Updated: 12/12/2012 11:37 AM At milepost 2 Note***: I-405 NB slowing to look, causing SR 167 NB backup (Tom)			

File: 800.12.11.8.12

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[P6]
	*STATE CODE	[53]
	*SHRP SECTION ID	[6049]

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
11/30/12		No Changes			
11/1/12		11/1/12 Kent P6 Problem connecting or staying connected. Removed ZDX modem [REDACTED]. Installed ZDX modem #6083691. Had Tony called to verify connection. (HN) Note***: missing data 11/1-2, 7-11 (Tom)	HOANG		
11/27/12		11/27/12 Kent P6 Problem connecting to site, taking too long to download. Replaced RJ-11, phone cable, and direct burial cable from our cabinet to the interface with no help. Phone line is a scratchy. Contacted phone company for repair. (HN) Note***: no data Nov 1, 2, 7-11. File for 11/4 goes from 0000 to 2300 with a second file for 2300 to 0000 11/5 (Daylight/Standard adjust). No data 22-28 so there probably won't be enough data for November. (Tom)	HOANG		

File: 80.12.11.8.12

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P6]
	*STATE CODE	[53]
	*SHRP SECTION ID	[6049]

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
10/31/12		No Changes			
10/3/12		<p>HIGHEST IMPACT</p> <p>I-405 Northbound - On the I-405 northbound on-ramp from SR167 I/C (MP 2) there is a disabled vehicle (on fire) blocking the right lane. The Incident Response Team has arrived on the scene.</p> <p>Last Updated: 10/3/2012 12:57 PM</p> <p>At milepost 2 (Tom)</p>			
10/26/12		<p>HIGHEST IMPACT</p> <p>SR 167 Northbound - Update 8:19 AM : On SR 167 northbound just north of I-405 I/C (MP 26) there is a (4 car) collision blocking the left lane and partially blocking the right lane. Medical Aid, Fire Assistance, the Incident Response Team, Tow Assistance, and the State Patrol have arrived on the scene.</p> <p>Last Updated: 10/26/2012 8:20 AM</p> <p>At milepost 26 (Tom)</p>			
10/30/12		<p>Webcam at 180th shows traffic backup Northbound on SR 167 at 10:50am due to a military convoy going Northbound on I-405 (Tom)</p>			

[illegible]

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P6]
	*STATE CODE	[53]
	*SHRP SECTION ID	[6049]

File: 807 12.11.8.12

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
9/30/12		No Changes			
9/4/12		LOW IMPACT SR 167 Both Directions - Tuesday, Sept. 4 to the morning of Friday, Sept. 7 - Crews will close the carpool lane in both directions of SR 167 between S. 192nd to I-405, nightly, for barrier work. The northbound lane will close from 8 p.m. to 4:30 a.m. The southbound lane will close from 9 p.m. to 5 a.m. Last Updated: 9/4/2012 2:56 PM From milepost 24 to milepost 27 (Tom)			

9/13/12		<p>2:35pm webcam shows brushfire on SR 167 Southbound at Green River mp 18.99; traffic getting by in HOV and center lane (until fire department took center lane). Fire stretches a couple hundred yards (Tom)</p> <p>HIGHEST IMPACT SR 167 Southbound - Update 2:46 PM : On SR 167 southbound just south of SR 516 (MP 19) there is an incident blocking the 2 right lanes. Fire Assistance, the Incident Response Team, and the State Patrol have arrived on the scene. Last Updated: 9/13/2012 2:47 PM At milepost 19</p> <p>SR 167 Southbound - Update 3:17 PM : On SR 167 southbound just south of SR 516 (MP 19) there is an incident blocking the right lane. The current backup is 5 miles.</p> <p>HIGHEST IMPACT SR 167 Southbound - Update 3:15 PM : On SR 167 southbound at S 212th St (MP 22) there is a collision blocking the 2 left lanes. Medical Aid, Fire Assistance, and the Incident Response Team have arrived on the scene. Last Updated: 9/13/2012 3:15 PM At milepost 22</p>			
9/24/12		<p>Main Message: Start 7:07 PM; Cleared 7:31 AM : On SR 167 northbound just north of S 212th St (MP 22) there is a collision blocking the HOV lane. Medical Aid, Fire Assistance, the Incident Response Team, and the State Patrol have arrived on the scene. (Tom)</p>			
9/25/12		<p>Main Message: Start 5:35 AM; Cleared 5:58 AM : On SR 167 northbound just south of I-405 (MP 25) there is a collision blocking the 2 right lanes. The Incident Response Team and the State Patrol have arrived on the scene. (Tom)</p>			

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[P6]
	*STATE CODE	[53]
	*SHRP SECTION ID	[6049]

 LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

 MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
6/30/12		No Changes			
6/12/12		Collision SR 167 NB @ S 180th St Cleared 3:49 PM : On SR 167 northbound at S 180th St (MP 25) there is a collision blocking the right lane. Medical Aid, Fire Assistance, Tow Assistance, and the State Patrol have arrived on the scene. (Tom)			

800.12.11.8.12

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	<p>*STATE ASSIGNED ID [P6]</p> <p>*STATE CODE [53]</p> <p>*SHRP SECTION ID [6049]</p>
---	--

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
4/30/12		No Changes			
4/12/12		<p>HIGHEST IMPACT</p> <p>SR 167 Northbound - Update 1:17 PM : On SR 167 northbound at S 212th St (MP 22) there is a collision blocking the right lane. Medical Aid, Fire Assistance, and the Incident Response Team have arrived on the scene. Last Updated: 4/12/2012 1:18 PM At milepost 22 (Tom)</p>			
4/17/12		<p>HIGHEST IMPACT</p> <p>SR 167 Northbound - Update 9:17 AM : On SR 167 northbound at SR 516/Willis St (MP 20) there is a collision (rollover) blocking the 2 right lanes and the ramp. Medical Aid and Fire Assistance have arrived on the scene. Last Updated: 4/17/2012 9:19 AM At milepost 20 (Tom) HOV only lane open</p>			

4/25/12		<p>HIGHEST IMPACT</p> <p>SR 167 Southbound - Update 12:46 PM : On SR 167 southbound at Rainier Ave (MP 27) there is a collision blocking the left lane and two left lanes north bound. Fire Assistance and the State Patrol have arrived on the scene.</p> <p>Last Updated: 4/25/2012 12:47 PM</p> <p>At milepost 27 (Tom)</p>			
4/26/12		<p>Update 9:55 AM : On SR 167 northbound just south of S 180th St (MP 24) there is a collision blocking the HOV lane. The Incident Response Team, Tow Assistance, and the State Patrol have arrived on the scene.</p> <p>Last Updated: 4/26/2012 9:57 AM</p> <p>At milepost 24 – jh</p>			

12/29/10		<p>Two Injured In Hwy. 167 Collision Involving State Trooper Patrol Car Two Lanes Blocked by Crash 11:05 p.m. PST, December 29, 2010 Emergency crews responded late Wednesday night to an accident on State Route 167 involving a Washington State Patrol Trooper. The collision involving the Troopers patrol car and another vehicle occurred around 10:30 p.m. Wednesday night, and it's not clear which driver was injured.</p> <p>WSP Spokesperson Julie Startup said the wreck happened when a WSP trooper was traveling northbound to the scene of an collision. The trooper was traveling in the HOV lane when the a car next to him lost control near S. 212th St. and spun in front of his cruiser. The cruiser t-boned the passenger car.</p> <p>The cruiser's airbags deployed and the trooper sustained minor injuries. He was taken to Valley Hospital to get checked out. The driver of the passenger car sustained serious injuries and was also transported to Valley Hospital.</p> <p>The accident blocked the two left lanes of Highway 167 Northbound just South of South 212th Street just after it happened.</p> <p>A second minor collision occurred a short time later when another trooper was traveling northbound on Hwy.167 in the HOV lane to assist with the first collision. A semi truck bumped a passenger car into the cruiser causing the second crash. No one was injured in that collision. (Tom)</p>			
12/30/10		<p>HIGHEST IMPACT SR 167 Southbound - Update 2:15 PM : On SR 167 southbound at S 180th St (MP 25) there is a collision blocking the 2 right lanes. Fire Assistance, the Incident Response Team, and the State Patrol have arrived on the scene. At milepost 25 (Tom)</p>			

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P6)
	*STATE CODE	[53]
	*SHRP SECTION ID	[6049]

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
3/31/12		No Changes			
3/1/12		<p>HIGH IMPACT SR 167 Northbound - Heavy Traffic on SR 167 northbound from (MP 6) in Puyallup to (MP 11) at the Pierce King county line. This is due to a funeral procession. Beginning at 11:12 AM on March 01, 2012 until approximately 1:00 PM. A 5 mile traffic backup is being reported. Last Updated: 3/1/2012 11:16 AM From milepost 6 to milepost 11 (Tom)</p>			
3/20/12		<p>HIGHEST IMPACT I-405 Northbound - Update 9:22 AM : On I-405 northbound at SR167 (MP 2) there is an incident (loose debris) blocking the 3 right lanes. The Incident Response Team and the State Patrol have arrived on the scene. Last Updated: 3/20/2012 9:22 AM At milepost 2 (Tom)</p>			

3/22/12		<p>HIGHEST IMPACT</p> <p>SR 167 Southbound - Update 12:54 PM : On SR 167 southbound just north of S 180th St (MP 25) there is a collision blocking the left lane and the HOV lane. Medical Aid, Fire Assistance, the Incident Response Team, and the State Patrol have arrived on the scene.</p> <p>Last Updated: 3/22/2012 12:54 PM</p> <p>At milepost 25 (Tom)</p>			

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P6)
	*STATE CODE	[53]
	*SHRP SECTION ID	[6049]

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
2/29/12		No Changes			
2/9/12		HIGHEST IMPACT SR 167 Northbound - Update 7:29 AM : On SR 167 northbound at S 180th St (MP 25) there is a collision blocking the HOV lane. The Incident Response Team and the State Patrol have arrived on the scene. Last Updated: 2/9/2012 7:30 AM At milepost 25 (Tom)			

SHEET 15
LTPP TRAFFIC DATA

LOG OF CHANGES AT GPS TEST
LOCATIONS WITH PERM. AVC OR WIM

*STATE ASSIGNED ID [P6)
*STATE CODE [53]
*SHRP SECTION ID [6049]

LOCATION SR 167 TYPE EQUIP. Piezo (Class 1)

MP # 23.7 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		OUT OF STUDY			
1/31/12		No Changes			
1/4/12		HIGHEST IMPACT SR 167 Southbound - Update 2:40 PM : On SR 167 southbound just south of I-405 I/C (MP 26) there is a collision blocking the 2 right lanes. Fire Assistance, the Incident Response Team, and the State Patrol have arrived on the scene. At milepost 26 (Tom)			

1/5/11 ¹²		<p>Note***: multiple police agencies in foot pursuit at Jct SR 167 and I-405 at 2:30pm; capture made on I-405 SB at ramp to I-5 NB (Tom)</p> <p>HIGHEST IMPACT I-405 Southbound - On I-405 southbound just south of SR 167 (MP 1) there is an incident blocking the HOV lane. At milepost 1</p> <p>HIGHEST IMPACT I-405 Northbound - Update 2:44 PM : On I-405 northbound just south of SR 167 (MP 1) there is an incident blocking the right lane. The Incident Response Team and the State Patrol have arrived on the scene. At milepost 1</p>			
1/19/11 ¹²		<p>HIGHEST IMPACT – 2:32pm SR 167 Southbound - On SR 167 southbound just south of S 180th St (MP 25) there is an incident blocking the right lane. Fire Assistance and the State Patrol have arrived on the scene. At milepost 25 (Tom)</p>			