

<p align="center">SHEET 15 LTPP TRAFFIC DATA</p> <p align="center">LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM</p>	*STATE ASSIGNED ID	[P08]
	*STATE CODE	[53]
	*SHRP SECTION ID	[7409]

LOCATION SR 82 TYPE EQUIP. Piezo (Class 1)

MP # 48.5 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
		Due to continual ghost axle problems, this site will no longer be part of our submittal until this problem can be resolved.			
10/29/01		29 Oct 2001 – Zillah (P08) <u>Was</u> Report of WBD wt. diff. errors. <u>Action</u> Could not reproduce reported error, but discovered WBP generating "significant weight difference" errors. Lowered calibration factor on piezo #7 to correct. <u>Now</u> All good data continues, with fewer errors.	Rich Rempfer		

SHEET 15 LTPP TRAFFIC DATA LOG OF CHANGES AT GPS TEST LOCATIONS WITH PERM. AVC OR WIM	*STATE ASSIGNED ID	[P08]
	*STATE CODE	[53]
	*SHRP SECTION ID	[7409]

LOCATION SR 82 TYPE EQUIP. Piezo (Class 1)

MP # 48.5 MODEL # IRD 1060

DATE OF CHANGE	TIME OF CHANGE	DESCRIPTION OF CHANGE	PERSON MAKING CHANGE	PHONE #	NEW EQUIP. SERIAL #
					9104-1032
02/20/01		<u>Zillah WIM</u> Was: No answer Action: Found GFI tripped; reset it. Site could use some resealing around loops. Now: All good data, beginning 2-21-01. RR KL	RICH REMPFER		

800-12-11-8-12