From Griffee, Mark months of the second and second & Subject: 1269 Madison SE, Cleo's Takeout Ontober 20, 2015 at 9:06 AM Co. Schaut, Paul and come and the second of the Fleet, Mark

Ramun,

Here is the correction list for 1269 Madison SE. I will follow up with a formal correction notice to the owner.

- Grease ducts must be welded connections at all joints. 1.
- Exhaust fans must be operational and in good repair.
- Make up air unit must be operational and in good repair. 3.
- Gas pipe must be supported under hoods.
- Hoods must be cleaned following NFPA cleaning requirements.
- 6. Back wall must have plastic removed from under hood and walls shall be smooth, cleanable surfaces.
- 7. Hood suppression system must be re-tested.

Please let me know if you have any questions and call when ready for an inspection.

Regards


Mark Griffee Mechanical Inspector City of Grand Rapids 1120 Monroe Ave, NW Grand Rapids, MI 49503 (616) 456-4544



Development Center Home Page Online Inspection Services

Customer Feedback Form Visit us on facebook!





Type:

Mechanical Complaint

Address:

1269 MADISON AVE SE

Parcel:

41-18-06-129-049

Description:

This hood system has been red tagged and shut down by inspector Griffee. The health Dept. has been notified.

Assigned Staff: Mark Griffee (616) 456-4544 mgriffee@grand-rapids.mi.us

File Date:

10/6/2015

OWNER

RESPONSIBLE PARTY

COMPLAINT INFORMATION

Inspector Area

SE

Service Area

South

Warning

Neighborhood

Southeast Community

Ward

3

PROCESSING STATUS (chronological)

Intake

10/6/2015

Staff: Laura Lundy

llundy@grand-rapids.mi.us

Inspect

Inspections

10/7/2015

Staff: Mark Griffee

mgriffee@grand-rapids.mi.us

Posted Warning

INSPECTIONS

Date

Inspection Type

Result

Inspector

10/06/2015

Mechanical Initial

Posted Warning

Mark Griffee (616) 456-4544

Hood systems do not have proper duct connections, appears to be warm air duct dropped through curbs and no welded connections.

1 fan and make up air unit not operating.

Kitchen space is in poor condition with plaster falling down, signs of a roof leak, walls behind hood with plastic sheeting covering

holes and peeling paint.

Notified Jim Boyd with KCHD same day.

Printed: 10/8/2015 (V360_Public_Record_Summary)

Type:

Mechanical Complaint

Address:

1269 MADISON AVE SE

Parcel:

41-18-06-129-049

Description:

Complaint- furnace installed without the proper permits

Assigned Staff: Mark Griffee (616) 456-4544 mgriffee@grand-rapids.mi.us

File Date:

10/6/2015

MECH CON REG

OWNER

RESPONSIBLE PARTY

Warning

JACOBSON HTR CO.

JEFFREY JON VANDERSON

3303 EASTERN SE

GRAND RAPIDS, MI 49508

COMPLAINT INFORMATION

Inspector Area

SE

Service Area

South

Neighborhood

Southeast Community

Ward

3

PROCESSING STATUS (chronological)

<u>Intake</u>

10/6/2015

Staff:

Inspect

Inspections

10/7/2015 Staff: I

Posted Warning

INSPECTIONS

Date

Inspection Type

Result

Inspector

10/06/2015

Mechanical Initial

Posted Warning

Furnace installed by Jacobson's without permits.

Roof top unit decommissioned and condensing furnace installed.

No rough inspection on ductwork performed, no gas pressure test for new piping and I do not see any ventilation air.

Mike Deyoung at Jacobson's notified 10-7-15 @ 8:40 am. He remembers the job and will get permit in.

Plans are required.

Printed: 10/8/2015 (V360_Public_Record_Summary)

Page 2 of 2

t. E. I. LL			
637 Long Sand Lake 49343	Rd Mi 616-427-77.	INVOICE NO. INVOICE DATE CUSTOMER ORDER NUMBER	
(SOLD TO: CLEO) 1269 Mad!	5 fish+Chi	ship to:	
SALESPERSON	SHIPPED VIA	TERMS	F.O.B.
QTY ORDERED QTY SHIPPED	DESCR	PTION	. UNIT AMOUNT
	equipment.	2 existing Is + fans. of I used st fan. of Stainless I hood t cooking d air balance it y of GR. e rating mate	rials
adams: NC2812/NC3812	Does Not Roofing, El or reconne fire Syster Thank You	n at	\$9,9850

11-12