

Atchison County Community Schools Elementary School Gymnasium Roof Replacement

Project Progress Photos

Completion Date:

September 2015

Staging area of the roof replacement project



Progress of the existing roof tear-off and the construction of the new roof system.



A proper roof expansion joint
was installed to prevent splitting
of the roof membrane.



Final inspection photographs of
the new roof system.



