

Property I.D.[®]

DISCLOSE WITH CONFIDENCE

INVOICE

1001 Wilshire Blvd. • Los Angeles • CA 90017 • Phone: (800) 626-0106 • FAX: (800) 626-3863 • WWW.PROPERTYID.COM

Escrow or Title Co.:

MICHELLE K PARK
CORNERSTONE TITLE
21269 STEVENS CREEK BOULEVARD #630
CUPERTINO, 95014
Escrow / File #: 338314

Invoice #: 2141582101

Invoice Date: 10/9/2009

Ordered by:

SKY KIM
ELITE REALTY SERVICES - SAN JOSE
2787 MOOREPARK AVENUE
SAN JOSE, CA 95128

Site Address:

80 GLENMEAD COURT
MOUNTAIN VIEW, CA 94040
SANTA CLARA COUNTY
APN: 148-35-020

Product Description	Quantity	Unit Price	Amount
Mandatory Disclosure Report	1	\$114.00	\$114.00
Environmental Hazards Report	1	\$49.00	\$49.00
C.L.U.E. Risk Report	1	\$19.50	\$19.50

To ensure processing of your payment please:

- Write the Property ID invoice number on your check
- Include "Tear-Off" Remittance Stub with your payment
- Do not staple. Do not send cash

Adjustment: \$64.00

Subtotal: \$118.50

Amount Paid: \$0.00

Total Due: \$118.50

IMPORTANT: In the event that this invoice becomes delinquent, all outstanding balances will be assessed an additional past due charge of 1% of the total invoice for each month thereafter, with a maximum of 12% per annum. Unpaid reports are NOT insured and may NOT be used in subsequent transactions for the property for which the report was issued or for any other property. Payment of the report is required to obtain the benefits of any insurance and/or liability protections.

Thank You For Your Business

COPYRIGHT © 2009 PROPERTY I.D., All rights reserved.



PLEASE DETACH AND SEND WITH REMITTANCE

Invoice #: 2141582101

Invoice Date: 10/9/2009

Ordered by:

SKY KIM
ELITE REALTY SERVICES - SAN JOSE
2787 MOOREPARK AVENUE
SAN JOSE, CA 95128

Site Address:

80 GLENMEAD COURT
MOUNTAIN VIEW, CA 94040
SANTA CLARA COUNTY
APN: 148-35-020

MAIL PAYMENT TO:

Property I.D.
1001 Wilshire Blvd., Los Angeles, CA 90017

Total Due: \$118.50



Mandatory Residential Disclosure Report Environmental Hazards Report

SUBJECT PROPERTY:
80 GLENMEAD COURT
MOUNTAIN VIEW, CA 94040
APN 148-35-020
SANTA CLARA COUNTY

DISCLOSE WITH CONFIDENCE™

PROPERTY I.D. PLAZA, 1001 WILSHIRE BL., LOS ANGELES, CA 90017

P: (800) 626-0106 F: (800) 626-3863 • Platinum Services P: (800) 920-5603 F: (800) 920-5605

WWW.PROPERTYID.COM

IMPORTANT NOTICE *For the convenience of real estate agents, escrow officers, sellers and buyers, a disclosure receipt is provided herein. It is important that the recipient of the report acknowledge acceptance of the report by signing the receipt. Thereafter each party to the transaction may retain a copy of the receipt for their records.*

When Printed by Property I.D. Corporation, three original copies of the report are issued for distribution to the parties involved in the transaction.

COPYRIGHT © 2009 PROPERTY I.D., All rights reserved. No part of this publication may be reproduced, stored in a retrieval system, or transmitted by any means (electronic, mechanical, photocopying or otherwise) without the prior permission of Property I.D. COPYRIGHT is not claimed as to any part of original paperwork by the federal or state government.

NATURAL HAZARD DISCLOSURE STATEMENT AND DISCLOSURE REPORT RECEIPT

This statement applies to the following property: 80 GLENMEAD COURT MOUNTAIN VIEW, CA 94040; SANTA CLARA COUNTY; APN# 148-35-020 Date: 2009-10-09 09:36:00

The transferor and his or her agent(s) or a third-party consultant disclose the following information with the knowledge that even though this is not a warranty, prospective transferees may rely on this information in deciding whether and on what terms to purchase the Subject Property. Transferor hereby authorizes any agent(s) representing any principal(s) in this action to provide a copy of this statement to any person or entity in connection with any actual or anticipated sale of the property. The following are representations made by the transferor and his or her agent(s) based on their knowledge and maps drawn by the state and federal governments. This information is a disclosure and is not intended to be part of any contract between the transferee and transferor. THIS REAL PROPERTY LIES WITHIN THE FOLLOWING HAZARDOUS AREA(S):

- A SPECIAL FLOOD HAZARD AREA** (Any type Zone "A" or "V") designated by the Federal Emergency Management Agency. Refer to Report.
Yes ___ No X Do not know and information not available from local jurisdiction ___
- AN AREA OF POTENTIAL FLOODING** shown on a dam failure inundation map pursuant to Section 8589.5 of the Government Code. Refer to Report.
Yes ___ No X Do not know and information not available from local jurisdiction ___
- A VERY HIGH FIRE HAZARD SEVERITY ZONE** pursuant to Section 51178 or 51179 of the Government Code. The owner of this property is subject to the maintenance requirements of Section 51182 of the Government Code. Refer to Report.
Yes ___ No X
- A WILDLAND AREA THAT MAY CONTAIN SUBSTANTIAL FOREST FIRE RISKS AND HAZARDS** pursuant to Section 4125 of the Public Resources Code. The owner of this property is subject to the maintenance requirements of Section 4291 of the Public Resources Code. Additionally, it is not the state's responsibility to provide fire protection services to any building or structure located within the wildlands unless the Department of Forestry and Fire Protection has entered into a cooperative agreement with a local agency for those purposes pursuant to Section 4142 of the Public Resources Code. Refer to Report.
Yes ___ No X
- AN EARTHQUAKE FAULT ZONE** pursuant to Section 2622 of the Public Resources Code. Refer to Report.
Yes ___ No X
- A SEISMIC HAZARD ZONE** pursuant to Section 2696 of the Public Resources Code. Refer to Report.
Yes (Landslide Zone) ___ Yes (Liquefaction Zone) ___ No X Map not yet released by state ___

THESE HAZARDS MAY LIMIT YOUR ABILITY TO DEVELOP THE REAL PROPERTY, TO OBTAIN INSURANCE, OR TO RECEIVE ASSISTANCE AFTER A DISASTER. THE MAPS ON WHICH THESE DISCLOSURES ARE BASED ESTIMATE WHERE NATURAL HAZARDS EXIST. THEY ARE NOT DEFINITIVE INDICATORS OF WHETHER OR NOT A PROPERTY WILL BE AFFECTED BY A NATURAL DISASTER. TRANSFEREE(S) AND TRANSFEROR(S) MAY WISH TO OBTAIN PROFESSIONAL ADVICE REGARDING THOSE HAZARDS AND OTHER HAZARDS THAT MAY AFFECT THE PROPERTY.

Signature of Transferor(s) _____ Date _____

Signature of Transferor(s) _____ Date _____

Agent(s) _____ Date _____

Agent(s) _____ Date _____

Check only one of the following:

Transferor(s) and their agent(s) represent that the information herein is true and correct to the best of their knowledge as of the date signed by the transferor(s) and agent(s).

Transferor(s) and their agent(s) acknowledge that they have exercised good faith in the selection of a third-party report provider as required in Civil Code Section 1103.7, and that the representations made in this Natural Hazard Disclosure Statement are based upon information provided by the independent third-party disclosure provider as a substituted disclosure pursuant to Civil Code Section 1103.4. Neither transferor(s) nor their agent(s) (1) has independently verified the information contained in this statement and report or (2) is personally aware of any errors or inaccuracies in the information contained on the statement. This statement was prepared by the provider below:

Third-Party Disclosure Provider(s) _____ Property I.D. _____ Date October 9, 2009

Transferee represents that he or she has read and understands this document. Pursuant to Civil Code Section 1103.8, the representations made in this Natural Hazard Disclosure Statement do not constitute all of the transferor's or agent's disclosure obligations in this transaction.

Items 7-17 below indicate additional statutory disclosures and legal information that may be provided in the report.

- ENVIRONMENTAL RISK REPORT** (Enclosed if ordered and automatically enclosed for Santa Clara and San Mateo Counties.)
 - INDUSTRIAL USE ZONE DETERMINATION** (where available) pursuant to Section 1102.17 of the California Civil Code. Refer to Report.
 - FLOOD HAZARD DETERMINATION** pursuant to 42 U.S.C. Section 4001 *et seq.* Refer to Report.
 - LOCAL JURISDICTION HAZARDS** (May include but will not be limited to one or more of the following: Fault Activity, Methane Gas, Landslide Inventory Reports, Liquefaction Susceptibility, Fire, Naturally Occurring Asbestos, Airport Influence, Tsunami, Radon, Williamson Act, Right to Farm, Groundwater Deficiency, Hydro Compaction, Dam Failure Inundation Hazards, Critical Habitats, Duct Sealing Requirements, Methamphetamine Contamination, Mines, and Underground Reservoirs) Refer to Report.
 - MELLO-ROOS & SPECIAL ASSESSMENTS** pursuant to Section 53311-53365.7 / 53754 of the California Government Code; **NOTICE OF SUPPLEMENTAL PROPERTY TAX BILL** pursuant to Civil Code Section 1102.6c. Refer to Report.
 - MILITARY ORDINANCE FACILITIES** pursuant to California Civil Code Sections 1102.15 and 1940.7. Refer to Report.
- Items 13-17 below are guides enclosed in Buyer's Copy of report.
- ENVIRONMENTAL HAZARDS:** "A Guide for Homeowners, Buyers, Landlords and Tenants" pursuant to California Health and Safety Code Section 25100 *et seq.*, 25417, and 26100, Business and Professions Code Section 10084, and Civil Code Section 2079.7. Refer to Report.
 - EARTHQUAKE SAFETY:** "The Homeowner's Guide To Earthquake Safety" and "Residential Earthquake Hazards Report" form pursuant to California Business and Professions Code Section 10149, and Government Code Sections 8897.1, 8897.2, and 8897.5. Refer to Report.
 - RESIDENTIAL EARTHQUAKE HAZARDS REPORT FORM** pursuant to California Business and Professions Code Section 10149, and California Government Code Sections 8897.1, 8897.2, and 8897.5. Refer to enclosed "The Homeowner's Guide to Earthquake Safety".
 - LEAD-BASED PAINT:** "Protect Your Family From Lead In Your Home" pursuant to HUD Mortgage Letter 92-94, Title X of Housing and Com. D.V. Act of 1992. Refer to Report.
 - MOLD:** Chapter VI re mold, pursuant to Health and Safety Code Section 25100 *et seq.*, 25417, and 26100, Business and Professions Code Section 10084, and Civil Code Section 2079.7. Refer to Report.

Signature of Transferee(s) _____ Date _____

Signature of Transferee(s) _____ Date _____



ORDER ID #: 2141582
 ORDER DATE: 10/09/2009
 ESCROW / FILE NUMBER:
 338314

ESCROW AGENT:
 MICHELLE K PARK
 CORNERSTONE TITLE
 21269 STEVENS CREEK BOULEVARD #630
 CUPERTINO,
 95014

SUBJECT PROPERTY:
 80 GLENMEAD COURT
 MOUNTAIN VIEW, CA 94040
 SANTA CLARA COUNTY
 APN: 148-35-020

ORDERED BY:
 SKY KIM
 ELITE REALTY SERVICES - SAN JOSE
 2787 MOOREPARK AVENUE
 SAN JOSE, CA 95128

TABLE OF CONTENTS

NATURAL HAZARD DISCLOSURE STATEMENT AND RECEIPT	Preface	OIL AND GAS WELL PROXIMITY	25
SUMMARY OF RESULTS	2	PERCHLORATE CONTAMINATION	26
FLOOD HAZARD ZONES	5	NOTICE OF RIGHT TO FARM	27
DAM FAILURE INUNDATION	6	LAND CONSERVATION DETERMINATION	28
FIRE HAZARDS	7	PROPERTY TAX RECORDS	29
EARTHQUAKE FAULT ZONES	9	GENERAL NOTICES OF REQUIRED DISCLOSURES	32
LANDSLIDE SUSCEPTIBILITY	11	METHAMPHETAMINE CONTAMINATION	32
LIQUEFACTION SUSCEPTIBILITY	12	MEGAN'S LAW - SEX OFFENDER DATABASE	32
SOIL HAZARDS	14	ABANDONED WELLS	32
NATURALLY OCCURRING ASBESTOS	15	ENVIRONMENTAL HAZARDS REPORT	33
RADON GAS POTENTIAL	16	RECORDS SUMMARY	33
PROTECTED SPECIES / HABITATS	17	NPL/CERCLIS	34
COASTAL PROTECTION ZONES	18	RCRA	35
SAN FRANCISCO BAY CONSERVATION	19	SWIS	38
NOTICE OF DUCT SEALING REQUIREMENTS	20	SMBRPD / Brownfields	38
AIRPORT PROXIMITY	21	LUST	40
MILITARY ORDNANCE AND DEFENSE SITES	22	SLIC	43
AREAS OF INDUSTRIAL / COMMERCIAL USE	23	UNMAPPED SITES	44
ABANDONED / ACTIVE MINES	24		

Safety Guides are included at the end of the Buyer's Copy of reports printed by Property I.D. Links to download the guides are included when reports are delivered electronically.

NOTICE TO BUYER:

This report applies to the property described by the street address and/or county assessor's parcel number as shown above. Please verify this information for accuracy. If this report has been issued in connection with an identified escrow and your escrow transaction number fails to match the escrow number enumerated in this report, then this report is invalid and must be reordered.

This report is issued as of the date shown above and is based upon an examination of maps as published by government agencies. This report does not constitute an opinion as to the advisability of completing the transaction.

SUMMARY OF RESULTS

For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

STATUTORY DISCLOSURES

DISCLOSURE	DETERMINATION	DISCLOSURE DETAIL
FEMA Flood Zone	IN	ZONE X500 (NOT SPECIAL FLOOD HAZARD AREA)
OES Dam Inundation	NOT IN	DAM INUNDATION AREA
High Fire Severity - State	NOT IN	VERY HIGH FIRE HAZARD SEVERITY ZONE
Wildland Fire Area - State	NOT IN	STATE FIRE RESPONSIBILITY AREA
Alquist-Priolo Fault Zone	NOT IN	EARTHQUAKE FAULT ZONE
CGS Landslides	NOT IN	EARTHQUAKE-INDUCED LANDSLIDE HAZARD ZONE
Seismic Hazard : Liquefaction	WITHIN 1/4 MILE OF	LIQUEFACTION HAZARD ZONE

STATE-WIDE DISCLOSURES

DISCLOSURE	DETERMINATION	DISCLOSURE DETAIL
Liquefaction	IN	AREA WITH MODERATE LIQUEFACTION SUSCEPTIBILITY
Faults - USGS	NOT WITHIN 1/4 MILE OF	FAULT
Fire Hazard Rating	IN	AREA RATED LOW FOR FIRE HAZARD SEVERITY
Faults - State	NOT WITHIN 1/4 MILE OF	FAULT
Landslide Inventory	NOT IN	IDENTIFIED EARTH MOVEMENT
Liquefaction Prone Soils	IN	POTENTIALLY LIQUEFIABLE SOILS
Naturally Occuring Asbestos	NOT IN	NATURALLY OCCURRING ASBESTOS HAZARD ZONE
Radon Gas	IN	ZONE 2 FOR RADON GAS POTENTIAL
Protected Species / Habitats	NOT IN	AREA WITH PROTECTED SPECIES OR HABITATS
California Coastal Commission Jurisdiction	NOT IN	CALIFORNIA COASTAL COMMISSION JURISDICTION AREA
Duct Sealing Requirement	IN	ZONE OFFICIALLY EXEMPTED FROM CALIFORNIA ENERGY COMMISSION DUCT SEALING REQUIREMENTS
Airport Influence Area	NOT IN	AIRPORT INFLUENCE AREA
Airport Vicinity	NOT WITHIN 2 MILES OF	FAA APPROVED LANDING FACILITY
Military Facilities	NOT WITHIN 1 MILE OF	FORMER MILITARY ORDNANCE SITE
Mining Operations	NOT WITHIN 1 MILE OF	IDENTIFIED MINING OPERATIONS, ACTIVE OR ABANDONED
Oil and Gas Wells	NOT WITHIN 500 FEET OF	OIL OR GAS WELL, ACTIVE OR ABANDONED

SUMMARY OF RESULTS

(continued)

STATE-WIDE DISCLOSURES

(continued)

DISCLOSURE	DETERMINATION	DISCLOSURE DETAIL
Right to Farm	NOT WITHIN ONE MILE OF	AGRICULTURAL ACTIVITY
Land Conservation Act	NOT IN	LANDS UNDER CONTRACT PURSUANT TO THE CALIFORNIA LAND CONSERVATION (WILLIAMSON) ACT AT THE TIME THE DATA WAS OBTAINED.
Special Tax Assessment District	IN	SPECIAL TAX ASSESSMENT DISTRICT
Rate Based Taxes	SUBJECT TO	AD VALOREM TAXES
Mello-Roos Tax District	DOES NOT	CURRENTLY HAVE MELLO ROOS TAXES LEVIED AGAINST IT.

LOCAL DISCLOSURES

DISCLOSURE	DETERMINATION	DISCLOSURE DETAIL
Dam Inundation - Local	NOT IN	DAM INUNDATION AREA
Liquefaction - Local	IN	MODERATE LIQUEFACTION POTENTIAL
Bay Area Conservation	NOT IN	THE SAN FRANCISCO BAY CONSERVATION AND DEVELOPMENT COMMISSION JURISDICTION AREA
Landuse - Local	IN OR ADJACENT TO	INDUSTRIAL AND/OR COMMERCIAL LAND USE (LIGHT INDUSTRIAL)
Salt Water Flooding - Local	NOT IN	HIGH POTENTIAL FOR SALT WATER FLOODING FROM FAILURE OF DIKES
Fault Rupture Zones - Local	NOT IN	FAULT RUPTURE HAZARD ZONE
Faults - Local	NOT WITHIN 1/4 MILE OF	FAULT
Landslides - Local	NOT IN	LANDSLIDE HAZARD ZONE
Liquefaction - Local	WITHIN 1/4 MILE OF	LIQUEFACTION HAZARD ZONE
Compressible Soil - Local	NOT IN	HIGH POTENTIAL FOR COMPRESSIBLE SOILS AND DIFFERENTIAL SETTLEMENT
Industrial / Commercial Use - Local	NOT IN	INDUSTRIAL AND/OR COMMERCIAL USE ZONE
Perchlorate - Local	NOT IN	PERCHLORATE STUDY AREA

DISCLOSURE NOTICES

METHAMPHETAMINE CONTAMINATION	see under DISCLOSURE NOTICES
MEGAN'S LAW - SEX OFFENDER DATABASE	see under DISCLOSURE NOTICES
ABANDONED WELLS	see under DISCLOSURE NOTICES

ENVIRONMENTAL HAZARDS

AN ENVIRONMENTAL HAZARDS REPORT IS INCLUDED WITH THIS REPORT	see ENVIRONMENTAL HAZARDS REPORT
--	----------------------------------

SUMMARY OF RESULTS

(continued)

THIS "SUMMARY OF RESEARCH RESULTS" MERELY SUMMARIZES THE RESEARCH RESULTS CONTAINED IN THE PROPERTY I.D. MANDATORY DISCLOSURE REPORT AND DOES NOT OBTAIN THE NEED TO READ THE REPORT IN ITS ENTIRETY. THE TRANSFEROR(S) AND TRANSFEREE(S) MUST READ THE REPORT IN ITS ENTIRETY.

FLOOD HAZARD ZONES

For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

Based on PROPERTY I.D.'s research of the Flood Insurance Rate Maps issued by the Federal Emergency Management Agency, the following determination is made:

SUBJECT PROPERTY IS LOCATED IN ZONE X500 (NOT A SPECIAL FLOOD HAZARD AREA)

EXPLANATION OF FEMA FLOOD ZONE DESIGNATIONS

Any zones type "A" or "V" are Special Flood Hazard Areas, zones "B", "C", "D", "X" are not.

A	AREAS OF 100-YEAR FLOOD; BASE FLOOD ELEVATIONS AND FLOOD HAZARD FACTORS NOT DETERMINED.
AC*	AREAS OF FLOODING CONTAINED BY FLOOD CONTROL MEASURES; INCLUDES AREAS OF FLOODING CONTAINED BY CHANNEL OR BASIN. (* represents a wildcard character)
AE	BASE FLOOD ELEVATION DETERMINED
AH	AREAS OF 100-YEAR SHALLOW FLOODING WHERE DEPTHS ARE BETWEEN ONE (1) AND THREE (3) FEET; BASE FLOOD ELEVATIONS ARE SHOWN, BUT NO FLOOD HAZARD FACTORS ARE DETERMINED.
AO	AREAS OF 100-YEAR SHALLOW FLOODING WHERE DEPTHS ARE BETWEEN ONE (1) AND THREE (3) FEET; AVERAGE DEPTHS OF INUNDATION ARE SHOWN, BUT NO FLOOD HAZARD FACTORS ARE DETERMINED.
AR	AREAS OF 100-YEAR FLOOD, WHERE RESTORATION OF LEVEE SYSTEM TO LEVEL OF VASE FLOOD IS UNDERWAY (TEMPORARY UNTIL FLOOD PROTECTION SYSTEM IS RESTORED)
A1-A30	AREAS OF 100-YEAR FLOOD; BASE FLOOD ELEVATIONS AND FLOOD HAZARD FACTORS DETERMINED.
A99	AREAS OF 100-YEAR FLOOD TO BE PROTECTED BY FLOOD PROTECTION SYSTEM UNDER CONSTRUCTION; BASE FLOOD ELEVATIONS AND FLOOD HAZARD FACTORS NOT DETERMINED.
B	AREAS BETWEEN THE LIMITS OF THE 100-YEAR FLOOD AND THE 500-YEAR FLOOD; OR CERTAIN AREAS SUBJECT TO 100-YEAR FLOODING WITH AVERAGE DEPTHS LESS THAN ONE (1) FOOT OR PROTECTED BY LEVEES.
C	AREAS OF MINIMAL FLOODING; AREAS OUTSIDE 100-YEAR FLOODING
D	AREAS OF UNDETERMINED, BUT POSSIBLE, FLOOD HAZARDS.
V	AREAS OF 100-YEAR COASTAL FLOOD WITH VELOCITY (WAVE ACTION); BASE FLOOD ELEVATIONS AND FLOOD HAZARD FACTORS NOT DETERMINED.
V1-V30	AREAS OF 100-YEAR COASTAL FLOOD WITH VELOCITY (WAVE ACTION)' BASE FLOOD ELEVATIONS AND FLOOD HAZARD FACTORS DETERMINED.
VE	COASTAL FLOOD WITH VELOCITY HAZARD (WAVE ACTION); BASE FLOOD ELEVATIONS DETERMINED.
X	AREAS DETERMINED TO BE OUTSIDE 500-YEAR FLOOD PLAIN.
X500	AREAS OF 500-YEAR FLOOD; AREAS OF 100-YEAR FLOOD WITH AVERAGE DEPTHS OF LESS THAN ONE (1) FOOT OR WITH DRAINAGE AREAS LESS THAN 1 SQUARE MILE; AND AREAS PROTECTED BY LEVEES FROM 100-YEAR FLOOD.
X*PL	AREAS PROTECTED FROM 100-YEAR FLOOD BY LEVEE, DIKE, OR OTHER STRUCTURE. OVERTOPPING OR FAILURE OF THIS STRUCTURE IS POSSIBLE. COMMUNITIES SHOULD ISSUE EVACUATION PLANS AND ENCOURAGE PROPERTY OWNERS BEHIND THESE STRUCTURES TO PURCHASE FLOOD INSURANCE. (* represents a wildcard character)

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

DAM FAILURE INUNDATION
For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

Based on PROPERTY I.D.'s research of specific maps or data obtained from the Office of Emergency Services, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A DESIGNATED DAM INUNDATION AREA

Based on PROPERTY I.D.'s research of specific maps or data for the Bay Area, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A DAM INUNDATION AREA

Based on PROPERTY I.D.'s research of specific maps or data for Santa Clara County, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN AN OFFICIALLY DESIGNATED AREA OF HIGH POTENTIAL FOR SALT WATER FLOODING FROM FAILURE OF DIKES

DISCUSSION:

The dam inundation program began in response to the Sylmar earthquake of February 9, 1971, which caused severe damage to the Upper and Lower Van Norman Dams, and threatened to cause extensive damage to life and property had a dam failure occurred. The California legislature added sections 8589.5 to the California Government Code, requiring dam owners to provide the Governor's Office of Emergency Services with an inundation map showing the extent of damage to life and property that would occur, given a complete and sudden dam failure at full capacity, i.e. a worst case scenario, regardless of the likelihood of such an event.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

FIRE HAZARDS

For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

VERY HIGH FIRE HAZARD ZONE

Based on PROPERTY I.D.'s research of the current maps and/or information issued by the California Department of Forestry and Fire Protection and Santa Clara County, The following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A VERY HIGH FIRE HAZARD SEVERITY ZONE

DISCUSSION:

In an effort to prepare measures to retard the spread of fires, and reduce the potential intensity of uncontrolled fires that could destroy resources, life, or property, the California Department of Forestry and Fire Protection identifies Very High Fire Hazard Severity Zones. These areas are classified as such based upon fuel loading, slope, fire history, weather, and other relevant factors. For an area designated as a very high fire hazard severity zone, vegetation removal or management must be undertaken for fire prevention or suppression purposes. Other measures may be required, such as the maintenance of fire breaks around the property, clearance of brush and other flammable substances, the provision and maintenance of screens on chimneys and stovepipes, and a prescribed fire retardant roof.

WILDLAND FIRE (STATE FIRE RESPONSIBILITY AREA)

Based on PROPERTY I.D.'s research of the current maps issued by the California Department of Forestry and Fire Protection, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A DESIGNATED STATE FIRE RESPONSIBILITY AREA

DISCUSSION:

A State Fire Responsibility Area is defined as lands exclusive of cities and federal lands regardless of ownership, classified by the State Board of Forestry as areas in which the primary financial responsibility for preventing and suppressing fire is that of the State. These are lands covered wholly or in part by timber, brush, undergrowth or grass, whether of commercial value or not, which protect the soil from erosion, retard runoff of water or accelerated percolation, and lands used principally for range or forage purposes. State Fire Responsibility Areas are generally wildland areas, and may require state-imposed additional duties, such as maintaining fire breaks.

FIRE HAZARDS

(continued)

FIRE HAZARD SEVERITY RATING

Based on PROPERTY I.D.'s research of the current maps issued by the California Department of Forestry and Fire Protection, the following determination is made:

SUBJECT PROPERTY IS LOCATED IN AN AREA RATED LOW FOR FIRE HAZARD SEVERITY

DISCUSSION:

Fire ratings can be used to estimate the potential for impacts on assets susceptible to fire. Impacts are more likely to occur and/or be of increased severity for the higher rating classes. Fire Ratings are based on vegetation fuels, terrain, weather, and fire history, as well as input from local fire authorities. These factors are combined to create 4 threat classes: low, moderate, high, and very high. Additional information regarding the development of fire ratings is available via the CDF-FRAP web site. <http://frap.cdf.ca.gov/projects/hazard/fhz.html>.

Discussion:

The Director of the California Department of Forestry (CDF) identifies Very High Fire Hazard Severity Zones (VHFHSZ) based on statewide criteria. But at its discretion, a local agency may include or exclude areas from the VHFHSZ following a finding, supported by substantial evidence, that modifications to the fire hazard zones are necessary for effective fire protection.

Note: If the property is located in a State Fire Responsibility area, Seller shall, within the time specified, disclose this fact in writing to Buyer (Public Resources Code Section 4136). Disclosure may be made in the Real Estate Transfer Disclosure Statement (CAR Form TDS-14). Government regulations may impose building restrictions and requirements that may substantially impact and limit construction and any remodeling or improvement.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

EARTHQUAKE FAULT ZONES

For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

Based on PROPERTY I.D.'s research of maps or data obtained from the State of California in accordance with the Alquist-Priolo Earthquake Fault Zone Act, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN AN OFFICIAL EARTHQUAKE FAULT ZONE

DISCUSSION:

If the Subject Property is partially or wholly within an OFFICIAL EARTHQUAKE FAULT ZONE, it may be subject to (city, county, or state) requirements necessitating geologic study prior to any new or additional construction. When a property is located in this zone, it may not mean that a fault line exists on the property. In certain areas, the zones around the faults being studied are more than one-quarter of a mile wide.

Earthquake Fault Zones are delineated and adopted by the State of California as part of the Alquist-Priolo Earthquake Fault Zone Act of 1972 to assure that homes, offices, hospitals, public buildings, and other structures for human occupancy are not built on active faults. Earthquake Fault Zones are areas on both sides of known or suspected active earthquake faults. The State Mining and Geology Board has adopted policies and criteria for implementing the zones.

Based on PROPERTY I.D.'s research of maps or data obtained from the United States Geologic Survey, following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 1/4 MILE OF A MAPPED FAULT

Based on PROPERTY I.D.'s research of specific maps or data from the State of California, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 1/4 MILE OF A MAPPED FAULT

Based on PROPERTY I.D.'s research of specific maps or data for Santa Clara County, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 1/4 MILE OF A MAPPED FAULT

SUBJECT PROPERTY IS NOT LOCATED IN AN OFFICIALLY DESIGNATED FAULT RUPTURE HAZARD ZONE

DISCUSSION:

EARTHQUAKE FAULT ZONES

(continued)

As a part of long-term planning, localities are required to include mapping of known seismic or other geologic hazards on a local level. Information may vary between jurisdictions, and may include information about all locally-known seismic hazard zones, including an area's susceptibility to strong ground shaking, liquefaction, landslides or other ground failure.

The absence of earthquake activity at a particular location does not necessarily mean that earthquakes will not occur there in the future. Moderate to large earthquakes have often been preceded by or followed by long periods of quiescence. The apparent correlation between seismic activity and mapped faults should confine the areas of higher probability of earthquake occurrence to somewhat restricted zones.

Fault rupture can occur during moderate to large earthquakes and is a function of magnitude and the total length of the fault. Fault rupture accounts for only a small percentage of earthquake damage and may be rapid and sudden, as with a major earthquake, or can occur over an extended period of time.

DEFINITIONS:

For fault disclosures that contain fault activity information, the definitions below describe these activity designations.

Active - "Active" faults are defined as faults that have been active within the last 0 to 11,000 years.

Potentially Active - "Potentially Active" faults are defined as faults that may have been active between 11,000 years and 500,000 years ago.

Conditionally Active - "Conditionally Active" faults are defined as faults that may have had activity 750,000 years ago or uncertain activity.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

LANDSLIDE SUSCEPTIBILITY

For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

Based on PROPERTY I.D.'s research of the current maps issued by the California Geological Survey, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN AN OFFICIALLY DESIGNATED EARTHQUAKE-INDUCED LANDSLIDE HAZARD ZONE

Note: Additional / local determination(s) below, when listed, may differ from the seismic hazard determination found in the Natural Hazard Disclosure Statement ("NHDS"). Differentiation can occur because the determination made in the NHDS is based on specific maps prepared by the California Geologic Survey (State Seismic Hazard Mapping Act), while the determination(s) below are based on different official maps and/or information.

Based on PROPERTY I.D.'s research of specific maps or data for California, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN AN AREA OF IDENTIFIED EARTH MOVEMENT

Based on PROPERTY I.D.'s research of specific maps or data for Santa Clara County, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN AN OFFICIAL LANDSLIDE HAZARD ZONE

DISCUSSION:

Landslides and other ground failures may occur during earthquakes, triggered by the strain induced in soil and rock by the ground shaking vibrations, and during non-earthquake conditions, most frequently during the rainy season. Both natural and man-made factors contribute to these slope failures.

Although landslides due to slope failure are most frequent in "wet years" with above-average rainfall, they can occur at any time. The presence or absence of deep-rooted vegetation; surface and subsurface drainage conditions; thickness and engineering characteristics of soils and underlying weathered, partially-decomposed rock; orientation of bedding or locally-high rainfall can all affect slope stability.

The influence of bedrock lithology, steepness of slope, and rates of erosion, at the very least, must all be considered to generate an accurate susceptibility map. Any slope can be rendered unstable by construction activities and almost any unstable slope can also be mitigated by accepted geotechnical methods.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

LIQUEFACTION SUSCEPTIBILITY

For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

Based on PROPERTY I.D.'s research of the current maps issued by the California Geological Survey, the following determination is made:

SUBJECT PROPERTY IS LOCATED WITHIN 1/4 MILE OF AN OFFICIALLY DESIGNATED LIQUEFACTION HAZARD ZONE

Note: Additional / local determination(s) below, when listed, may differ from the seismic hazard determination found in the Natural Hazard Disclosure Statement ("NHDS"). Differentiation can occur because the determination made in the NHDS is based on maps prepared by the California Geologic Survey in accordance with the State Seismic Hazard Mapping Act, while the determinations below are based on official maps prepared for another mapping program.

Based on PROPERTY I.D.'s research of the current maps issued by the United States Geological Survey (USGS), the following determination is made:

SUBJECT PROPERTY IS LOCATED IN AN AREA WITH MODERATE LIQUEFACTION SUSCEPTIBILITY

Based on PROPERTY I.D.'s research of specific maps or data for California, the following determination is made:

SUBJECT PROPERTY IS LOCATED IN AN AREA OF POTENTIALLY LIQUEFIABLE SOILS

Based on PROPERTY I.D.'s research of specific maps or data for the Bay Area, the following determination is made:

SUBJECT PROPERTY IS LOCATED IN AN OFFICIALLY DESIGNATED AREA OF MODERATE LIQUEFACTION POTENTIAL

Based on PROPERTY I.D.'s research of specific maps or data for Santa Clara County, the following determination is made:

SUBJECT PROPERTY IS LOCATED WITHIN 1/4 MILE OF A LIQUEFACTION HAZARD ZONE

LIQUEFACTION SUSCEPTIBILITY

(continued)

DISCUSSION:

Liquefaction is the sudden loss of soil strength resulting from shaking during an earthquake. The effect on structures and buildings can be devastating, and is a major contributor to urban seismic risk. Areas most susceptible to liquefaction are underlain by non-cohesive soils, such as sand and silt, that are saturated by water.

Mapped liquefaction areas are those where historic occurrence of liquefaction, or local geological, geotechnical conditions indicate a potential for permanent ground displacement such that mitigation as defined in Public Resources Code Section 2693(c) would be required. Section 2693(c) defines "mitigation" to mean those measures that are consistent with established practice and that will reduce seismic risk to acceptable levels.

Note: The map upon which this determination is based may not show all areas that have the potential for liquefaction or other earthquake and geologic hazards. Also, a single earthquake capable of causing liquefaction may not uniformly affect the entire area. Liquefaction zones may also contain areas susceptible to the effects of earthquake induced landslides. This situation typically exists at or near the toe of existing landslides, down slope from rock fall or debris flow source areas, or adjacent to steep stream banks.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

SOIL HAZARDS
For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

SUBSIDENCE

Based on PROPERTY I.D.'s research of specific maps or data for Santa Clara County, the following determination is made:

**SUBJECT PROPERTY IS NOT LOCATED IN AN OFFICIALLY DESIGNATED AREA OF
HIGH POTENTIAL FOR COMPRESSIBLE SOILS AND DIFFERENTIAL SETTLEMENT**

DISCUSSION:

Subsidence is the gradual settling or sinking of the earth's surface with little or no horizontal motion due to the loss of solids or liquids from the subsurface. The compaction of alluvium and settling of the land surface is a process that occurs over several years, except when prompted by seismic shaking. Subsidence can cause property damage and could progressively deteriorate structures over time. As such, stricter construction and development requirements may apply that could affect building materials and standards used. Structures may experience more hairline cracks in the walls and slabs. Inundation or flooding may also be a secondary effect of subsidence.

In Santa Clara County Compressible Soils are an officially recognized Geologic Hazard Zone (GHZ.) In those areas, local ordinances require that the owner/applicant submit a geologic report (prepared and signed by a Certified Engineering Geologist [CEG]) for review by the County Geologist prior to approval of certain applications for construction.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

NATURALLY OCCURRING ASBESTOS

For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

Based on PROPERTY I.D.'s research of current maps and/or information issued by the California Geological Survey, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A NATURALLY OCCURRING ASBESTOS HAZARD ZONE

DISCUSSION:

Natural asbestos commonly occurs in association with altered ultramafic rocks, including serpentinite or serpentine - the California state rock. State and federal officials consider all types of asbestos to be hazardous because asbestos is a known carcinogen. Wind and water can carry asbestos fibers, and certain human activities such as mining, grading, quarrying operations, construction or driving over unpaved roads or driving on a road paved in part with asbestos-bearing rock, can release dust containing asbestos fibers. As with any other potential environmental hazard, it is recommended that Buyers fully investigate and satisfy themselves as to the existence of exposed naturally occurring asbestos / serpentine rock on the Property or within its vicinity or any serpentine-surfaced roads within the vicinity of the Property and the hazards, if any, posed thereby. That investigation should include consulting with appropriate expert(s) who can identify and test any exposed naturally occurring asbestos / serpentine rock on the Property or within its vicinity to determine whether it may present a health risk to Buyers. Buyers are encouraged to review all relevant information resulting from these studies and other information pertaining to the risk of exposure to harmful forms of naturally occurring asbestos fibers prior to removing their inspection contingency. Exposure to asbestos may create a significant health risk, and the presence of asbestos-bearing minerals may result in restrictions on the use or development of the Property. You should consider the potential risks associated with the Property before you complete your purchase and determine whether they are acceptable to you.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

RADON GAS POTENTIAL

For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

Based on PROPERTY I.D.'s research of specific maps or data obtained from the U.S. Environmental Protection Agency, the following determination is made:

THE ENTIRE COUNTY IN WHICH THE SUBJECT PROPERTY IS LOCATED IS
DESIGNATED AS A ZONE 2 FOR RADON GAS POTENTIAL

DEFINITION:

Zone 1 - Highest Potential (greater than 4 pCi/L) (picocuries per liter)

Zone 2 - Moderate Potential (from 2 to 4 pCi/L) (picocuries per liter)

Zone 3 - Low Potential (less than 2 pCi/L) (picocuries per liter)

DISCUSSION:

Radon is a naturally occurring colorless, odorless radioactive gas formed by the natural disintegration of uranium in soil, rock and ground water as it radioactively transmutes to form stable lead.

Radon gas forms from the decay of radioactive elements at depth. Air pressure inside a building is usually lower than pressure in the soil around the building's foundation. Because of this difference in pressure, buildings can act like a vacuum, drawing radon in through foundation cracks and other openings. As cracks develop in rocks, radon gas can rise into the local ground water and may also be present in well water and can be released into the air in buildings when water is used for showering and other household uses. In most cases, radon entering a building through water is a small risk compared with radon entering a building from the soil. In a small number of homes, the building materials can give off radon, although building materials alone rarely cause radon problems. The Surgeon General has warned that radon is the second leading cause of lung cancer in the United States. Only smoking causes more lung cancer deaths. Smokers that live in homes with high radon levels, are at an especially high risk for developing lung cancer.

The U.S. Environmental Protection Agency's (EPA) action level for indoor radon levels is 4 pCi/L, at which homes should be fixed. Even at lower levels Radon can still be dangerous, so the EPA recommends homeowners consider fixing their homes when the radon levels are between 2 pCi/L and 4 pCi/L.

The only way to determine radon levels for a specific property is by testing. For further information about radon testing and mitigation, contact the California Department of Health Services at <http://www.dhs.ca.gov>, The National Environmental Health Association (NEHA) at <http://www.neha.org>, and the National Environmental Radon Safety Board (NRSB) at <http://www.nrsb.org>.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

PROTECTED SPECIES / HABITATS

For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

Based on PROPERTY I.D.'s research of the current maps and/or information obtained from federal, state, county, and local habitat conservation departments, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN AN AREA WITH PROTECTED SPECIES OR HABITATS

DISCUSSION:

The species and/or habitat(s) listed above, if any, represent rare, sensitive, threatened, endangered, or special status plants, animals, natural communities, or habitats. Some of the species listed may not currently be considered endangered, threatened, sensitive, or protected, at the time of the report, but do have the potential of receiving an upgraded status.

Landowners with property in conservation areas may be subject to development fees at the time a grading permit is obtained, and/or may be required to secure a habitat assessment conducted by a biologist or specialist approved by the United States Fish and Wildlife Service, and/or the California Department of Fish and Game, and/or the local jurisdiction habitat conservation department. Fee revenues are generally expended for land acquisition, biologic research and other conservation and mitigation activities necessary to help implement the applicable species habitat conservation plans. A habitat assessment involves a field survey to ascertain the actual presence of the particular species upon the Subject Property. These habitat preservation measures may also limit the landowner's ability to develop the property. Affected landowners should check the applicable jurisdiction's ordinances, mitigation fees, and local planning jurisdictions.

Note: A lack of listed species and/or habitats in this report does not necessarily mean that there are no rare species or habitats in this area. Areas that have not been surveyed for rare species will not show results in this report. Land that has not been surveyed for rare plants and animals retains the potential to support rare elements.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

COASTAL PROTECTION ZONES

For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

Based on PROPERTY I.D.'s research of the current maps and/or information obtained for California, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A CALIFORNIA COASTAL COMMISSION JURISDICTION AREA

DISCUSSION:

The California Coastal Commission, in partnership with coastal cities and counties, plans and regulates the use of land and water in the coastal areas. Development activities, which are broadly defined by the Coastal Act to include (among others) construction of buildings, divisions of land, and activities that change the intensity of use of land or public access to coastal waters, generally require a coastal permit from either the Coastal Commission or the local government through Local Coastal Programs (LCP's).

LCP's are basic planning tools used by local governments to guide development in the coastal zone, in partnership with the California Coastal Commission. LCP's contain the ground rules for future development and protection of coastal resources in the 74 coastal cities and counties. The LCP's specify appropriate location, type, and scale of new or changed uses of land and water. Each LCP includes a land use plan and measures to implement the plan (such as zoning ordinances). Prepared by local government, these programs govern decisions that determine the short-term and long-term conservation and use of coastal resources.

For more information contact your local Coastal Commission Office.

COASTAL COMMISSION OFFICES

Headquarters	(415) 904-5200 (San Francisco)
North Coast District	(707) 445-7833 (Eureka)
North Central Coast District	(415) 904-5260 (San Francisco)
Central Coast District	(831) 427-4863 (Santa Cruz)
South Central Coast District	(805) 585-1800 (Ventura)
South Coast District	(562) 590-5071 (Long Beach)
San Diego Coast District	(619) 767-2370 (San Diego)

Coastal Commission Local Assistance Website: <http://www.coastal.ca.gov/la/landx.html>

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

NOTICE OF SAN FRANCISCO BAY CONSERVATION AND DEVELOPMENT COMMISSION JURISDICTION

For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN# 148-35-020

Based on PROPERTY I.D.'s research of the current maps issued by the San Francisco Bay Conservation and Development Commission, the following determination is made:

**SUBJECT PROPERTY IS NOT LOCATED IN THE SAN FRANCISCO BAY
CONSERVATION AND DEVELOPMENT COMMISSION JURISDICTION AREA**

DISCUSSION:

If the Subject Property is located in the San Francisco Bay Conservation and Development Commission Jurisdiction, use and development of property within the commission's jurisdiction may be subject to special regulations, restrictions and permit requirements. You may wish to investigate and determine whether they are acceptable to you and your intended use of the property before you complete your transaction.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

NOTICE OF DUCT SEALING REQUIREMENTS
For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

Based on PROPERTY I.D.'s research of the the official climate zone maps issued by the California Energy Commission, the following determination is made:

SUBJECT PROPERTY IS LOCATED IN A ZONE OFFICIALLY EXEMPTED FROM CALIFORNIA ENERGY COMMISSION DUCT SEALING REQUIREMENTS

DISCUSSION:

The California Energy Commission's ("CEC") duct sealing requirements became effective on October 1, 2005, California Code of Regulations, Title 24. Some areas in specific climate zones as designated by the CEC are exempt from compliance and the requirements do not apply to properties in the exemption zones unless otherwise adopted by local governments. Properties that are not located in the exemption zones must comply with the requirements.

Depending upon certain conditions, if a central air conditioner or furnace was installed or replaced, the ducts may require testing for leakage. If significant leakage is found, repairs may be required to seal the ducts. Additional testing may then be required to verify that the work was done properly. It is strongly recommended that all of this work be done by licensed contractors who should obtain all required permits. These new duct sealing requirements may impact a Seller's disclosure obligations and/or any negotiations between principals regarding replacing heating, ventilating and air conditions (HVAC) systems. These new requirements may increase the costs associated with replacing or installing an HVAC system.

13 SEER - Seasonal Energy Efficiency Ratio is the Federal Government's minimum standard efficiency rating for heating, ventilating, air conditioning and heat pumps. The US Department of Energy requires central air conditioners and heat pumps to meet an efficiency rating of 13 SEER. For further information contact the California Energy Commission at 800-772-3300 or go to www.energy.ca.gov/title24/changeout.

Note: Property I.D. cannot determine the condition, required testing, or sealing needed for the HVAC system of the Subject Property, nor can Property I.D. verify any information provided about the condition of the HVAC system.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

AIRPORT PROXIMITY

For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

Based on PROPERTY I.D.'s research of specific maps or data obtained from local land use commissions, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN AN AIRPORT INFLUENCE AREA

Based on PROPERTY I.D.'s research of specific maps or data for the Federal Aviation Administration (FAA) and the U.S. Department of Transportation, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 2 MILES OF AN FAA APPROVED LANDING FACILITY

DISCUSSION:

NOTICE OF AIRPORT IN VICINITY - Pursuant to Section 1103.4 of the Civil Code: If the above-referenced property is located in the vicinity of an airport, within what is known as an Airport Influence Area, the property may be subject to some of the annoyances or inconveniences associated with proximity to airport operations (for example: noise, vibration or odors). Individual sensitivities to those annoyances can vary from person to person. You may wish to consider what airport annoyances, if any, are associated with the property before you complete your purchase and determine whether they are acceptable to you.

Note: In some instances the location of an airport facility's property line was not made available by the FAA. In those cases the FAA-designated central point of the facility was used as the center for the two mile proximity determination.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

MILITARY ORDNANCE AND DEFENSE SITES
For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

FORMER MILITARY SITES

Based on PROPERTY I.D.'s research of the current maps or data issued by the U.S. Army Corps of Engineers, in conjunction with the Department of Defense, of former Federal and State Defense Sites, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 1 MILE OF A FORMER MILITARY ORDNANCE SITE

Each site's evaluation is contained within an Inventory Project Report (INPR), which indicates a Risk Assessment Code (RAC) for each site. The RAC score is used to prioritize the remedial action at the site. A one (1) RAC score indicates a high likelihood of hazard severity and/or hazard probability. The five (5) RAC score indicates the least hazardous category.

RISK ASSESSMENT CODE:

RAC 1 Imminent Hazard

RAC 2 High Priority

RAC 3 Recommend further action to determine presence of ordnance

RAC 4 Recommend further action to determine presence of ordnance

RAC 5 Recommend no further action

NO RAC No RAC score available

DISCUSSION:

The sites are former locations used by various United States armed forces during the Second World War, and they have been reported and identified as contaminated with ordnance. Some confirmed sites have different kinds of contaminants - not all are artillery/ordnance contaminants.

Many sites are known by the federal and state government as former defense sites, whereupon there is potential for ordnance and similar explosive type contaminants, however this potential may not be confirmed.

Due to national security concerns, the US Army Corps of Engineers has not provided public updates on Formerly Used Defense Sites (FUDS) since January 2003.

Note: The above mentioned determination is made from a list of known Formerly Used Defense Sites in the state of California that are listed in the official government databases. There is a possibility that the database utilized does not include some of the most recently modified Risk Assessment Code (RAC) scores, recently discovered sites and/or information exempt from release.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

AREAS OF INDUSTRIAL / COMMERCIAL USE

For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

LAND USE AND PLANNING

Based on PROPERTY I.D.'s research of specific maps or data for the Bay Area, the following determination is made:

SUBJECT PROPERTY IS LOCATED IN OR IS ADJACENT TO AN AREA OF INDUSTRIAL AND/OR COMMERCIAL LAND USE (LIGHT INDUSTRIAL)

PLANNING

Based on PROPERTY I.D.'s research of specific maps or data for Santa Clara County, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A DESIGNATED INDUSTRIAL AND/OR COMMERCIAL USE ZONE

DISCUSSION:

Industrial or commercial use zones or districts may be established by cities and/or counties wherein certain manufacturing, commercial or airport uses are expressly permitted.

Pursuant to Section 1102.17 of the Civil Code, the seller of residential real property subject to this article who has actual knowledge that the property is affected by, or zoned to allow, an industrial use described in Section 731a of the Code of Civil Procedure, which allows manufacturing, commercial or airport uses in zones that have been established under authority of law for those uses, shall give written notice of that knowledge as soon as practicable before transfer of title.

The existence of various conditions such as traffic, noise, odors, pollution, obstructed views, and other such conditions that are reasonable and necessary in Industrial Use Zones, cannot be enjoined or restrained, nor shall such use be deemed a nuisance as outlined in Section 731a of the Code of Civil Procedure.

Note: Where not specifically identified, determinations may be based on maps or data made for Land Use and Planning purposes, and may not reflect all local zoning. Zoning changes occur often. This report should not be relied upon to provide any specific determination of the current zoning or allowed activities on or near the the Subject Property.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

ABANDONED / ACTIVE MINES

For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

Based on PROPERTY I.D.'s research of specific maps or data obtained from the Office of Mines and Reclamation and the U.S. Geological Survey, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 1 MILE OF IDENTIFIED MINING OPERATIONS, ACTIVE OR ABANDONED

DISCUSSION:

Since the 1849 Gold Rush, mines have been dug and abandoned throughout the State of California. The result is that in the state there are tens of thousands of active and abandoned mines, many unmapped, that can pose safety, health, and environmental hazards. Sites can possess serious physical safety hazards, such as open shafts or adits (mine tunnels), and many mines have the potential to contaminate surface water, groundwater, or air with acid-rock drainage, mercury, arsenic, cyanide, asbestos, lead, chromium, or other contaminants.

The cost of closure and remediation of abandoned mines falls on the current property owner and any potentially responsible parties that can be located and are financially liable. Most current landowners had nothing to do with the historic mining, unlike the potentially responsible parties, and the clean-up costs can be daunting.

Further information is available from the Department of Conservation, Office of Mine Reclamation, Abandoned Mine Lands Unit (AMLU) http://www.conservation.ca.gov/omr/abandoned_mine_lands/Pages/Index.aspx and the U.S. Geological Survey, <http://minerals.usgs.gov>.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

OIL AND GAS WELL PROXIMITY
For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

Based on PROPERTY I.D.'s research of specific maps or data for California, the following determination is made:

**SUBJECT PROPERTY IS NOT LOCATED WITHIN 500 FEET OF AN IDENTIFIED OIL
OR GAS WELL, ACTIVE OR ABANDONED**

DISCUSSION:

Abandoned oil and gas wells dot the landscape of California. Identified wells have been mapped and are monitored by the California Department of Conservation; and are generally regulated by State and Local agencies. While abandoned wells that are properly capped and monitored present a low hazard risk, improper capping or plugging of abandoned wells can lead to a variety of problems. Improperly capped wells can release noxious chemicals into the air, or allow chemicals to leach into groundwater. Abandoned oil and gas wells are prone to buildup of methane gas which can create an explosion hazard if not properly monitored and cleaned. Improperly capped wells can lead to sinkhole development. Wells can pose a serious threat to the safety of humans, especially children, and to animals. Questions of jurisdiction and responsibility in regards to capping and maintenance of abandoned wells may exist.

For more information regarding abandoned oil and gas wells in California, contact the following agencies: State of California Dept. of Conservation - Oil, Gas, and Geothermal Division at <http://www.conservation.ca.gov/dog/Pages/Index.aspx> ; California Environmental Protection Agency <http://www.calepa.ca.gov>

Note: This hazard determination only identifies properties in proximity to abandoned wells that have been mapped by the California Department of Conservation. Unmapped abandoned wells that are not identified in this disclosure could exist on or near the Subject Property. Unmapped and unidentified wells can pose a greater risk to health and safety as they are not monitored and may not have received the appropriate mitigation measures.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

PERCHLORATE CONTAMINATION

For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

Based on PROPERTY I.D.'s research of specific maps or data for Santa Clara County, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A PERCHLORATE STUDY AREA

DISCUSSION:

Perchlorate is both a natural and man-made salt that is used as an oxidizer and used in the production of highway flares, rocket fuel, air bag inflators, matches, fireworks, dyes, lubricating oils, electroplating and medical specialty tests.

The extent of the contamination and the potential hazards to the health of residents in the perchlorate study area is the subject of ongoing investigation, but it is considered to have adverse health effects and water suspected to contain perchlorate should be avoided for drinking and cooking. Conventional water treatment methods, such as carbon filters, air stripping, household water filters, chlorination, aeration and boiling are not effective in removing perchlorate. However, reverse osmosis, distillation and specialized ion exchange resins can be successful in removing perchlorate.

The investigation area is bounded approximately by Tennant Avenue on the north, Masten Avenue on the south, Center Avenue on the east and Monterey Highway on the west. You should consider using bottled water if you obtain your drinking water from a well in the investigation area until the investigation is complete. The water district has an unlimited supply of bottled water for residents in the investigation area who have contacted the Perchlorate Hotline at 408-265-2607 Ext. 2649 to schedule a well test. For further information go to www.valleywater.org, or call the Perchlorate Hotline.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

NOTICE OF RIGHT TO FARM
For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

Based on PROPERTY I.D.'s research of the current county-level GIS "Important Farmland Map," issued by the California Department of Conservation, Division of Land Resource Protection, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN ONE MILE OF AN OFFICIALLY DESIGNATED AREA OF AGRICULTURAL ACTIVITY

The following notice applies to properties located within one mile of agricultural activity.

NOTICE:

This property is located within one mile of farm or ranch land designated on the current county-level GIS "Important Farmland Map," issued by the California Department of Conservation, Division of Land Resource Protection. Accordingly, the property may be subject to inconveniences or discomforts resulting from agricultural operations that are a normal and necessary aspect of living in a community with a strong rural character and a healthy agricultural sector. Customary agricultural practices in farm operations may include, but are not limited to, noise, odors, dust, light, insects, the operation of pumps and machinery, the storage and disposal of manure, bee pollination, and the ground or aerial application of fertilizers, pesticides, and herbicides. These agricultural practices may occur at any time during the 24-hour day. Individual sensitivities to those practices can vary from person to person. You may wish to consider the impacts of such agricultural practices before you complete your purchase. Please be advised that you may be barred from obtaining legal remedies against agricultural practices conducted in a manner consistent with proper and accepted customs and standards pursuant to Section 3482.5 of the Civil Code or any pertinent local ordinance.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

LAND CONSERVATION DETERMINATION
For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

Based on PROPERTY I.D.'s research of specific maps or data for the California Department of Conservation, Division of Land Resource Protection and in conjunction with local county agencies, the following determination is made:

SUBJECT PROPERTY IS NOT / WAS NOT LOCATED IN LANDS UNDER CONTRACT PURSUANT TO THE CALIFORNIA LAND CONSERVATION (WILLIAMSON) ACT AT THE TIME THE DATA WAS OBTAINED.

DISCUSSION:

The Williamson Act was passed by the California Legislature in 1965 to preserve agricultural and open space lands in Agricultural Preserves by discouraging premature and unnecessary conversion to urban uses. The term "Agricultural Preserve" is an area for which a city or county will enter into contracts with landowners to devote land to agricultural or open-space uses, pursuant to the California Land Conservation (Williamson) Act. Preserves are regulated by rules and restrictions designated in the resolution to ensure that the land within the Preserve is maintained for agricultural or open space use.

The Williamson Act authorizes local governments and property owners to (voluntarily) enter into 10-year rolling term contracts to commit land to specified uses. In return, restricted parcels may be assessed for property tax purposes at a rate consistent with their actual use, rather than potential market value. However, a Williamson Act contract on the property does not by itself necessarily guarantee that the property will be assessed at a reduced value for property tax purposes. A Williamson Act contract runs with the land and is binding on all successors in interest of the landowner. A landowner's failure to meet the conditions of the contract may be considered a breach of the contract, which will allow the local government to sue the landowner and/or not renew the contract.

Additionally, if the Subject Property is located at or near Agricultural Preserves, inconvenience or discomfort may arise from the use of the land for agricultural activity or processing activity in a manner consistent with proper and accepted customs and standards. Agricultural activity, operation, or facility, or appurtenances thereof shall include, but not be limited to, the cultivation and tillage of the soil, dairying, the production, cultivation, growing, and harvesting of any agricultural commodity including timber, viticulture, apiculture, or horticulture, the raising of livestock, fur bearing animals, fish, or poultry, and any practices performed by a farmer or on a farm as incident to or in conjunction with those farming operations, including preparation for market, delivery to storage or to market, or delivery to carriers for transportation to market. Agricultural processing activity, operation, facility, or appurtenances thereof includes, but is not limited to, the canning or freezing of agricultural products, the processing of dairy products, the production and bottling of beer and wine, the processing of meat and egg products, the drying of fruits and grains, the packaging and cooling of fruits and vegetables, and the storage or warehousing of any agricultural products, and includes processing for wholesale or retail markets of agricultural products.

When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency. No visual examination of the Subject Property was performed. This report is not a substitute for a visual examination and/or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained. Property I.D. has acted in good faith to obtain, from governmental agencies, the adopted publicly distributed natural hazard disclosure information appropriate for inclusion in the Natural Hazard Disclosure Report pursuant to Civil Code Section 1103 et seq. The inclusion of any specific determination in this report does not preclude the possibility that other information could exist that would provide additional or different determinations for the Subject Property. If a recipient of this report has information that is different from a determination contained in this report, or has any questions about this report, he or she should contact Property I.D. before using this document.

PROPERTY TAX RECORDS
For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

Based on Property I.D.'s research of available tax records from Santa Clara County for the 2008-2009 tax year, the following determinations are made:

TOTAL ANNUAL TAX \$8,840.67*

* This amount represents the total annual tax fee based on the levies and property valuation as listed in the identified tax records as of the beginning of the identified tax year. This amount is subject to change pursuant to the purchase price of the property and/or changes to the assessed value, and does not include supplemental tax bills or penalty fees.

Mello-Roos Community Facilities District Levies - Details

Notice of Special Tax

SUBJECT PROPERTY DOES NOT CURRENTLY HAVE MELLO ROOS TAXES LEVIED AGAINST IT.

The Mello-Roos Community Facilities District Act, enacted in 1982, allows local governments to create tax districts to finance public facility and service improvements such as sewers, electrical upgrades, infrastructure, parks, etc. Mello-Roos taxes must be voted on and approved by a 2/3 majority vote of the property owners in the respective district.

Note: By voter approval new Mello-Roos taxes may be levied against this property in the future.

Special Assessment Levies - Details

Notice of Special Assessment

SUBJECT PROPERTY IS LOCATED IN A SPECIAL TAX ASSESSMENT DISTRICT

Special Assessments are taxes levied against parcels for public projects in which the amount of the charge is based on the benefit of the project to the parcel. Assessments based on the 1915 Bond Act are among special assessments, and are generally used to fund public improvement projects such as streets and sewer systems.

Note: By voter approval new Special Assessment taxes may be levied against this property in the future.

Code	Description	Contact	Phone	Amount
856	MV-WHISMAN SCH TAX	CRAIG GOLDMAN	(650)526-3548	\$75.00
880	SCVWD FLOOD ASSMT, NORTHWEST	SPECIAL TAX BEN. ASSMT HOTLINE	(408)265-2607 x 281	\$47.88
820	SCVWD CLEAN SAFE CREEKS	JULIE WILSON	(408)265-3137	\$23.46
847	S.C. COUNTY - VECTOR CONTROL DIST	JEANETTE HYNSON	(800)273-5167	\$5.08
848	MOSQUITO ASMT #2	JEANETTE HYNSON	(800)273-5167	\$5.02

Property Value Adjusted (Ad Valorem) Levies - Details

SUBJECT PROPERTY IS SUBJECT TO AD VALOREM TAXES

Ad Valorem taxes, also known as “Rate-Based Taxes” are charges calculated as a percentage of the total value of real property, including improvement and land values as determined by the county assessor. California’s standard 1% property tax is included among these rate based taxes.

Note: By voter approval new Ad Valorem taxes may be levied against this property in the future.

Code	Description	Contact	Phone	Rate	Amount
P13	PROP. 13 STANDARD 1% TAX	SANTA CLARA COUNTY TAX COLLECTOR	(408) 808-7900	1%	\$7793.43 *
AV	CO RETIREMENT LEVY	SANTA CLARA COUNTY TAX COLLECTOR	(408) 808-7900	0.0388%	\$302.39 *
AV	MTN VIEW ELEM 1998	SANTA CLARA COUNTY TAX COLLECTOR	(408) 808-7900	0.0294%	\$229.13 *
AV	MV-LOS ALTOS HIGH BOND NO 1	SANTA CLARA COUNTY TAX COLLECTOR	(408) 808-7900	0.0148%	\$115.34 *
AV	EL CAMINO HOSPITAL 2003	SANTA CLARA COUNTY TAX COLLECTOR	(408) 808-7900	0.0129%	\$100.54 *
AV	FOOTHILL-DE ANZA COLL 1999	SANTA CLARA COUNTY TAX COLLECTOR	(408) 808-7900	0.0106%	\$82.61 *
AV	SCVWD-STATE WATER PROJ	SANTA CLARA COUNTY TAX COLLECTOR	(408) 808-7900	0.0059%	\$45.98 *
AV	FOOTHILL COLLEGE 2006	SANTA CLARA COUNTY TAX COLLECTOR	(408) 808-7900	0.0017%	\$13.25 *
AV	SCVWD-ZONE W-1 BOND	SANTA CLARA COUNTY TAX COLLECTOR	(408) 808-7900	0.0002%	\$1.56 *

* This amount represents the fees based on the property valuation as listed in the identified tax records as of the beginning of the identified tax year. This amount is subject to change pursuant to the purchase price of the property and/or changes to the assessed value and does not include supplemental tax bills.

Discussion:

This is a notification to you prior to your purchasing this property. If this property is within the above-named assessment district(s), the assessment district(s) issued bonds to finance the acquisition or construction of certain public improvements that are of direct and special benefit to property within the assessment district. The bonds will be repaid from annual assessment installments on property within the assessment districts. If this property is subject to annual assessment installments, the assessment districts will appear on the property tax bills, in addition to the regular property taxes and any other charges and levies that will be listed on the property tax bill. If you fail to pay assessment installments when due each year, the property may be foreclosed upon and sold. Assessment installments will be collected each year until the assessment bonds are repaid. These facilities may not yet have all been constructed or acquired and it is possible that some may never be constructed or acquired. This assessment and the benefits from the public facilities for which it pays should be taken into account in deciding whether to buy this property. This disclosure notice is made pursuant to Government Code Section 53754 and Civil Code Section 1102.6b and satisfies the 1915 Bond and Special Assessment disclosure requirements.

Note: The applicable county tax assessor/collector and Property I.D. update their Tax Assessment information yearly or quarterly. Only Assessments that were levied against properties at the time Property I.D. obtained the tax records are disclosed. This information is subject to change and Property I.D. is not

PROPERTY TAX RECORDS

(continued)

responsible for any changes that may occur. No study of the public records was made by Property I.D. to determine the presence of any other tax or assessment. The above explanation of Special Assessments is intended to be general in nature and is not a substitute for a tax bill, title report or title insurance. Detailed information may be available by contacting the agency that administers the Special Assessment. If detailed information is desired, Property I.D. recommends that an appropriate professional consultant be retained.

In some cases (including some condos, mobile homes, and new subdivisions), the tax roll data disclosed may represent the entire amount for the main parcel when the individual parcels have not been segregated.

NOTICE OF YOUR SUPPLEMENTAL PROPERTY TAX BILL

California property tax law requires the Assessor to revalue real property at the time the ownership of the property changes. Because of this law, you may receive one or two supplemental tax bills, depending on when your loan closes. The supplemental tax bills are not mailed to your lender. If you have arranged for your property tax payments to be paid through an impound account, the supplemental tax bills will not be paid by your lender. It is your responsibility to pay these supplemental bills directly to the Tax Collector. If you have any question concerning this matter, please call your local Tax Collector's Office.

Note: This is a notice to you that the County Assessor will revalue the property and you will be responsible for paying the taxes due according to the reassessed value. It is not a disclosure of actual supplemental property taxes.

GENERAL NOTICE OF TRANSFER FEE DISCLOSURE

Some properties may be affected by transfer fees. In the event that the property being transferred is subject to a transfer fee, the transferor is required to make this disclosure. A transferor may request the title company that issued the preliminary title report to provide copies of the documents for review in order for the transferor to determine if the property being transferred is subject to a transfer fee.

A "transfer fee" is any fee payment requirement imposed within a covenant, condition or restriction (CC&R), contained in any deed, contract, security instrument, or other document affecting the transfer or sale of, or any interest in, real property that requires a fee be paid upon transfer of the real property.

If the property being transferred is subject to a transfer fee, the transferor shall provide, at the same time as the transfer disclosure statement is provided, an additional disclosure that includes (1) notice that payment of a transfer fee is required upon transfer of the property; (2) the amount of the fee required for the asking price of the real property and a description of how the fee is calculated; (3) notice that the final amount of the fee may be different if the fee is based upon a percentage of the final sale price; (4) the entity to which funds from the fee will be paid; (5) the purpose for which the funds from the fee will be used; (6) the date or circumstances under which the obligation to pay the transfer fee expires, if any.

You may wish to investigate and determine whether the imposition of a transfer fee, if any, is acceptable to you and your intended use of the property before you complete your transaction.

GENERAL NOTICES OF REQUIRED DISCLOSURES

METHAMPHETAMINE CONTAMINATION

Methamphetamine use and production are growing throughout the State of California. Properties may be contaminated by hazardous chemicals used or produced in the manufacture of methamphetamine where those chemicals remain and where the contamination has not been remediated. Once the methamphetamine laboratories have been closed, the public may be harmed by the material and residues that remain.

Because the methamphetamine manufacturing process leads to chemical contamination, the Methamphetamine Contaminated Cleanup Act of 2005 requires a property owner to disclose in writing to a prospective buyer if local health officials have issued an order prohibiting the use or occupancy of a property contaminated by methamphetamine laboratory activity. The owner must also provide the buyer with a copy of the pending order to acknowledge receipt in writing. Property owner(s) must retain a methamphetamine laboratory site remediation firm that is an authorized contractor meeting certain requirements, as defined, to remediate the contamination caused by a methamphetamine laboratory activity. Civil penalties up to \$5,000 can be imposed upon a property owner who does not provide a notice or disclosure required by the act, or upon a person who violates an order issued by the local health officer prohibiting use or occupancy of a property contaminated by a methamphetamine laboratory activity. In addition, local health and law enforcement agencies are required to take specified action, including the filing of a lien against a property for cleanup of the contamination.

Realtors and Property I.D. do not have the requisite expertise to determine the need for testing or cleanup of methamphetamine contamination and cannot verify the information provided about such contamination by others.

MEGAN'S LAW - SEX OFFENDER DATABASE

Pursuant to Section 290.46 of the Penal Code, information about specified registered sex offenders is made available to the public via an Internet website maintained by the Department of Justice at www.meganslaw.ca.gov. This site provides access to information on persons required to register in California as sex offenders. Specific home addresses are displayed for many offenders in the California communities; as to these persons, the site displays the last registered address reported by the offender. Additional offenders are included on the site with listing by ZIP Code, city, and county. Information on other offenders is not included on this site, but is known to law enforcement personnel.

The California Legislature has created this statewide website to enable the public to secure information regarding the location of registered sex offenders. Anyone who is interested in this information should go on-line at www.meganslaw.ca.gov prior to removing their inspection contingency. Brokers and Property I.D. cannot and will not verify the information provided by the Government. Neither Brokers nor Property I.D. make any representations or guarantees as to the timeliness or accuracy of the information supplied at this website.

ABANDONED WELLS

The Department of Water Resources estimates that there are approximately 750,000 water wells scattered throughout the State of California - some of these wells are abandoned. Wells that have been abandoned pose a serious threat to the safety of humans, especially children, and to animals. Section 24400 of the California Health and Safety Code requires that abandoned excavations be fenced, covered, or filled. In addition, abandoned wells may act as conduits for the contamination of groundwater since inadequately constructed wells provide a physical connection between sources of pollution and useable water.

ENVIRONMENTAL HAZARDS REPORT

For
80 GLENMEAD COURT, MOUNTAIN VIEW, CA 94040
APN 148-35-020

This Environmental Hazards Report provides information on known, existing and historic hazardous substance contaminated sites that may be on or near the Subject Property, as listed by the Environmental Protection Agency and/or other specified regulatory bodies.

RECORDS SUMMARY

Mapped Sites			
Type	Description	Regulatory Info	# Sites
NPL/CERCLIS	National Priorities List / Comprehensive Environmental Response, Compensation, and Liability Information System	EPA	3
RCRA	Resource Conservation and Recovery Act	EPA	13
SMBRPD	Site Mitigation & Brownfields Reuse Program Database	CA Department of Toxic Substances	5
SWIS	Solid Waste Information System	CA Integrated Waste Management Board	0
LUST	Leaking Underground Storage Tanks	CA Water Resources Control Board	5
SLIC	Spills, Leaks, Investigation and Cleanup	CA Water Resources Control Board	3

Unmapped Sites			
Type	Description	Regulatory Info	# Sites
NPL/CERCLIS - Unmapped	National Priorities List / Comprehensive Environmental Response, Compensation, and Liability Information System	EPA	0
RCRA - Unmapped	Resource Conservation and Recovery Act	EPA	24
SMBRPD - Unmapped	Site Mitigation & Brownfields Reuse Program Database	CA Department of Toxic Substances	0
SWIS - Unmapped	Solid Waste Information System	CA Integrated Waste Management Board	0
LUST - Unmapped	Leaking Underground Storage Tanks	CA Water Resources Control Board	31
SLIC - Unmapped	Spills, Leaks, Investigation and Cleanup	CA Water Resources Control Board	4

NPL/CERCLIS Site Details

The CERCLIS database is the Comprehensive Environmental Response, Compensation and Liability Information System that contains information on hazardous waste sites, potentially hazardous waste sites and remedial activities across the nation. CERCLIS is based on the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), commonly known as Superfund, enacted by Congress on December 11, 1980. The database includes sites that are on the National Priorities List (NPL) or being considered for the NPL. The NPL is the Environmental Protection Agency's (EPA) database of uncontrolled or abandoned hazardous waste sites identified for remedial actions under the Superfund program. A site must meet or surpass a predetermined hazard ranking system score, be chosen as a state's top priority site, or meet three specific criteria set jointly by the US Department of Health and Human Services and the US EPA in order to become an NPL site. More information can be obtained from www.epa.gov/superfund/action/index.htm website. This report lists CERCLA sites identified as being within 1 mile of Subject Property.

CERCLIS SITE ID: 0905988	
IDEAL SERVICE LAUNDRY 113 ESCUELA AVE. MOUNTAIN VIEW, CA 94041	Distance: 0.6 mi Direction: SE
Latitude: 0	Longitude: 0
NPL Status: Not on the NPL - No Further Remedial Action Planned Status Date: 08/30/2004	
Superfund ID: CAN000905988	Site Type:
EPA Region: Region 9	Category:
Area:	Responsible Agency: Not a Federal Facility

CERCLIS SITE ID: 0901126	
JASCO CHEMICAL CORP. 1710 VILLA ST MOUNTAIN VIEW, CA 94041	Distance: 0.8 mi Direction: SE
Latitude: 37.3988	Longitude: -122.0882
NPL Status: Currently on the Final NPL Status Date: N/A	
Superfund ID: CAD009103318	Site Type:
EPA Region: Region 9	Category: Chemical Plant
Area: 2 Acres	Responsible Agency: Not a Federal Facility

NPL/CERCLIS

Site Details

(continued)

CERCLIS SITE ID: 0900392	
SIERRA VISTA PROPERTIES 465 SIERRA VISTA WAY MOUNTAIN VIEW, CA 94035	Distance: 0.8 mi Direction: NE
Latitude: 0	Longitude: 0
NPL Status: Not on the NPL - Other Cleanup Activity: State-Lead Cleanup Status Date: 12/05/2001	
Superfund ID: CAD982400285	Site Type:
EPA Region: Region 9	Category:
Area:	Responsible Agency: Not a Federal Facility

RCRA Site Details

RCRA is the Resource Conservation and Recovery Act, which was enacted by Congress in 1976. RCRA's primary goals are to protect human health and the environment from the potential hazards of waste disposal, to conserve energy and natural resources, to reduce the amount of waste generated, and to ensure that wastes are managed in an environmentally sound manner. Specifically, RCRA regulates the management of hazardous wastes from the point of origin to the point of final disposal. Additional information is available on www.epa.gov/epaoswer/osw/laws-reg.htm website.

This report lists RCRA sites identified as being within 1/2 mile of Subject Property.

RCRA SITE ID: CAD981583644	
FABTRON INC 2287 MORA DR MOUNTAIN VIEW, CA 94040	Distance: 0.0 mi Direction: SW
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA SITE ID: CAD000819821	
SYMTRON CORP MOUNTAIN VIEW DIV 2235 MORA DR MOUNTAIN VIEW, CA 94040	Distance: 0.1 mi Direction: SE
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

**RCRA
Site Details**
(continued)

RCRA SITE ID: CAD983610338	
CALIFORNIA CLEANERS 2425 CALIFORNIA ST MOUNTAIN VIEW, CA 94040	Distance: 0.2 mi Direction: SW
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA SITE ID: CAD980675961	
SHELL SERVICE STATION 110 N RENGSTORFF MOUNTAIN VIEW, CA 94040	Distance: 0.2 mi Direction: E
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: 1	
Waste: IGNITABLE WASTE	

RCRA SITE ID: CAR000042630	
WALGREENS 2659 112 RENGSTORFF MOUNTAIN VIEW, CA 94043	Distance: 0.2 mi Direction: E
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: 2	
Waste: SILVER; D000*	

RCRA SITE ID: CAR000055251	
SAVON 3797 2535 CALIFORNIA ST MOUNTAIN VIEW, CA 94040	Distance: 0.3 mi Direction: W
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: 2	
Waste: SILVER; D000*	

RCRA SITE ID: CAD981424641	
HEWLETT PACKARD OFFICE COMPLEX 100 MAYFIELD AVE MOUNTAIN VIEW, CA 94040	Distance: 0.3 mi Direction: NW
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

**RCRA
Site Details**
(continued)

RCRA SITE ID: CAD981632151	
SUNBEAM CLEANERS 128 N RENGSDORFF MOUNTAIN VIEW, CA 94040	Distance: 0.3 mi Direction: E
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA SITE ID: CAD981635998	
CALIFORNIA CLEANERS 2520 CALIFORNIA ST MOUNTAIN VIEW, CA 94040	Distance: 0.3 mi Direction: W
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA SITE ID: CAD000627745	
QUALEX INC 555 SHOWERS DR MOUNTAIN VIEW, CA 94040	Distance: 0.4 mi Direction: SW
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: 1	
Waste: SILVER	

RCRA SITE ID: CAT080019961	
PACIFIC BELL 2465 LATHAM STREET MOUNTAIN VIEW, CA 94040	Distance: 0.4 mi Direction: SW
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA SITE ID: CAD983672197	
TAYLOR RENTALS 2246 W EL CAMINO REAL MOUNTAIN VIEW, CA 94040	Distance: 0.5 mi Direction: S
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

**RCRA
Site Details**
(continued)

RCRA SITE ID: CAD981411887	
EXXON RAS NO 73542 584 N RENGSTORFF MOUNTAIN VIEW, CA 94040	Distance: 0.5 mi Direction: S
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: 3	
Waste: IGNITABLE WASTE; BENZENE: D000*	

Note: When the Waste field contains "*" the contents of the field have been truncated at 255 characters, due to database limitations. When the Waste field contains "**" the list of contaminants is truncated after the first five, due to database limitations. For more information on a listed site contact the Environmental Protection Agency.

**SWIS
Site Details**

The Solid Waste Information System (SWIS) database is provided by the California Integrated Waste Management Board (CIWMB). The SWIS database contains information on solid waste facilities, operations, and disposal sites throughout the State of California. The types of facilities found in this database include landfills, transfer stations, material recovery facilities, composting sites, transformation facilities, waste tire sites, and closed disposal sites. For more information contact the CIWMB at: Tel: (916) 341-6322, email: samerine@ciwmb.ca.gov, and URL: www.ciwmb.ca.gov/SWIS/. This report lists SWIS sites identified as being within 1/2 mile of Subject Property.

NO MAPPED SWIS SITES WERE FOUND IN PROXIMITY OF THE SUBJECT PROPERTY

**SMBRPD / Brownfields
Site Details**

Site Mitigation and Brownfields Reuse Program (SMBRP) database contains information on sites that are contaminated, or thought to be contaminated, and are underutilized due to perceived remediation costs and liability concerns. A brownfields site is land, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. When agricultural and green spaces are developed for residential, commercial or industrial uses, infrastructure such as roads and sewers must be developed. EPA's Brownfields Program is designed to prevent, assess, safely clean up, and sustainably reuse brownfields. California SMBRP is overseen by the Department of Toxic Substances Control (DTSC) that has integrated existing programs and developed a number of new tools to facilitate reuse of brownfields properties. Additional information is available on www.dtsc.ca.gov/SiteCleanup/Brownfields/ website. This report lists SMBRP sites identified as being within 1/2 mile of Subject Property.

**SMBRPD / Brownfields
Site Details**
(continued)

SMBRPD SITE ID: 43360128	
TRW/VIDAR 77 ORTEGA AVENUE MOUNTAIN VIEW, CA 94040	Distance: 0.0 mi Direction: W
Latitude: 37.403611	Longitude: -122.1025
NPL Status: NO	Status: Certified / Operation & Maintenance
Regulatory Agency: SMBRP	Status Date: 7/10/2001
Site Type: State Response	Details: State Response or NPL
APNs: 147-54-031, 147-54-037, 147-54-038 and 147-54-039	Past Uses: MANUFACTURING - ELECTRONIC
Confirmed Contaminants: 300,223,002,730,028,000,000,000,000,000	Potential Contaminants: 30022, 30027, 30028, 30194, 30195, 30593
Site Management: GW, OIL, EXT	Affected Media: OTH

SMBRPD SITE ID: 43360069	
PLESSEY MICRO SCIENCE 2274 MORA DRIVE MOUNTAIN VIEW, CA 94040	Distance: 0.0 mi Direction: SW
Latitude: 37.403233	Longitude: -122.102136
NPL Status: NO	Status: Certified / Operation & Maintenance
Regulatory Agency: SMBRP	Status Date: 6/28/2007
Site Type: State Response	Details: State Response or NPL
APNs: 147-54-026, 147-54-027, 147-54-028, 147-54-029, 147-54-030	Past Uses: MANUFACTURING - ELECTRONIC
Confirmed Contaminants: 30,003,300,223,002,700,000,000,000,000,000,000,000,000, 000,000,000	Potential Contaminants: 30003, 30022, 30027, 30028, 30136, 30153, 30195, 30272, 30550, 30593
Site Management: NONE SPECIFIED	Affected Media: OTH, SOIL

SMBRPD SITE ID: 43360135	
PLESSEY #3 2256 MORA DRIVE MOUNTAIN VIEW, CA 94040	Distance: 0.1 mi Direction: SE
Latitude: 37.402924	Longitude: -122.101025
NPL Status: NO	Status: No Further Action
Regulatory Agency: SMBRP	Status Date: 10/5/2001
Site Type: State Response	Details: State Response or NPL
APNs: 147-54-024 and 147-54-025	Past Uses: MANUFACTURING - ELECTRONIC
Confirmed Contaminants: 3,002,230,027	Potential Contaminants: 30022, 30027
Site Management: NONE SPECIFIED	Affected Media: OTH

**SMBRPD / Brownfields
Site Details**
(continued)

SMBRPD SITE ID: 43360130	
SYMTRON #2	
111 ORTEGA AVENUE	Distance: 0.1 mi
MOUNTAIN VIEW, CA 94040	Direction: SW
Latitude: 37.403056	Longitude: -122.102778
NPL Status: NO	Status: No Further Action
Regulatory Agency: SMBRP	Status Date: 6/29/2001
Site Type: State Response	Details: State Response or NPL
APNs: 147-54-009	Past Uses: MANUFACTURING - ELECTRONIC
Confirmed Contaminants: 3,002,230,027	Potential Contaminants: 30022, 30027
Site Management: NONE SPECIFIED	Affected Media: OTH

SMBRPD SITE ID: 43360124	
SYMTRON CORP.	
2235-2245 MORA DR.	Distance: 0.1 mi
MOUNTAIN VIEW, CA 94040	Direction: S
Latitude: 37.4025	Longitude: -122.101389
NPL Status: NO	Status: No Further Action
Regulatory Agency: SMBRP	Status Date: 6/29/2001
Site Type: State Response	Details: State Response or NPL
APNs: 147-54-016, 147-54-017, 147-54-018, 147-54-019	Past Uses: MANUFACTURING - OTHER
Confirmed Contaminants: 300,133,002,230,027	Potential Contaminants: 30013, 30022, 30027
Site Management: NONE SPECIFIED	Affected Media: OTH

Note: When a field contains "*" the contents of the field have been truncated due to database limitations. More information than that listed may available. For more information on this site contact the Department of Toxic Substances Control.

**LUST
Site Details**

The Leaking Underground Storage Tank (LUST) database identifies underground tanks that currently have, or in the past had, unauthorized releases (leaks) that may pose a danger to public health and the environment. Cleanup of soil and groundwater contamination is overseen generally by the State Water Resources Control Board. Additional information is available on www.swrcb.ca.gov/ust/index.html website.

This report lists LUST sites identified as being within 1/2 mile of Subject Property.

LUST
Site Details
(continued)

LUST SITE ID: T0608501243	
Shell 110 N Rengstorff Ave Mountain View, CA 94043	Distance: 0.2 mi Direction: E
Regional Case No.:	Discovery:
Local Case No.: 06S2W17R01f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 1/14/1989 12:00:00 AM
Local Agency: SANTA CLARA HLTH DEPT - TOXICS	Stop Method:
Operator:	Closed: 4/11/2005
Program: LUST	Cause:
Status: Case Closed	Source:
Enforcement: Informal Staff Enforcement Letter	MTBE Test: Detected
Type: Other Groundwater (not used for drinking water)	MTBE Test Date: 7/13/1999 12:00:00 AM
Substance: Gasoline - Automotive	Abatement:
Summary:	

LUST SITE ID: T0608500963	
Mountain View Center 2540 California St Mountain View, CA 94035	Distance: 0.3 mi Direction: W
Regional Case No.:	Discovery:
Local Case No.: 06S2W17P01f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 1/1/1990 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 6/27/1995
Program: LUST	Cause:
Status: Case Closed	Source:
Enforcement:	MTBE Test: Not required to be tested
Type: Other Groundwater (not used for drinking water)	MTBE Test Date:
Substance: Not reported	Abatement:
Summary:	

LUST
Site Details
(continued)

LUST SITE ID: T0608500515	
Digas 555 Showers Dr Mountain View, CA 94040	Distance: 0.3 mi Direction: SW
Regional Case No.:	Discovery:
Local Case No.: 06S2W20C02f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 10/2/1986 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 9/17/1997
Program: LUST	Cause:
Status: Case Closed	Source:
Enforcement: Notice of Violation	MTBE Test: Detected
Type: Other Groundwater (not used for drinking water)	MTBE Test Date: 5/27/1997 12:00:00 AM
Substance: Gasoline - Automotive	Abatement:
Summary:	

LUST SITE ID: T0608500644	
Franciscan Glass Co. 100 San Antonio Cir Mountain View, CA 94040	Distance: 0.5 mi Direction: NW
Regional Case No.:	Discovery:
Local Case No.: 06S2W17L01f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 10/1/1986 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 3/5/1991
Program: LUST	Cause:
Status: Case Closed	Source:
Enforcement: Notice of Responsibility	MTBE Test: Not tested
Type: Soil impacted	MTBE Test Date:
Substance: Gasoline - Automotive	Abatement:
Summary:	

LUST
Site Details
(continued)

LUST SITE ID: T0608500581	
Exxon #7-3542 584 N Rengstorff Ave Mountain View, CA 94040	Distance: 0.5 mi Direction: S
Regional Case No. :	Discovery:
Local Case No. : 06S2W16E01f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 1/20/1988 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 11/3/2004
Program: LUST	Cause:
Status: Case Closed	Source:
Enforcement: Informal Staff Enforcement Letter	MTBE Test: Detected
Type: Other Groundwater (not used for drinking water)	MTBE Test Date: 5/27/2003 12:00:00 AM
Substance: Gasoline - Automotive	Abatement:
Summary:	

Note: When a field contains '*' no descriptive information was available for the code provided. Where a field contains '**' the contents of the field have been truncated at 255 characters, due to database limitations. For more information on this site contact the State Water Resources Control Board.

SLIC
Site Details

The Spills, Leaks, Investigation and Cleanups (SLIC) program is designed to protect and restore water quality from spills, leaks, and similar discharges. SLIC sites are typically sites where a spill or leak has occurred on the ground surface from a source other than an Underground Storage Tank (UST). Cleanup levels for groundwater and surface water are determined based on application of existing laws, regulations, plans, and policies. SLIC cases are overseen by the State Water Resources Control Board. Additional information is available on www.swrcb.ca.gov/rwqcb1/programs/slic.html website.

This report lists SLIC sites identified as being within 1/2 mile of Subject Property.

SLIC SITE ID: SL0608508217	
PLESSEY INC. 2294 MORA DR MOUNTAIN VIEW, CA	Distance: 0.0 mi Direction: W
Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)	Regional Case No. : 43s1033
Substance: Solvents	Status: Case Open

**SLIC
Site Details**
(continued)

SLIC SITE ID: SL18311731	
IRM COST SHARING SITE 2520 CALIFORNIA STREET MOUNTAIN VIEW, CA	Distance: 0.3 mi Direction: W
Lead Agency:	Regional Case No.:
Substance: *VOC	Status: Verification Monitoring Underway

SLIC SITE ID: SLT2O111117	
ONE HOUR CLEANERS 580 RENGSTORFF AVE N MOUNTAIN VIEW, CA 94040	Distance: 0.4 mi Direction: S
Lead Agency:	Regional Case No.:
Substance:	Status:

Note: When a field contains "*" no descriptive information was available for the substance code provided. For more information on this site contact the State Water Resources Control Board.

UNMAPPED SITES

Although the Environmental Site records are official, some of the records may contain missing, non-specific, or incorrect information regarding the names, addresses or other attributes, due to errors and omissions prior to their submission to the governing regulatory body. This factor prevents some sites from being precisely located. It is for this reason that a site may be listed in this "unmapped sites" section of the report.

The information in the environmental report comes directly from the official hazardous substance site lists, which include sites with incomplete information as well. Accordingly, Property I.D. includes those unmapped sites that might be within one half-mile of the Subject Property based upon the available information provided by the EPA and/or other regulatory bodies.

RCRA - Unmapped Site Details

RCRA SITE ID: CAD981394950	
RECHE CORPORATION 1400 STIERLIN RD #D-1 MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA - Unmapped Site Details

(continued)

RCRA SITE ID: CAD981388010	
MMR TECHNOLOGIES, INC 1400 STIERLIN RD A5 MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA SITE ID: CAD981630239	
LIFESOURCE INC 105 S DRIVE SUITE H MOUNTAIN VIEW, CA 94040	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA SITE ID: CAR000018853	
SCVTA TASMAN BLOCK C110 MIDDLEFIELD AND CENTRAL EXPWY MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA SITE ID: CAR000063586	
DCI MANAGEMENT GROUP NO 77 2290 EL CAMINO REAL NO 1 MOUNTAIN VIEW, CA 94040	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: 2	
Waste: TETRACHLOROETHYLENE; D000*	

RCRA SITE ID: CAD981632631	
MILLERS CLEANERS 1554 MIRAMOTE AVE LOS ALTOS, CA 94022	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA - Unmapped Site Details

(continued)

RCRA SITE ID: CAD981657778	
HUNTINGTON MECHANICAL LABS INC 1040 LAVENIDA MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Large Quantity Generator	Operating Status:
No. Reported Products: 2	
Waste: * CHROMIUM; WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR Z	

RCRA SITE ID: CAD056183833	
UNITED SCIENTIFIC CORPORATION 1400 D STIERLIN ROAD MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA SITE ID: CAD059494146	
MINIMATICS INC 2470 CHARLESTON RD MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA SITE ID: CAD981369150	
HARRIS BROADCAST MICROWAVE OPR 967 STIERLIN RD MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA - Unmapped Site Details

(continued)

RCRA SITE ID: CAD054801477	
LGM MFG INC 723 STIERLIN ROAD MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA SITE ID: CAD981371412	
CRYSTACOMM INC 1599 STIERLIN RD MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA SITE ID: CAD980814735	
DREXLER TECHNOLOGY CORP 2644 BAYSHORE FRONTAGE RD MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA SITE ID: CAD009212838	
PRINTEX CORPORATION PLYMOUTH & COLONY STS. MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA - Unmapped Site Details

(continued)

RCRA SITE ID: CAR000164293	
RGRP N101 WESCOAT AND MCCORD AVE MOFFETT FIELD, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Large Quantity Generator	Operating Status:
No. Reported Products: 2	
Waste: * 1,1-DICHLOROETHYLENE; THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND	

RCRA SITE ID: CAR000014621	
WALGREENS 3344 4470 EL CAMINO REAL PALO ALTO, CA 94306	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Large Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA SITE ID: CAD983617135	
HOLIDAY CLEANERS 660 B SAN ANTONIO RD MOUNTAIN VIEW, CA 94040	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA SITE ID: CAD980675904	
SHELL SERV STATION MT VIEW 807 STIERLIN RD MOUNTAIN VIEW, CA 94040	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA - Unmapped Site Details

(continued)

RCRA SITE ID: CAR000016782	
ALZA CORP (M3A/B/C) 1058 B HUFF AVE MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Large Quantity Generator	Operating Status:
No. Reported Products: 12	
Waste: ** IGNITABLE WASTE; CORROSIVE WASTE; REACTIVE WASTE; MERCURY; CHLOROFORM	

RCRA SITE ID: CAR000101345	
DYMOND DEVELOPMENT 1201 SAN ANTONIO RD PARKING LO MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: 4	
Waste: TETRACHLOROETHYLENE; TRICHLORETHYLENE; VINYL CHLORIDE; D000*	

RCRA SITE ID: CAD982037632	
SANTA CLARA COUNTY HEALTH DEPT 750 MOFFETT BLVD MOUNTAIN VIEW, CA 94040	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA SITE ID: CAD054613583	
SUN MICROSYSTEMS 1201 SAN ANTONIO RD MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA SITE ID: CAD982475477	
RUDOLPH AND SLETTEN INC 1250 L'AVENIDA MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

RCRA - Unmapped Site Details

(continued)

RCRA SITE ID: CAD982356990	
ST JOSEPH COLLEGE 7600 ST JOSEPH AVE LOS ALTOS, CA 94022	Distance: (exact location not mapped) Direction: (exact location not mapped)
Generator Status: Small Quantity Generator	Operating Status:
No. Reported Products: N/A	
Waste:	

LUST - Unmapped Site Details

LUST SITE ID: T0608591652	
HYATT RICKEYS 4201 4219 EL CAMINO REAL PALO ALTO, CA 94306	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.: 43S0514	Discovery: Tank Closure
Local Case No.:	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Regional Board Lead	Reported: 7/14/1983 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed:
Program: SLIC	Cause: No Description
Status: Pollution Characterization	Source: No Description
Enforcement:	MTBE Test: Not required to be tested
Type: Soil impacted	MTBE Test Date:
Substance: Solvents	Abatement:
Summary:	

LUST - Unmapped Site Details

(continued)

LUST SITE ID: T0608591744	
GOODSELL AND VOCKE INC 1401 STIERLIN RD MOUNTAIN VIEW, CA 94040	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.: 43-1914	Discovery: Tank Closure
Local Case No.: 43-1914	Discovered: 4/14/1987 12:00:00 AM
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed: 4/14/1987
Lead Agency: Regional Board Lead	Reported: 9/4/1990 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed:
Program: SLIC	Cause: Structural Failure
Status: Leak Confirmation	Source: Tank
Enforcement:	MTBE Test: Not required to be tested
Type: Soil impacted	MTBE Test Date:
Substance: Paint thinner	Abatement:
Summary: SMS ALSO-FILE 14TH FL	

LUST SITE ID: T0608501146	
Rudolph & Sletton 1250 L'Avenida Ave Mountain View, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.:	Discovery:
Local Case No.: 06S2W15E02f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 8/7/1987 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 4/10/1997
Program: LUST	Cause:
Status: Case Closed	Source:
Enforcement: Notice of Responsibility	MTBE Test: Detected
Type: Other Groundwater (not used for drinking water)	MTBE Test Date: 5/2/1996 12:00:00 AM
Substance: Gasoline - Automotive	Abatement:
Summary:	

LUST - Unmapped Site Details

(continued)

LUST SITE ID: T0608591674	
PRECISION PHOTOGLASS INC 1090 B LAVENIDA AVE MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.: 43S0718	Discovery: Tank Closure
Local Case No.:	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed: 6/8/1994
Lead Agency: Regional Board Lead	Reported: 1/1/1985 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed:
Program: SLIC	Cause: No Description
Status: Leak Confirmation	Source: No Description
Enforcement:	MTBE Test: Not required to be tested
Type: Other Groundwater (not used for drinking water)	MTBE Test Date:
Substance: * 108952	Abatement:
Summary:	

LUST SITE ID: T0608539087	
Cuernavaca Townhomes 1386 Cuernavaca Cir Mountain View, CA 94040	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.:	Discovery:
Local Case No.: 06S2W34A01f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 1/1/1989 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 9/24/1990
Program: LUST	Cause:
Status: Case Closed	Source:
Enforcement:	MTBE Test: Not required to be tested
Type: Soil impacted	MTBE Test Date:
Substance: Not reported	Abatement:
Summary:	

LUST - Unmapped Site Details

(continued)

LUST SITE ID: T0608591665	
GOODSELL VOCKE INC 1401 STIERLIN RD MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.: 43S0657	Discovery: Tank Closure
Local Case No.:	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed: 1/14/1987
Lead Agency: Regional Board Lead	Reported: 4/14/1987 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed:
Program: SLIC	Cause: No Description
Status: Leak Confirmation	Source: No Description
Enforcement:	MTBE Test: Not required to be tested
Type: Other Groundwater (not used for drinking water)	MTBE Test Date:
Substance: Lacquer thinner	Abatement:
Summary:	

LUST SITE ID: T0608591629	
TCI 1245 1675 SPACE PKWY MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.: 43S0282	Discovery: Tank Closure
Local Case No.:	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Regional Board Lead	Reported: 1/1/1986 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed:
Program: SLIC	Cause: No Description
Status: Remediation Plan	Source: No Description
Enforcement:	MTBE Test: Not required to be tested
Type: Other Groundwater (not used for drinking water)	MTBE Test Date:
Substance: TCE	Abatement:
Summary:	

LUST - Unmapped Site Details

(continued)

LUST SITE ID: T0608591630	
SANTA CLARA COUNTY TRANSP AGENCY 1235 LAVENIDA AVE MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.: 43S0284	Discovery: Tank Closure
Local Case No.:	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Regional Board Lead	Reported: 1/1/1986 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed:
Program: SLIC	Cause: No Description
Status: Pollution Characterization	Source: No Description
Enforcement:	MTBE Test: Not required to be tested
Type: Other Groundwater (not used for drinking water)	MTBE Test Date:
Substance: Waste oil/Used oil	Abatement:
Summary:	

LUST SITE ID: T0604192352	
Moffett Federal Airfield Tank 69 47 Building 47 Mountain View, CA 0	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.: 43D9014	Discovery:
Local Case No.:	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed: 1/1/1965
Lead Agency: Regional Board Lead	Reported: 6/15/1991 12:00:00 AM
Local Agency:	Stop Method:
Operator:	Closed: 7/9/2003
Program: DOD	Cause:
Status: Case Closed	Source:
Enforcement:	MTBE Test: Detected
Type: Undetermined	MTBE Test Date:
Substance: * Solvents	Abatement:
Summary:	

LUST - Unmapped Site Details

(continued)

LUST SITE ID: T0608591817	
MOFFETT FEDERAL AIRFIELD TANK #77 UNKNOWN BAYSHORE PKWY MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.: 43-2317	Discovery: Tank Closure
Local Case No.: 06S2W14D03	Discovered: 3/4/1999 12:00:00 AM
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed: 3/4/1999
Lead Agency: Regional Board Lead	Reported: 3/4/1999 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed:
Program: DOD	Cause: No Description
Status: Leak Confirmation	Source: No Description
Enforcement:	MTBE Test: Not required to be tested
Type: Undetermined	MTBE Test Date:
Substance: Diesel fuel oil and additives	Abatement:
Summary: NEW CASE PER SCVWD 3RD QTR 98' UPDATE. RWQCB-DOD DIVISION OVERSEEING THIS CASE.	

LUST SITE ID: T0608501574	
Dr. Warren Mills Residence 10675 Eloise Cir Unincorporated, CA 94022	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.:	Discovery:
Local Case No.: 07S2W05Q02f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 1/1/1990 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 4/18/1996
Program: LUST	Cause:
Status: Case Closed	Source:
Enforcement:	MTBE Test: Not required to be tested
Type: Soil impacted	MTBE Test Date:
Substance: Fuel oils Nos. 1, 2, 3, 4, 5 and 6	Abatement:
Summary:	

LUST - Unmapped Site Details

(continued)

LUST SITE ID: T0608591802	
CHARLESTON BUSINESS PARK 2400 60 CHARLESTON RD MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.: 43-1986	Discovery: Tank Closure
Local Case No.: SBS0240	Discovered: 12/31/1987 12:00:00 AM
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed: 7/22/1994
Lead Agency: Regional Board Lead	Reported: 7/22/1994 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed:
Program: SLIC	Cause: No Description
Status: Leak Confirmation	Source: No Description
Enforcement:	MTBE Test: Not required to be tested
Type: Other Groundwater (not used for drinking water)	MTBE Test Date:
Substance: Solvents	Abatement: *NT
Summary: TANK CASE PER SAH - SMS ALSO SEE HK FOR FILE	

LUST SITE ID: T0608504656	
NAS Moffett Field (J09CA104800) Mountain View, CA	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.:	Discovery:
Local Case No.: 201271	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Regional Board Lead	Reported:
Local Agency:	Stop Method:
Operator:	Closed:
Program: DOD	Cause:
Status:	Source:
Enforcement:	MTBE Test: Not required to be tested
Type:	MTBE Test Date:
Substance:	Abatement:
Summary:	

LUST - Unmapped Site Details

(continued)

LUST SITE ID: T0607592365	
Moffett Federal Airfield Site 19, Tank 14 158 Building 158 Mountain View, CA 0	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.: 43D9035	Discovery:
Local Case No.:	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed: 1/1/1965
Lead Agency: Regional Board Lead	Reported: 5/11/1990 12:00:00 AM
Local Agency:	Stop Method:
Operator:	Closed: 9/26/2002
Program: DOD	Cause:
Status: Case Closed	Source:
Enforcement:	MTBE Test: Not required to be tested
Type: Soil impacted	MTBE Test Date:
Substance: * 9	Abatement:
Summary:	

LUST SITE ID: T0608500965	
Moyers Residence 10501 W Loyola Dr Los Altos Hills, CA 94022	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.:	Discovery:
Local Case No.: 07S2W08B01f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 10/1/1991 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 7/24/1992
Program: LUST	Cause:
Status: Case Closed	Source:
Enforcement: Notice of Responsibility	MTBE Test: Not required to be tested
Type: Soil impacted	MTBE Test Date:
Substance: Diesel fuel oil and additives	Abatement:
Summary:	

LUST - Unmapped Site Details

(continued)

LUST SITE ID: T0608502008	
SANTA CLARA COUNTY TD NORTH COACH MAINT 1235 L'AVENIDA AVE MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.: 43-2185	Discovery: Tank Closure
Local Case No.: 43-2185	Discovered: 9/15/1997 12:00:00 AM
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Regional Board Lead	Reported: 9/15/1997 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 9/15/1997
Program: LUST	Cause: No Description
Status: Case Closed	Source: No Description
Enforcement:	MTBE Test: Not tested
Type: Other Groundwater (not used for drinking water)	MTBE Test Date:
Substance: Gasoline - Automotive	Abatement: *NT
Summary: CLOSED 9/97 PER RWQCB; REFER TO RBFILE# 43-1243 FOR REPORTS, CASE HISTORY, ETC	

LUST - Unmapped Site Details

(continued)

LUST SITE ID: T0608501221	
SANTA CLARA COUNTY TRANS DIST N COACH TRM 1235 L'AVENIDA AVE MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.: 43-1243	Discovery: Tank Closure
Local Case No.: 06S2W15E03	Discovered: 8/25/1986 12:00:00 AM
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Regional Board Lead	Reported: 8/25/1986 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 9/11/1997
Program: LUST	Cause: Structural Failure
Status: Case Closed	Source: Tank
Enforcement:	MTBE Test: Not required to be tested
Type: Other Groundwater (not used for drinking water)	MTBE Test Date:
Substance: Waste oil/Used oil	Abatement: Remove free product; Excavate and Treat
Summary: TRNSFRRD FROM SCVWD DUE TO SOLVENTS.SEE HTK FOR FILE. CLOSED 9/97 PER RWQCB	

LUST SITE ID: T0608500364	
Chevron #9-0288 2300 Homestead Rd Los Altos, CA 94022	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.:	Discovery:
Local Case No.: 07S2W10G01f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 1/1/1989 12:00:00 AM
Local Agency: SANTA CLARA HLTH DEPT - TOXICS	Stop Method:
Operator:	Closed:
Program: LUST	Cause:
Status: Remedial Action Underway	Source:
Enforcement: Informal Staff Enforcement Letter	MTBE Test: Detected
Type: Drinking Water Aquifer	MTBE Test Date: 2/1/1999 12:00:00 AM
Substance: Gasoline - Automotive	Abatement:
Summary:	

LUST - Unmapped Site Details

(continued)

LUST SITE ID: T0608550915	
Marshall Gregory Property 10450 W Loyola Dr Los Altos Hills, CA 94022	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.:	Discovery:
Local Case No.: 07S2W08B02f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 1/1/1991 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 2/28/1992
Program: LUST	Cause:
Status: Case Closed	Source:
Enforcement:	MTBE Test: Not required to be tested
Type: Soil impacted	MTBE Test Date:
Substance: Not reported	Abatement:
Summary:	

LUST SITE ID: T0608502007	
SANTA CLARA COUNTY TD NORTH COACH MAINT 1235 L'AVENIDA AVE MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.: 43-2184	Discovery: Tank Closure
Local Case No.: 43-2184	Discovered: 8/18/1997 12:00:00 AM
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Regional Board Lead	Reported: 9/15/1997 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 9/15/1997
Program: LUST	Cause: No Description
Status: Case Closed	Source: No Description
Enforcement:	MTBE Test: Not required to be tested
Type: Other Groundwater (not used for drinking water)	MTBE Test Date:
Substance: Diesel fuel oil and additives	Abatement: *ET FP
Summary: CLOSED 9/97 PER RWQCB; REFER TO RBFILE# 43-1243 FOR REPORTS, CASE HISTORY, ETC	

LUST - Unmapped Site Details

(continued)

LUST SITE ID: T0608500828	
Lee Property 1400 Tracy Ct Los Altos Hills, CA 94022	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.:	Discovery:
Local Case No.: 06S3W27A01f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 8/15/1988 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 2/25/1992
Program: LUST	Cause:
Status: Case Closed	Source:
Enforcement: Notice of Responsibility	MTBE Test: Not required to be tested
Type: Soil impacted	MTBE Test Date:
Substance: Diesel fuel oil and additives	Abatement:
Summary:	

LUST SITE ID: T0608500874	
Marynoll Residence 23000 Cristo Rey Dr Unincorporated, CA 94022	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.:	Discovery:
Local Case No.: 07S2W09J01f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 10/11/1991 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 12/29/1995
Program: LUST	Cause:
Status: Case Closed	Source:
Enforcement:	MTBE Test: Not tested
Type: Soil impacted	MTBE Test Date:
Substance: Gasoline - Automotive	Abatement:
Summary:	

LUST - Unmapped Site Details

(continued)

LUST SITE ID: T0608501748	
COASTSIDE NURSERY 1360 L'AVENIDA AVE MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.: 43-1821	Discovery: Tank Closure
Local Case No.: 06S2W15E01	Discovered: 2/4/1988 12:00:00 AM
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Regional Board Lead	Reported: 2/4/1988 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 2/20/1997
Program: LUST	Cause: Structural Failure
Status: Case Closed	Source: Tank
Enforcement:	MTBE Test: Not tested
Type: Other Groundwater (not used for drinking water)	MTBE Test Date:
Substance: Gasoline - Automotive	Abatement: *NT
Summary: SMS ALSO-CLOSED.CLOSED PER RWQCB 2/20/97.	

LUST SITE ID: T0608590132	
Kaiser Sand & Gravel 1065 L'Avenida Ave Mountain View, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.:	Discovery:
Local Case No.: 06S2W15F01f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 12/27/1985 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 4/3/2001
Program: LUST	Cause:
Status: Case Closed	Source:
Enforcement: Informal Staff Enforcement Letter	MTBE Test: Detected
Type: Other Groundwater (not used for drinking water)	MTBE Test Date: 5/29/1998 12:00:00 AM
Substance: Gasoline - Automotive	Abatement:
Summary:	

LUST - Unmapped Site Details

(continued)

LUST SITE ID: T0608598655	
TEXACO (CVX #21-1179) 975 Shoreline (Stierlin Rd) Blvd Mountain View, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.:	Discovery:
Local Case No.: 06S2W15M02f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 7/17/1989 12:00:00 AM
Local Agency: SANTA CLARA HLTH DEPT - TOXICS	Stop Method:
Operator:	Closed:
Program: LUST	Cause:
Status: Pollution Characterization	Source:
Enforcement: Informal Staff Enforcement Letter	MTBE Test: Detected
Type: Other Groundwater (not used for drinking water)	MTBE Test Date: 8/28/2002 12:00:00 AM
Substance: Gasoline - Automotive	Abatement:
Summary:	

LUST SITE ID: T0608501863	
McColl Residence 13151 W Sunset Dr Los Altos Hills, CA 94022	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.:	Discovery:
Local Case No.: 06S2W31C02f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 12/5/1994 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 5/15/1995
Program: LUST	Cause:
Status: Case Closed	Source:
Enforcement:	MTBE Test: Not required to be tested
Type: Soil impacted	MTBE Test Date:
Substance: Fuel oils Nos. 1, 2, 3, 4, 5 and 6	Abatement:
Summary:	

LUST - Unmapped Site Details

(continued)

LUST SITE ID: T0608591729	
US NAVY HOUSING PROJECT MOFFETT & MDDLFLD W MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.: 43D1583	Discovery: Tank Closure
Local Case No.: 43D1583	Discovered: 10/22/1987 12:00:00 AM
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed: 1/2/1965
Lead Agency: Regional Board Lead	Reported: 10/22/1987 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed:
Program: DOD	Cause: Structural Failure
Status: Leak Confirmation	Source: Tank
Enforcement:	MTBE Test: Not required to be tested
Type: Soil impacted	MTBE Test Date:
Substance: Diesel fuel oil and additives	Abatement: *NT
Summary:	

LUST SITE ID: T0608501723	
William M. & Barbara Eastman 13221 W Sunset Dr Los Altos Hills, CA 94022	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.:	Discovery:
Local Case No.: 06S2W31C01f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 8/4/1989 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 11/6/1990
Program: LUST	Cause:
Status: Case Closed	Source:
Enforcement: Notice of Responsibility	MTBE Test: Not required to be tested
Type: Soil impacted	MTBE Test Date:
Substance: Diesel fuel oil and additives	Abatement:
Summary:	

LUST - Unmapped Site Details

(continued)

LUST SITE ID: T0608502006	
SANTA CLARA COUNTY TD NORTH COACH MAINT 1235 L'AVENIDA AVE MOUNTAIN VIEW, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.: 43-2183	Discovery: Tank Closure
Local Case No.: 43-2183	Discovered: 9/12/1997 12:00:00 AM
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed: 9/12/1997
Lead Agency: Regional Board Lead	Reported: 9/12/1997 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 9/12/1997
Program: LUST	Cause: No Description
Status: Case Closed	Source: No Description
Enforcement:	MTBE Test: Not required to be tested
Type: Soil impacted	MTBE Test Date:
Substance: Mineral spirits	Abatement: Excavate and Dispose; Remove free product
Summary: REFER TO RB FILE# 43-1243 FOR RELATED INFORMATION. CLOSED 9/97 PER RWQCB	
LUST SITE ID: T0608501848	
SAN ANTONIO PRESERVE 7400 ST JOSEPH'S AVE LOS ALTOS, CA 94022	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.: 43-2006	Discovery: Tank Closure
Local Case No.: 43-2006	Discovered: 8/19/1994 12:00:00 AM
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed: 9/21/1994
Lead Agency: Regional Board Lead	Reported: 8/30/1994 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 10/12/1995
Program: LUST	Cause: No Description
Status: Case Closed	Source: No Description
Enforcement:	MTBE Test: Not required to be tested
Type: Soil impacted	MTBE Test Date:
Substance: Diesel fuel oil and additives	Abatement: Excavate and Dispose
Summary: ARCHIVED 5/17/96 CONTROL NO 120-072 SRC 0904722	

LUST - Unmapped Site Details

(continued)

LUST SITE ID: T0608502059	
J.C. Penney San Antonio at Alma St Rd Mountain View, CA 94043	Distance: (exact location not mapped) Direction: (exact location not mapped)
Regional Case No.:	Discovery:
Local Case No.: 06S2W17F01f	Discovered:
Regional Board: SAN FRANCISCO BAY REGIONAL WATER QUALITY CONTROL BOARD (REGION 2)	Confirmed:
Lead Agency: Local Agency Lead	Reported: 10/8/1992 12:00:00 AM
Local Agency: SANTA CLARA VALLEY WATER DISTRICT UNDERGROUND STORAGE TANK PROGRAM	Stop Method:
Operator:	Closed: 5/23/1996
Program: LUST	Cause:
Status: Case Closed	Source:
Enforcement: Notice of Responsibility	MTBE Test: Not tested
Type: Other Groundwater (not used for drinking water)	MTBE Test Date:
Substance: Gasoline - Automotive	Abatement:
Summary:	

SLIC - Unmapped Site Details

SLIC SITE ID: SL0608526227	
MEW-RGRP, N101 SYSTEM WESTCOAT AND MCCORD MOUNTAIN VIEW, CA	Distance: (exact location not mapped) Direction: (exact location not mapped)
Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)	Regional Case No.: 43s1047
Substance: Solvents	Status: Case Open

SLIC SITE ID: SL0608543158	
PLYMOUTH/COLONY NO FORMAL ADDRESS MOUNTAIN VIEW, CA	Distance: (exact location not mapped) Direction: (exact location not mapped)
Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)	Regional Case No.:
Substance:	Status:

SLIC - Unmapped Site Details

(continued)

SLIC SITE ID: SL720991217	
CTS PRINTEX, MOUNTAIN VIEW	Distance: (exact location not mapped)
MOUNTAIN VIEW, CA	Direction: (exact location not mapped)
Lead Agency:	Regional Case No. :
Substance:	Status: Regulatory Review

SLIC SITE ID: SL0608596212	
1201 SAN ANTONIO ROAD	Distance: (exact location not mapped)
1201 SAN ANTONIO ROAD	Direction: (exact location not mapped)
Mountain View, CA	
Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)	Regional Case No. : 43S0967
Substance: *SUB031	Status: Pollution Characterization

TERMS AND CONDITIONS

The Report is subject to each of the following Terms and Conditions. Each Recipient (as that term is defined below) of the Report hereby acknowledges and agrees that the Report is subject to the following Terms and Conditions, and each Recipient agrees to be bound by such Terms and Conditions. Use of this Report by any Recipient constitutes acceptance of the Terms and Conditions to the Report. The Terms and Conditions below are hereby incorporated by this reference into the Report.

The following persons or entities are deemed "Recipients" of this Report: (1) the seller of the real property that is the subject of the specific transaction for which this Report was issued; (2) that seller's agent and broker; (3) the buyer of the real property that is the subject of the specific transaction for which this Report was issued; and (4) that buyer's agent and broker. This Report is for the exclusive use of the Recipients. No person or entity, other than the Recipients, shall be entitled to use or rely on the Report. This Report may not be used, referred to, or relied upon by any person or entity other than the Recipients. No person or entity, other than the Recipients, shall be deemed, treated, or considered to be a beneficiary (intended or otherwise) of this Report.

This Report has been issued in connection with a particular transaction for the sale of the real property described in the Report. The Report may only be used in connection with that particular transaction. If an escrow number has been provided to Property I.D., then this Report may only be used in connection with that particular escrow. The Report may not be used for any other transaction or escrow.

The Report may not be used, for any purpose, if the Recipients have not paid for the Report.

This Report is made for the real property specifically described in the Report (the "Subject Property"). The Subject Property shall not include any property beyond the boundaries of the real property described in the Report. The Subject Property shall not include any structures (whether located on the Subject Property, or not), easements, or any right, title, interest, estate, or easement in any abutting streets, roads, alleys, lanes, ways, or waterways.

No determination is made and no opinion is expressed, or intended, by this Report concerning the right, entitlement, or ability to develop or improve the Subject Property. Property I.D. has no information concerning whether the Subject Property can be developed or improved. Property I.D. expresses no opinion or view, and assumes no responsibility, with respect to the development or improvement of the Subject Property.

No determination is made and no opinion is expressed, or intended, by this Report as to title to the Subject Property. No determination is made and no opinion is expressed, or intended, by this Report concerning whether the Subject Property is comprised of legal lots in conformance with the California Subdivision Map Act or local ordinances.

No determination is made and no opinion is expressed, or intended, by this Report concerning architectural, structural, mechanical, engineering, or legal matters. No determination is made and no opinion is expressed, or intended, by this Report concerning structures or soils on or outside of the Subject Property, including, without limitation, habitability of structures or the Subject Property, suitability of the Subject Property for construction or improvement, potential for soil settlement, drainage, soil subsidence, or other soil or site conditions. No determination is made and no opinion is expressed, or intended, by this Report concerning the marketability or value of the Subject Property.

Property I.D. has not conducted any testing of the Subject Property. Property I.D. has not conducted any physical or visual examination or inspection of the Subject Property. This Report is not a substitute for a physical or visual examination or inspection of the Subject Property.

No determination is made and no opinion is expressed, or intended, by this Report concerning the existence of hazardous or toxic materials or substances, or any other defects, on or under the Subject Property, unless specifically described in the Report.

No determination is made and no opinion is expressed, or intended, by this Report concerning any condition of the Subject Property, unless that condition is specifically described in the Report. The Report is intended to address only those matters expressly described in the text of the Report. The Report is not intended to address any matter (either expressly or impliedly) not specifically described in the text of the Report.

This Report is issued as of the date identified in the Report. Property I.D. shall have no obligation to advise any Recipient of any information learned or obtained after the date of the Report even if such information would modify or otherwise affect the Report.

No determination is made and no opinion is expressed, or intended, by this Report concerning the need to purchase earthquake or flood insurance for the Subject Property.

Property I.D. maintains insurance with limits of \$20,000,000.00. Recipients of paid reports may request a copy of Property I.D.'s certificates of insurance from Property I.D.'s legal department. Real estate brokerages may request that Property I.D. name them as additional insured under Property I.D.'s policy. Please contact your Property I.D. sales executive or Property I.D. directly at (800) 626-0106.

In preparing the Report, Property I.D. has accurately reported on information contained in Government Records. Property I.D. has reviewed and relied upon those Government Records specifically identified and described in the Report. Property I.D. has not reviewed or relied upon any Government Records that are not specifically identified in the Report. Property I.D. also has not reviewed any parcel maps, plat maps, survey maps, surveyor maps, assessor maps, assessor parcel maps, developer maps, or engineering maps, whether or not such maps have been recorded. No determination is made and no opinion is expressed, or intended, by the Report concerning any matters identified in Government Records that were not reviewed by Property I.D. If any Recipient has a question concerning the specific Government Records reviewed (or not reviewed) by Property I.D., then the Recipients should contact Property I.D.'s Customer Service Department at (800) 920-5603.

Property I.D. has relied upon the Government Records specifically identified in the Report without conducting an independent investigation of their accuracy. Property I.D. assumes no responsibility for the accuracy of the Government Records identified in the Report.

To the extent that any Recipient has provided information to Property I.D. (including, without limitation, a legal description of the Subject Property), Property I.D. has relied upon that information in preparing this Report. Property I.D. has not conducted an independent investigation of the accuracy of the information provided by the Recipient. Property I.D. assumes no responsibility for the accuracy of information provided by the Recipient.

Except as specifically described in the Report, Property I.D. makes no warranty or representation of any kind, express or implied, with respect to the Report. Property I.D. expressly disclaims and excludes any and all other express and implied warranties, including, without limitation, warranties of merchantability or fitness for a particular purpose.

Property I.D. shall have no responsibility, or liability, for any lost profits, consequential damages, special damages, indirect damages, or incidental damages allegedly suffered as a result of the use of, or reliance on, the Report.

The Report shall be governed by, and construed in accordance with, the laws of the State of California.

This Report constitutes the entire, integrated agreement between Property I.D. and Recipients, and supersedes and replaces all prior statements, representations, negotiations, and agreements.

If any provision of the Terms and Conditions to this Report is determined to be invalid or unenforceable for any reason, then such provision shall be treated as severed from the remainder of the Terms and Conditions, and shall not affect the validity and enforceability of all of the other provisions of the Terms and Conditions.

Any dispute, controversy, or claim arising out of, or relating in any way, to the Report, shall be resolved by arbitration in Los Angeles, California, in accordance with the arbitration rules of the Judicial Arbitration and Mediation Service ("JAMS"). The prevailing party in the arbitration shall be entitled to its attorneys' fees and costs, including, without limitation, the fees of the arbitrator.