

## **FEDERAL ANNUAL** TRAILER INSPECTION

COUNCIL BLUFFS
3119 S 96 St
Council Bluffs, IA 51501
712 368-2241
889 621-7788
Fay 712-906-3141

[] SIOUX FALLS 1403 (E. Bonson I. I. SOUC FAR, SD 57104 603-338-6365 803-245-7895 Fax: 605-338-9385

© DAVENPORT 986 W 766 Sr. Discrepcial IA 52806 563-586-2990 690-423-8468 Five 563-586-2982

○ SIOUX CITY 5300X CITY 5207 S. Lewis Blod 5304 Gey, (A. 51106 712-258-9430 877-941-8347 Fax: 712-258-4845

Cl EAST PEORIA
1001 FLMan SI
End Provis, it, 61611
200-0421-0504
Pay 300 404-036

OES MORIES
3015 Advintues/and Dr
Aboura 45-0009
510-067-3090
500-0492-3355
Fax 5110-967-0281

3 KANSAS CITY
7500 D.E. Gerdher Are
600sas Caly MO 64120
800-224-5015
Fax: 816-241-2300

□ FARGO

3 FARGO 3739 38th St. SW 8args: Ett 88104 701-277-7171 877-277-7171 Fax: 701-277-4654

© CHAMPAIGN 2909 W Bloomington Flid Champaign, R. 61822 317-353-6950 835-826-4295 Eur. 717-353-653 2

13 MICH JAN 3710 Cricago Dr SW Grandstin Mil 49416 616 532-2347 Fax 616-932-2393

## HIM HANNY TRHOV TRAHERCING

			en iiivun iiimillioint.
MOTOR CARRIER OPERATOR GREAT South	was Bank		
ADDRESS	ENN DUNI		
CITY, STATE, ZIP CODE			
PHONE NUMBER ***			
Branch Location ACTOONA	Tele. # ( )	Branch	Address
Unit # 531023 Hubodometer Rea	ding <u>NIA</u>		Make / Year Great Vo.No
Serial # License #	5 d 5 3 3	StateH	Inspection Date 8 50
Unit # 531023 Hubodometer Rea  Serial # License # V  License # V  This vehicle was inspected in accordance with the require	1	die C to out about a B of D C	O.T. mile 40 CED port 306 on the above listed
This vehicle was inspected in accordance with the require The inspector hereby certifies that he/she is qualified insp	янень сончаней игмры	ary or to sun enabler is or tyc	7.1. tule 49 CrK part 390 on the above insect
INSPECTOR BEN Brucke		Bu	Breig
(✓) Item is ok (N/A) Item not	applicable	(X) Repairs needed	(0) Repairs ma
A. Lines, Fittings & Connections	I. UNDER	STRUCTURE  No. 10 Pin Plate	
B. V. Frame, Rails & Crossmembers		D. King Pin Plate E. King Pin	
C. Landing Gear, Landing Gear Braces	& Subframe		
/.		KES AND SPRINGS	
A. Push-Pull Valve B. Slider and /or Bogie Subframe	H. Brake Drun I. Align Axles	Torque Suspension (	N. Cam Shafts & Bushings D. Slack Adjuster
C. Air lines & Fittings	Enctanare	1	Adjust Brakes (Manual Only)
C. Air lines & Fittings D. Air Tanks & Bleeders E. Air Valves Brake Linings	J. Spring Leav K. V. U-bolts & S	es, Airsprings <b>Skock5</b> G addles	Push Rod Free Travel  Axle & Brake Chamber
F. Brake Linings Action G. Anchor Pins & Cam Rollers	L. Hangers &	Bracers S s & Bushings	S. 🗶 A.B.S. Operational
o		ASSEMBLIES	
Curb Side	HIL WEILER	Road Side	
A Mismatched Tires		H. V Mismatched Tir	
B. Tire Probe & Condition C. <b>N/4</b> Lock Rings		I. Tire Probe & Co J. NA Lock Rings	manion
D. Tread Depth E. Rims & Hubs		K. Tread Depth L. Rims & Hubs	
F. Tire Pressure		M. V Tire Pressure	
G. Lug Nuts		N. Lug Nuts	
	IV. BODY	AND LIGHTS	
A. Marker Lights B. Tail Lights & Reflectors C. Push Rod & Thimble D. Diede Air & Electric Lines Gladbur		F. Pintle Hook & I G. A Safety Loop	Latch
C. V Push Rod & Thimble		H. Hinges, Lock B. Case & Operato	ars & Keepers / Overhead Door Track
E. NA Pintle Air & Electric Lines, Gladhar	ds, Scals	I. A.B.S. Light	1
• • •		RTER DOLLY ONLY	
A. 🕅. Fifth Wheel	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	C. A/A Draw Bar Eye	
A. A Fifth Wheel B. A Safety Chain & Hook		. ,	
This vehicle	: has been inspected and comp	olies with 49 CFR Part 396, Appe	endix G
THE ABOVE REPAIRS OR ADJUSTMENTS (IF ANY	WERE PERFORMED B	Y:	
Check if same as above Or detail below if other			
REPAIR COMPANY	Steet	dty	state Ліргос
Date Repair Person		Signature	

## JIM HAWK TRUCK TRAILERS INC.

Council Bluffs, Davenport, Des Moines, Sioux Falls, East Peoria, Fargo, Kansas City, Sioux City and Chicago

## JIM HAWK - DES MOINES

3515 ADVENTURE LAND DR. P.O. BOX 217 ALTOONA, IA 50009 (515) 967-3800

INVOICE DATE 08/31/2017 08:34AM PAGE INVOICE NO. 2-272430136 1 CUSTOMER NO. BRANCH 2 \* 00102

CASH SALE ACCOUNT

SOLD TO:

C.O.D. ONLY

P.O. BOX 217

ALTOONA IA 50009

GREAT SOUTHERN BANK

SHIP TO:

763-255-1705

7685 ZACHARY LN

MAPLE GROVE MN 55369

O19960  * * * C. O. D. S A L E * * *  PROMISE DATE  COMPLETION DATE: 08/30/2017  UNIT: 531023 YEAR: 2004 MAKE/MODEL: GREAT DANE SERIAL: 1GRAA06215J606389 MILEAGE:  JOB#01 30 000 00 FEDERAL INSPECTIONS FEDERAL INSPECTION  HOLES HAVE BEEN PATCHED AT RIGHT FRONT CORNER LFI AND RFO TIRES WEARING BAD RIGHT SIDE PANEL PUSHED OUT SOME MINOR SCUFFING ON BOTH SIDES AT REAR HALF RAILS GOOD BRAKE LINING 20%  WORK NEEDED /LEFT MUDFLAP MISSING AND BRACKET BENT ABS LIGHT ON FEW RAIL BOLTS MISSING LEFT FRONT SHOCK BUSHING LOOSE AIR TANK LOOSE LICENSE PLATE LIGHT- LEFT SIDE TIRES  8 - 9 7 - 11 9 - 2 8 - 8 1 ALL 1200-2 LUBRIPLATE GREASE TUBES	JC VPER I	000/000 EXTENSION
* * * * C. O. D. S A L E * * *  PROMISE DATE  COMPLETION DATE: 08/30/2017  UNIT: 531023 YEAR: 2004 MAKE/MODEL: GREAT DANE SERIAL: 1GRAA06215J606389 MILEAGE:  JOB#01 30 000 00 FEDERAL INSPECTIONS FEDERAL INSPECTION HOLES HAVE BEEN PATCHED AT RIGHT FRONT CORNER LFI AND RFO TIRES WEARING BAD RIGHT SIDE PANEL PUSHED OUT SOME MINOR SCUFFING ON BOTH SIDES AT REAR HALF RAILS GOOD BRAKE LINING 20% WORK NEEDED /LEFT MUDFLAP MISSING AND BRACKET BENT ABS LIGHT ON FEW RAIL BOLTS MISSING LEFT FRONT SHOCK BUSHING LOOSE AIR TANK LOOSE LICENSE PLATE LIGHT- LEFT SIDE TIRES RIGHT SIDE TIRES 8 - 9 7 - 11 9 - 2 8 - 8		
* * * * C. O. D. S A L E * * *  PROMISE DATE  COMPLETION DATE: 08/30/2017  UNIT: 531023 YEAR: 2004 MAKE/MODEL: GREAT DANE SERIAL: 1GRAA06215J606389 MILEAGE:  JOB#01 30 000 00 FEDERAL INSPECTIONS FEDERAL INSPECTION  HOLES HAVE BEEN PATCHED AT RIGHT FRONT CORNER LFI AND RFO TIRES WEARING BAD RIGHT SIDE PANEL PUSHED OUT SOME MINOR SCUFFING ON BOTH SIDES AT REAR HALF RAILS GOOD BRAKE LINING 20%  WORK NEEDED /LEFT MUDFLAP MISSING AND BRACKET BENT ABS LIGHT ON FEW RAIL BOLTS MISSING LEFT FRONT SHOCK BUSHING LOOSE AIR TANK LOOSE LICENSE PLATE LIGHT- LEFT SIDE TIRES RIGHT SIDE TIRES 8 - 9 7 - 11 9 - 2 8 - 8	IPER 1	EXTENSION
PROMISE DATE  COMPLETION DATE: 08/30/2017  UNIT: 531023 YEAR: 2004 MAKE/MODEL: GREAT DANE SERIAL: 1GRAA06215J606389 MILEAGE:  JOB#01 30 000 00 FEDERAL INSPECTIONS FEDERAL INSPECTION HOLES HAVE BEEN PATCHED AT RIGHT FRONT CORNER LFI AND RFO TIRES WEARING BAD RIGHT SIDE PANEL PUSHED OUT SOME MINOR SCUFFING ON BOTH SIDES AT REAR HALF RAILS GOOD BRAKE LINING 20% WORK NEEDED /LEFT MUDFLAP MISSING AND BRACKET BENT ABS LIGHT ON FEW RAIL BOLTS MISSING LEFT FRONT SHOCK BUSHING LOOSE AIR TANK LOOSE LICENSE PLATE LIGHT- LEFT SIDE TIRES RIGHT SIDE TIRES 8 - 9 7 - 11 9 - 2 8 - 8		
COMPLETION DATE: 08/30/2017  UNIT: 531023 YEAR: 2004 MAKE/MODEL: GREAT DANE SERIAL: 1GRAA06215J606389 MILEAGE:  JOB#01 30 000 00 FEDERAL INSPECTIONS  FEDERAL INSPECTION  HOLES HAVE BEEN PATCHED AT RIGHT FRONT CORNER LFI AND RFO TIRES WEARING BAD RIGHT SIDE PANEL PUSHED OUT  SOME MINOR SCUFFING ON BOTH SIDES AT REAR HALF RAILS GOOD  BRAKE LINING 20%  WORK NEEDED /LEFT MUDFLAP MISSING AND BRACKET BENT ABS LIGHT ON  FEW RAIL BOLTS MISSING  LEFT FRONT SHOCK BUSHING LOOSE  AIR TANK LOOSE  LICENSE PLATE LIGHT-  LEFT SIDE TIRES  RIGHT SIDE TIRES  8 - 9  7 - 11  9 - 2		
UNIT: 531023 YEAR: 2004 MAKE/MODEL: GREAT DANE SERIAL: 1GRAA06215J606389 MILEAGE:  JOB#01 30 000 00 FEDERAL INSPECTIONS FEDERAL INSPECTION HOLES HAVE BEEN PATCHED AT RIGHT FRONT CORNER LFI AND RFO TIRES WEARING BAD RIGHT SIDE PANEL PUSHED OUT SOME MINOR SCUFFING ON BOTH SIDES AT REAR HALF RAILS GOOD BRAKE LINING 20% WORK NEEDED /LEFT MUDFLAP MISSING AND BRACKET BENT ABS LIGHT ON FEW RAIL BOLTS MISSING LEFT FRONT SHOCK BUSHING LOOSE AIR TANK LOOSE LICENSE PLATE LIGHT- LEFT SIDE TIRES RIGHT SIDE TIRES 8 - 9 7 - 11 9 - 2 8 - 8		
SERIAL: 1GRAA06215J606389 MILEAGE:  JOB#01 30 000 00 FEDERAL INSPECTIONS  FEDERAL INSPECTION  HOLES HAVE BEEN PATCHED AT RIGHT FRONT CORNER  LFI AND RFO TIRES WEARING BAD  RIGHT SIDE PANEL PUSHED OUT  SOME MINOR SCUFFING ON BOTH SIDES AT REAR HALF  RAILS GOOD  BRAKE LINING 20%  WORK NEEDED /LEFT MUDFLAP MISSING AND BRACKET BENT  ABS LIGHT ON  FEW RAIL BOLTS MISSING  LEFT FRONT SHOCK BUSHING LOOSE  AIR TANK LOOSE  LICENSE PLATE LIGHT-  LEFT SIDE TIRES  RIGHT SIDE TIRES  8 - 9  7 - 11  9 - 2  8 - 8		
JOB#01 30 000 00 FEDERAL INSPECTIONS  FEDERAL INSPECTION  HOLES HAVE BEEN PATCHED AT RIGHT FRONT CORNER LFI AND RFO TIRES WEARING BAD RIGHT SIDE PANEL PUSHED OUT SOME MINOR SCUFFING ON BOTH SIDES AT REAR HALF RAILS GOOD BRAKE LINING 20%  WORK NEEDED /LEFT MUDFLAP MISSING AND BRACKET BENT ABS LIGHT ON FEW RAIL BOLTS MISSING LEFT FRONT SHOCK BUSHING LOOSE AIR TANK LOOSE LICENSE PLATE LIGHT- LEFT SIDE TIRES  RIGHT SIDE TIRES  7 - 11 9 - 2  8 - 8		
FEDERAL INSPECTION HOLES HAVE BEEN PATCHED AT RIGHT FRONT CORNER LFI AND RFO TIRES WEARING BAD RIGHT SIDE PANEL PUSHED OUT SOME MINOR SCUFFING ON BOTH SIDES AT REAR HALF RAILS GOOD BRAKE LINING 20% WORK NEEDED /LEFT MUDFLAP MISSING AND BRACKET BENT ABS LIGHT ON FEW RAIL BOLTS MISSING LEFT FRONT SHOCK BUSHING LOOSE AIR TANK LOOSE LICENSE PLATE LIGHT- LEFT SIDE TIRES RIGHT SIDE TIRES 7 - 11 9 - 2 8 - 8		
HOLES HAVE BEEN PATCHED AT RIGHT FRONT CORNER LFI AND RFO TIRES WEARING BAD RIGHT SIDE PANEL PUSHED OUT SOME MINOR SCUFFING ON BOTH SIDES AT REAR HALF RAILS GOOD BRAKE LINING 20% WORK NEEDED /LEFT MUDFLAP MISSING AND BRACKET BENT ABS LIGHT ON FEW RAIL BOLTS MISSING LEFT FRONT SHOCK BUSHING LOOSE AIR TANK LOOSE LICENSE PLATE LIGHT- LEFT SIDE TIRES RIGHT SIDE TIRES 8 - 9 7 - 11 9 - 2 8 - 8		
LFI AND RFO TIRES WEARING BAD RIGHT SIDE PANEL PUSHED OUT SOME MINOR SCUFFING ON BOTH SIDES AT REAR HALF RAILS GOOD BRAKE LINING 20% WORK NEEDED /LEFT MUDFLAP MISSING AND BRACKET BENT ABS LIGHT ON FEW RAIL BOLTS MISSING LEFT FRONT SHOCK BUSHING LOOSE AIR TANK LOOSE LICENSE PLATE LIGHT- LEFT SIDE TIRES RIGHT SIDE TIRES 8 - 9 7 - 11 9 - 2 8 - 8		
RIGHT SIDE PANEL PUSHED OUT  SOME MINOR SCUFFING ON BOTH SIDES AT REAR HALF RAILS GOOD  BRAKE LINING 20%  WORK NEEDED /LEFT MUDFLAP MISSING AND BRACKET BENT ABS LIGHT ON FEW RAIL BOLTS MISSING LEFT FRONT SHOCK BUSHING LOOSE AIR TANK LOOSE LICENSE PLATE LIGHT- LEFT SIDE TIRES  RIGHT SIDE TIRES  8 - 9  7 - 11 9 - 2  8 - 8		
RAILS GOOD BRAKE LINING 20% WORK NEEDED /LEFT MUDFLAP MISSING AND BRACKET BENT ABS LIGHT ON FEW RAIL BOLTS MISSING LEFT FRONT SHOCK BUSHING LOOSE AIR TANK LOOSE LICENSE PLATE LIGHT- LEFT SIDE TIRES RIGHT SIDE TIRES 8 - 9 7 - 11 9 - 2 8 - 8		
RAILS GOOD BRAKE LINING 20% WORK NEEDED /LEFT MUDFLAP MISSING AND BRACKET BENT ABS LIGHT ON FEW RAIL BOLTS MISSING LEFT FRONT SHOCK BUSHING LOOSE AIR TANK LOOSE LICENSE PLATE LIGHT- LEFT SIDE TIRES RIGHT SIDE TIRES 8 - 9 7 - 11 9 - 2 8 - 8		
WORK NEEDED /LEFT MUDFLAP MISSING AND BRACKET BENT ABS LIGHT ON FEW RAIL BOLTS MISSING LEFT FRONT SHOCK BUSHING LOOSE AIR TANK LOOSE LICENSE PLATE LIGHT- LEFT SIDE TIRES RIGHT SIDE TIRES 8 - 9 7 - 11 9 - 2 8 - 8		
ABS LIGHT ON FEW RAIL BOLTS MISSING LEFT FRONT SHOCK BUSHING LOOSE AIR TANK LOOSE LICENSE PLATE LIGHT- LEFT SIDE TIRES  8 - 9 7 - 11 9 - 2 8 - 8		
FEW RAIL BOLTS MISSING LEFT FRONT SHOCK BUSHING LOOSE AIR TANK LOOSE LICENSE PLATE LIGHT- LEFT SIDE TIRES  8 - 9  7 - 11  9 - 2  8 - 8		
LEFT FRONT SHOCK BUSHING LOOSE AIR TANK LOOSE LICENSE PLATE LIGHT- LEFT SIDE TIRES  8 - 9  7 - 11  9 - 2  8 - 8		
AIR TANK LOOSE LICENSE PLATE LIGHT- LEFT SIDE TIRES  8 - 9  7 - 11  9 - 2  8 - 8		
LICENSE PLATE LIGHT- LEFT SIDE TIRES  8 - 9  7 - 11  9 - 2  8 - 8		
LEFT SIDE TIRES  8 - 9  7 - 11  9 - 2  8 - 8		
8 - 9 9 - 2 7 - 11 8 - 8		
9 - 2 8 - 8		
1 ALL 1200-2 LUBRIPLATE GREASE TUBES		CT 171.4
	7.74EA	7.74
PARTS SUBTOTAL 1.50 HOURS LABOR SUBTOTAL		7.74 120.00
1.50 HOURS LABOR SUBTOTAL SHOP SUPPLIES		9.00
** JOB SUBTOTAL		136.74
00B 30B1017H		1301,71
*TOTAL PARTS:		7.74
*TOTAL LABOR:		120.00
*TOTAL SHOP SUPPLIES:		9.00
* *Ste&OØrVPebsit& AvAvvR.jħtttcom		
L USED TRAILERS ARE SOLD IN "AS IS" CONDITION, AND NO WARRANTY, EXPRESSED OR IMPLIED, IS MADE. THE NE TRAILERS, INC. IN RESPECT TO THE GOODS DESCRIBED HEREIN IS IN LIEU OF ANY AND ALL OTHER WARRAN' PLIED WARRANTY OF MERCHANTABILITY IS MADE AND THERE ARE NO WARRANTIES WHICH EXTEND BEYOND THE DI	TIES, EXPRE	ESSED OR IMPLIED, NO
FREIGHT SUBTOTAL TAX STATUS/STATE SALES		PLEASE PAY
136.74 TAXABLE IA	8.20	144.94
IN CONSIDERATION OF THE EXTENSION OF CREDIT BY		TERMS
TRAILERS, THE OBLIGOR GUARANTEES THE FULL AND PAYMENT OF PRINCIPAL, INTEREST, AND ANY COLLECT INCLUDING ATTORNEY'S FEES TO JIM HAWK TRUCK TRU	ION COSTS,	