

ASA-SE-2

| Engine Record General Informa | | |
|---|-------------------------|----------------|
| - LucomiNG | Model 0-36 | 0-C1= |
| Manufacturer LycomiNG Serial L-40595-36H | Type Certificate | 286 |
| Serial Comments installed in | aircraft: MANCE 14 4 18 | OV Thi- 47000T |
| Maula M4-7-1848 5/4 2204 | | RE. NSIYOR |
| Minimum Octano Fuel 100/1001 | | Winter 30 |
| tagneto Time | Point Setting | Firing Order |
| park Plug Gap | | |

| TE | TACH | FLIGI | HT TIN | TAL ME IN RVICE | Description of Inspections, Tests, Repairs and All Entries must be endorsed with Harms, Plating and Cantilland All Technician or Repair Facility. (See back pages for other tasks) |
|--------------|--------|---------------------------|--|--|--|
| | | 3/6/6 | 1916 | 1998 | CASA CASA CASA CASA CASA CASA CASA CASA |
| 120 | | | NEW R | FCIPPO | ST-Ma-da-Gallan-Cat VIII VIII CAT CAT A CIA CA |
| | Aviat | is to certi | ify that sted as ulations orthine | the engin prescribe No fur ess Direct | ne as described hereinafter has been manufactured ed by LYCOMING specifications and Federal rither run-in is required. All applicable Federal |
| 2 M | DDEL | | 60-C1 | | |
| <0 | 17,432 | 1/4 | 1. | | SERIAL NO. L-40595-36A |
| DA | TE 7 | 120/ | 06 | | DURNLY |
| | | | | | (AUTHORIZED REPRESENTATIVE) |
| L | CO | MIN | G | | LYCOMING ENGINES 652 Oliver Street |
| | | | | | Williamsport, PA 17701 U.S.A. |
| | | 3 (Rev. 3/03 | | 3 | |
| _ | | | | | |
| - | | RECORDING | TODAY'S FLIGHT | TIME IN | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of |
| - | 1006 | RECORDING TACH TIME | | TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
| <u></u> | TE I | TACH | | TIME IN | Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
| <u></u> | TE I | TACH | | TIME IN SERVICE | Entries must be endorsed with Name, Rating and Certificate Number of |
| <u></u> | TE I | TACH | | TIME IN SERVICE | Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) ENGINE IN SERVICE AT THIS TIME. |
| <u></u> | TE I | TACH | | TIME IN SERVICE | Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) ENGINE IN SERVICE AT THIS TIME. HOURS INCLUDE PRODUCTION FLIGHT TEST. |
| <u></u> | TE I | TACH | | TIME IN SERVICE | Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) ENGINE IN SERVICE AT THIS TIME. HOURS INCLUDE PRODUCTION FLIGHT TEST. |
| <u></u> | TE I | TACH | | TIME IN SERVICE | Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) ENGINE IN SERVICE AT THIS TIME. HOURS INCLUDE PRODUCTION FLIGHT TEST. |
| <u></u> | TE I | TACH | | TIME IN SERVICE | Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) ENGINE IN SERVICE AT THIS TIME. HOURS INCLUDE PRODUCTION FLIGHT TEST. |
| <u></u> | TE I | TACH | | TIME IN SERVICE | Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) ENGINE IN SERVICE AT THIS TIME. HOURS INCLUDE PRODUCTION FLIGHT TEST. SIGNED: CHARLES DERMYRE, FAA DMIR142071CE |
| <u></u> | TE I | TACH | | TIME IN SERVICE | Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) ENGINE IN SERVICE AT THIS TIME. HOURS INCLUDE PRODUCTION FLIGHT TEST. SIGNED: CHARLES DERMYRE FAA DMIR142071CE |
| <u></u> | TE I | TACH | | TIME IN SERVICE | Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) ENGINE IN SERVICE AT THIS TIME. HOURS INCLUDE PRODUCTION FLIGHT TEST. SIGNED: CHARLES DERMYRE FAA DMIR142071CE |
| <u></u> | TE I | TACH | | TIME IN SERVICE | Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) ENGINE IN SERVICE AT THIS TIME. HOURS INCLUDE PRODUCTION FLIGHT TEST. SIGNED: CHARLES DERMYRE, FAA DMIR142071CE LYCONING 652 Oliver Street Williamsport, PA 17701 U.S.A. 570/323-6181 |
| <u></u> | TE I | TACH | | TIME IN SERVICE | Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) ENGINE IN SERVICE AT THIS TIME. HOURS INCLUDE PRODUCTION FLIGHT TEST. SIGNED: CHARLES DERMYRE FAA DMIR142071CE LYCONING 652 Clove Street Williamsport, PA 17701 U.S.A 570/323-6181 ENGINE SERIAL NUMBER 2 - 40 59 5 3 6 A |
| <u></u> | TE I | TACH | | TIME IN SERVICE | Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) ENGINE IN SERVICE AT THIS TIME. HOURS INCLUDE PRODUCTION FLIGHT TEST. SIGNED: CHARLES DERMYRE, FAA DMIR142071CE CHARLES DERMYRE, FAA DMIR142071CE SIGNED: CHARLES DERMYRE, FAA DMIR142071CE SIGNED: CHARLES DERMYRE, FAA DMIR142071CE ENGINE Serial NUMBER C - 40 59 5 3 6 A IN SERVICE DATE 0 2 0 6 ENG. II. 1 6 |
| <u>.</u> | TE I | TACH | | TIME IN SERVICE | Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) ENGINE IN SERVICE AT THIS TIME. HOURS INCLUDE PRODUCTION FLIGHT TEST. SIGNED: CHARLES DERMYRE FAA DMIR142071CE LYCONING 652 Clove Street Williamsport, PA 17701 U.S.A 570/323-6181 ENGINE SERIAL NUMBER 2 - 40 59 5 3 6 A |
| <u>.</u> | TE I | TACH | | TIME IN SERVICE | Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) ENGINE IN SERVICE AT THIS TIME. HOURS INCLUDE PRODUCTION FLIGHT TEST. SIGNED: CHARLES DERMYRE, FAA DMIR142071CE CHARLES DERMYRE, FAA DMIR142071CE SIGNED: CHARLES DERMYRE, FAA DMIR142071CE SIGNED: CHARLES DERMYRE, FAA DMIR142071CE ENGINE Serial NUMBER C - 40 59 5 3 6 A IN SERVICE DATE 0 2 0 6 ENG. II. 1 6 |

| YEAR ZOOT | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific strains) |
|--------------|---------------------------|-------------------|-----------------------------|--|
| 5-3 | 25.9 | | 25.9 | THE LIB CHILDRES THAT CITY TO THE |
| | 1402H - LA | 100 | BUN. | EMETHE LEAK CHECKED AND RETURNS |
| | TO SER | VZG | I with | ATE, K WS how 240137002 A.P |
| 2007 | | | | |
| 5/17 | 55.6 | - | 55.6 | CHANGED OIL OFSCER. FILLED WITH |
| | | | | 8 chs ATROSOFIL WI 100 OIL. |
| | | | | 15. 17. 17. 18. 18. 18. 18. 18. 18. 18. 18. 18. 18 |
| 100 | 86.2 | 1 | 5.2 | |
| -25 | | | | CHANGED OIL FILTER. FILLED WITH |
| | | | | 8 of AEROCHELL W/100. |
| | | | | V. WILLOWS MORLINS |
| - | _ | | | |
| | | | | |
| | | | 2 | |

| tions YEAR FOR ZU | TACH | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-------------------|------------------|-------------------|-----------------------------|---|
| G-8 | 112.0 | | 112.0 | 100 HR. I HSPECTION CHW THIS DATE. |
| 2 | | | | WE FILLED WITH & OHS AFROSHELL |
| | w1100 93 | | IFAN, | CAP. POTATED PLUCE. CHECKED COME. |
| - - | AT 30 P | 27 | 72025 | AND PUSH - PULL CHBLES. A.D. CHECK |
| - | | | | TO DENENTED AND SURVEY |
| -/= | | | | TR. K. Willes 260137002 A.P |
| | | | | I certify that this ENCINE |
| | | | | has been inspected in accordance with an |
| 7 | | | | to be in an airworthy condition. Name Y. W. S. A. No. 2 60137002 |
| | | _ | | Date 6-8-97 Tach 112-0 I.I. 112-0 |
| 1 | | | | |
| - | | | | |
| - | Name of the last | | | |

| YEAR 2007 | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries) CHAPCED OSL AND FELTER |
|-----------|---------------------------|-------------------|-----------------------------|--|
| 7-12 | 138.9 | | 138.9 | CHANCED OSL AND FILTER. PILLED WITH 8 94 NEROSHELL WILLS OF |
| רפורונג | 179.9 | | 179.9 | CHANCED OIL & FILTER. FILLED CHANCET OF ATTER CHANCET OF A STATE |
| | | 200 | | 15. M. 7 HOD S CO13 2005 4. 6 |
| | | | | |
| | | | | |
| | | | 4 5 | |
| | | | | |
| | 1 | | | |

and Alterations
ficate Number of year TACH TACH TIME

SUED

DATE

LES D

OIL.

Description of Inspections, Tests, Repairs and Alterations
Entries must be endorsed with Name, Rating and Certificate Number of
Technician or Repair Facility. (See back pages for other specific entries.)



290 Harper Blvd. Ste, I - Moultne, GA - 31788 - 229-985-6197

9/28/07 TACH: 222.1

100 HR. INSPECTION CW THIS DATE. CHANGED OIL, FILTER, CHECKED ALL OIL AND FUEL SCREENS. FIILLED WITH 8 QTS. AEROSHELL W/100 OIL. CLEAN, GAP, ROTATED PLUGS. CHECKED COMP. AT 80 PSI 1/77 2/77 3/77 4/78. INSPECTED AND LUBED ALL CONTROL. AND PUSH PULL CABLES. A D.s CHECKED THRU 2007-19F, ENGINE RUN UP AND RETURNED TO SERVICE THIS DATE.

2008

K. Wilher 260137002 A.P.

2007
10-26 249.9
249.9
249.9
CHANGED OSL & FSINER, FSILED WITH
8 9th AEROSHELL WILLOW OSL.

X. Will be 260137002 A.P.

TOTAL

TIME IN SERVICE

| TEM Zuan | RECORDING TACH TIME | TODAY'S FLIGHT | TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries) |
|-------------|---------------------------|-------------------|--------------------|--|
| 12-17 | 276.2 | | Z76.2 | CHUNCED OIL WHO LICES TENESTED |
| | | | | N. W. 17 19 2 8001 810 9 8 14 16 14 18 18 18 18 18 18 18 18 18 18 18 18 18 |
| 3-4-08 | 302. | | 342. | CHANGED OZI AND FINER, FILLED |
| 3.11.44 | | | | WITH 8 of AFRESHELL WILL OIL. |
| | | | | V. Willia 260137002 ALP |
| 4-4-68 | 331. 0 | 3 | 331-0 | CHANGED OIL AND FILTER FILED |
| | | | | ITO DOLLIN HITHROSTA OF BATICA |
| | | | | K. WILLIAM 260187002 A+P |
| | | | | 100 HR. THOPECTONA CIM THIS DATE. |
| - | | - | | CHECKED ALL FUEL SCREEMS. CHECKED |
| - | | - | | come. AT 80 PST 1/77 2/77 3/72 4/7. |
| - | | - | - 1 | CLEAN, GAY, ROTATED PLUGS, Lyc. A.D. |
| | | 100 | | 2006-06-16 CRANKSHAFT NIA BY EDG MODE |
| | - | - | _ | COOL-16-21 CZ ECT RODS NIA FACTORY RID |

| rs and Alterations intificate Number of ther specific entries.) | TEAR | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|---|------|---------------------------|-------------------|-----------------------------|---|
| EVICEO | DATE | - | | 1000 | 2006-12-07 F.CS CYL. HIA FACTORY CHI |
| ZL. | | | | | Sage-SO-Od CENTICOUNTY HIM BY ENG WILL |
| | | | | - | 2007-09-19 RI SAP CYL. HIA FACTORY CYL. INSTALLED |
| | | | | | 2008-06-51 SHORECTSON SREND HIM BY MODE. |
| LLED | | | | | 008-06F. ENGZUR RUL-UP AND RETURNED TO |
| | | SERVICE | THIS | DATE. | V. WILW 260137492 A+A |
| | | - | | 155101 | |
| | | | | | has been inspected in accordance with an |
| RD | | | | | hspection and was determined |
| | | | | | to be in an airworthy condition. Name V-11494 5.A. No. 240137002 |
| | | | _ | | Date 4-4-08 Tach 331-0 T.T. 331-0 |
| E. 2 | 800 | | | | |
| 0.3 | 5-30 | 364.8 | 3 | 364.8 | CHANGED OIL, FILTER. FILLED WITH |
| 177 | | | | | 8 OHS. WI 100 AEROSHELL. |
| | | | | | 8 Off. W/100 AEROSHELL. V. WI VED 260137002 AOP |
| OFL. | | | | | |
| DS THST. | | | | | |

| 75AA 200B 0ATE 6-10 | RECORDING TACH TIME | TUDAY | TOTAL TIME IN SERVICE 374. 2 | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entres) PERLICED STRETER WITH BRENICEHOUS DATE. V. WILLIAM 260137002 A.P. DATE. V. WILLIAM 260137002 A.P. |
|------------------------------|---------------------------|-------|------------------------------|--|
| 2008 9-15 | 402.3 | | 402.3 | CHANGED OTL & FILTER. FILLED WITH 8 OF PEROTHELL WIGO OTL. V. WILL BOD 260137002 ALP |
| | | | | |
| 9.1 | | | | 70 100 2524 100 10 10 10 10 10 10 10 10 10 10 10 10 |

| 290 Harper Bivd. Ste. 1- Moutigie, GA - 31788 - 229-985-6197 1723/09 TACH: 435.0 TTSN: 435.0 0-360-C1F SN L-40595- 180 Harper Bivd. Ste. 1- Moutigie, GA - 31788 - 229-985-6197 190 Harper Bivd. Ste. 1- Moutigie, GA - | |
|--|---------------------|
| 290 Harper Blvd. Ste. 1: Moultigle, GA. 31788 - 229-985-6197 1/23/09 TACH: 435.0 TTSN: 435.0 D-360-C1F SN L-4050- 100 HR INSPECTION CWT HIS DATE. CHANGED OIL FILTER.C ALL OIL & FUEL SCREENS, FILLED WITH 6 OTS. AEROSHELL V OIL. CLEAN, GAP, ROTATED PLUGS. #1/17: #276, #3/17, #4/17. SI. B. 583-08 CW STEP 28.3 THIS DATE OK, NO FUTHER INSPI- PER THIS BULLETIN ARE REQUIRED UNLESS BRUSH OR DIS OR ASSY. IS REPLACED. MAG PN 4370 SN 05111420, PN 43 S/N 05102190. AD 2008-19-05 ECI CYL. ASSY. NA FACTORY (S/N 05102190. AD 2008-19-05 ECI CYL. ASSY. ASSY. NA FACTORY (S/N 05102190. AD 2008-19-05 ECI CYL. ASSY. | CALLERY PA |
| 290 Harper Blvd. Ste. 1: Moultigle, GA. 31788 - 229-985-6197 1/23/09 TACH: 435.0 TTSN: 435.0 D-360-C1F SN L-4050-100 HR INSPECTION CW THIS DATE. CHANGED OIL FILTER.C ALL OIL & FUEL SCREENS, FILLED WITH 6 OTS. AEROSHELL V OIL CLEAN, GAP, ROTATED PLUGS. #1/17: #276, #3/77, #4/77.5 S.B. 583-08 CW STEP 283 THIS DATE OK, NO FUTHER INSPI PER THIS BULLETIN ARE REQUIRED UNLESS BRUSH OR DIS OR ASSY. IS REPLACED. MAG PN 4370 SN 05111420, PN 43 S/N 05102190. AD 2008-19-05 ECI CYL. ASSY, NA FACTORY (S/N 05102190. AD 2008-19-05 ECI CYL. ASS | |
| 290 Harper Blvd. Ste. 1: Moultigle, GA. 31788 - 229-985-6197 1/23/09 TACH: 435.0 TTSN: 435.0 D-360-C1F SN L-4050- 100 HR INSPECTION CWT HIS DATE. CHANGED OIL FILTER.C ALL OIL & FUEL SCREENS, FILLED WITH 6 OTS. AEROSHELL V OIL. CLEAN, GAP, ROTATED PLUGS. #1/17: #276, #3/17, #4/17. SI. B. 583-08 CW STEP 28.3 THIS DATE OK, NO FUTHER INSPI- PER THIS BULLETIN ARE REQUIRED UNLESS BRUSH OR DIS OR ASSY. IS REPLACED. MAG PN 4370 SN 05111420, PN 43 S/N 05102190. AD 2008-19-05 ECI CYL. ASSY. NA FACTORY (S/N 05102190. AD 2008-19-05 ECI CYL. ASSY. ASSY. NA FACTORY (S/N 05102190. AD 2008-19-05 ECI CYL. ASSY. | , |
| TYEAR RECORDING TODAY'S TOTAL TIME IN SERVICE THIS DATE. YEAR TACH DATE THIME TIME TIME TO THE TODAY'S TOTAL TIME IN SERVICE TIME TIME TO THE TODAY'S TOTAL TIME IN SERVICE THIS DATE. TO SERVICE TODAY'S TOTAL TIME IN SERVICE TODAY'S TOTAL TIME IN SERVICE TO SERVICE THIS DATE. Description of Inspections, Tests Entires must be endorsed with Name, Rat Technician or Repair Facility. (See back to the control of the co | |
| TOTAL THE BUTLETING TOTAL TIME TIME TIME TIME TOTAL TOTAL TIME TIME TOTAL TOTAL 260137002 A&P/IA AG4.3 CNAMAGED OZL > FILTE Description of Inspections, Tests Technician or Repair Facility. (See back processed with Name, Rat Technician or Repair Facility. (See back processed with Name, Rat Total processed of the Agas and Agas | 30M |
| VEAR RECORDING TODAY'S TOTAL SERVICE TIME INSPECTION AND FOUND TO BE IN ARROWS WITH TIME IN SERVICE TIME TIME IN SERVICE TIME TIME IN SERVICE TIME TIME IN SERVICE TIME AS A SERVICE TO SERVICE OF A SERVICE SERVICE TO SERVICE OF A SERVICE SERVICE OF A SERVICE SERVICE OF A SERVICE | V/100 |
| PER THIS BULLETIN ARE RECORDING OR ASSY, IS REPLACED, MAG PIN 4370 S.N. 05111420, P.N. 43 OR ASSY, IS REPLACED, MAG PIN 4370 S.N. 05111420, P.N. 43 OR ASSY, IS REPLACED, MAG PIN 4370 S.N. 05111420, P.N. 43 OR ASSY, IS REPLACED THRU 2009-01F, I CERTIFY THAT INSTALLED, ADS CHECKED THRU 2009-01F, I CERTIFY THAT ENGINE HAS BEEN INSPECTED IJAM A 100 HR AND AN ANN INSPECTION AND FOUND TO BE IN AIRWORTHY CONDITION IS RETURNED TO SERVICE THIS DATE. 260137002 A&PAIA 260137002 A&PAIA | ECTIONS |
| SIN 05102190. AD 2008-19-05 ECI CYL. AST INSTITUTE INSTALLED. ADS CHECKED THRU 2009-01F. I CERTIFY THAT INSTALLED. ADS CHECKED IRAW A 100 HR AND AN ANN INSPECTION AND FOUND TO BE IN AIRWORTHY CONDITION IS RETURNED TO SERVICE THIS DATE. 260137002 A&P/IA 260137002 A& | 71 |
| PENGINE HAS BEEN INSPECTION AND FOUND TO BE IN AIRWORTHY CONDITION INSPECTION AND FOUND TO BE IN AIRWORTHY CONDITION INSPECTION AND FOUND TO BE IN AIRWORTHY CONDITION INSPECTION AND FOUND TO SERVICE THIS DATE. 260137002 A&P/IA | THIS |
| INSPECTION AND FOUND TO BE IN AIRCUSTITION OF INSPECTION AND FOUND TO SERVICE THIS DATE. 260137002 A&P/IA 260137002 A& | |
| YEAR Zega TACH TIME DATE 3-24 466. S 466. S 466. S CHANGED OIL FILTE WITH 8 GAS AFROSHELL V. Wilke 260137803 CHANGED OIL FILTE WITH 8 GAS AFROSHELL V. Wilke 3404594 COOP 2009 514. Z 514. Z CHANGED OIL FILTE WITH 8 GAS AFROSHELL V. Wilke 3404594 | |
| YEAR ZOOP TACH TIME IN SERVICE 3-24 466.5 466.5 CHANCED OZL & FILTE WITH 2 QPS AFROSHELL V. WILKE 2 QPS AFROSHELL V. WILKE 3 QPS AFROSHELL V. | |
| 2009 6/11 494.3 494.3 CHANGED OZL & FILTE WITTH 9 945 AEROSHELL V. W. J. Man 260137602 6/11 494.3 CHANGED OZL & FILTE WITTH 8 945 AFROSHELL V. W. J. Man 3404594 V. W. J. Man 3404594 2009 -20 514.2 CHANGED OZL & FILTE 8 945 AFROSHELL W/100 | |
| 2009 6/11 494.3 494.3 CHANGED OZL & FILTE WITTH 9 945 AEROSHELL V. W. J. Man 260137602 6/11 494.3 CHANGED OZL & FILTE WITTH 8 945 AFROSHELL V. W. J. Man 3404594 V. W. J. Man 3404594 2009 -20 514.2 CHANGED OZL & FILTE 8 945 AFROSHELL W/100 | |
| 2009 6/11 494.3 494.3 CHANGED OZL & FILTE WITTH 9 945 AEROSHELL V. W.J. hus 260137602 WITTH 9 945 AFROSHELL V. W.J. hus 3404594 V. W.J. hus 3404594 2009 -20 514.2 CHANGED OZL & FILTE 8 945 AFROSHELL 8 945 AFROSHELL W/100 | |
| 2009 6/11 494.3 494.3 CHANGED OZL & FILTE WITTH 9 OFL & FILTE WITT | |
| 2009 6/11 494.3 494.3 CHANGED OZL & FILTE WITTH 9 OFL & FILTE WITT | |
| 2009 6/11 494.3 494.3 CHANGED OZL & FILTE WITTH 9 OFL & FILTE WITT | |
| 2009 6/11 494.3 494.3 CHANGED OZL & FILTE WITTH 9 945 AEROSHELL V. W.J. hus 260137602 WITTH 9 945 AFROSHELL V. W.J. hus 3404594 V. W.J. hus 3404594 2009 -20 514.2 CHANGED OZL & FILTE 8 945 AFROSHELL 8 945 AFROSHELL W/100 | Repairs and Alterna |
| 2009 2009 6/11 494.3 494.3 CHANGED OZL & FILTE WITTH 8 GAS AFROSHELL V. WILL PUB 3404594 V. WILL PUB 3404594 2009 20 514.2 SIA.2 CHANGED OZL & FILTE 8 GAS AFROSHELL 8 OAR AFROSHELL W/100 | absolic solve |
| 6/11 494.3 494.3 CHANGED OIL & FILTER WISTIN 8 945 AFROSHED V. WIND 3404594 2009 -20 514.2 CHANGED OIL & FILTER 8 945 AFROSHED WILLIAM 1000 | F3LLFO |
| 6/11 494.3 494.3 CHANGED OIL & FILTER WISTIN 8 945 AFROSHED V. WIND 3404594 2009 -20 514.2 CHANGED OIL & FILTER 8 945 AFROSHED WILLIAM 1000 | 4-6 of. |
| 2009 -20 514.2 514.2 CHAMCED 021 - FILLE 8 642 NEROSHEN 2009 -20 514.2 CHAMCED 021 - FILLE 8 642 NEROSHEN W/100 | |
| 2009 -20 514.2 514.2 CHAMCED OFF. FILTER 8 9/2 AFROSHED 2009 -20 514.2 CHAMCED OFF. FILTER 8 9/2 AFROSHED W/100 | R. FILLEN |
| 2009 -20 514.2 514.2 CHAMCED OFLE FILTE 8 gls AFROSHELL W/100 | LL W/100. |
| -20 514.2 514.2 CHAMCED OFL- FILTE | A-8 |
| -20 514.2 514.2 CHAMCED OFL- FILTE | |
| 8 gts AFR92HELL W/100 | 300 100 |
| 8 gts AFR934561 W/100 | R. FILLED W |
| | |
| | |
| T. May 100 Tags | 3-11 |
| | |
| | |
| | |
| | |

| ber of ntries.) | YEAR RECORD TACH TIME | TODAY'S | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) | | |
|--------------------|------------------------|---------------------------|-------------------------------|--|--------------|-----|
| | BATE | | | | - 1 | |
| - | - | | | | _ 8 | |
| | | + | | Flight, Inc. | - | |
| | - | | | 290 Harner Blvd. Ste. I - Moultrie, GA - 31788 - 229-985-6197 | | |
| - 1 - | | | | 8/21/09 TACH: 528.7 0-360-C1F S/N L-40595-36A | 220 | F |
| | | | - | CHECKED ALL OIL & FUEL SCREENS. FILLED WITH 8 QTS. AEROSHELL W/100 OIL CHECKED COMP. AT 80 PSI #1/78,#2/76, | - | ı |
| | | 1 -1 | 220-4 | #3/76, #4/78. REPLACED ALL SPARK PLUGS P/N UREM-38E. CHECKED TIMMING OF MAGS TO ENGINE. ADs CHECKED THRU | - | ı |
| 4/- | | | - | 09-17F. ENGINE RUN-UP AND RETURNED TO SERVICE. I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED I/AW A 100 HR AND | | N |
| - 1 - | | | - | AN ANNUAL INSPECTION AND FOUND TO BE IN AIRWORTHY CONDITION AND IS RETURNED TO SERVICE THIS DATE. | | М |
| - - | | | - | 3404594 A&P/IA K. W. W. W. W. | | |
| -1- | | | - | | | |
| | | | | | | |
| | | | | | - | |
| | | | 1 | | | |
| | | | 1.100 - 10.00 | | MISTERS. | er |
| - | NAME OF TAXABLE PARTY. | | | The state of the s | - ALC: 120 | |
| | | 1000 | SELL ME | The state of the s | - 1 | |
| | | Ken y | T was votal | Description of Inspections, Tests, Repairs and | | |
| | YEAR ZOOA | RECORDING TACH TIME | TODAY'S TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific are of | YEAR | No. |
| | 200A DATE | TACH | EXIGNT TIME IN | Chauses Ole & Filte File | YEAR POOLS | T T |
| | 2009 | TACH | FLIGHT TIME IN | Chauses Ole & Filte File | 2009 | 1 |
| | 200A DATE | TACH TIME | FLIGHT TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Flating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries) Chambers are Filippe. Filippe with 8 qts will so MFROSINTH. Y. Wilhow 3404594 A.P CHAMCED OIL & FILTER. FILIPO WITH 8 qts will so AFROSHELL OIL. W. Wilhow 3404594 A.P | ZOO9 DATE | 1 |


600.0

10/20/09 600.0

CHANGED OIL & FILTER FILLED WITH

gots who AEROSHELL OZL.

K. Wil kin 3404594 A+P



mber of entries.)

| YEAR ZOIO DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|----------------------|---------------------------|-------------------|-----------------------------|---|
| 5/14 | 667.5 | | 667.5 | Syls AFROGHELL WIW OIL. V. WID OM 3409594 A-7 |
| -23 | 694.7 | | 696·7 | CHANGED OSL & FSCHER, FILLED WITH BORS AFROSHELL WIND OSL. V. WILLOW BADASGA AND |
| | | | | |
| | | | | |

| YEAR | RECORDING TACH | TODAY'S FLIGHT | TOTAL TIME IN SERVICE |
|------|-------------------|-------------------|-----------------------------|
| DATE | TIME | | - Herebyton |

Description of Inspections, Tests, Repairs and Alterations
Entries must be endorsed with Name, Rating and Certificate Number of
Technician or Repair Facility. (See back pages for other specific entries.)




290 Harper Blvd. Ste. I · Moultrie, GA · 31788 · 229-985-6197
9-14-10 TACH : 715.4 TTSN : 715.4 S/N L-40595-36A
100 HR INSPECTION CW THIS DATE. CHANGED OIL AND FILTER.
CHECKED ALL OIL AND FUEL SCREENS, FILLED WITH 8 OTS. AEROSHELL W/100 OIL. CLEAN, GAP, ROTATED PLUGS. CHECKED COMP.
AT 80 PSI #1/75, #2/77, #3/75, #4/77. AD 09-25-12 ECI CYL. N/A. ENG.
HAS FACTORY CYL. INSTALLED. ADS C/W THRU 2010-18F. ENGINE
RUN-UP, LEAK CHECKED, AND RETURNED TO SERVICE. I CERTIFY
THAT THIS ENGINE HAS BEEN INSPECTED I/A/W A 100 HR AND AN
ANNUAL INSPECTION AND FOUND TO BE IN AIRWORTHY CONDITION
AND IS RETURNED TO SERVICE THIS DATE.

3404594 A&P/IA L. W. A VAN

| YEAR 2010 DATE | Time | FI | ODAY'S LIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alteration. Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|----------------------|-------|-----------------|----------------------------|-----------------------------|---|
| 11/10 | 743. | 6 | | 743.6 | K. WAYON 3404594 NOP |
| 3.8-11 | יסרר. | 0 | - | 770. | Softs AFFORMENT PAINTER EZMED MITH |
| 6.1-11 | 800-0 | | 9 | 100.0 | CHANCEO DIL + FILTER FILLED WITH BOTE. KROSHELL W/100 OIL. L. WAYNO 3404594 ALP |
| - | | | | | |
| YEAR RETAR | CH FI | ODAY'S LIGHT | TOTAL TIME IN SERVIC | N Entr | scription of Inspections, Tests, Repairs and Alterations ries must be endorsed with Name, Rating and Certificate Number of hnician or Repair Facility. (See back pages for other specific entries.) |

| YEAR 2012 DATE | RECORDING TACH TIME | FLIGHT | TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterat Entries must be endorsed with Name, Rating and Certificate Numbe Technician or Repair Facility. (See back pages for other specific ent |
|----------------------|--|--|--|--|
| 5.8 | 818.2 | | 848.5 | CHANGED CIL FILTER AIR FILLS |
| | | | | FILLED WITH 8 OTS WIND AFROSHELL |
| | | | 2.0 | K. Widhy 3404594 K+P |
| | 100 hr. and fue REM 33 #3/78, 1 that this and fou | 1/21/1 inspecti el screen BE. Chec 44/78. Al s engine nd to be | 3 Tach: 90 on c/w this os, filled with cked timing obs c/w thru has been in in airworthy | Ght, Inc. TE. I Moultrie Ga. 31788 229-985-6197 20.0 TTSN: 900.0 S/N L-40595-36A date. Changed oil, filter, and air filter, checked all oil 8 qts. Aeroshell w/100. Replaced spark plugs p/n of mags to engine. Checked comp #1/77, #2/75, 1/18/13. Engine run-up and leak checked. I certify respected I/a/w a 100 hr. and an annual inspection by condition and is returned to service this date. |
| | - | | | |
| | | | NAME OF THE OWNER, OWNE | |
| YEAR Zai3 | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
| DATE | TACH | TODAY'S FLIGHT | TIME IN | Technician or Repair Facility. (See back pages for other specific entires) Changed 4:1 and filter. Filled with 8 als |
| 2013 | TACH | TODAY'S FLIGHT | TIME IN SERVICE | Technician or Repair Facility. (See back pages for other specific entries) Changed ail and filter. Filled with agic |
| DATE | TACH | TODAY'S FLIGHT | TIME IN SERVICE | Technician or Repair Facility. (See back pages for other specific entires) Changed 4:1 and filter. Filled with 8 als |
| 2013 BATE G-13 | 935, à | FLIGHT | TIME IN SERVICE | Technician or Repair Facility. (See back pages for other specific entires) Changed oil and filter. Filled with Egls W/100 atc., Astosnell. Z. Wishus 3404504 A.P Changes oil o Factor. Filled with |
| 2013 BATE G-13 | TACH | FLIGHT | TIME IN SERVICE | Technician or Repair Facility. (See back pages for other specific entries) Changed ail and filter. Filled with agic w/100 atc., Astosnell. X. Willow 3404504 A.P CHANGED OTL & FICTER. FILLER WITH 8 chs AFROSHELL W/100. |
| 2013 BATE G-13 | 935, à | FLIGHT | TIME IN SERVICE | Technician or Repair Facility. (See back pages for other specific entires) Changed ail and filter. Filled with agis w/100 atc., Astosnell. X. Wibou 3404504 A.P |
| 2013 BATE G-13 | 935, à | FLIGHT | TIME IN SERVICE | Technician or Repair Facility. (See back pages for other specific entries) Changed ail and filter. Filled with agic w/100 atc., Astosnell. X. Willow 3404504 A.P CHANGED OTL & FICTER. FILLER WITH 8 chs AFROSHELL W/100. |
| 2013 BATE G-13 | 935, à | FLIGHT | TIME IN SERVICE | Technician or Repair Facility. (See back pages for other specific entries) Changed ail and filter. Filled with agic w/100 atc., Astosnell. X. Willow 3404504 A.P CHANGED OTL & FICTER. FILLER WITH 8 chs AFROSHELL W/100. |
| 2013 BATE G-13 | 935, à | FLIGHT | TIME IN SERVICE | Technician or Repair Facility. (See back pages for other specific entries) Changed ail and filter. Filled with agic w/100 atc., Astosnell. X. Willow 3404504 A.P CHANGED OTL & FICTER. FILLER WITH 8 chs AFROSHELL W/100. |
| 2013 BATE G-13 | 935, à | FLIGHT | TIME IN SERVICE | Technician or Repair Facility. (See back pages for other specific entries) Changed ail and filter. Filled with agic w/100 atc., Astosnell. X. Willow 3404504 A.P CHANGED OTL & FICTER. FILLER WITH 8 chs AFROSHELL W/100. |
| 2013 BATE G-13 | 935, à | FLIGHT | TIME IN SERVICE | Technician or Repair Facility. (See back pages for other specific entries) Changed ail and filter. Filled with agic w/100 atc., Astosnell. X. Willow 3404504 A.P CHANGED OTL & FICTER. FILLER WITH 8 chs AFROSHELL W/100. |
| 2013 BATE G-13 | 935, à | FLIGHT | TIME IN SERVICE | Technician or Repair Facility. (See back pages for other specific entries) Changed ail and filter. Filled with agic w/100 atc., Astosnell. X. Willow 3404504 A.P CHANGED OTL & FICTER. FILLER WITH 8 chs AFROSHELL W/100. |
| 2013 BATE G-13 | 935, à | FLIGHT | TIME IN SERVICE | Technician or Repair Facility. (See back pages for other specific entries) Changed ail and filter. Filled with agic w/100 atc., Astosnell. X. Willow 3404504 A.P CHANGED OTL & FICTER. FILLER WITH 8 chs AFROSHELL W/100. |
| 2013 BATE G-13 | 935, à | FLIGHT | TIME IN SERVICE | Technician or Repair Facility. (See back pages for other specific entries) Changed ail and filter. Filled with agic w/100 atc., Astosnell. X. Willow 3404504 A.P CHANGED OTL & FICTER. FILLER WITH 8 chs AFROSHELL W/100. |
| 2013 BATE G-13 | 935, à | FLIGHT | TIME IN SERVICE | Technician or Repair Facility. (See back pages for other specific entries) Changed ail and filter. Filled with agic w/100 atc., Astosnell. X. Willow 3404504 A.P CHANGED OTL & FICTER. FILLER WITH 8 chs AFROSHELL W/100. |

| - | YEAR | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME I SERVICE | N E | escription of Inspections, Tests, Repairs and All intries must be endorsed with Name, Rating and Certificate N echnician or Repair Facility. (See back pages for other speci- | terations umber of fic entries.) |
|---|------|---------------------------|-------------------|---|---|--|--|
| | | | | 100 hr. screens w/100 o Engine engine I to be in | 290 Harpe 3/16#4 inspection Checked iil. Checked run-up an has been airworthy | Filipht, Inc. Pright, Inc. P | |
| | | ZO14 T | RECORDING ACH | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and All Entries must be endorsed with Name. Rating and Certificate N Technician or Repair Facility. (See back pages for other specific Changed Oil & Filter. Filled with addressed I) with a factor of the second o | ic entres. |
| | | | | 8/1 100 hr. in screens, Checked 8-15-201 Engine ru a 100 hr i service th | 90 Harper B 15/14 Tach respection of checked filt comp. #1/7 4. Inspected inspection a his date. | Industrie Ga. 31788 229-985-6197 1 1062.3 TTSN: 1062.3 S/N L-40595-36A withis date. Changed oil, filter, checked all oil and fuel ter for metal, no metal. Filled with 8 qts. Aeroshell w/100. 16, #2/78, #3/77, #4/73. Clean and gap plugs. ADs c/w thru d and lubed all engine controls and push pull cables. checked. I certify that this engine has been inspected l/a/w and found to be in airworthy condition and is returned to | |



| TRANSPORT PLANT TOTAL SERVICE TOTAL SERVIC | TODAYS TODAYS TOTAL SECONDUM TODAYS TOTAL TIME TIME TODAYS TOTAL TIME TIME TODAYS TOTAL TIME TODAYS TOTAL TIME TODAYS TOTAL TIME TODAYS TOTAL TODAYS TOTAL TODAYS TOTAL TIME TODAYS TOTAL TODAYS TOTAL TODAYS TOTAL TODAYS TOTAL TIME TODAYS TOTAL TODAYS TOTAL TIME TODAYS TOTAL TIME TODAYS TOTAL TIME TODAYS TOTAL TODAYS TOTAL TIME TODAYS TOTAL TIME TODAYS TOTAL TODAYS TOTAL TIME TODAYS TOTAL TODAYS TOTAL TIME TODAYS TOTAL TIME TODAYS TOTAL TODAYS TOT | | | AND DESCRIPTION OF THE PERSON. | | |
|--|--|-----------|-----------|--------------------------------|----------------|--|
| 4-)3 III3.7 Changed Off, Fifty, Ast Fifty, Fitted with Sqs Agrashal willow Oil. Leak Check and Pcherned To Service This Dote. 200 Harper Blid. STE Moutrie Go. 31789 220-696-6187 100/15 Tach: 1141 7 TTSN: 1141 7 SN: 1441 7 SN: 14505-296. 100 hr inspection of whis date, Checked all oil and fuel screens. Checked filter for metal, no metal. Clean and gap plug. Filled with 8 dp. Aerashal WillOO oil. Checked comp. 8178, 8279, 875, 8473. Checked siming of mage to eng. Alba cive thru 10-2-2015 inspected and lubed all engine engine has been inspected. In service this date. 3404504 A8P/IA 1120 1183.1 | Granged 1917, First, Name Fisher, Fished with Sephs Agresshell willow 01. Leak Check and Rehrings Inc. 250 Harper Blvd. STE. I Mouthe Ga. 31789 229-966-6197 100 hr inspection civ this date. Changed oil, fifter, checked at oil and fuel sephs of the se | | TACH TIME | | TIME IN | recrimination repair receive, tobe back pages for other and more in |
| RECORDING TOBAY'S TOTAL THE IN TOBAY'S THE INDUSTRIES TOBAY'S THE INDUSTRIES TOBAY'S THE INDUSTRIES TOBAY'S TOTAL THE IN TOTAL THE IN TOBAY'S TOTAL THE IN TOTA | Peterned To Service This Date. 200 Harper Blvd. STE. I Moutite Ga. 31769 229-965-9187 100 ht inspection ov this date. Changed oil, fifter, checked and and fuel controls and push-pulcables. Engine run-up, leak checked. I certify that this engine has been inspected live at 100 hr and an annual inspection and found to be in altivority condition and is returned to service this date. 3404594 A&P/IA Description of Inspections, Tests, Repairs and Atternation of the inspected live at 100 hr and an annual inspection and found to be in altivority condition and is returned to service this date. 3404594 A&P/IA Description of Inspections, Tests, Repairs and Atternation of the inspected live at 100 hr and an annual inspection and found to be in altivority condition and is returned to service this date. 3404594 A&P/IA Description of Inspections, Tests, Repairs and Atternation of the inspected live at 100 hr and an annual inspection and found to be in altivority condition and is returned to service this date. 183-1 Changed Ci. Tilled w-th September 1970 September 2070 September | 500 | | | 1113.7 | Changed Oil, Filter, Aur Filter, Filled |
| 230 Harper Blvd. STE. I Moutire Ga. 31789. 229-685-6197 100 Fr Inspection over this date. Changed oil, filter, checked all oil and fuel socreens. Checked filter for metal. One metal. Clean and gap plugs. Filed with 8 dp. Aeroshell W/100 oil. Checked comp. 817/4. 827/0. 827/5. 447/3. Checked filming of mags to eng. Abox over the 10-2-2015 inspected and lubed all engine controls and push-pull cables. Engine run-up, leak checked. Lertify that this imper has been imspected law a 100 for and an annual inspection and found to 9 in airworthy condition and is returned to service this date. 3404594 ABPI/A 120 | 250 Harper Blvd. STE. I. Moutine Ga. 31788. 229.085-6197 100 hr. inspection of with is date. Changed oil, filter, checked all oil and fuel screens. Checked filter for metal, on metal. Clean and gap plugs. Filed with 6 dts. Aeroshell W/100 oil. Checked comp. \$17.4, \$270, \$375, \$473. Checked liming of maga to eng. Abs. of thur 10-2-2015 inspected and blvd all engine controls and push-pull cathese. Engine nur-up, leak checked. I certify that this engine hab been inspected inlow a 100 hr and an annual inspection and found to be in arworthy condition and is returned to service this date. 3404594 ABP/IA Description of Inspections. Tests, Repairs and Alterr Entires must be endorsed with Name, Rating and Certificate Name Technician or Repair Facility. (See back pages for orbits specific to the service this date. 3404594 ABP/IA 1188. Description of Inspections. Tests, Repairs and Alterr Technician or Repair Facility. (See back pages for orbits specific to the service this date. 3404594 ABP/IA 1188. Description of Inspections. Tests, Repairs and Alterr Technician or Repair Facility. (See back pages for orbits specific to the service this date. 3404594 ABP/IA 1188. Description of Inspections. Tests, Repairs and Alterr Technician or Repair Facility. (See back pages for orbits specific to the service this date. 3404594 ABP/IA 1188. Description of Inspections. Tests, Repairs and Alterr Tests, Repairs and Alterr Tests and Certificate Name Tests and Certificate Name Tests. (See back pages for pages of the specific specific to the service this date.) 1189. Description of Inspections. Tests, Repairs and Alterr Tests. (See back pages for pages of the specific specific to the service this date.) 1189. Description of Inspections. Tests, Repairs and Alterr Tests. (See back pages for pages for see pages for pages for pages for see pages for pages for see pages for pages f | | | | | Bots Aeroshell w/100 0:1. Leak Check and |
| 290 Harper Blvd, STE. I Moutirie Ga. 31788 229-985-6197 1007 in Inspection of with date. Changed oil, filter, checked all oil and fuel screens. Checked filter for metal, no metal. Clean and gap plugs. Filled with 8 dps. Arcabell WIOO oil. Checked comp. #174, #2770, #375, #473. Checked liming of mags to eng. ADs over thru 10-2-2015 Inspected and tubed all engine controls and pash-poli catales. Engine ru-u-up, leak checked I certify that this engine has been inspected laviv a 100 hr and an annual inspection and found to be in alwardly condition and is entured to service this date. 3404594 A&P/IA 183.1 1 | 290 Harper Blvd. STE. I. Moutrie Ga. 31788. 229-965-6197 100 ht inspection of whise date. Changed oil, filter, checked all oil and fuel soreens. Checked filter for metal, no metal. Clean and gap plugs. Filled with 8 date. Aerosale Wildro Oil. Checked comp. 817/4. 27/70, 837/5, 497/3. Checked liming of maga to eng. Albs ow thru 10-2-2015 inspected and lubed all engine controls and push-poli clattes. Engine run-up, leak checked. I certify that this engine has been inspected laws a 100 hr and an annual inspection and found to be in airvorthy condition and just or returned to service this date. 3404594 A8P/IA 183.1 183 | | | - | | Refurned To Service This Date. |
| 200 Harper Blvd. STE I Moultrie Ga. 31788 229-965-9187 100hr inspection State Changed oil, filer, checked all oil and fuel screens. Checked from the date. Changed oil, filer, checked all oil and fuel screens. Checked from the date. Changed oil, filer, checked all oil and fuel screens. Checked from the date. Changed oil, filer, checked all oil and fuel screens. Checked thing of maga to eng. Also dive thru 101-22015 inspected and lubed all engine controls and push-pull cables. Engine push been inspected laws a 100 br and an annual inspection and found to be in airworthy condition and is returned to service this date. 3404594 ABPIIA 1183.1 129 183.1 120 183.1 183.1 120 183.1 120 183.1 120 183.1 120 183.1 183.1 120 183.1 183.1 120 183.1 | 290 Harper Blvd. STE. I Mouttrie Ga. 31788 229-965-6197 109 ht impaction ow this date. Changed oil, filter, checked all oil and fuel screens. Checked filter for metal, no metal. Clean and gap plugs. 4 february 100 https://dx.edu.com/prices/filter/ | | - | | | K. 144 No. 3404244 Arp |
| 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-965-6197 100 Fr 100 Fr 120 Tach: 1141.7 TTSN: 1141.7 SN: 1141.7 | 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-685-6197 100715 Tach: 1141.7 TTSN: 1141.7 SN L-40595-98A 100716 Inaccion de with date. Changed oil, filter, checked all oil and fuel scriense. Checked filter for metal, no metal. Clean and gap plus. Filled with 8 gis. Aerosine With 200 L. Ohcicked comp. 8174, 8270. 8775, 84775. 6476. Schecked library of mags to eng. ADs ow thru 10-2-2015 inspected and bubed all engine confrols and push-pull cables. Engine run-up, leak checked. Learlify that this engine has been inspected itaw a 100 hr and an annual inspection and found to be in arworthy condition and is returned to service this date. 3404594 A8.P/IA 1083-1 1083-1 1083-1 1083-1 1083-1 290 Harper Bivd. STE. I Mouthie Ga. 31788 229-985-6195-3/29/16 Tach: 1223.4 SIN L-40595-981-6195-3/29/14 Tach: 1234.4 TTSN: 1223.4 SIN L-40595-981-6195-3/29/14 Tach: 1234.5 TTSN: 1233.4 SIN L-40595-981-6195-3/29/14 Tach: 1234.5 TTSN: 1233.4 SIN L-40595-981-6195-3/29/14 Tach: 1234.5 TTSN: 1234.5 SIN L-40595-981-6195-3/29/14 TTSN: 1234.5 SIN L-40595-98-6195-3/29/14 TTSN: 1234.5 SI | | | | | |
| 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-965-6197 100 Fr 100 Fr 120 Tach: 1141.7 TTSN: 1141.7 SN: 1141.7 | 290 Harper Bird. STE. 1 Moultrie Ga. 31788 229-965-6187 100/FIS Tach: 1141/F TTSN: 1141/F SIN L-40595-98A 100 hr in Checked With date. Changed oil, filler, checked all oil and fuel screens, hecked all oil and the screens, hecked all oil and the screens of the checked all oil and the screens of the screens | | | - | | |
| 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-965-6197 100 Fr 100 Fr 120 Tach: 1141.7 TTSN: 1141.7 SN: 1141.7 | 290 Harper Bird. STE. 1 Moultrie Ga. 31788 229-965-6197 109/15 Tach: 1141.7 TTSN: 1141.7 SIN L-40595-58A 100 hr in Checked With date. Changed oil, filler, checked all oil and fuel date. Changed oil filler, checked all oil and fuel date. Changed oil filler, one state of the fuel checked ch | | | - | | MAULE > |
| 100/HS Tach: 1141.7 TTSN: 1141.7 TSN: 1141.7 SN: 1141.7 SN: 141.7 SN: 141.2 | 100 Fin Specifion of Miss date. Changed oil, filter, checked all oil and fuel screens. Checked filter for metal, no metal. Clean and gap plugs. Filled with 8 gts. Acroshel W100 oil. Checked comp. \$1774, \$2770, \$2778, \$4773. Checked filming of mags to eng. ADs civ thru 10-2-2015 Inspected and lubed all engine controls and push-pull cables. Engine num. by, leak checked. I certify that this engine has been inspected leave a 100 hr and an annual inspection and found to be in ainvortry condition and its returned to service this date. 3404594 A&P/IA Description of Inspections, Tests, Repairs and Altern Table Interest the service of | - | | _ | | Flight, Inc. |
| TODAY'S TOTAL THE TREE TIME TIME TIME | TODAY'S TABLE T | - | | | 290 Harper 8 | Blvd. STE. I Moultrie Ga. 31788 229-985-6197 |
| qts. Aerosnell W/100 oil. Checked comp. #1/74, #2/70, #3/75, #4/73. Checked timing of mags to eng. Abo cwt htm 10-2-2015 inspected and lubed all engine controls and push-pull cables. Engine run-up, leak checked. I certify that this engine has been inspected law a 100 hr and an annual inspection and found to be in airworthy condition and is returned to service this date. 3404594 A8P/IA TIME IN SERVICE 1183.1 Description of Inspections, Tests, Repairs and Alterations that the properties of the specific and found to be in airworthy condition and is returned to service this date. 3404594 A8P/IA Description of Inspections, Tests, Repairs and Alterations that the properties of the specific and the service this date. 3404594 A8P/IA Description of Inspections, Tests, Repairs and Alterations that the service this date. 3404594 A8P/IA Description of Inspections, Tests, Repairs and Alterations that the service that the service this date. 120 II 83.1 Leave Checked Arabitation of Repair Facility. (See back pages for other specific entries). 290 Harper Blvd. STE. I Moultine Ga. 31788 229-985-6195 342916 Tach: 1223.4 TTSN: 1223.4 SNIL 440595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, snor metal. Filled with 8 days. Aeroshell with 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected laws a 100 hr and an annual inspection and found to be in airwo condition and is returned to service this date. | general will be send or service this date. RECORDING ITEMS TODAY'S TOTAL TIME IN SERVICE TODAY'S TOTAL TIME IN SERVICE TODAY'S TOTAL TIME IN SERVICE TOTAL TIME IN SERVICE TODAY'S TOTAL TIME IN SERVICE TOTAL TIME IN SERVICE TODAY'S TOTAL TIME IN SERVICE TOTAL TIME IN SERVICE TODAY'S TOTAL TIME IN SERVICE TOTAL TOTAL TIME IN SERVICE T | | | 100 hr | inspection ch | W this date. Changed oil, filter, checked all oil and fuel |
| TODAY'S THE TIME IN SERVICE TIME IN SERVICE 120 H83.1 100 hrs. secondary in the Highest Properties of Taylor of The Service this date. 240 hrs. secondary in the Highest Properties of Taylor of The Service this date. 250 hrs. secondary in the Highest Properties of Taylor of The Service this date. 260 hrs. secondary in the Highest Properties of Taylor of The Service and Alterations Technician or Repair Facility. (See back page for other specific entries) 120 hrs. secondary in the Service of Taylor of Taylo | TODAY'S TOTAL TIME IN SERVICE TIME 1-20 183.1 Description of Inspections, Tests, Repairs and Atternation of Inspection and found to be in airworthy condition and is returned to service this date. 3404594 A8,P/IA Description of Inspections, Tests, Repairs and Atternation of Inspection and found to be in airworthy condition and is returned to service this date. 3404594 A8,P/IA Description of Inspections, Tests, Repairs and Atternation of Inspection of Ins | | | qts. Ae | erosheli W/100 | 0 oil. Checked comp. #1/74 #2/70 #3/75 #4/73 Checked |
| TODAY'S TOTAL TIME IN FLIGHT TIME IN SERVICE THES MUST be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries) Lear Changed Oil, Filher. Filled with 84F here Shell w/low o'l. Leak Chacked hand Certificate Number of Service Thy's Date. 3404594 A 8 P/IA 183.1 | TODAY'S TOTAL TIME IN SERVICE 1-20 1183.1 Description of Inspections, Tests, Repairs and Atternatives must be endorsed with Name, Rating and Certificate Number Technician or Repair Facility. (See back pages for other specific entry) in the service by the serv | | | COUILO | s and push-pi | ull cables. Engine nin-tin, leak chacked, I contifu that this |
| RECORDING TODAY'S TOTAL TIME IN SERVICE THE TACH TIME IN SERVICE 1:20 183.1 1 | TODAY'S TOTAL TIME IN SERVICE TIME IN SERVICE TIME IN SERVICE TIME IN SERVICE THE INSERVICE | | | to be in | nas been ins | pected I/a/w a 100 hr and an annual inspection and found indition and is returned to service this date. |
| Technician or Repair Facility. (See back pages for other specific entries.) 183.1 Changed Oil, Filter. Filled with Rott 120 183.1 Leak Chacked had Returned to Service This Date. 3404594 A - P 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-965-619 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 dis. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwork condition and is returned to service this date. | Technician or Repair Facility. (See back pages for other specific e particulate Number 1:20 183.1 | | | | | |
| Technician or Repair Facility. (See back pages for other specific entries.) 183.1 Changed Oil, Filter. Filled with Rott 120 183.1 Leak Chacked had Returned to Service This Date. 3404594 A - P 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-965-619 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 dis. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwork condition and is returned to service this date. | Technician or Repair Facility. (See back pages for other specific e pages f | | | -37 | | |
| Technician or Repair Facility. (See back pages for other specific entries.) 183.1 Changed Oil, Filter. Filled with Rott 120 183.1 Leak Chacked had Returned to Service This Date. 3404594 A - P 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-965-619 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 dis. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwork condition and is returned to service this date. | Technician or Repair Facility. (See back pages for other specific e partire pages for other specific e pages for other s | | | | | The second secon |
| Technician or Repair Facility. (See back pages for other specific entries.) 183.1 Changed Oil, Filter. Filled with Rott 120 183.1 Leak Chacked had Returned to Service This Date. 3404594 A - P 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-965-619 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 dis. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwork condition and is returned to service this date. | Technician or Repair Facility. (See back pages for other specific e affection of Repair Facility. (See back pages for other specific e specific | - | | | | |
| Technician or Repair Facility. (See back pages for other specific entries.) 183.1 Changed Oil, Filter. Filled with Rott 120 183.1 Leak Chacked had Returned to Service This Date. 3404594 A - P 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-965-619 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 dis. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwork condition and is returned to service this date. | Technician or Repair Facility. (See back pages for other specific e partire pages for other specific e pages for other pages for other specific e pages for other specific e pages | | | | | |
| Technician or Repair Facility. (See back pages for other specific entries.) 183.1 Changed Oil, Filter. Filled with Rott 120 183.1 Leak Chacked had Returned to Service This Date. 3404594 A - P 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-965-619 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 dis. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwork condition and is returned to service this date. | Technician or Repair Facility. (See back pages for other specific e part 120 1183.1 1183. | | | | and the last | |
| Technician or Repair Facility. (See back pages for other specific entries.) 183.1 Changed Oil, Filter. Filled with Rott 120 183.1 Leak Chacked had Returned to Service This Date. 3404594 A - P 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-965-619 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 dis. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwork condition and is returned to service this date. | Technician or Repair Facility. (See back pages for other specific e part 120 1183.1 1183. | 1000 | | | | |
| Technician or Repair Facility. (See back pages for other specific entries.) 183.1 Changed Oil, Filter. Filled with Rott 120 183.1 Leak Chacked had Returned to Service This Date. 3404594 A - P 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-965-619 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 dis. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwork condition and is returned to service this date. | Technician or Repair Facility. (See back pages for other specific e pages f | - 1 - | T-sappawg | | | Description of Inspections, Teste Bank |
| 1.20 1183.1 Changed Oil, Filher. Filled with 8ate here shell w/100 oil. Leak Checked had lecturned to Scruice This Date. 290 Harper Bird. STE. I Mouthire Ga. 31788 229-985-619: 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection civ this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal. Filled with 8 qts. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwiccondition and is returned to service this date. | 1.20 1183.1 Changed Oil, Filher. Filled with 8df here Shell w/100 oil. Leak Chacked Returned to Scruice This Date. 3404594 A - 9 290 Harper Blvd. STE. I Moutrie Ga. 31788 229-985-6197 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil at screens, checked filter for metal, no metal. Filled with 8 qts. Aerosho Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 cranksha 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screen c/w thru 3-11-2016. Inspected and lubed all engine controls and put cables. Engine run-up, leak checked. I certify that this engine has be inspected i/a/w a 100 hr and an annual inspection and found to be condition and is returned to service this date. | | RECUMBING | | | Contries and Alternation |
| 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-985-619 3/29/16 Tach: 1223.4 TTSN: 1223.4 S.N.L40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal, Filled with 8 qts. Aerosheil w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and ilubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwing condition and is returned to service this date. | 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-985-6197 3/29/16 Tach. 1223.4 TTSN: 1223.4 SIN L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil at screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshic Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 cranksha 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screens, checked silver for metal. The screen complete controls and public controls and public controls. Engine run-up, leak checked. I certify that this engine has be inspected i/a/w a 100 hr and an annual inspection and found to be condition and is returned to service this date. | | TACH | FLIGHT | | Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other see all the control of the con |
| 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-985-619 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 qis. Aerosheli w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwic condition and is returned to service this date. | 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-985-619 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil as screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshe Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 cranksha 2012-03-07 carb niz by model. 2015-02-07 prop gov. shaft set screens, checked site in spected and lubed all engine controls and put cables. Engine run-up, leak checked. I certify that this engine has be inspected i/a/w a 100 hr and an annual inspection and found to be condition and is returned to service this date. | 20 K4 | TACH | | SERVICE | Technician or Repair Facility. (See back pages for other specific entries |
| 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-985-619 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-38A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74 AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/b by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwing condition and is returned to service this date. | 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-985-619 3/29/16 Tach. 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil as screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshic Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 cranksha 2012-03-07 carb n/b by model. 2015-02-07 prop gov. shaft set screens, checked site of the state of the st | DATE | TACH | | SERVICE | Changed Oil, Filter. Filled with Bate |
| 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-985-619 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwing condition and is returned to service this date. | 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-985-619 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil as screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshi Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 cranksha 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screen c/w thru 3-11-2016. Inspected and lubed all engine controls and purcables. Engine run-up, leak checked. I certify that this engine has be inspected i/a/w a 100 hr and an annual inspection and found to be condition and is returned to service this date. | DATE DATE | TACH | | SERVICE | Changed Oil, Filter. Filled with Bate |
| 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection of this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in ainwed condition and is returned to service this date. | 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil at screens, checked filter for metal, no metal. Filled with 8 qts. Aerosht Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 cranksha 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screen c/w thru 3-11-2016. Inspected and lubed all engine controls and purcables. Engine run-up, leak checked. I certify that this engine has be inspected i/a/w a 100 hr and an annual inspection and found to be condition and is returned to service this date. | 20 K4 | TACH | | SERVICE | Changed Oil, Filter. Filled with Bate here Shell w/100 oil. Leak Chacked here Returned to Service This Date. |
| 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwic condition and is returned to service this date. | 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil at screens, checked filter for metal, no metal. Filled with 8 qts. Aerosht Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 cranksha 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screen/w thru 3-11-2016. Inspected and lubed all engine controls and puscables. Engine run-up, leak checked. I certify that this engine has be inspected i/a/w a 100 hr and an annual inspection and found to be condition and is returned to service this date. | 20 K4 | TACH | | SERVICE | Changed Oil, Filter. Filled with Bate here Shell w/100 oil. Leak Chacked here Returned to Service This Date. |
| 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwic condition and is returned to service this date. | 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil at screens, checked filter for metal, no metal. Filled with 6 qts. Aeroshh Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 cranksha 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screen c/w thru 3-11-2016. Inspected and lubed all engine controls and puscables. Engine run-up, leak checked. I certify that this engine has be inspected i/a/w a 100 hr and an annual inspection and found to be condition and is returned to service this date. | 20 K4 | TACH | | SERVICE | Changed Oil, Filter. Filled with Bate here Shell w/100 oil. Leak Chacked here Returned to Service This Date. |
| 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwic condition and is returned to service this date. | 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil at screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshic Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 cranksha 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screen c/w thru 3-11-2016. Inspected and lubed all engine controls and puscables. Engine run-up, leak checked. I certify that this engine has be inspected i/a/w a 100 hr and an annual inspection and found to be condition and is returned to service this date. | 20 K4 | TACH | | SERVICE | Changed Oil, Filter. Filled with Bate here Shell w/100 oil. Leak Chacked here Returned to Service This Date. |
| 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwic condition and is returned to service this date. | 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil at screens, checked filter for metal, no metal. Filled with 8 qts. Aerosht Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 cranksha 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screen c/w thru 3-11-2016. Inspected and lubed all engine controls and puscables. Engine run-up, leak checked. I certify that this engine has be inspected i/a/w a 100 hr and an annual inspection and found to be condition and is returned to service this date. | 20 Kg | TACH | | SERVICE | Changed Oil, Filter. Filled with Bate here Shell w/100 oil. Leak Chacked here Returned to Service This Date. |
| 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwic condition and is returned to service this date. | 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil at screens, checked filter for metal, no metal. Filled with 8 qts. Aerosht Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 cranksha 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screen c/w thru 3-11-2016. Inspected and lubed all engine controls and puscables. Engine run-up, leak checked. I certify that this engine has be inspected i/a/w a 100 hr and an annual inspection and found to be condition and is returned to service this date. | 20 Kg | TACH | | SERVICE | Changed Oil, Filter. Filled with Bate here Shell w/100 oil. Leak Chacked here Returned to Service This Date. |
| 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwic condition and is returned to service this date. | 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil at screens, checked filter for metal, no metal. Filled with 6 qts. Aerosht Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 cranksha 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screen c/w thru 3-11-2016. Inspected and lubed all engine controls and purcables. Engine run-up, leak checked. I certify that this engine has be inspected i/a/w a 100 hr and an annual inspection and found to be condition and is returned to service this date. | 20 K4 | TACH | | SERVICE | Changed Oil, Filter. Filled with Bate here Shell w/100 oil. Leak Chacked here Returned to Service This Date. |
| screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshell w/10 Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft. n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwic condition and is returned to service this date. | screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshic Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 cranksha 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screen c/w thru 3-11-2016. Inspected and lubed all engine controls and purcables. Engine run-up, leak checked. I certify that this engine has be inspected i/a/w a 100 hr and an annual inspection and found to be condition and is returned to service this date. | DATE | TACH | | SERVICE | Technician or Repair Facility. (See back pages for other specific entries Changed Oil, Filher. Filled with Bate hero shell w/low oil. Leak Checked has Returned to Service This Date. 3404594 A P 290 Harper Blvd. STE. I Moulting Ga. 31788. 229.985.619 |
| Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft n/a. 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw n/a. c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwo | Checked comp. #1/76, #2/76, #3/77, #4/74, AD 2012-19-0 cranksha 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set scre c/w thru 3-11-2016. Inspected and lubed all engine controls and pur cables. Engine run-up, leak checked. I certify that this engine has be inspected i/a/w a 100 hr and an annual inspection and found to be condition and is returned to service this date. | DATE DATE | TACH | | SERVICE | Technician or Repair Facility. (See back pages for other specific entries. Changed Oil, Filher. Filled with Bate hero Shell w/100 oil. Leak Checked has leturned to Scruice This Date. 3404594 A . P 290 Harper Blvd. STE. I Moultine Ga. 31788 229-985-6197 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N I. 40595-38A |
| c/w thru 3-11-2016. Inspected and lubed all engine controls and push pull cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwing condition and is returned to service this date. | c/w thru 3-11-2016. Inspected and lubed all engine controls and pur cables. Engine run-up, leak checked. I certify that this engine has be inspected i/a/w a 100 hr and an annual inspection and found to be condition and is returned to service this date. | 20 Kg | TACH | | SERVICE | Technician or Repair Facility. (See back pages for other specific entries Changed Oil, Filher. Filled with 8 afters shell w/100 oil. Leak Chacked have between to Service This Date. 3404594 A P 290 Harper Blvd. STE. I Moultine Ga. 31788 229-985-619 3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and file. |
| cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airwin condition and is returned to service this date. | cables. Engine run-up, leak checked. I certify that this engine has be inspected i/a/w a 100 hr and an annual inspection and found to be condition and is returned to service this date. | DATE | TACH | | SERVICE | Technician or Repair Facility. (See back pages for other specific entries Changed Oil, Filter. Filled with Bate here shell w/100 oil. Leak Checked here shell w/100 hr. inspection c/w this date. Changed oil, filter, checked all oil and filter screens, checked filter for metal, no metal. Filled with 8 gts. Aeroshell w/100 oil. (Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft of the checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft of the checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft of the checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft of the checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft of the checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft of the checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft of the checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft of the checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft of the checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft of the checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft of the checked comp. |
| condition and is returned to service this date. | condition and is returned to service this date. | 20 Kg | TACH | | SERVICE | Technician or Repair Facility. (See back pages for other specific entries Changed Oil, Filher. Filled with Bate here shell w/100 oil. Leak Checked has Returned to Service This Date. 290 Harper Blvd. STE. I Moultine Ga. 31788 229-985-619-3/29/16 Tach: 1223.4 TTSN: 1223.4 S/N L-40595-36A 100 hr. inspection civ this date. Changed oil, filter, checked all oil and fine screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshell w Checked comp. #1/76, #3/77, #4/74. AD 2012-19-0 crankshaft in 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw in |
| | | DATE DATE | TACH | | SERVICE | Technician or Repair Facility. (See back pages for other specific entries Changed Oil, Filher. Filled with Bate here shell w/loo oil. Leak Checked has Returned to Scruice Twis Date. 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-985-619: 3/29/16 Tach: 1223.4 TTSN: 1223.4 SN L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and for screens, checked filter for metal, no metal. Filled with 8 qts. Aeroshell w Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft checked comp. #1-2016-0.0-10 y model. 2015-02-07 prop gov. shaft set screw in c/w thru 3-11-2016. Inspected and lubed all engine controls and push p cables. Engine run-up, leak checked. I certify that this engine has been |
| 3404594 A&P/IA - K- 13-90 314 | 3404594 A&P/IA | DATE DATE | TACH | | SERVICE | Technician or Repair Facility. (See back pages for other specific entries.) Changed Oil, Filter. Filled with 8 afters of Shell w/100 oil. Leak Checked have between the Service This Date. 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-985-619: 3/29/16 Tach: 1223.4 TTSN: 1223.4 SN L-40595-36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fiscreens, checked filter for metal, no metal. Filled with 8 ats. Aeroshell w Checked comp. #1/76, #2/76, #3/77, #4/74. AD 2012-19-0 crankshaft in 2012-03-07 carb n/a by model. 2015-02-07 prop gov. shaft set screw in cw thru 3-11-2016. Inspected and lubed all engine controls and push p cables. Engine run-up, leak checked. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual inspection and found to be in all spected i/a/w a 100 hr and an annual |
| | | DATE | TACH | | SERVICE | Technician or Repair Facility. (See back pages for other specific entries.) Changed Oil, Filter. Filled with 8aft here Shell w/100 oil. Leak Chacked here specific entries. Shell w/100 oil. Leak Chacked here shell w/100 oil. Stell w/100 oil. Shell w/100 oil |
| | | 20 K4 | TACH | | SERVICE | Technician or Repair Facility. (See back pages for other specific entries.) Changed Oil, Filter. Filled with 8aft here Shell w/100 oil. Leak Chacked here specific entries. Shell w/100 oil. Leak Chacked here shell w/100 oil. Stell w/100 oil. Shell w/100 oil |

| YEAR | RECORDING TACH | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterative Fine Property of the Pages for other specific specifi |
|--------------|-------------------|-------------------|-----------------------------|--|
| DATE | TIME | | 1248.7 | and all the same and the same a |
| 8-3 17 | 248.7 | | | 8 de A ero Snell w/100 Oil Leak Checker |
| | | | - | And Reducted to Service This Date. |
| - | | | | V. wishes 3404594 Nep Dole |
| 10-31-16 12 | 46.3 | - | 266.3 | Engine Removed From Maule My. 1901 |
| 10-31-16 112 | | | | N3140R SIN 47010T And Removed From |
| | | | | Service This Date. |
| | | | | K. Wisker 3404694 A.P |
| | | | | Engine Removed From Maula M.4.180 |
| | | | | SIM YTO 10T NBILLEN TOLOR THE |
| | | | | 4 + NOSNONE and bul. X |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

ate Number of specific entries.)

with ecked

VOB1 -

1804

| YEAR 2018 BATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE |
|----------------------|---------------------------|-------------------|-----------------------------|
| 4-4 | -0- | | 1266.3 |

Description of Inst Entries must be endo Technician or Rep

Tests, Repairs and Alterations arme, Rating and Certificate Number of (See back pages for other specific entries.)



4/4/18 0-360-C1F S/N L-40595-36A Tach: 0 TTSN: 1286.3 TTSMOH: 0
Engine disassembled due to prop strike inspection and overhaul. Crankshaff, crank gear, camshaft, connecting rods, lifters, rocker arms, hydraulic units and all steef parts were sent out to Aircraft Specialties Services for inspection see yellow tags w/o 246374 dated 1/9/18. Cylinders were sent to Harrison Engine Services for NuChrome and overhaul see form 8130-3 w/o 98376 thru 98379. Crankcase sent to CSI for inspection see 8130-3 w/o CSI-28059 dated 1/4/18. Engine was reassembled with the following new parts: 1 crank gear both STD-213, 8 rod bearings, 8 rod nuts, 8 rod bolts, 2 Frw main bearings SL 13884A, 4 main bearings, 4 pistons SL 75089A, 8 piston pin plugs 72198, 4 ring sets SL 5401-SC, 4 rocker shafts SL 13790A, 4 hose STD-18214 & SL 69603, 8 thrust buttons 12892, 1 o/n gasket set 75439-1, 1 fuel pump LW-16335 s/n RC04160626, 8spark plugs REM-37BY, 2 magnetos p/n 4370 s/n 17110394 and 4371 s/n 17040874, 1 ignition harness M4001, 1 carburetor HA-6 p/n 10-5255 s/n 75C58704, 1 starter 149-12LS s/n H-R113173, 1 O/H Alternator ALY-8520 s/n H-R081502, 1 belt 37A19773-376. All work was done i/a/w Lycoming O/H manual p/n 60294-7. Engine was filled with 9 qts. Aero Shell mineral oil, pre-oiled and run-in i/a/w break-in procedure per NuChrome clyinders. I certify that this engine has been inspected i/a/w a 100 hr and an annual inspection and found to be in airworthy condition and is returned to service this date. See AD list.

| YEAR Zº18 | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries |
|-----------------------------------|---------------------------|-------------------|-----------------------------|---|
| DATE | 9.9 | | 12762 | Changed O:1. Fifter Filled With Bots |
| 10-13 | | | | Acro Shell Straight Mineral G.1. |
| TTSMALT | 7.5 | | | Acro Snell Straight Mineral Oil. V. W. Dress 3404594 APP |
| | | | | |
| 2019 | | | - 200 | Flight, Inc. |
| 3/28 | 24.0 | | 1290.3 | Figit, iiica |
| | | | | 290 Harper Blvd. STE. 1 Moultrie Ga. 31788 229-985-6197 |
| T.T.S.M. | 24. 6 | | | 3/28/19 Tach: 24.0 TTSMOH: 24.0 TTSN: 1290.3 S/N L-40595 100 hr. inspection c/w this date. No oil change this date. Checked com #1/80, #2/79, #3/80, #4/80. Clean plugs. Checked timing of mags to e Engine leak checked and flight tested. Inspected and lubed all engine and push-pull cables. ADs c/w thru 2019-06. I certify that this engine t inspected i/a/w a 100 hr. and an annual inspection and found to be in |
| | | | | - condition and is returned to service this date. |
| | | | | 3404594 A&P/IA L: 154 84 |
| | | | | |
| | | | | |
| | | - 1-22 | | |
| YEAR 2020 BATE | RECORDING TACH TIME | TODAY'S | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
| 2020 BATE | TACH | FLIGHT | TIME IN | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
| 2020 BATE 3/27 | TACH TIME | FLIGHT | TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
| 2020 BATE 3/27 T.T. S. M | TACH TIME | FLIGHT | TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
| 2020 BATE 3/27 T.T. S. M | 43.8 0. H. | FLIGHT | TIME IN SERVICE | 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-985-6197 3/27/2020 Tach: 43.8 TTSN: 1310.1 TTSMOH: 43.8 S/N L-40595.36A |
| 2020 BATE 3/27 | 43.8 0. H. | FLIGHT | TIME IN SERVICE | 290 Harper Blvd. STE. I. Moultrie Ga. 31788 229-985-6197 3/27/2020 Tach: 43.8 TTSN: 1310.1 TTSMOH: 43.8 S/N L-40595.36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens. Checked filter for metal no metal this date. Filed with 8 qts, Aeroshi W/100 oil. Checked comp. #1/79, #2/78, #3/78, #4/79. Clean and gaped plug Checked timing of mags to engine. Engine leak checked. Inspected and lube all engine controls and push-pull cables. ADs civ thru 2020-07. I certify that this engine has been inspected via/w a 100 hr. and an annual inspection and femot to be in airwanthy condition and is returned to service this date. |
| 2020 pate 3/27 T.T. S. M | 43.8 0. H. | FLIGHT | TIME IN SERVICE | 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-985-6197 3/27/2020 Tach: 43.8 TTSN: 1310.1 TTSMOH: 43.8 S/N L-40595.36A 100 hr. inspection c/w this date. Changed oil, filter, checked all oil and fuel screens. Checked filter for metal no metal this date. Filled with 8 qfs. Aeroshe W/100 oil. Checked comp. #1/79, #2/78, #3/78, #4/79. Clean and gaped plug Checked timing of mags to engine. Engine leak checked. Inspected and lube all engine controls and push-pull cables. ADs civ thru 2020-07. I certify that |

| EAR RECORD TACH TIME | TODAY'S | TOTAL TIME I SERVICE | N Er | escription of Inspections, Tests, Repairs and Alterations ntries must be endorsed with Name, Rating and Certificate Number of echnician or Repair Facility. (See back pages for other specific entries.) |
|---|----------------|----------------------------|----------------------------|---|
| 27 45.5 MOH 45.5 | | 1311.7 | | |
| | | | 10 #1 pt 15 be | 290 Harper Blvd. STE. I Moultrie Ga. 31788 229-985-6197 0/27/2020 Tach: 45.5 TTSN: 1311.7 TTSMOH: 45.5 SrN L-40595-3 00 hr. inspection c/w this date. No oil change this date. Checked comp. 1/77, #2/77, #3/76, #4/76. Inspected and lubed all engine controls and public dables. McCauley AD 20-19-06 Prop Gov. model DC290D1/T12 shill cables. McCauley AD 20-19-06 Prop Gov. model DC290D1/T12 shill cables. McCauley AD 20-19-06 Prop Gov. model DC290D1/T12 shill cables. Wcall for the control of the control |
| | | | | A A |
| | | - | | |
| YEAR | RECORDING TACK | TODAY'S FLIGHT | TIME IN | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name Property and Alterations |
| YEAR 2621 DATE 10/14 TTSMOH | | | | Technician or Repair Facility. (See back pages for other specific entries.) |
| 2021 DATE 10/14 | TACH TIME | | TIME IN SERVICE | Technician or Repair Facility. (See back pages for other specific entries.) |
| 2021 DATE 10/14 | TACH TIME | | TIME IN SERVICE | 290 Harper Blvd. STE. I Moultirle Ga. 31788 229-985-8197 10/14/202 Tach. 46.1 TTSN: 1312.3 TTSMOH: 46.1 SIN L-40595-36A 100 hr. inspection c/w this date. No oil change this date. Checked comp. #1/777, #2/77, #4/76 Checked timing of mags to engine. Inspected lubed all engine controls and push-pull cables. Lyc. AD 20-25-12 SAP crankshaft n/a by p/n. ADs c/w thru 2021-21. Loertify that this engine has been inspected valve a 100 hr. and an annual inspection and found to be airworthy condition and is returned to service this date. |
| 2021 DATE 10/14 | TACH TIME | | TIME IN SERVICE | Technician or Repair Facility. (See back pages for other specific entries.) 290 Harper Blvd. STE. I Moultine Ga. 31788 229-985-6197 10/14/202 Tach: 46.1 TTSN: 1312.3 TTSMOH: 46.1 SIN L-40595-984 100 hr. inspection c/w this date. No oil change this date. Checked comp. #1/77, #2/77, #3/76, #4/76. Checked timing of mags to engine. Inspected lubed all engine controls and push-pull cables. Lyc. AD 20-25-12 SAP crankshaft n/a by p/n. ADs c/w thru 2021-21. I certify that this engine has been inspected l/ai/w a 100 hr. and an annual inspection and found to be |

| | YEAR 2022 | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries) |
|---|-----------|--|--|--|--|
| 4 | DATE | 91.7 | | 1,357.9 | |
| | 2/1 | 91.1 | | 1,000 | 2/1/22 N3171H Tach: 91.7 Drained oil and changed filter (AA48110-2). Inspected filter and sump |
| 進品 | | | | | screen, no contamination noted. Oil sample taken. Serviced with 7 ne |
| | | - | | | AeroShell 100 + and one PT CamGuard. B. J. Boyle A&P 1867597 IA |
| | | | | | B. J. Boyle A&P 1807397 IA |
| | | | | | |
| | | | | _ | 05/19/2022 N3171H Tach: 116.4 |
| 20 | 5/19 | 116.4 | | | Drained oil and changed filter (AA48110-2). Inspected filter and sump screen, no contamination noted. Serviced with 7 Qts of AeroShell 100+ |
| | | | | | and one PT CamGuard. Replaced air filter BA-6108 |
| - 1 | 100000 | | | | B. J. Boyle A&P 1867597 IA R |
| 8 | - | | | | - |
| | | | | 1 | ARLIN'S AIRCRAFT SERVICE, INC. 200 Wings Way, Belgrade, MT 59714 (406)-898-2012 CRS QMSR150N (KBZN) |
| | - | | | DATE | REGISTRATION ENGINE SERIAL TAC SMOH |
| | - | | | 20 AUG | NEMISTRATION 1 40000 36A 1423 1423 |
| 鹅 | - | | | Removes | Speine for an engine prop strike inspection, See enclosed engine log books |
| | | | | /6 | That Was |
| | M | | | Artin C | Wass R&P 1340061 |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | 1 | 100 | |
| | | Carried States | A. 15 | W. T. | TO BE STORY OF THE |
| | | | WI | STE | RN Engine Model: 0-360-C19 |
| Iteration | | | WI | ESTE | Engine Model: 0-360-C15- Serial Number: 1-40595-36A ns |
| Number of | s - | | COLDS | EAL AIRCRAFT | ENGINES 1 |
| umber of | - Tr a | 21 Creative | COLDS | EAL AIRCRAFT | ENGINES 1408.6 TTE, 142.3 TSO 1 3.) |
| fic entries.) | | | GOLD S | eal aircrapt introse, CO 8140 | ENGINES DI CRS # WS9R5753 Time: 1408.6 TTE, 142.3 TSO Work Order: W059471 Dute: 5 DEC 2022 |
| vumber of fic entries.) | | This engine was | GOLD S Place Ms s disassemb | led and cleaned | ENGINES OI CRS # WS9R5753 Time: 1408.6 TTE, 142.3 TSO Work Order: W059471 Dute: 5 DEC 2022 for a prop strike inspection per Lycoming SB 533C. |
| Number of fic entries.) | | This engine was Crankense mate penetrant inspec | GOLD S Place Mc s disassemb | led and cleaned PK 146PT was residently to the second control of | for a prop strike inspection per Lycoming SB 533C. epaired by Divco, Inc. see 8130-3 form Invoice # 135976 dated 13 Oct 2022. Fluorescent sump and ring generating particle inspection and magnification per Lycoming SB 533C. |
| Number of fic entries.) | | This engine was Crankense mate penetrant inspec Crankshaft S/N | GOLD s Place Ms s disassemb th number T teled access V5379441 | led and cleaned PK 146PT was r ry housing, oil s 4 was visual, a idler gear, but | ENGINES 11 CRS # WS9R5753 Time: 1408.6 TTE, 142.3 TSO Work Order: W059471 Date: 5 DEC 2022 for a prop strike inspection per Lycoming SB 533C. epaired by Divco, Inc, see 8130-3 form Invoice # 135976 dated 13 Oct 2022. Fluorescent sump and ring gear. invoice and imagnetic particle inspected. Magnetic particle inspected connecting rods. Invoice pump shaft, filed nump plumper, fuel nump idler penr, oil pame drive shaft, oil reconnecting rods. |
| Number of ific entries.) | | This engine was Crankense mate penetrant inspec Crankshaft S/N crankshaft gear, drive and driven | Place Mo s disassemb h number T eted accesse V53794412 idler shafts gear, thru | led and cleaned PK 146PT was ray housing, oil s st was visual, di t, idler gear, hyd boils, rocker arm | Fine: 1408.6 TTE, 142.3 TSO Work Order: W059471 Dute: 5 DEC 2022 for a prop strike inspection per Lycoming SB 533C. repaired by Divco, Inc., see 8130-3 form Invoice # 135976 dated 13 Oct 2022. Fluorescent sump and ring gear. Intensional, and magnetic particle inspected. Magnetic particle inspected connecting rods. Iraulic pump shaft, fuel pump plunger, fuel pump idler gear, oil pump drive shaft, oil pump ins, and pushrod sockets. |
| vumber of fic entries.) | | This engine was Crankense mate penetrant inspec Crankshaft Sov crankshaft gear, drive and driven Installed repaire | Place Ms s disassemb h number T teed access v53794412 idler shafts gear, thru d camshaft | led and cleaned PK 146PT was r ry housing, oil of st was visual, oil, oil, oil, oil, oil, oil, oil, oi | FINGINES OF CRS # WS9R5753 Time: 1408.6 TTE, 142.3 TSO Work Order: W059471 Date: 5 DEC 2022 for a prop strike inspection per Lycoming SB 533C. repaired by Divco, Inc, see 8130-3 form Invoice # 135976 dated 13 Oct 2022. Fluorescent innersional, and magnetic particle inspected. Magnetic particle inspected connecting rods, resulic pump shaft, fuel pump plunger, fuel pump idler gear, oil pump drive shaft, oil pump ns, and pushrod sockets. V18840 (LW11754), see Aircraft Specialties Services, Inc 8130-3 forms (x2) Work Order 275479 dated. |
| number of fic entries.) | | This engine was Crankense mate penetrant inspec Crankshaft S/N crankshaft gear, drive and driven Installed repaire 1 NOV 2022. In 17 OCT 2022. 3 | GOLD S Place Ms s disassemb in number T ened accesse V53794412 idler shafts a gear, thru d camshaft installed over | led and cleaned PK 146PT was r ry housing, oil s st was visual, di s, idler gear, hyd boils, rocker arm part number LV rhauled lifters 7 w rocker arm bu | Fine: 1408 6 TTE, 142.3 TSO Work Order: W059471 Dute: 5 DEC 2022 for a prop strike inspection per Lycoming SB 533C. repaired by Divco, Inc, see 8130-3 form Invoice # 135976 dated 13 Oct 2022. Fluorescent sump and ring gear. Intensional, and magnetic particle inspected. Magnetic particle inspected connecting rods, traulic pump shaft, fuel pump plunger, fuel pump idler gear, oil pump drive shaft, oil pump ns, and pushrod sockets. V18840 (LW11754), see Aircraft Specialties Service, Inc 8130-3 Work Order 275351 dated ashings \$1.74637. Installed new rocker shafts \$1.13790A. |
| number of incentries.) ump 7 Qts of | | This engine was Crankense mate penetrant inspec Crankshaft S/N crankshaft gear, drive and driven Installed repaire 1 NOV 2022. In 17 OCT 2022. 3 | GOLD S Place Ms s disassemb in number T ened accesse V53794412 idler shafts a gear, thru d camshaft installed over | led and cleaned PK 146PT was r ry housing, oil s st was visual, di s, idler gear, hyd boils, rocker arm part number LV rhauled lifters 7 w rocker arm bu | FINGINES OF CRS # WS9R5753 Time: 1408.6 TTE, 142.3 TSO Work Order: W059471 Date: 5 DEC 2022 for a prop strike inspection per Lycoming SB 533C. repaired by Divco, Inc, see 8130-3 form Invoice # 135976 dated 13 Oct 2022. Fluorescent innersional, and magnetic particle inspected. Magnetic particle inspected connecting rods, resulic pump shaft, fuel pump plunger, fuel pump idler gear, oil pump drive shaft, oil pump ns, and pushrod sockets. V18840 (LW11754), see Aircraft Specialties Services, Inc 8130-3 forms (x2) Work Order 275479 dated. |
| number of incentries.) ump 7 Qts of | | This engine was Crankense mate penetrant inspec Crankshaft S/N crankshaft S/N crankshaft gear, drive and driven Installed repaire 1 NOV 2022. If 17 OCT 2022. 1 Installed new ma | GOLD s Place Me s disassemb h number I tied access V5379441: idler shafts i gear, thru d camshaft istalled ove installed ne ignetos mo | led and cleaned PK 146PT was r ry housing, oil s 4 was visual, di , idler gear, hyd boits, rocker am part number LV rhauled lifters 7 w rocker arm be del 4371 serial r | Fine: 1408 6 TTE, 142.3 TSO Work Order: W059471 Dute: 5 DEC 2022 for a prop strike inspection per Lycoming SB 533C. repaired by Divco, Inc, see 8130-3 form Invoice # 135976 dated 13 Oct 2022. Fluorescent sump and ring gear. Imensional, and magnetic particle inspected. Magnetic particle inspected connecting rods, raulic pump shaft, fuel pump plunger, fuel pump idler gear, oil pump drive shaft, oil pump ns, and pushrod sockets. V18840 (LW11754), see Aircraft Specialties Service, Inc 8130-3 forms (x2) Work Order 275479 dated (2877, see Aircraft Specialties Services, Inc 8130-3 forms (x2) Work Order 275351 dated schings SL74637. Installed new rocker shafts SL13790A. number 22080225, and P/N: 4370 serial number 22080851. |
| number of fice entries.) | | This engine was Crankense mate penetrant inspec Crankshaft S/N crankshaft S/N crankshaft gear, drive and driven Installed repaire 1 NOV 2022. In 17 OCT 2022. I Installed new ma Cylinders, P/N: | GOLD s Place Ms s disassemb in number T idea access v5379441; idler shafts a gear, thru d camshaft installed ove installed ne installed | led and cleaned PK 146PT was represented by the serial number LV rhauled lifters 7 w rocker arm but del 4371 serial reservances. | Fine: 1408 6 TTE, 142.3 TSO Work Order: W059471 Dute: 5 DEC 2022 for a prop strike inspection per Lycoming SB 533C. repaired by Divco, Inc, see 8130-3 form Invoice # 135976 dated 13 Oct 2022. Fluorescent sump and ring gear. Intensional, and magnetic particle inspected. Magnetic particle inspected connecting rods, traulic pump shaft, fuel pump plunger, fuel pump idler gear, oil pump drive shaft, oil pump ins, and pushrod sockets. V18840 (LW11754), see Aircraft Specialties Service, Inc 8130-3 Work Order 275479 dated 2877, see Aircraft Specialties Services, Inc 8130-3 forms (x2) Work Order 275351 dated ashings SI.74637. Installed new rocker shafts SI.13790A. Insumber 22080225, and P/N: 4370 serial number 22080851. |
| number of fice entries.) | | This engine was Crankense mate penetrant inspec Crankshaft S/N crankshaft S/N crankshaft gear, drive and driven Installed repaire 1 NOV 2022. Ir 17 OCT 2022. 1 Installed new ma Cylinders, P/N; and new ring set Complied with A | GOLD s Place Me s disassemb in number I ited access V5379441: idler shafts gear, thru d camshaft istalled ove installed ac ignetos mo LW-12427, P/N: SL5. I)2004-10 | led and cleaned PK 146PT was r ry housing, oil s 4 was visual, di, idler gear, hyd boits, rocker arm part number LV rhauled lifters 7 w rocker arm bu del 4371 serial r serial numbers 401-SC installee -14 and MSB 4 | Fine: 1408 6 TTE, 142.3 TSO Work Order: W059471 Dute: 5 DEC 2022 for a prop strike inspection per Lycoming SB 533C. repaired by Divco, Inc, see 8130-3 form Invoice # 135976 dated 13 Oct 2022. Fluorescent sump and ring gear. Intensional, and magnetic particle inspected. Magnetic particle inspected connecting rods, raulic pump shaft, fuel pump plunger, fuel pump idler gear, oil pump drive shaft, oil pump ns, and pushrod sockets. VI 8840 (LW 11754), see Aircraft Specialties Service, Inc 8130-3 forms (x2) Work Order 275479 dated (2877, see Aircraft Specialties Services, Inc 8130-3 forms (x2) Work Order 275351 dated shings SL 74637. Installed new rocker shafts SL 13790A. Installed new piston pins SL 13444-1. TSC: inspected crankshaft counterbore recess, installation of crankshaft gear, installation of |
| number of incentries.) ump 7 Qts of | | This engine was Crankense mate penetrant inspec Crankshaft S/N crackshaft gear, drive and driven Installed repaire 1 NOV 2022. In 17 OCT 2022. I Installed new ma Cylinders, P/N: and new ring set Complied with A new dowel, and Complied with A | GOLD S Place Ms s disassemb in number T cited accessor V5379441; idler shafts a gear, thru d camshaft installed ove installed acc installed ac | led and cleaned PK 146PT was represented by the serial part number LV represented by the serial numbers and the se | Time: 1408 6 TTE, 142.3 TSO Work Order: W059471 Dute: 5 DEC 2022 for a prop strike inspection per Lycoming SB 533C. repaired by Divco, Inc, see 8130-3 form Invoice # 135976 dated 13 Oct 2022. Fluorescent sump and ring gear. imensional, and magnetic particle inspected. Magnetic particle inspected connecting rods, resulte pump shaft, fuel pump plunger, fuel pump idler gear, oil pump drive shaft, oil pump ns, and pushrod sockets. V18840 (LW11754), see Aircraft Specialties Service, Inc 8130-3 forms (x2) Work Order 275479 dated 28577, see Aircraft Specialties Services, Inc 8130-3 forms (x2) Work Order 275351 dated 285ngs S1.74637. Installed new rocker shafts S1.13790A. number 22080225, and P/N: 4370 serial number 22080851. 1) 043332-12, 2) 043332-6, 3) 043332-18, and 4) 043088-19 were honed to STD limits d. Installed new piston pins S1.13444-1. 75C: inspected crankshaft counterbore recess, installation of crankshaft gear, installation of |
| number of iffic entries.) ump 7 Qts of | " a | This engine was Crankense mate penetrant inspec Crankshaft S/N crankshaft S/N crankshaft gear, drive and driven Installed repaire 1 NOV 2022. If 17 OCT 2022. I Installed new ma Cylinders, P/N: and new ring set Complied with A new dowel, and i Complied with A P/N: ST-531. Bi | GOLD is Place Mic sides accessory to the mumber I thed accessory 5379441; idler shafts a gear, thru id camshaft istalled over installed over installed net agnetos mo LW-12427, P/N: SL5-AD2004-10 new bolt P-LD 2017-16 ushings did | led and cleaned PK 146PT was r ry housing, oil s 4 was visual, di 6, idler gear, hyd boits, rocker arm part number LV rhauled lifters 7 w rocker arm be del 4371 serial i serial numbers 401-SC installee -14 and MSB 4 N: STD-2246 a 6-11 and MSB 6 not move. | Time: 1408 6 TTE, 142.3 TSO Work Order: W059471 Dute: 5 DEC 2022 for a prop strike inspection per Lycoming SB 533C. repaired by Divco, Inc, see 8130-3 form Invoice # 135976 dated 13 Oct 2022. Fluorescent sump and ring gear. Imensional, and magnetic particle inspected. Magnetic particle inspected connecting rods, raulic pump shaft, fuel pump plunger, fuel pump idler gear, oil pump drive shaft, oil pump ns, and pushrod sockets. V18840 (LW11754), see Aircraft Specialties Service, Inc 8130-3 forms (x2) Work Order 275479 dated (2877, see Aircraft Specialties Services, Inc 8130-3 forms (x2) Work Order 275351 dated schings SL74637. Installed new rocker shafts SL13790A. number 22080225, and P/N: 4370 serial number 22080851. 1) 043332-12, 2) 043332-6, 3) 043332-18, and 4) 043088-19 were boned to STD limits d. Installed new piston pins SL13444-1. 75C; inspected crankshaft counterbore recess, installation of crankshaft gear, installation of and new lock plate. 632 by completion of the connecting rod bushing press out verification procedure using tool |
| number of iffic entries.) ump 7 Qts of | " a | This engine was Crankense mate penetrant inspec Crankshaft S/N crankshaft S/N crankshaft gear, drive and driven Installed repaire 1 NOV 2022. If 17 OCT 2022. I Installed new ma Cylinders, P/N: and new ring set Complied with A new dowel, and i Complied with A P/N: ST-531. Bi | GOLD is Place Mic sides accessory to the mumber I thed accessory 5379441; idler shafts a gear, thru id camshaft istalled over installed over installed net agnetos mo LW-12427, P/N: SL5-AD2004-10 new bolt P-LD 2017-16 ushings did | led and cleaned PK 146PT was r ry housing, oil s 4 was visual, di 6, idler gear, hyd boits, rocker arm part number LV rhauled lifters 7 w rocker arm be del 4371 serial i serial numbers 401-SC installee -14 and MSB 4 N: STD-2246 a 6-11 and MSB 6 not move. | Time: 1408 6 TTE, 142.3 TSO Work Order: W059471 Dute: 5 DEC 2022 for a prop strike inspection per Lycoming SB 533C. repaired by Divco, Inc, see 8130-3 form Invoice # 135976 dated 13 Oct 2022. Fluorescent sump and ring gear. Imensional, and magnetic particle inspected. Magnetic particle inspected connecting rods, raulic pump shaft, fuel pump plunger, fuel pump idler gear, oil pump drive shaft, oil pump ns, and pushrod sockets. V18840 (LW11754), see Aircraft Specialties Service, Inc 8130-3 forms (x2) Work Order 275479 dated (2877, see Aircraft Specialties Services, Inc 8130-3 forms (x2) Work Order 275351 dated schings SL74637. Installed new rocker shafts SL13790A. number 22080225, and P/N: 4370 serial number 22080851. 1) 043332-12, 2) 043332-6, 3) 043332-18, and 4) 043088-19 were boned to STD limits d. Installed new piston pins SL13444-1. 75C; inspected crankshaft counterbore recess, installation of crankshaft gear, installation of and new lock plate. 632 by completion of the connecting rod bushing press out verification procedure using tool |
| ump 7 Qts of | " a | This engine was Crankshaft S/N crankshaft S/N crankshaft S/N crankshaft gear, drive and driven Installed repaire 1 NOV 2022. If 17 OCT 2022. If Installed new ma Cylinders, P/N: and new ring set Complied with A new dowel, and complied with A p/N: ST-531. But Engine was reassed for leak are not problematic services. | GOLD is Place Mic s disassemble is disassemble in number T ined access V5379441: idler shafts i gear, thru d camshaft istailed ove installed ac inst | led and cleaned PK 146PT was reproduced and cleaned PK 146PT was reproduced and cleaned of the second and cleaned of the second and cleaned and cleaned and cleaned and the second and cleaned and the second and cleaned and the second and the secon | Time: 1408 6 TTE, 142.3 TSO Work Order: W059471 Dute: 5 DEC 2022 for a prop strike inspection per Lycoming SB 533C. repaired by Divco, Inc, see 8130-3 form Invoice # 135976 dated 13 Oct 2022. Fluorescent sump and ring gear. mensional, and magnetic particle inspected. Magnetic particle inspected connecting rods, raulic pump shaft, firel pump plunger, fuel pump idler gear, oil pump drive shaft, oil pump ins, and pushrod sockets. V18840 (LW11754), see Aircraft Specialties Service, Inc 8130-3 forms (x2) Work Order 275479 dated (2877, see Aircraft Specialties Services, Inc 8130-3 forms (x2) Work Order 275351 dated sshings SL74637. Installed new rocker shafts SL13790A. number 22080225, and P/N: 4370 serial number 22080851. 1) 043332-12, 2) 043332-6, 3) 043332-18, and 4) 043088-19 were boned to STD limits d. Installed new piston pins SL13444-1. 75C; inspected crankshaft counterbore recess, installation of crankshaft gear, installation of and look plate. 632 by completion of the connecting rod bushing press out verification procedure using tool of main bearings, new rod bolts and nuts, new gaskets, and seals. Engine was run in a test rick was done per Lycoming Overhaul manual No. 60294-7-14, Table of Limits, and |
| ump 7 Qts of | | This engine was Crankshaft S/N crankshaft S/N crankshaft S/N crankshaft gear, drive and driven Installed repaire 1 NOV 2022. If 17 OCT 2022. If Installed new mis Cylinders, P/N: 1 and new ring set Complied with A new dowel, and 1 Complied with A new dowel, and 2 Complied with A p/N: ST-531. But Engine was reass cell for leak and applicable service. | GOLD is Place Me disassemble s disassemble h number T ted access V5379441; diler shafts o gear, thru d camshaft stalled ove installed ac agnetos mo LW-12427, P/N: SL5- kD2004-10 new bolt Pi AD 2017-16 ushings did sembled us operations te publicati | led and cleaned PK 146PT was r ry housing, oil s 4 was visual, di , idler gear, hyd boits, rocker arm part number LV rhunded lifters 7 w rocker arm bu del 4371 serial r , serial numbers 101-SC installed 14 and MSB 4 N: STD-2246 a 6-11 and MSB 6 not move. ing new rod and check. All wor | Time: 1408 6 TTE, 142.3 TSO Work Order: W059471 Dute: 5 DEC 2022 for a prop strike inspection per Lycoming SB 533C. repaired by Divco, Inc, see 8130-3 form Invoice # 135976 dated 13 Oct 2022. Fluorescent sump and ring gear. mensional, and magnetic particle inspected. Magnetic particle inspected connecting rods, and pushrod sockets. V18840 (LW11754), see Aircraft Specialties Service, Inc 8130-3 forms (x2) Work Order 275479 dated (2877, see Aircraft Specialties Services, Inc 8130-3 forms (x2) Work Order 275351 dated ashings \$1.74637. Installed new rocker shafts \$1.13790A. Installed new piston pins \$1.13444-1. TSC; inspected crankshaft counterbore recess, installation of crankshaft gear, installation of and new lock plate. d main bearings, new rod bolts and nuts, new gaskets, and seals. Engine was run in a test rick was done per Lycoming Overhaul manual No. 60294-7-14, Table of Limits, and |
| Alteration: Number of iffic entries.) sump 7 Qts of | | This engine was Crankshaft S/N crankshaft S/N crankshaft S/N crankshaft gear, drive and driven Installed repaire 1 NOV 2022. If 17 OCT 2022. If Installed new mis Cylinders, P/N: 1 and new ring set Complied with A new dowel, and 1 Complied with A new dowel, and 2 Complied with A p/N: ST-531. But Engine was reass cell for leak and applicable service. | GOLD is Place Me disassemble s disassemble h number T ted access V5379441; diler shafts o gear, thru d camshaft stalled ove installed ac agnetos mo LW-12427, P/N: SL5- kD2004-10 new bolt Pi AD 2017-16 ushings did sembled us operations te publicati | led and cleaned PK 146PT was r ry housing, oil s 4 was visual, di , idler gear, hyd boits, rocker arm part number LV rhunded lifters 7 w rocker arm bu del 4371 serial r , serial numbers 101-SC installed 14 and MSB 4 N: STD-2246 a 6-11 and MSB 6 not move. ing new rod and check. All wor | Time: 1408 6 TTE, 142.3 TSO Work Order: W059471 Dute: 5 DEC 2022 for a prop strike inspection per Lycoming SB 533C. repaired by Divco, Inc, see 8130-3 form Invoice # 135976 dated 13 Oct 2022. Fluorescent sump and ring gear. mensional, and magnetic particle inspected. Magnetic particle inspected connecting rods, and pushrod sockets. V18840 (LW11754), see Aircraft Specialties Service, Inc 8130-3 forms (x2) Work Order 275479 dated (2877, see Aircraft Specialties Services, Inc 8130-3 forms (x2) Work Order 275351 dated ashings \$1.74637. Installed new rocker shafts \$1.13790A. Installed new piston pins \$1.13444-1. TSC; inspected crankshaft counterbore recess, installation of crankshaft gear, installation of and new lock plate. d main bearings, new rod bolts and nuts, new gaskets, and seals. Engine was run in a test rick was done per Lycoming Overhaul manual No. 60294-7-14, Table of Limits, and |
| number of office entries.) ump 7 Qts of | | This engine was Crankshaft S/N crankshaft S/N crankshaft S/N crankshaft gear, drive and driven Installed repaire 1 NOV 2022. If 17 OCT 2022. If Installed new mis Cylinders, P/N: 1 and new ring set Complied with A new dowel, and 1 Complied with A new dowel, and 2 Complied with A p/N: ST-531. But Engine was reass cell for leak and applicable service. | GOLD is Place Me disassemble s disassemble h number T ted access V5379441; diler shafts o gear, thru d camshaft stalled ove installed ac agnetos mo LW-12427, P/N: SL5- kD2004-10 new bolt Pi AD 2017-16 ushings did sembled us operations te publicati | led and cleaned PK 146PT was r ry housing, oil s 4 was visual, di , idler gear, hyd boits, rocker arm part number LV rhunded lifters 7 w rocker arm bu del 4371 serial r , serial numbers 101-SC installed 14 and MSB 4 N: STD-2246 a 6-11 and MSB 6 not move. ing new rod and check. All wor | Time: 1408 6 TTE, 142.3 TSO Work Order: W059471 Dute: 5 DEC 2022 for a prop strike inspection per Lycoming SB 533C. repaired by Divco, Inc, see 8130-3 form Invoice # 135976 dated 13 Oct 2022. Fluorescent sump and ring gear. mensional, and magnetic particle inspected. Magnetic particle inspected connecting rods, raulic pump shaft, firel pump plunger, fuel pump idler gear, oil pump drive shaft, oil pump ins, and pushrod sockets. V18840 (LW11754), see Aircraft Specialties Service, Inc 8130-3 forms (x2) Work Order 275479 dated (2877, see Aircraft Specialties Services, Inc 8130-3 forms (x2) Work Order 275351 dated sshings SL74637. Installed new rocker shafts SL13790A. number 22080225, and P/N: 4370 serial number 22080851. 1) 043332-12, 2) 043332-6, 3) 043332-18, and 4) 043088-19 were boned to STD limits d. Installed new piston pins SL13444-1. 75C; inspected crankshaft counterbore recess, installation of crankshaft gear, installation of and look plate. 632 by completion of the connecting rod bushing press out verification procedure using tool of main bearings, new rod bolts and nuts, new gaskets, and seals. Engine was run in a test rick was done per Lycoming Overhaul manual No. 60294-7-14, Table of Limits, and |
| number of iffic entries.) ump 7 Qts of | | This engine was Crankshaft S/N crankshaft S/N crankshaft S/N crankshaft gear, drive and driven Installed repaire 1 NOV 2022. If 17 OCT 2022. If Installed new mis Cylinders, P/N: 1 and new ring set Complied with A new dowel, and 1 Complied with A new dowel, and 2 Complied with A p/N: ST-531. But Engine was reass cell for leak and applicable service. | GOLD is Place Me disassemble s disassemble h number T ted access V5379441; diler shafts o gear, thru d camshaft stalled ove installed ac agnetos mo LW-12427, P/N: SL5- kD2004-10 new bolt Pi AD 2017-16 ushings did sembled us operations te publicati | led and cleaned PK 146PT was r ry housing, oil s 4 was visual, di , idler gear, hyd boits, rocker arm part number LV rhunded lifters 7 w rocker arm bu del 4371 serial r , serial numbers 101-SC installed 14 and MSB 4 N: STD-2246 a 6-11 and MSB 6 not move. ing new rod and check. All wor | Time: 1408 6 TTE, 142.3 TSO Work Order: W059471 Dute: 5 DEC 2022 for a prop strike inspection per Lycoming SB 533C. repaired by Divco, Inc, see 8130-3 form Invoice # 135976 dated 13 Oct 2022. Fluorescent sump and ring gear. imensional, and magnetic particle inspected. Magnetic particle inspected connecting rods, resulte pump shaft, fuel pump plunger, fuel pump idler gear, oil pump drive shaft, oil pump ns, and pushrod sockets. V18840 (LW11754), see Aircraft Specialties Service, Inc 8130-3 forms (x2) Work Order 275479 dated 28577, see Aircraft Specialties Services, Inc 8130-3 forms (x2) Work Order 275351 dated 285nings SL74637. Installed new rocker shafts SL13790A. number 22080225, and P/N: 4370 serial number 22080851. 1) 043332-12, 2) 043332-6, 3) 043332-18, and 4) 043088-19 were honed to STO limits d Installed new piston pins SL13444-1. 75C; inspected crankshaft counterbore recess, installation of crankshaft gear, installation of and new lock plate. 632 by completion of the connecting rod bushing press out verification procedure using tool d main bearings, new rod bolts and nuts, new gaskets, and seals. Engine was run in a test rick was done per Lycoming Overhaul manual No. 60294-7-14, Table of Limits, and hove was repaired and inspected I/A/W current FAA Regulations and found Airworthy for repair are on file at this Repair Station under above work order. |

| | YEAR | Ø AI | SERVICE, INC. | FT | nd Alteration cate Number of specific entres |
|---|--------------|--|---|--|---|
| - | DATE | 300 Win | es Way, Belgrade, MT 59714 (466) 49 CRS QMSR154% (KRZN) | W-1412 | - |
| | | DATE REGISTRATION IN 171H | ENGINE SERIAL # 0-360-CIF L-46595-36A | 142.3 142 | |
| | | inspection completed this date. Cleans detergent) and filter. Checked alternate engine with new engine mounts. Had a assembly, 978 BA6110 Rev. 6. Check been inspected in accordance with a 10 condition. Alan C. Wann A&P 2186273 | e Checked starter Pressure checker rack in the left muffler repaired. Instead ad controls. Washed and ran engine. | d exhaust system. Installed talled a new Brackett air filte. I certify that this entire has | |
| | | | | | |
| | | | | | |
| | | | | | |
| _ | | | | | |
| ALC: N | | | | | |
| MA - | | | | | |
| DA | | | | | |
| 2 | | | | | |
| 2 | | | | | *** |
| 2 | | | | | 228 |
| d Atterations to Humber can | 74 | NS171H | Date 01-09-2025 | TACIA | |
| 1 Atterations to Number of ecific entries.) | YEAR | LYCOMING 0-360-C1F | Date 01-09-2025 S/N L-40595-36A | TACH: 168,3 | TSN: - |
| Alterations to Humber of ecitic entries.) | YIAA GATI | LYCOMING 0-360-C1F - Removed Engine for prop str | 6/N L-40595-36A ke inspection. | 168.3 | 168.3 |
| Atterations to Number of ecitic entries.) | _ | LYCOMING 0-360-C1F - Removed Engine for prop str | 6/N L-40595-36A ke inspection. | 168.3 | 168.3 |
| Afterations to humber of ecitic entries.) | _ | LYCOMING 0-380-C1F - Removed Engine for prop str. - This engine was disassemble - C/W AD2004-10-14 and MSE - No new or recurring AD'S due - Reinstalled engine on aircraft | 8/N L-40595-36A ke inspection. d and cleaned for prop strike is 475C Inspected and installed at this time. | 168.3 Inspection per Lycoming I new bolt P/N STD-224 | 168.3 3 SB 533C. 46 and new lock plate. |
| Atterations a Number of actic entries.) | _ | LYCOMING 0-380-C1F - Removed Engine for prop str This engine was disassemble - C/W AD2004-10-14 and MSE - No new or recurring AD'S du - Reinstalled engine on aircraft - Drained engine oil, Removed with Aeroshell W 100 Plus Avi | S/N L-40595-36A ke inspection. d and cleaned for prop strike is 475C Inspected and installed at this time. oil filter, Inspected oil filter. No ation oil 7 quarts and AAA811 | nspection per Lycoming I new bolt P/N STD-224 or discrepancies noted. | 168.3 3 SB 533C. 46 and new lock plate. |
| Attorations to Humber of ecitic entries.) | _ | LYCOMING 0-360-C1F - Removed Engine for prop striction of the engine was disassemble. C/W AD2004-10-14 and MSE. No new or recurring AD'S due. Reinstalled engine on aircraft. Drained engine oil, Removed with Aeroshell W 100 Plus Av. Checked compressions 1.) Av. | 8/N L-40595-36A Ke inspection. d and cleaned for prop strike is 475C Inspected and installed at this time. oil filter, Inspected oil filter. No ation oil 7 quarts and AA4811 /80 2.) 77/80 3.) 76/80 4.) 76 | nspection per Lycoming I new bolt P/N STD-224 or discrepancies noted. | 168.3 3 SB 533C. 46 and new lock plate. |
| Atterations to Number of ectic entries.) | _ | LYCOMING 0-360-C1F - Removed Engine for prop str This engine was disassemble - C/W AD2004-10-14 and MSE - No new or recurring AD'S due - Reinstalled engine on aircraft - Drained engine oil, Removed with Aeroshell W 100 Plus Avi - Checked compressions 1.) 76 - Removed, Inspected, cleaned - Replaced air filter BA-6108 | S/N L-40595-36A ke inspection. d and cleaned for prop strike is 475C Inspected and installed at this time. oil filter, Inspected oil filter. No attion oil 7 quarts and AA4811 /80 2.) 77/80 3.) 76/80 4.) 76 and gaped spark plugs. | nspection per Lycoming I new bolt P/N STD-224 or discrepancies noted. | 168.3 3 SB 533C. 46 and new lock plate. |
| Atterations to Number of ecitic entries.) | _ | LYCOMING 0-360-C1F - Removed Engine for prop str This engine was disassemble - CW AD2004-10-14 and MSE - No new or recurring AD'S due - Reinstalled engine on aircraft - Drained engine oil, Removed with Aeroshell W 100 Plus Avi - Checked compressions 1.) 76 - Removed, Inspected, cleaned - Replaced air filter BA-6108 - Cleaned and inspected fuel se | S/N L-40595-36A ke inspection. d and cleaned for prop strike is 475C Inspected and installed at this time. oil filter, Inspected oil filter. No attion oil 7 quarts and AA4811 /80 2.) 77/80 3.) 76/80 4.) 76 I and gaped spark plugs. | nspection per Lycoming I new bolt P/N STD-224 or discrepancies noted. | 168.3 3 SB 533C. 46 and new lock plate. |
| Alterations to Number of ecific entries.) | _ | LYCOMING 0-360-C1F - Removed Engine for prop str This engine was disassemble - CW AD2004-10-14 and MSE - No new or recurring AD'S due - Reinstalled engine on aircraft - Drained engine oil, Removed - with Aeroshell W 100 Plus Avi - Checked compressions 1, 76 - Removed, Inspected, cleaned - Replaced air filter BA-6108 - Cleaned and inspected fuel so - Inspected Exhaust - Cleaned Engine and Lubed Ei | 8/N L-40595-36A ke inspection. d and cleaned for prop strike it 475C Inspected and installed at this time. oil filter, Inspected oil filter. No ation oil 7 quarts and AA4811 /80 2.) 77/80 3.) 76/80 4.) 76 I and gaped spark plugs. creens. | nspection per Lycoming I new bolt P/N STD-224 or discrepancies noted. | 168.3 3 SB 533C. 46 and new lock plate. |
| Afterations le Number of ectic entries.) | _ | LYCOMING 0-360-C1F - Removed Engine for prop str This engine was disassemble - CW AD2004-10-14 and MSE - No new or recurring AD'S due - Reinstalled engine on aircraft - Drained engine oil, Removed - with Aeroshell W 100 Plus Avi - Checked compressions 1, 76 - Removed, Inspected, cleaned - Replaced air filter BA-6108 - Cleaned and inspected fuel se - Inspected Exhaust - Cleaned Engine and Lubed Ei - Ran engine leak and ops chee | S/N L-40595-36A ke inspection. d and cleaned for prop strike is 475C Inspected and installed at this time. oil filter, Inspected oil filter. No ation oil 7 quarts and AA4811 /80 2.) 77/80 3.) 76/80 4.) 76 I and gaped spark plugs. preens. orgine Controls. iked good at this time. | nspection per Lycoming I new bolt P/N STD-224 or discrepancies noted. | 168.3 3 SB 533C. 46 and new lock plate. |
| a Atterations to Number of ecitic entries.) | _ | LYCOMING 0-360-C1F Removed Engine for prop strict This engine was disassemble. C/W AD2004-10-14 and MSE. No new or recurring AD'S due. Reinstalled engine on aircraft. Drained engine oil, Removed with Aeroshell W 100 Plus Avi. Checked compressions 1.) 76. Removed, Inspected, cleaned. Replaced air filter BA-6108. Cleaned and inspected fuel see Inspected Exhaust. Cleaned Engine and Lubed Et. Ran engine leak and ops checked. All work performed IAW Lycomitation. | S/N L-40595-36A ke inspection. d and cleaned for prop strike is 475C Inspected and installed at this time. oil filter, Inspected oil filter. No ation oil 7 quarts and AA4811 /80 2.) 77/80 3.) 76/80 4.) 76 and gaped spark plugs. creens. ogine Controls. sked good at this time. ning Overhaul Manual. | 168.3 Inspection per Lycoming I new bolt P/N STD-224 D discrepancies noted. 0-2 oil filter. //80 | 9 SB 533C. 16 and new lock plate. Serviced engine |
| Alterations to Number of ecitic entries.) | _ | LYCOMING 0-360-C1F - Removed Engine for prop strict This engine was disassemble CW AD2004-10-14 and MSE No new or recurring AD'S due Reinstalled engine on aircraft. - Drained engine oil, Removed with Aeroshell W 100 Plus Awi Checked compressions 1.) 76 - Removed, Inspected, cleaned Replaced air filter BA-6108 - Cleaned and inspected fuel se Inspected Exhaust. - Cleaned Engine and Lubed Er Ran engine leak and ops checked and work performed IAW Lycom COMPLIED WITH Engine100 HR | S/N L-40595-36A ke inspection. d and cleaned for prop strike is 475C Inspected and installed at this time. oil filter, Inspected oil filter. No ation oil 7 quarts and AA4811 /80 2.) 77/80 3.) 76/80 4.) 76 and gaped spark plugs. creens. organe Controls. cked good at this time. ning Overhaul Manual. NSPECTION THIS DATE IN | 168.3 Inspection per Lycoming I new bolt P/N STD-224 O discrepancies noted. 0-2 oil filter. //80 ACCORDANCE WITH | 9 SB 533C. 16 and new lock plate. Serviced engine |
| d Alterations le Number of ectic entries.) | _ | LYCOMING 0-360-C1F Removed Engine for prop strict This engine was disassemble. C/W AD2004-10-14 and MSE. No new or recurring AD'S due. Reinstalled engine on aircraft. Drained engine oil, Removed with Aeroshell W 100 Plus Avi. Checked compressions 1.) 76. Removed, Inspected, cleaned. Replaced air filter BA-6108. Cleaned and inspected fuel see Inspected Exhaust. Cleaned Engine and Lubed Et. Ran engine leak and ops checked. All work performed IAW Lycomitation. | S/N L-40595-36A ke inspection. d and cleaned for prop strike is 475C Inspected and installed at this time. oil filter, Inspected oil filter. No ation oil 7 quarts and AA4811 /80 2.) 77/80 3.) 76/80 4.) 76 and gaped spark plugs. creens. organe Controls. cked good at this time. ning Overhaul Manual. NSPECTION THIS DATE IN | 168.3 Inspection per Lycoming I new bolt P/N STD-224 O discrepancies noted. 0-2 oil filter. //80 ACCORDANCE WITH | 9 SB 533C. 16 and new lock plate. Serviced engine |
| a Atterations to Number of ecitic entries.) | _ | LYCOMING 0-360-C1F - Removed Engine for prop strict This engine was disassemble CW AD2004-10-14 and MSE No new or recurring AD'S due Reinstalled engine on aircraft. - Drained engine oil, Removed with Aeroshell W 100 Plus Awi Checked compressions 1.) 76 - Removed, Inspected, cleaned Replaced air filter BA-6108 - Cleaned and inspected fuel se Inspected Exhaust. - Cleaned Engine and Lubed Er Ran engine leak and ops checked and work performed IAW Lycom COMPLIED WITH Engine100 HR | S/N L-40595-36A ke inspection. d and cleaned for prop strike is 475C Inspected and installed at this time. oil filter, Inspected oil filter. No ation oil 7 quarts and AA4811 /80 2.) 77/80 3.) 76/80 4.) 76 and gaped spark plugs. creens. organe Controls. cked good at this time. ning Overhaul Manual. NSPECTION THIS DATE IN | nspection per Lycoming I new bolt P/N STD-224 D discrepancies noted. 0-2 oil filter. /80 ACCORDANCE WITH I return to service. Jason Barb | 9 SB 533C. 16 and new lock plate. Serviced engine |
| Afterations to Number of social entries.) | _ | LYCOMING 0-360-C1F - Removed Engine for prop strict This engine was disassemble CW AD2004-10-14 and MSE No new or recurring AD'S due Reinstalled engine on aircraft. - Drained engine oil, Removed with Aeroshell W 100 Plus Awi Checked compressions 1.) 76 - Removed, Inspected, cleaned Replaced air filter BA-6108 - Cleaned and inspected fuel se Inspected Exhaust. - Cleaned Engine and Lubed Er Ran engine leak and ops checked and work performed IAW Lycom COMPLIED WITH Engine100 HR | S/N L-40595-36A ke inspection. d and cleaned for prop strike is 475C Inspected and installed at this time. oil filter, Inspected oil filter. No ation oil 7 quarts and AA4811 /80 2.) 77/80 3.) 76/80 4.) 76 and gaped spark plugs. creens. organe Controls. cked good at this time. ning Overhaul Manual. NSPECTION THIS DATE IN | nspection per Lycoming I new bolt P/N STD-224 D discrepancies noted. 0-2 oil filter. //80 ACCORDANCE WITH In return to service. | 9 SB 533C. 16 and new lock plate. Serviced engine |
| A Atterations to Number of ecitic entries.) | _ | LYCOMING 0-360-C1F - Removed Engine for prop strict This engine was disassemble CW AD2004-10-14 and MSE No new or recurring AD'S due Reinstalled engine on aircraft. - Drained engine oil, Removed with Aeroshell W 100 Plus Awi Checked compressions 1.) 76 - Removed, Inspected, cleaned Replaced air filter BA-6108 - Cleaned and inspected fuel se Inspected Exhaust. - Cleaned Engine and Lubed Er Ran engine leak and ops checked and work performed IAW Lycom COMPLIED WITH Engine100 HR | S/N L-40595-36A ke inspection. d and cleaned for prop strike is 475C Inspected and installed at this time. oil filter, Inspected oil filter. No ation oil 7 quarts and AA4811 /80 2.) 77/80 3.) 76/80 4.) 76 and gaped spark plugs. creens. organe Controls. cked good at this time. ning Overhaul Manual. NSPECTION THIS DATE IN | nspection per Lycoming I new bolt P/N STD-224 D discrepancies noted. 0-2 oil filter. /80 ACCORDANCE WITH I return to service. Jason Barb | 9 SB 533C. 16 and new lock plate. Serviced engine |
| 1 Atterations la Number of social entries.) | _ | LYCOMING 0-360-C1F - Removed Engine for prop strict This engine was disassemble CW AD2004-10-14 and MSE No new or recurring AD'S due Reinstalled engine on aircraft. - Drained engine oil, Removed with Aeroshell W 100 Plus Awi Checked compressions 1.) 76 - Removed, Inspected, cleaned Replaced air filter BA-6108 - Cleaned and inspected fuel se Inspected Exhaust. - Cleaned Engine and Lubed Er Ran engine leak and ops checked and work performed IAW Lycom COMPLIED WITH Engine100 HR | S/N L-40595-36A ke inspection. d and cleaned for prop strike is 475C Inspected and installed at this time. oil filter, Inspected oil filter. No ation oil 7 quarts and AA4811 /80 2.) 77/80 3.) 76/80 4.) 76 and gaped spark plugs. creens. organe Controls. cked good at this time. ning Overhaul Manual. NSPECTION THIS DATE IN | nspection per Lycoming I new bolt P/N STD-224 of discrepancies noted. 0-2 oil filter. //80 ACCORDANCE WITH I return to service. Jason Barb | 9 SB 533C. 16 and new lock plate. Serviced engine |
| d Alterations ale Number of pecific entries;) | _ | LYCOMING 0-360-C1F - Removed Engine for prop strict This engine was disassemble CW AD2004-10-14 and MSE No new or recurring AD'S due Reinstalled engine on aircraft. - Drained engine oil, Removed with Aeroshell W 100 Plus Awi Checked compressions 1.) 76 - Removed, Inspected, cleaned Replaced air filter BA-6108 - Cleaned and inspected fuel se Inspected Exhaust. - Cleaned Engine and Lubed Er Ran engine leak and ops checked and work performed IAW Lycom COMPLIED WITH Engine100 HR | S/N L-40595-36A ke inspection. d and cleaned for prop strike is 475C Inspected and installed at this time. oil filter, Inspected oil filter. No ation oil 7 quarts and AA4811 /80 2.) 77/80 3.) 76/80 4.) 76 and gaped spark plugs. creens. organe Controls. cked good at this time. ning Overhaul Manual. NSPECTION THIS DATE IN | nspection per Lycoming I new bolt P/N STD-224 of discrepancies noted. 0-2 oil filter. //80 ACCORDANCE WITH I return to service. Jason Barb | 9 SB 533C. 16 and new lock plate. Serviced engine |

