



For: N 745LS

Aircraft Propeller Log

PROPELLER MAINTENANCE RECORD

Propeller Mfr. Sensenich Hub Model 74Dm658-1-52
Hub Serial No. A49443 Blade Design _____
Blade S/N _____ Blade S/N _____ Blade S/N _____ Blade S/N _____
Clamp S/N _____ Clamp S/N _____ Clamp S/N _____ Clamp S/N _____
Blade Angles: Low _____ High/Feather _____ Start _____ Reverse _____
Deice Boot _____ Wire Harness _____
Manufactures recommended TBO as of Feb. 29, 2012 is 2000 hours and/or _____ months

Aircraft Mfr. _____ Model _____ Registration _____
Engine Mfr. _____ Model _____

Owners Name: _____
Address: _____

PROPELLER MAINTENANCE LOG

Description of Inspections and Repairs
ALL DATA must be endorsed with the name, rating and certificate number of either the FAA Repair Station or the mechanic.

DATE	TOTAL TIME	TIME S.O.H.	DESCRIPTION OF WORK	SIGNATURE
2-29-12			 PRECISION PROPELLER SERVICE, INC. 4777 W AERONCA ST. BOISE, IDAHO U.S.A. 208-344-5161 Make: Sensenich Model: 74DM6S8-1-52 S/N: A49443 TT: Unknown TSOH: -0- DESCRIPTION OF WORK ACCOMPLISHED Overhauled and reconditioned in accordance with Sensenich S/M SPRM-590. Recontoured blade leading and tips and reconditioned prop. Set balance. Checked blade width and thickness. Repitched prop from 2 52" Set angles and face alignment. Liquid penetrant inspected prop and spacer. Alodine and painted Anodized spacer and installed. MAINTENANCE RELEASE The work and/or inspection of the part or parts identified heron has been done in accordance with current Federal Administration Regulations and was found to be airworthy. Pertinent details of the repair are on file at this repair under Work Order No: 27288 Dated: February 29, 2012 Signature of authorized person <u>Brian Hefeld</u> F.A.A. CERTIFIED REPAIR STATION NO. FG6R5	



PROPELLER MAINTENANCE LOG

Description of Inspections and Repairs
ALL DATA must be endorsed with the name, rating and certificate number of either the FAA Repair Station or the mechanic.

DATE	TOTAL TIME	TIME S.O.H.	DESCRIPTION OF WORK	SIGNATURE
2-3-12		0.9	INSTALLED PROPELLER ONTO CITABRIA N745LS THIS DATE. PMP TRACK CHECK OK. <u>Colton Pemberton</u> 2165146 A4P Installed on Bellanca Citabria 7GCAA SN: 291-74 N745LS Date: 5/27/2011 Tach Time: 3405.87 3445.56 Inspected propeller in accordance with FAR 43 Appendix D. Checked for any applicable AD notes, none due. I certify that this propeller has been inspected per FAR part 43 Appendix D and found to be in an airworthy condition. Propeller returned to service this date. Ryan A. Pemberton A&P 2754837IA <u>Ryan A. Pemberton</u>	



PROPELLER MAINTENANCE LOG

Description of Inspections and Repairs
ALL DATA must be endorsed with the name, rating and certificate number of either
the FAA Repair Station or the mechanic.

DATE	TOTAL TIME	TIME S.O.H.	DESCRIPTION OF WORK	SIGNATURE
			Installed on Bellanca Citabria 7GCAA SN: 291-74 N745LS Date: 5/8/2013 Tach Time: 3187.05 Inspected propeller in accordance with FAR 43 Appendix D, ANNUAL INSPECTION. Checked for any applicable AD notes, none due. I certify that this propeller has been inspected per FAR part 43 Appendix D, ANNUAL INSPECTION and found to be in an airworthy condition. Propeller returned to service this date. Ryan A. Pemberton A&P 2754837IA 	
			Installed on Bellanca Citabria 7GCAA SN: 291-74 N745LS Date: 8/25/14 Tach Time: 3213.08 Inspected propeller in accordance with FAR 43 Appendix D, ANNUAL INSPECTION. Checked for any applicable AD notes, none due. I certify that this propeller has been inspected per FAR part 43 Appendix D, ANNUAL INSPECTION and found to be in an airworthy condition. Propeller returned to service this date. Ryan A. Pemberton A&P 2754837 IA 	



PROPELLER MAINTENANCE LOG

Description of Inspections and Repairs
ALL DATA must be endorsed with the name, rating and certificate number of either
the FAA Repair Station or the mechanic.


DATE	TOTAL TIME	TIME S.O.H.	DESCRIPTION OF WORK	
			Date: 9/25/2015 Tach Time: 3221.34 hrs Inspected propeller in accordance with FAR 43 Appendix D, ANNUAL INSPECTION. Checked for any applicable AD notes, none due. I certify that this propeller has been inspected per FAR part 43 Appendix D, ANNUAL INSPECTION and found to be in an airworthy condition. Propeller returned to service this date. Ryan A. Pemberton A&P 2754837 IA 	
			Installed on Bellanca Citabria 7GCAA SN: 291-74 N745LS Date: 9/27/16 Tach Time: 3233.97 hrs TTSMOH:88.41hrs Inspected propeller in accordance with FAR 43 Appendix D, ANNUAL INSPECTION. Checked for any applicable AD notes, none due. I certify that this propeller has been inspected per FAR part 43 Appendix D, ANNUAL INSPECTION and found to be in an airworthy condition. Propeller returned to service this date. Ryan A. Pemberton A&P 2754837 IA 	

PROPELLER MAINTENANCE LOG

Description of Inspections and Repairs
ALL DATA must be endorsed with the name, rating and certificate number of either the FAA Repair Station or the mechanic.

DATE	WORK	SIGNATURE
Installed on Bellanca Citabria 7GCAA SN: 291-74 N745LS Date: 10/27/2017 Tach Time: 3252.06 hrs TTSMOH: 106.05hrs	Inspected propeller in accordance with FAR 43 Appendix D, ANNUAL INSPECTION. Checked for any applicable AD notes, none due. I certify that this propeller has been inspected per FAR part 43 Appendix D, ANNUAL INSPECTION and found to be in an airworthy condition. Propeller returned to service this date.	Ryan A. Pemberton A&P 2754837 IA 
Installed on Bellanca Citabria 7GCAA SN: 291-74 N745LS Date: 1/7/2019 Tach Time: 3258.17 hrs TTSMOH: 112.16hrs		
Inspected propeller in accordance with FAR 43 Appendix D, ANNUAL INSPECTION. Checked for any applicable AD notes, none due. I certify that this propeller has been inspected per FAR part 43 Appendix D, ANNUAL INSPECTION and found to be in an airworthy condition. Propeller returned to service this date.		Ryan A. Pemberton A&P 2754837 IA 

PROPELLER MAINTENANCE LOG

ALL DATA			er
DATE	TOTAL TIME	TIME S.O.H.	SIGNATURE
			Installed on Bellanca Citabria 7GCAA SN: 291-74 N745LS Date: 3/13/2020 Tach Time: 3277.78 hrs TTSMOH: 131.77hrs
			Inspected propeller in accordance with FAR 43 Appendix D, ANNUAL INSPECTION. Checked for any applicable AD notes, none due. I certify that this propeller has been inspected per FAR part 43 Appendix D, ANNUAL INSPECTION and found to be in an airworthy condition. Propeller returned to service this date.
			Ryan A. Pemberton A&P 2754837 IA 
4-23-21	TACH	3371.46	SPAN 165.45 ANNUAL INSPECTION NO ADS AT THIS TIME FOUND AIRWORTHY. Next On AFD 3577 IA

PROPELLER MAINTENANCE LOG				
Description of Inspections and Repairs				
ALL DATA must be endorsed with the name, rating and certificate number of either the FAA Repair Station or the mechanic.				
DATE	TOTAL TIME	TIME S.O.H.	DESCRIPTION OF WORK	SIGNATURE
			Late Aircraft Repair	
8-3-2022	Tach 3355.46	N745LS Bellanca 7GCAA	Dress blades as needed and inspect propeller IAW FAR 43 Appendix D.	
I certify that this Propeller has been inspected in accordance with a 100hr/Annual inspection and is found to be in an Airworthy condition at this time.				
Kevin Late	AP3112349IA			

[illegible]