



The Standard

PROPELLER LOG

ABA-6P-1

OLD LogBook Full



SOUTH COAST PROPELLER SERVICE, INC.



FAA Approved Repair Station
S6PR302X

1-866-875-6377
205-426-7022
FAX 205-426-7026

5750 Durose Drive
Bessemer, AL 35022

PROPELLER LOGBOOK



The Standard

PROPELLER LOG

ASA-SP-1

OLD LogBook Full



COAST PROPELLER SERVICE



☐ HUB & BL

N50071 AIR TRACTOR S/N 402B-1019 HOBBS: 7814.7 10/15/2021

MODEL: HC-B3TN-3D S/N BUA21085 BLADE L52588, L52594, L52595

Year: _____

Date: _____

Next Inspection

Due: _____

Performed 100 hour Inspection IAW Hartzell Maintenance Manual and FAR 43 Appendix D. Checked for cracks and leaks, checked bolts, screws and blades. Greased hub. I certify that this propeller has been inspected IAW Hartzell 100 hour inspection and is deemed in an airworthy condition for safe operation. Return to service.

END _____

Robert L. Montgomery AP3439772IA

Total Time _____

Year: _____

Date: _____

Next Inspection

Due: _____

N50071 AIR TRACTOR S/N 402B-1019 HOBBS: 7904.3 1/23/2022

MODEL: HC-B3TN-3D S/N BUA21085 BLADE L52588, L52594, L52595

Performed 100 hour Inspection IAW Hartzell Maintenance Manual and FAR 43 Appendix D.

Checked for cracks and leaks, checked bolts, screws and blades. Greased hub. I certify that this propeller has been inspected IAW Hartzell 100 hour inspection and is deemed in an airworthy condition for safe operation. Return to service.

END _____

Robert L. Montgomery AP3439772IA

Year: _____

Date: _____

Next Inspection

Due: _____

Time Since
Overhaul

Mech. Cert. # or Repair Station # _____

N50071 AIR TRACTOR S/N 402B-1019 HOBBS: 8002.1 3/3/2022

MODEL: HC-B3TN-3D S/N BUA21065 BLADE L52588, L52594, L52595

ALTERATIONS ☐

Year: _____

Date: _____

Next Inspection

Due: _____

Performed 100 hour inspection IAW Hartzell Maintenance Manual and FAR 43 Appendix D. Checked for cracks and leaks, checked bolts, screws and blades. Greased hub. I certify that this propeller has been inspected IAW Hartzell 100 hour inspection and is deemed in an airworthy condition for safe operation. Return to service.

END _____

Robert L. Montgomery AP3439772IA

Year: _____

Date: _____

Next Inspection

Due: _____

N50071 AIR TRACTOR S/N 402-0774 TACH: 8094.7 ACTT: 8094.7 1/15/2023

Model: HC-B3TN-3D S/N BUA21065 Blades: L52588, L52594, L52595

Performed Annual Inspection IAW Hartzell maintenance Manual. Checked for cracks and leaks, checked bolts, screws and blades. Greased hub. All AD's checked through bi-weekly 2023-02. Recurring AD 2005-14-12 complied with by visual and torque test. I certify that this propeller has been inspected IAW Hartzell Annual Inspection and FAR 43 Appendix D and is deemed in an airworthy condition for safe operation. Return to service.

Year: _____

Date: _____

Next Inspection

Due: _____

Robert L. Montgomery AP3439772IA

Time Since
Overhaul

Mech. Cert. # or Repair Station # _____

☐ HUB 8

N50071 AIR TRACTOR S/N 402-0774 TACH: 8207.8 ACTT: 8207.8 3/9/2024

Model: HC-B3TN-3D S/N BUA21065 Blades: L52588, L525594, L52595

Year: _____

Date: _____

Next Inspec

Due: _____

Performed Annual Inspection IAW Hartzell maintenance Manual. Checked for cracks and leaks, checked bolts, screws and blades. Greased hub. All AD's checked through bi-weekly 2024-05. Recurring AD 2005-14-12 complied with by visual and torque test. I certify that this propeller has been inspected IAW Hartzell Annual Inspection and FAR 43 Appendix D and is deemed in an airworthy condition for safe operation. Return to service.

Robert L. Montgomery AP3439772IA END _____

Year: _____

Robert L. Montgomery AP3439772IA

Date: _____

Next Inspection
Due: _____

Time Since
Overhaul _____

Mech. Cert. # or Repair Station # _____

Year: _____

Total Time
in Service _____

Description _____

Date: _____

Next Inspection
Due: _____

Time Since
Overhaul _____

Mech. Cert. # or Repair Station # _____

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Date: April 24, 2025

Make: Hartzell

Model: HC-B3TN-3D

S/N: BUA21065

Hobbs Time: 8262.4

TSO: 305.4



Phone: 432-249-0576

Performed annual inspection with reference to FAR Part 43 Appendix D and applicable Hartzell Maintenance Manual. AD's checked and current through 2025-09. I certify that this propeller has been inspected in accordance with FAR 43 Appendix D Annual Inspection and was determined to be in airworthy condition.

END

William Langham

AP38233391A

William Langham