



EBEY'S LANDING NATIONAL HISTORICAL RESERVE

PNRO INVENTORY

National Park Service
Pacific Northwest Region
Cultural Resources Division

Westin Building, Room 1920
2001 Sixth Avenue
Seattle, Washington 98121

NAME(S) OF STRUCTURE Reverend Lindsey House		DATE OF CONSTRUCTION 1889	SITE ID. NO. [] [] [] [] [] [] [] [] [] []			
SITE ADDRESS (STREET & NO.) 206 N. Main St.		ADDITION(S)	SCALE 1:24000		QUAD NAME Coupeville	
CITY/VICINITY Coupeville			UTM ZONE [] [] [] [] [] [] [] [] [] []		EASTING [] [] [] [] [] [] [] [] [] []	
COUNTY Island		STATE Washington		CROSS REFERENCE LA 30		
OWNER/ADMIN ADDRESS Fran Einterz P.O. Box 595 Coupeville, WA 98239	parcel # 13233-180-395	☒ CONTRIBUTING ☐ NON-CONTRIBUTING		DANGER OF DEMOLITION? (SPECIFY THREAT) ☐ YES ☒ NO ☐ UNKNOWN		

DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.

Vernacular Farmhouse with Italianate elements. Wood frame set on concrete foundation; T-shape (34' x 30') with 1-story addition on west facade; 3 bays wide; 1½-stories; wood shingle siding with decorative shingles on gable ends; asphalt-shingled bellcast gable roof with cross gable on east facade; off-center entrance on east facade; corbelled interior off-center chimney. Exterior features include 1/1 double-hung sash with molded cornice and plain surrounds; multi-pane fixed sash; 2-story bay window on east facade with bracketed cornices; plain cornice; decorative frieze board; corner boards; hip roof wrap-around porch with carved brackets and chamfered posts; wood panel front door with transom. Notable landscape features include 1 wood frame, gable roof outbuilding and 1 concrete block outbuilding.

This house was constructed in 1889 for Reverend Lindsey, pastor of the Congregational Church and first principal of the Puget Sound Academy. The structure remains a private residence with an upstairs apartment. Few changes have been made to the exterior of the structure.

1995: The outbuildings were removed; one contributing building

PUBLIC ACCESSIBILITY	☒ YES, LIMITED ☐ NO	☐ YES, UNLIMITED ☐ UNKNOWN	EXISTING SURVEYS	☒ NR ☐ HABS ☐ NHL	☐ LCS ☐ NPS	☐ STATE ☐ COUNTY	☐ LOCAL ☐ OTHER
LOCATED IN AN HISTORIC DISTRICT?	☒ YES ☐ NAME	☐ NO Cent. Whid. Isl. Hist. Dist.	CONDITION	☐ EXCELLENT ☒ GOOD	☐ FAIR ☐ DETERIORATED	☐ RUINS	

SIGNIFICANCE

This building represents a period of community growth and stability characterized by an increased awareness and application of traditional building methods. This property is significant under National Register criterion C, because it embodies the distinctive characteristics of architectural expressions and methods of construction that represent the period of community development in the Reserve, from 1871 until 1910. It retains integrity of location, setting, materials, design, workmanship, feeling and association.

A black and white photograph of a small, rustic wooden house. The house features a steep gable roof and a small porch on the right side. The exterior is clad in horizontal wooden siding. A large, dense bush is in the foreground, partially obscuring the house. The house is surrounded by trees and foliage, suggesting a rural or wooded setting. The photograph is framed by a white border.

A black and white photograph of a large, two-story wooden house with a steep, shingled roof and a prominent chimney. The house is surrounded by dense trees and shrubbery, with a lawn in the foreground.

Summer, 1983