

EBEY'S LANDING
NATIONAL
HISTORICAL RESERVE

PNRO
INVENTORY

National Park Service
Pacific Northwest Region
Cultural Resources Division


Westin Building, Room 1920
2001 Sixth Avenue
Seattle, Washington 98121

NAME(S) OF STRUCTURE Reuble Farm		DATE OF CONSTRUCTION 1921 ADDITION(S)	SITE ID. NO.									
SITE ADDRESS (STREET & NO.) 556 S. Fort Casey Road			SCALE 1:24000	QUAD NAME Coupeville								
CITY/VICINITY Coupeville			UTM ZONE 10	EASTING 5247105337305								
COUNTY Island	STATE Washington		CROSS REFERENCE LA53									
OWNER/ADMIN ADDRESS Gus Reuble 492 S. Fort Casey Rd. Coupeville, WA 98239		parcel #R13110-403-2899	☒ CONTRIBUTING ☐ NON- CONTRIBUTING									
DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. Bungaloid Farmhouse. Wood frame set on wood block foundation; square (35' x 35') with small gable-roofed addition on west facade; 3 bays wide; 1½-stories; clapboard siding; low-pitched, asphalt-shingled gable roof with extended eaves; center entrance on north and east facades; corbelled off-center chimney on north facade. Exterior features include 1/1 double-hung sash, 8-pane casement sash, 1-pane fixed sash, all with plain surrounds; shed-roofed dormer on north facade; plain frieze board; corner boards; knee braces; 1-story, hip-roofed porch on east facade with tuscan columns. Notable landscape features include 1 wood frame, gable-roofed milkhouse with shiplap siding, 2/2 double-hung sash, corner boards and exposed rafter ends; 1 wood frame, gambrel-roofed barn; 5 wood-frame outbuildings; 1 new trailer behind house. Gustave Reuble, Sr. had this farmhouse built for his family by local carpenter Mr. Dean. Dairy cows, hogs, and chickens were raised here, but Reuble was not a farmer. He was a Civil Service employee for the Fort Casey Military Reservation. He was the blacksmith there, and kept the horses and mules shod until funds ran out and he was replaced with a soldier, c. 1922. The house was last lived in c. 1979.			DANGER OF DEMOLITION? (SPECIFY THREAT) vacant; water damage									
CURRENT USE Vacant			ORIGINAL USE Residence									
<table border="0"><tr><td>PUBLIC ACCESSIBILITY</td><td>☒ YES, LIMITED ☐ NO</td><td>☐ YES, UNLIMITED ☐ UNKNOWN</td><td>EXISTING SURVEYS</td><td>☐ NR ☐ HABS ☐ NHL</td><td>☐ LCS ☐ NPS</td><td>☐ STATE ☐ COUNTY</td><td>☐ LOCAL ☐ OTHER</td></tr></table>					PUBLIC ACCESSIBILITY	☒ YES, LIMITED ☐ NO	☐ YES, UNLIMITED ☐ UNKNOWN	EXISTING SURVEYS	☐ NR ☐ HABS ☐ NHL	☐ LCS ☐ NPS	☐ STATE ☐ COUNTY	☐ LOCAL ☐ OTHER
PUBLIC ACCESSIBILITY	☒ YES, LIMITED ☐ NO	☐ YES, UNLIMITED ☐ UNKNOWN	EXISTING SURVEYS	☐ NR ☐ HABS ☐ NHL	☐ LCS ☐ NPS	☐ STATE ☐ COUNTY	☐ LOCAL ☐ OTHER					
LOCATED IN AN HISTORIC DISTRICT? ☒ YES ☐ NO NAME Cent. Whid. Isl. Hist. Dist.			CONDITION ☐ EXCELLENT ☐ GOOD ☒ FAIR ☒ DETERIORATED ☐ RUINS									
SIGNIFICANCE This substantial but simple farmhouse has remained virtually intact since first built. The entire complex has maintained integrity of design, materials, workmanship, and location, and is an important component of the cultural landscape.												


PHOTOGRAPHS AND SKETCH MAP OF LOCATION



FROM NE



FROM E



FROM NE

NEGATIVE NO. L1-35, C2-21-24

HABS/HAER QUALITY

☐ YES

☒ NO

REFERENCES

Reuble, Gus. Interview. September, 1983

INVENTORIED BY Luxenberg/Castellano/Lein

AFFILIATION

National Park Service

DATE

Summer, 1983