




Westin Building, Room 1920
2001 Sixth Avenue
Seattle, Washington 98121

NAME(S) OF STRUCTURE Sherman Hog House		DATE OF CONSTRUCTION c.1942		SITE ID. NO. [] [] [] [] [] [] [] [] [] []	
SITE ADDRESS (STREET & NO.) South Side West Hill Road, West of 1453 West Hill Road		ADDITION(S)		SCALE 1:24000	
CITY/VICINITY Coupeville		COUNTY Island		STATE Washington	
OWNER/ADMIN ADDRESS Robert Engle 750 S. Cathedral Dr. Coupeville, WA 98239		parcel #R13109-147-2530		QUAD NAME Coupeville	
DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S), PHYSICAL DIMENSIONS, MATERIALS, MAJOR ALTERATIONS, IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. Vernacular Barn. Wood frame set on concrete foundation; rectangle (60' x 200'); 3 bays wide; 1-story with clerestory; shiplap siding; wood-shingled clerestory roof; large sliding doors on north facade; off-set single entrance door on west facade; entrance on south facade. Exterior features include 4-pane hinged sash with plain surrounds across east and west facade and in clerestory; exposed rafter ends; fascia boards; corner boards. This large structure was built for Wilbur Sherman, by local carpenter Ralph Ward C.1942-43. Originally used as a hog house, it is presently used for hay storage and loafing. 1995: New metal roof installed 1994; one contributing structure.		☒ CONTRIBUTING ☐ NON-CONTRIBUTING		UTM ZONE 10	
		EASTING 5225955336865		NORTHING [] [] [] [] [] [] [] [] [] []	
		CROSS REFERENCE LA52		DANGER OF DEMOLITION? (SPECIFY THREAT)	
				☐ YES ☒ NO ☐ UNKNOWN	
		CURRENT USE Hay Storage/Loafing		ORIGINAL USE Hog House	
PUBLIC ACCESSIBILITY ☒ YES, LIMITED ☐ NO		☐ YES, UNLIMITED ☐ UNKNOWN		EXISTING SURVEYS ☐ NR ☐ HABS ☐ NHL ☐ LCS ☐ NPS ☐ STATE ☐ COUNTY ☐ LOCAL ☐ OTHER	
LOCATED IN AN HISTORIC DISTRICT? ☒ YES ☐ NAME Cent. Whid. Isl. Hist. Dist.		CONDITION ☐ EXCELLENT ☒ GOOD		☐ FAIR ☐ DETERIORATED ☐ RUINS	

SIGNIFICANCE This property is significant under National Register criterion A, for its association with agricultural land use patterns first established during the period of early settlement in the 1850s. It retains integrity of location, setting, materials, design, workmanship, feeling and association.

A black and white photograph of a large, dark, gabled barn with a gambrel roof. The barn is situated in a rural setting, with trees and bushes in the background and foreground. The barn has a dark, possibly wooden or metal, exterior. The roof is dark and has a gambrel shape. There are many windows along the side of the barn, some of which are visible. The foreground is filled with tall grass and bushes. The background shows a line of trees. The overall scene is a rural landscape.

FROM SE



FROM NE

☒ NO

REFERENCES Sherman, Wilbur. Interview. 30 August 1983.

DATE	Summer, 1983
------	--------------