

Mileage from Toronto	STATIONS AND BUILDINGS	DESCRIPTION AND DIMENSIONS.	When Built.	REMARKS. (CONDITION).
	Utopia--Cont.			
	Waiting room ----	Fr., shingle roof ---- 10'x14', ht 9' ---- 544 sq ft platform.	1895	Good
73.40	Section tool house --	Fr., shingle roof ---- 12'x14', ht 8' ---- 6'x12', ht 5' ----	1868	Poor
73.50	Section dwelling --	Sill fdn, fr., shgle roof 30½'x30½', ht 10' --- 12'x14', ht 7' ----	1895	Remodelled. Good Closet
73.50	Agent's dwelling ---	Sill fdn, fr., shgle roof 30½'x38½', ht 12' --- 10'x22', ht 7' ---- 10'x18', ht 6' ----	1895 1904	
	Shed ----	9½'x12', ht 7' ----		
	Stable ----	Fr., shingle roof ---- 14'x17', ht 10' ----	1883	Poor
	Stock yard ----	Addition ---- 9'x14', ht 6' ---- 32'x32½', 24'x32' ---	1903	Double chute
73.50	Angus			
	Station ----	Sill fdn, fr., shgle roof 22'x36', ht 15' ---- 2433 sq ft platform	1900	Good
	Ft. ho. & grain shed ----	Sill fdn, fr., shgle roof 30'x170½', ht 13' --- 1770 sq ft platform	1867	Fair
	Oil house&closet.	Fr., shingle roof ---- 8'x16', ht 8' ----	1895	Good
76.50	Brentwood			
	Flag station ----	Sill fdn, fr., shgle roof 10'x14', ht 10' ---- 203 sq ft platform. 160 ft gravel walk.	1904	
78.80	New Lowell			
	Station ----	Sill fdn, fr., shgle roof 22'x40', ht 15' ---- 2418 sq ft platform	1868	Good. Remod- elled 1900
	Ft. & grain ho.---	Sill fdn, fr., shgle roof 40½'x111', ht 14' --- 1306 sq ft platform	1868	
78.80	Section dwelling ---	25'x48', 23'x48' --- Sill fdn, fr., shgle roof 24'x30', ht 10' ---- 12'x16', ht 10' ---- 9'x21', ht 7' ----	1902 1868	Double chute Poor
	Addition ----	11'x28', ht 11' ----		
	Shed ----	Fr., board roof ----		
	Stable ----	Fr., shingle roof ---- 12'x14', ht 8' ----		Poor
79.08	Section tool house..	Fr., shingle roof ---- 12'x14', ht 8' ----		Poor
80.35	Section tool house..	Fr., shingle roof ---- 12'x14', ht 8' ----	1868	Poor
85.86	Stayner			
	Station ----	Sill fdn, fr., shgle roof 22'x42', ht 16' ---- 22'x48', ht 13' ---- 4578 sq ft platform	1874	Good. Remod elled 1902
	Shed ----			

Mileage from Toronto	STATIONS AND BUILDINGS	DESCRIPTION AND DIMENSIONS.	When Built.	REMARKS (CONDITION).
	Stayer---Cont. Ft. & grain ho.---	Sill fdn, fr., shngle roof 40'x20 ² , ht 13' 2232 sq ft platform	1874	Good
	Oil house -----	Fr., shingle roof 11'x14', ht 8'	1898	Good
	Agent's dwelling	Sill fdn, fr., shngle roof 23 ¹ / ₂ 'x28 ¹ / ₂ ', ht 11' 14'x18 ¹ / ₂ ', ht 11'	1863	Fair
	Addition -----	Fr., shingle roof 12'x26', ht 12'		
	Shed -----	Fr., shingle roof 8'x12', ht 9'		
	Addition -----	6 ¹ / ₂ 'x14', ht 6'		
	Shed -----	Fr., shingle roof 14'x24', ht 8'	1874	Fair
86.08	Section tool house.			
	Batteaux			
91.38	Shedler -----	Fr., shingle roof 11'x24', ht 8' 400 sq ft platform	1900	Good
93.97	Collingwood Exhibition siding -----	1600 sq ft platform		Poor
94.40	Section tool house.	Fr., shingle roof 12'x14', ht 8'	1868	Fair
94.60	Storehouse -----	Sill fdn, fr., shngle roof 30'x48 ¹ / ₂ ', ht 13' 412 sq ft platform 20'x40' (2)	1873	Good double chute
	Stock yard -----	Fr., shingle roof 13'x32', ht 9'	1868	Fair
	Cattle shed -----	Sill fdn, fr., shngle roof 16 ¹ / ₂ 'x32 ¹ / ₂ ', ht 12'	1890	Good
	Oil house & office	Fr., shingle roof 12'x20 ¹ / ₂ ', ht 8'	1882	Fair
	Lamp house -----			
	Fl. & bonded warehouse -----	Sill fdn, fr., shngle roof 30'x202', ht 14' 3904 sq ft platform	1903	Good
	Collingwood Station -----	Stone fdn, brick, shngle roof 40 ¹ / ₂ 'x70 ¹ / ₂ ', ht 20'	1873	Good
	Tower -----	Brick 88'x132 ¹ / ₂ ', ht 36'	1873	Good
	Addition -----	Fr., shingle roof 15'4" x 22', ht 18'	1873	Good
	Pavilion (S. end) -----	Fr., shingle roof 22'x45', ht 18'	1873	Good
	Pavilion (N. end) -----	Fr., shingle roof 22'x60' 5", ht 18'	1873	Close
	Agent's dwelling	Fr., shngle roof, sillfdn 20119 sq ft platform 28'x36 ¹ / ₂ ', ht 13' 14'x34 ¹ / ₂ ', ht 12' 16'x20 ¹ / ₂ ', ht 12' 14'x14 ¹ / ₂ ', ht 7'	1863	Good. Remodelled 1903.
94.60	Carpt. shop & oil room -----	Stone fdn, brick, corrugated iron roof 16'x40', ht 12'		Good