

Mileage from Toronto	STATIONS AND BUILDINGS	DESCRIPTION AND DIMENSIONS.	When Built.	REMARKS. (CONDITION).
34.39	Newmarket--Cont.			
	Freight shed -----	Sill fdn, fr., shgle roof 40'4"x15½', ht 14' --	1865	Poor
	Stock yard -----	45'x60½' 2776 sq ft platform		Two chutes
	Oil house -----	Fr., shingle roof ----- 6'x8', ht 8'	1906	Good
34.51	Section tool house..	Fr., shingle roof ----- 14'x18', ht 8' -----	1897	Good
38.06	Holland Landing			
	Station -----	Sill fdn, fr., shgle roof 24'4"x40½', ht 13'	1854	Fair
	Freight shed ----	Sill fdn, fr., shgle roof 24'4"x80'9", ht 20' 972 sq ft platform.	1854	Poor.
	Dwelling -----	Stone fdn, brick, shgle roof 30'x36½', ht 13' -----	1854	Poor. Closet
	Addition -----	Brick 4½'x7'9", ht 6' ----- 14½'x23', ht 12'		Poor
41.25	Pumphouse	Sill fdn, fr., shgle roof 38'x16'5", ht 12'	1902	Good
41.59	Section tool house..	Fr., shingle roof ----- 14'4"x20', ht 9'	1894	Fair
41.66	Stock yard -----	24'x54½'x85'		
41.80	Bradford			
	Station -----	Sill fdn, fr., shgle roof 40½'x234½', ht 16½' 8349 sq ft platform		Fair. Ft shed included
41.80	Dwelling (double) -	Sill fdn, fr., shgle roof 18'4"x61', ht 10' ----- 12½'x34'8", ht 9' ----- 20'x24', ht 12' ----- 12'x20', ht 9' ----- 12'x15', ht 9' ----- 12'x17', ht 9' -----	1878	Two closets Poor
44.53	Section tool house..	Sill fdn, fr., shgle roof 10'x12', ht 8' -----	1905	Good
49.22	Gilford			
	Station -----	Sill fdn, fr., shgle roof 30'4"x118', ht 12' -- 708 sq ft platform.	1870	Good
49.22	Station -----	Sill fdn fr., shgle roof 12'x18', ht 12' ----- 288 sq ft platform.	1901	Good
51.69	Section tool house..	Fr., shingle roof ----- 14'4"x16'4", ht 7' --	1894	Good
51.88	Agents dwelling ---	Sill fdn, fr., shgle roof 24'4"x30'4", ht 10½'	1868	Fair
	Addition -----	12'x28', ht 8' -----	1868	Fair
	Addition -----	12'x16'4", ht 6' -----		
	Addition -----	10'4'x14', ht 10' -----		Closet
	Stable -----	Fr., shingle roof ----- 14'4'x22½', ht 9½' --		Fair
51.94	Section dwelling ---	Sill fdn, fr., shgle roof 28½'x32', ht 10½' --	1890	Poor
	Addition -----	11'4'x13', ht 7' -----	1890	Poor
	Addition -----	13½'x19½', ht 10' -----	1890	Poor

Mileage from Toronto	STATIONS AND BUILDINGS	DESCRIPTION AND DIMENSIONS.	When Built.	REMARKS. (CONDITION).
52.02	311ford--Coat. Shed Stable	12½"x20", ht 7½" Fr., shingle roof 16½"x30½", ht 12"	1890 1863	Poor Poor
52.02	LaFroy Station Addition Freight & Grain house Stockyard Oil house Dwelling (double) Addition (2) Addition (2)	Sill fdn, fr., shgle roof 24½"x40½", ht 13" 4½"x15½", ht 11" 4939 sq ft platform Sill fdn, fr., shgle roof 40½"x14½", ht 13½" 44"x46" 1563 sq ft platform Fr., shingle roof 14½"x20½", ht 11" Sill fdn, fr., shgle roof (each) 18½"x30½", ht 12" 12"x17½", ht 9" 12½"x14", ht 10" Sill fdn fr., shgle roof 18½"x27½", ht 10" 14"x23", ht 10" 10½"x12", ht 8" 9"x12", ht 7" Fr., board roof Fr., shingle roof 13"x27", ht 12" Fr., shingle roof 12"x14", ht 8"	1854 1863 1873	Fair Closet Fair Chute
56.91	Section dwelling Addition Addition Shed Stable	Sill fdn fr., shgle roof 19½"x6½", ht 15½" 2601 sq ft platform Fr., shingle roof 6"x6", ht 7" Sill fdn fr., shgle roof 24½"x30½", ht 10½" 12½"x26", ht 7" 12½"x14½", ht 7" Fr., shingle roof 28"x32", ht 8" 32"x40"	1863 1863 1863 1863 1863	Poor Closet Poor Poor Poor
56.94	Section tool house	Fr., shingle roof 12"x14", ht 8"	1882	Poor
57.76	Craigvale Station Oil house Agent's dwelling Addition Shed Stable Stock yard	Sill fdn fr., shgle roof 19½"x6½", ht 15½" 2601 sq ft platform Fr., shingle roof 6"x6", ht 7" Sill fdn fr., shgle roof 24½"x30½", ht 10½" 12½"x26", ht 7" 12½"x14½", ht 7" Fr., shingle roof 28"x32", ht 8" 32"x40"	1892 1869	Fair Good. Closet
62.57	Allendale Yard Section tool house	Fr., shingle roof 12½"x20½", ht 9"	1891	Poor. Closet
62.71	Machine shop at- fached to walls of round house Addition (pump house & lava- tory) Addition (black- smith's coal ho) Hot water tank	Cement fdn, gravel rf 50"x180½", ht 21" Cement fdn, walls & roof 13½"x39½", ht 13" 9½"x23", 16" high 14"x31½", 11" high	1904 1904 1904 1904	Good