

Mileage from Hamilton	STATIONS AND BUILDINGS	DESCRIPTION AND DIMENSIONS.	When Built.	REMARKS. (CONDITION).
53.90	Caledon East			
	Station ..	Sill fdn, fr., shgle roof 21'8"x42', ht 16' --- 4024 sq ft platform	1903	Good. On piles
	Freight house ---	Sill fdn, fr., shgle roof 25½"x21½' ht 12' --- 1218 sq ft platform	1878	Good
	Pump house - - -	Stone fdn, fr., Canada plate roof ----- 16'x38½', ht 10' -----	1904	Good
	Stock yard -----	31'x46' -----	1895	Fair. One chute
56.60	Centreville			
	Section dwelling & waiting room ---	Sill fdn, fr., shgle roof 19'x31½', ht 11' --- 13'x24½' ht 11' --- 10½"x24½', ht 8' --- 607 sq ft platform.	1880	Good Closet
56.60	Stable -----	Fr., shingle roof 14'x24', ht 9' -----	1880	Poor
60.15	Section tool house..	Fr., shingle roof 16'x20', ht 8' -----	1893	Good
60.25	Palgrave			
	Station & ft. ho..	Sill fdn, fr., shgle roof 21½"x72½' ht 11' --- 3012 sq ft platform	1900	Good
	Oil house -----	Fr., shingle roof 8'x16½' ht 8' ----- 34'x48' -----	1892	Good. Closet One double chute
65.94	Section tool house..	Fr., shingle roof 16'x20', ht 8' -----	1895	Good
66.01	Tottenham			
	Station -----	Sill fdn, fr., shgle roof 25½"x101½', ht 12' --- 4504 sq ft platform	1878	Poor Closet
	Oil house -----	Fr., Canada plate roof 8'x12', ht 8' ----- 33'x41' -----	1897	Good Double chute
70.75	Section tool house..	Fr., shingle roof 16'x20', ht 8' ----- 44'x61' -----	1896	Good Double chute
70.73	Stock yard ----- Car repairers' shd	Sill fdn, fr., shgle roof 12'x16½'x12' -----	1897	Good
70.73	Beeton			
	Stat'n & dwelling	Sill fdn, fr., shgle roof 25½"x42½', ht 22' ---	1888	Fair
	Freight house ---	Sill fdn, fr., shgle roof 25½"x40', ht 13' --- 8854 sq ft platform	1888	Fair
75.50	Section tool house.	Fr., board roof 10'x20', ht 10' -----	1877	Poor
79.40	Section tool house..	Fr., board roof 10'x19', ht 10' -----	1878	Poor

Mileage from Hamilton	STATIONS AND BUILDINGS	DESCRIPTION AND DIMENSIONS.	When Built.	REMARKS. (CONDITION).
79.61	Cookstown Station -----	Sill fdn, fr., shgle roof 25'x01', ht 12' ----- 3283 sq ft platform	1877	Poor
	Oil house&closet	Fr., shingle roof ----- 8'x16', ht 10' ----- 36'x41' -----	1894	Good
85.22	Stock yard ----- Section tool house	Fr., shingle roof ----- 16'x20', ht 8' -----	1897	Double chute Good
85.50	Stock yard -----	41'x46 $\frac{1}{2}$ ' -----		One double chute
	Thornton Station -----	Sill fdn, fr., shgle roof 21'x42', ht 11' ----- 3048 sq ft platform	1878	Fair. Remod elled Closet
90.50	Vine Stat'n & dwelling	Sill fdn, fr., shgle roof 19 $\frac{1}{2}$ 'x50 $\frac{1}{2}$ ', ht 11' ---- 14 $\frac{1}{2}$ 'x16', ht 11' ----	1891	Good
	Addition ----- Tool house&shed	Fr., shingle roof ----- 14'x24', ht 12' ----- 1716 sq ft platform	1878	Closet Poor
94.75	Tool house -----	Fr., shingle roof ----- 12'x16', ht 8' -----	1905	Good

Mileage from Toronto

ALLANDALE to MEAFORD—14th District.

63.50	Section tool house	Fr., shingle roof ----- 16'x32', ht 8' -----	1880	Good
63.94	Section tool house	Fr., shingle roof ----- 12'x14', ht 8' -----	1873	Poor
68.75	Colwell Station -----	Fr., shingle roof ----- 19 $\frac{1}{2}$ 'x50', ht 12' ---- 2369 sq ft platform	1891	Good Closet
68.75	Section dwelling	Fr., shingle roof ----- 18'x24', ht 10' ----- 10'x24', ht 7' -----	1868	Poor
	Addition ----- Agent's dwelling	Sill fdn, fr., shgle roof 18 $\frac{1}{2}$ 'x27 $\frac{1}{2}$ ', ht 12' ---- 12 $\frac{1}{2}$ 'x14 $\frac{1}{2}$ ', ht 12' ----	1895	Good Closet
	Addition ----- Addition -----	10'x14', ht 7' -----		
71.25	Utopia Section dwelling	Sill fdn, fr., shgle roof 18 $\frac{1}{2}$ 'x23 $\frac{1}{2}$ ', ht 9' ---- 13'x20', ht 9' ---- 10'x20', ht 6 $\frac{1}{2}$ ' ----	1888	
	Addition ----- Addition ----- Shed -----	8'x19', ht 6' -----		Closet