

Mileage from Belleville Hb	STATIONS AND BUILDINGS	DESCRIPTION AND DIMENSIONS.	When Built.	REMARKS. (CONDITION).
163.58	Victoria Hbr. -Cont. Section tool house--	Fr., iron roof ----- 12½'x18½', ht 7' ----	1882 1896	Fair
164.00	Track scale shelter	Fr., shingle roof ----- 5½'x8', ht 8½' -----	1896	Fair
164.00	Midland Station -----	Stone fdn, fr., metallic Shingle roof ----- 22½'x72½', ht 17' --- 5558 sq ft platform	1889	Fair Closet
	Oil house -----	Fr., shingle roof ----- 8'x10', ht 8½' -----	1889	Fair
	Freight house --	30'x80', ht 13' ----- 1340 sq ft platform		Fair 30 added 1901
	Stock yard -----	33'x39' -----		Poor. One chute
	Car repair's shop & office -----	Sill fdn, fr., metallic roof ----- 14'x24', ht 12' ----		Poor
	Coal house -----	Fr., shingle roof ----- 14'x24', ht 12' ----		Fair
	Office & boiler house (motive power) -----	Stone fdn, fr., metallic roof ----- 17'x43', ht 12' ---- 16'x18', ht 12' ----	1896 1904	Fair Good
	Addition ----- Oil & coal house--	Stone fdn, fr., metallic roof ----- 12'x15', ht 11' ----	1896	Fair
	Bunk house ----	Rr., shingle roof ----- 12'x22', ht 12' ----	1896	Good
	Wood shed -----	Fr., shingle roof ----- 14'x20', ht 11' ----	1897	Good Closet
164.05	Elevator No. 2 ----	Stone fdn. on piles wood walls. Walls and part roof covered and with Canada plate balance of roof shingled -- 102'x106', ht 79' to first plate ----- 111'x6' to second plate -----	1890	Fair Capacity 440,000 bush. N. ½ built 1881, S. ½ built 1890

Mileage
from
Scarboro Jc**BLACKWATER JCT to LORNEVILLE JCT.****9th District.**

41.90	Blackwater Jct.			
42.06	Section tool house--	Fr., shingle roof ----- 12'x20', ht 7½' -----	1890	Good
43.83	Section tool house--	Fr., shingle roof ----- 16'x16', ht 7' -----	1880	Poor
44.02	Stock yard -----	39'x44' -----	1896	Fair. Dou- ble chute
44.02	Sunderland Station -----	Sill fdn fr., shgle roof 25'x60', ht 12' -----	1871	Fair

Mileage from Scarboro Jct.	STATIONS AND BUILDINGS	DESCRIPTION AND DIMENSIONS.	When Built.	REMARKS. (CONDITION).
	Sunderland-Cont			
	Coal house -----	660 sq ft platform 2296 sq ft cin walk Fr., shingle roof 18'x20½', ht 10'	1892	Closet Fair
	Ice house -----	Fr., board roof 12'x14', ht 9'	1892	Poor
	Agents dwelling	Sill fdn, fr., shngle roof 15'x28', ht 20'	1882	Fair
	Addition 13'x14'-- Shed -----	13'x14', ht 11' 12'x16', ht 9'	1882	Closet
49.80	Section tool house--	Fr., board roof 14'x18', ht 8'	1900	Good
50.00	Cannington Station -----	Stone & timber fdn, fr., shingle roof 22½'x30½', ht 12' 3760 sq ft platform	1886	Fair
	Coal house and closet -----	Fr., shingle roof 10'x18', ht 9'	1887	Fair
	Stock yard -----	40'x47½' 29'x33½'	1895	Fair. Dou- ble chute
54.00	Woodville Station -----	Sill fdn, fr., shngle roof 25½'x60½', ht 13' 3551 sq ft platform	1871	Fair. Remod- elled 1896
	Oil house -----	Fr., shingle roof 4½'x6', ht 7'	1883	Closet Fair
	Stock yards -----	(2) 40'x40'	1906	Good. Dou- ble chute Good
55.59	Section tool house--	Fr., shingle roof 14½'x20½', ht 8'		Good
	Addition -----	4½'x15', ht 6'		
55.67	Lorneville Jct.			
	Station -----	Fr., sill fdn, shngle roof 20½'x42½', ht 13'		Good. Remod- elled 1900
	Addition -----	18½'x19½', ht 13'		
	Oil house -----	Stone fdn, brick, shgle roof 10'x14', ht 8½' 6250 sq ft platform	1897	
	Car repairers offi.	Sill fdn, fr., shngle roof 12'x14', ht 10'	1887	Good
	Agents dwellin ---	Stone fdn, brick shgle roof 24½'x31'10", ht 22' 18'x20', ht 11½'	1887	Good
	Addition -----	Fr., shingle roof 5'x7½', ht 7½'	1876	Poor
	Stable -----	Fr., shingle roof 16'x22', ht 12'		Fair. Closet
	Stock yard -----	18'x33'x74'	1893	Good. Dou- ble chute
	Section tool house	Fr., shingle roof 12'x22', ht 7½'	1892	Good
	T'ck scale shelter	Fr., shingle roof 5'x12', ht 9'	1884	Poor