

Mileage from Scaboro Jct.	STATIONS AND BUILDINGS	DESCRIPTION AND DIMENSIONS.	When Built.	REMARKS. (CONDITION).
	Goodwood--Cont.			
	Oil & coal house	Fr., shingle roof 12'x17', ht 8'	1876	Closet
	Stock yard	39'x49'	1892	Fair. One chute
25.64	Section tool house	Fr., shingle roof 12'x19½', ht 10'	1905	Good
31.90	Section tool house	Fr., shingle roof 12'x20', ht 7'	1896	Fair
	Uxbridge			
32.06	Freight house	Sill fdn, fr., shgle roof 25½'x55', ht 13' 3010 sq ft platform	1871	Good
	Elevated oil ptfm. Station	12'x14' Concrete fdn, fr., shgle roof, brick to win- dowsills	1900	Good
	Addition	46'x22', ht 16'	1900	
	Pavillion	4308 sq ft platform	1900	
	Grain house	16'x22', ht 16' 15½'x22'	1871	Poor
	Stock yards (3)	Sill fdn, fr., shgle roof 40'x88½', ht 14' 528 sq ft platform	1903	Good. Two double chutes
32.48	Section tool house	Fr., shingle roof 14'x20', ht 7½'	1896	Fair
	Blackwater			
41.90	Stat'n & dwelling	Sill fdn, fr., shgle roof 20'x66', ht 12'	1883	
	Addition	16'x33½', ht 11'	1883	
	Addition	13'x16', ht 11'	1883	
	Addition	14'x14', ht 10½'	1883	
	Platform awning	Fr., board roof 12'x85', ht 9'	1883	Fair
	Shed	8'x14', ht 9'	1883	Fair
	Shed	12'x12½', ht 7'		Two closets
	Oil house	Fr., shgle roof walls covered with Can- ada plate	1883	
	Coal house	10'x14', ht 9'		
	Coal house	11'x16', ht 8'		
	Coal house	12'x18', ht 9'		
	Stockyards (2)	12092 sq ft ptfm. 40'x56', 30'x64'	1894	Fair. Dou- ble chute
	Restaurant	Sill fdn, on piles, fr., shingle roof	1888	Fair
	Addition	30½'x42½', ht 22½'		
	Addition	24½'x25', ht 12'	1888	
	Addition	14'x24', ht 10'	1888	
	Addition	7'x14', ht 9'	1888	
	Shed	8'x15', ht 6½'	1888	Closet
	Pumphouse	Concrete fdn, fr., met- allic roof	1905	Good
		16'x32', ht 8'		

Mileage from Toronto.	STATIONS AND BUILDINGS	DESCRIPTION AND DIMENSIONS.	When Built.	REMARKS. (CONDITIONS).
BLACKWATER JCT. to LINDSAY--10th District.				
51.10	Blackwater Jct.			
56.92	Section tool house	Fr., shingle roof ----- 10'x16', ht 7' -----	1886	Poor
56.99	Section dwelling	Stone fdn, fr., shingle roof, stone cellar 14'x37', ht 11' -----	1891	Fair. Rebuilt
	Addition -----	10'x23', ht 7' -----		
	Addition -----	6'x14', ht 9' -----		
	Stable frame	Fr., board roof -----		Poor Closet
57.02	Stockyard (2)	10'x17', ht 7' ----- 35'x35', 24'x35' ----	1903	Good. Dou- blue chute
57.08	Manilla Jct.			
12.59	Stat'n & dwelling	Sill fdn, fr., shgle roof 19'x71', ht 12' ----- 12'x18', ht 8' -----	1885 1893	Fair Fair
69.67	Baggage addition	Fr., board roof -----	1888	Fair
	Awning -----	8'x55', ht 8' ----- 17'x23', ht 11' -----	1835	Fair
	Dwelling addition	Fr., shingle roof -----	1886	Fair
	Freight house	21'x26', ht 11' ----- 7395 sq ft platform		
	Stable -----	Fr., shingle roof ----- 11'x15', ht 11' -----		Fair
	Shed 16' -----	16'x22', ht 7' -----		Poor
	Shed -----	5'x10', ht 7' -----		
62.05	Mariposa			
	Stat'n & dwelling	Sill fdn, fr., shgle roof 25'x61', ht 13' ----- 13'x13', ht 8' -----	1903 1899	Good Good
	Dwelling addition	Sill fdn, fr., shgle roof	1879	Fair
	Freight house	22'x33', ht 11' ----- Fr., shingle roof -----		Fair
	Oil house	5'x7', ht 7' ----- 3049 sq ft platform 17'x17', ht 7' -----		Closet
62.10	Section dwelling	Stone fdn, fr., shgle roof. ----- 17'x28', ht 13' -----	1885	Fair
	Addition -----	Stone fdn & cellar, fr. shingle roof -----	1885	Fair
	Addition -----	14'x15', ht 7½' ----- Sill fdn, fr., shgle roof		Fair
	Shed -----	Fr., board roof ----- 11'x22', ht 7' -----		Fair
	Stable -----	Fr., shingle roof ----- 12'x37', ht 9' -----		Good Closet
62.11	Stock yard	45'x86' -----	1898	Single and double chute
62.16	Section tool house	Fr., shingle roof ----- 10'x24', ht 7' -----	1882	Fair
	Addition -----	6'x12', ht 5' -----		Poor