

Mileage from Toronto	STATIONS AND BUILDINGS	DESCRIPTION AND DIMENSIONS.	When Built.	REMARKS. (CONDITION).
	Collingwood-Cont. Elevator -----	Stone fdn, on piles, wood fr., covered with Canada plate 61'x101', ht 62' & 137'	1871	Fair Capacity 165,000 bush.
	Engine shed ----	Fr., rufegated iron 22'x32', ht 14'	1889	Poor
	Lumber dock ---	Cribwork filled 700'x15'	1907	Good
	Elevator dock --	Piles & cribw'k plank- ed 523'x25'		
	Elevator dock --	Cribwork filled 363'x103'		
	Elevator dock --	Piles & cribw'k plank ed 161'x37'		
	Pile dock -----	Cribwork filled 360'x46'		
		Pile dock 132'x122'		
		14364 sq ft crib- work filled		
		Dock 1, side crib		
		Dock 1, side stone		
		600'x81'		
	Ft. shed at wharf	Shl fdn, fr., covered with cor.gated iron 77'x250', ht 133'	1905	Good
95.24	Lake Jct. -----	3360 sq ft platform	1902	Good
95.35	Section tool house	Fr., shingle roof 12'x14', ht 8'	1883	Fair
100.50	Craigleith Dwelling & wait- ing room -----	Shl fdn, fr., shingle roof 26'x28', ht 12'	1889	Good
	Addition -----	12 1/2'x26', ht 8'		
	Tower -----	8' diam, ht 17'		
	Shed -----	12'x20', ht 9'		
	Stable -----	Fr., shingle roof	1898	Good
	Addition -----	12'x16', ht 12'	1898	Good
		17'x12', ht 7'		
100.52	Section tool house	Fr., shingle roof 1680 sq ft platform 12'x14', ht 8'	1883	Poor
103.15	Fields Shelter -----	1680 sq ft platform	1904	
107.20	Stock yard -----	(2) 32'x48' (2) 32'x46'	1905	2 Single and 5 dbl chutes
	Thornbury Station -----	Shl fdn, fr., shingle roof 1905	1905	Good
	Ft. & grain house	Shl fdn, fr., shingle roof 40'x129', ht 13 1/2'	1905	Good
	Agent's dwelling -	3081 sq ft platform Shl fdn, fr., shingle roof 30 1/2'x38 1/2', ht 11'	1894	Good
		12'x14', ht 8'		

Mileage from Toronto	STATIONS AND BUILDINGS	DESCRIPTION AND DIMENSIONS.	When Built.	REMARKS (CONDITION).
	Thornbury--Cont.			
	Shed -----	5½'x14', ht 6' -----		Closet
	Section dwelling	Sill fdn, fr., shgle roof	1894	Good
		18½'x31', ht 11' -----		
	Addition -----	12'x16½', ht 8' -----		
	Addition -----	14'x18', ht 10' -----		
	Shed -----	4'x14', ht 6' -----		Closet
	Oil house -----	Fr., shingle roof -----	1905	Good
		14½'x28½', ht 9' -----		
107.20	Section tool house	Fr., shingle roof -----	1883	Fair
		12'x14', ht 8' -----		
114.75	Section tool house	Fr., shingle roof -----	1883	Fair
		12'x14', ht 8' -----		
	Stock yard -----	49'x54' 48'x54'		2 Single and 1 dbl. chute
	Lane -----	20'x114' -----		
115.00	Meaford			
	Station -----	Sill fdn, fr., shgle roof	1901	Good
		21'2"x59', ht 16'4'		
	Tower -----	12'x12', ht 26' -----		
	Pavilion -----	18'8"x25½', ht 12' -----		
		3040 sq ft platform		
	Agent's dwelling	Sill fdn, fr., shgle roof	1872	Poor
		30'x38', ht 11' -----		
	Addition -----	12'x14', ht 9' -----		
	Freight house	Sill fdn, fr., shgle roof	1902	Good
		20'x90', ht 12' -----		
		3020 sq ft platform		
	Coal platform	760 sq ft -----		

COLWELL to PENETANG—14th District.

69.90	Gravel pit shelter	Fr., shingle roof -----	1890	Fair
		16'x24', ht 8' -----		
71.92	Section dwelling	Sill fdn, fr., shgle roof	1880	Fair
		18½'x28½', ht 11' -----		
	Addition -----	12'x14', ht 11' -----		
	Shed -----	10'x10', ht 8' -----		Closet
71.95	Section tool house	Fr., shingle roof -----	1883	Fair
		12'x14', ht 8' -----		
76.50	Minessing			
	Agent's dwelling	Sill fdn, fr., shgle roof	1880	Fair
		18'x27', ht 10' -----		
	Addition -----	12'x14', ht 10' -----		
	Shed -----	10'x14', ht 7' -----		
	Shed -----	16'x16', ht 6' -----		Closet
76.50	Station	Sill fdn, fr., shgle roof	1880	Fair
		21'x69', ht 16' -----		
	Stock yard	1843 sq ft platform		Closet