

Mileage from Palmerston.	STATIONS.		Name and No. of Structure.		No. of Spans.	Length of Spans and Dimensions of Culverts.	Total length of Structure.	Height of Rail above River Bed.	When Built.	REMARKS.			
	SIDINGS	Kind of Structure.	NAME.	Bridge No.							feet.	ft.	ft.
15.65	Con. pipe.....		Culvert...		1	24"	36	7 1900	Under track.				
15.75	"		"		1	23"	37	9 1897	"				
15.85	Cedar box.....		"		1	3½x4	48	12 1888	} Combined.				
15.85	"		"		1	3½x4	48	12 1888					
16.01	"		"		1	3x3	36	8 1890	Under truck.				
16.42	Open C. pass....		"		1	6	38	8½ 1894	C. walls.				
16.68	Cedar box.....		"		1	5x6	28	6 1890	Under track.				
17.25	Deck Bridge...		Stream...	80	2	13	57	10 1896	Cedar piles, wood str.				
17.47	Cedar box.....		Culvert...		1	15			Under track.				
17.65	Deck Bridge...		Branch of Sangeen r.	81	1	2x3	49	12 1890	Under track.				
17.83	Holstein.								Ir. pl. gdrs. C. crib abuts.				
17.94	Cedar box.....		Culvert...		1	4x5	62	9 1893	Under track.				
18.63	Deck Bridge...		Stream...	82	1	13	163	26 1903	Cedar piles, wd. strs.				
					2	14							
					3	14½							
					3	15							
					1	15½							
19.77	Deck Bridge...		Culvert...	83	1	4	10	8 1899	Pile bents, pine strs.				
19.82	Cedar box.....		"		1	3x3	36	8 1893	Under track.				
19.94	Deck Bridge...		Stream...	84	1	10	16	9 1901	Pile bents, pine strs.				
20.16	Cedar box.....		Culvert...		1	2x2	30	6 1895	Undertrack.				
20.28	"		"		1	2½x3	32	5 1895	"				
21.12	Deck Bridge...		"	85	1	18	27	5 1903	Pile bents, wd. strs.				
21.25	"		"	86	1	19½	28	6 1903	"				
21.94	"		"	87	1	18½	27	6 1903	"				
22.01	Cedar box.....		"		1	1x1½	16	2 1897	Under track.				
22.21	"		"		1	2x2	24	4 1897	"				
22.56	Deck Bridge...		Stream...	88	1	10	16	11 1901	Pile bents, wd. strs.				
22.83	Cedar box.....		Culvert...		1	3x3½	32	8 1897	Under track.				
22.91	Con. pipe.....		"		1	30"	28	7 1900	"				
23.00	Cement pipe....		"		1	2	26	6 1897	"				
23.16	Cedar box.....		"		1	3x3½	30	6 1887	"				
23.22	Con. pipe.....		"		1	23"	32	6 1897	"				
23.34	"		"		1	20"	17	4 1897	"				
23.72	Cedar box.....		"		1	3x3	36	6½ 1894	"				
23.90	Varney.												
24.02	Cedar box.....		"		1	6x6¾	33	7 1901	"				
24.18	"		"		1	2½x3	26	5 1896	"				
24.40	"		"		1	2x3	24	6 1897	"				
24.62	"		"		1	3x4	40	9 1893	"				
25.15	"		"		1	2½x3	42	10 1893	"				
25.30	"		"		1	6x5¾	42	10 1893	"				
25.81	Deck Bridge...		C. pass. Crane's Cr	89	1	9	68	12½ 1896	Cedar piles, wood str.				
					3	14							
					1	15							
26.33	Deck Bridge...		Mill Race	90	2	14	75	16 1897	Cedar piles tres Ir. pl. gdr. wd. approaches.				
					1	43½							
26.42	Deck Bridge...		Branch of Sangeen R.....	91	2	16	120	18½ 1897	Approaches C. pile tres., w'd. strs. Ir. pl. gdr on c. crib.				
					1	17							
26 73	Durham.				1	67							

Mileage from Port Dover.	STATIONS. SIDINGS Kind of Structure.	Name and No. of Structure.		No. of Spans.	Length of Spans and Dimensions of Culverts. feet.	Total length of Structure. ft.	Height of Rail above River Bed. ft.	When Built.	REMARKS.
		NAME.	Bridge No.						
106.18	Harriston Jct.								
106.27	Cedar box.....	Culvert...	...	1	1x1	36	6	1893	Under track.
106.35	Vit. pipe.....	"	...	1	8"	16	4	1901	"
106.37	"	"	...	1	8"	16	4	1901	"
106.42	Cedar box.....	"	...	1	3x3	28	4½	1890	"
106.65	"	"	...	1	4x5½	36	7	1889	"
106.95	Open (C. pass.)..	"	92	1	6	36	7	1889	C. walls.
106.98	Con. pipe.....	"	...	1	22"	25	4	1898	Under track.
107.10	Cedar box.....	"	...	1	3x4	33	5½	1891	"
107.29	"	"	...	1	3x4	65	5½	1891	"
107.68	"	"	...	1	2x3	28	4	1891	"
107.79	"	"	...	1	2x3	24	4	1891	"
107.87	Deck Bridge...	Stream...	93	1	7½	14	8½	1902	W. str., w. w's.
108.07	Con. pipe.....	Culvert...	...	1	18"	21	4	1898	Under track.
108.28	"	"	...	1	2x2	29	5' 7"	1891	"
108.88	"	"	...	1	1x1	31	7	1893	"
109.06	Cedar box.....	"	...	1	3½x5½	39	6	1889	"
109.50	Deck Bridge...	Stream...	94	1	11	18	7	1897	W. str., w. w's
109.74	Cedar box.....	Culvert...	...	1	4x6	38	9	1889	Under track.
110.05	"	"	...	1	1x2	25	5½	1893	"
110.53	"	"	...	1	5x6	38	9	1889	"
110.74	Drew.								
111.06	Cedar box.....	"	...	1	1½x2	31	7½	1881	"
111.22	"	"	...	1	1' 7"x2	34	8½	1897	"
111.53	Con. pipe.....	"	...	1	12"	37	6	1898	"
111.66	Cedar box.....	"	...	1	1x1' 8"	28	5½	1893	"
111.84	"	"	...	1	2x3	28	7½	1881	"
112.03	Vit. pipe.....	"	...	1	6"	16	3	1902	"
112.05	"	"	...	1	6"	16	3	1902	"
112.73	Cedar box.....	"	...	1	8x2	28	3	1895	"
113.10	Cedar box.....	Culvert...	...	1	1x1	23	4½	1895	Under track.
113.35	Alsfeldt.								
113.57	Cedar box.....	"	...	1	1' 8"x 2	30	5	1895	"
113.74	Cast iron pipe..	"	...	1	3	96	35	1895	"
114.06	Cedar box.....	C. pass....	95	1	6x8	38	9' 3"	1890	"
114.45	"	Culvert....	...	1	1x1½	44	10	1893	"
114.75	Deck & ½ thro. Bridge	Public Rd	96	1	20½	88' 4	18	1905	Pl. gdr. ½ thro. gdr. Pile b'nts-wood str. ap proach.
				1	40' 2"				
				1	14				
115.28	Cedar box.....	Culvert...	...	1	1x1	30	10	1891	Under track.
115.55	Ayton.								
116.04	Con. pipe.....	"	...	1	2	40	9½	1898	"
116.35	Cedar box.....	"	...	1	6x9	28	16	1889	"
116.59	"	"	...	1	8x2	25	7	1881	"
116.83	"	"	...	1	4x2	23	4	1893	"
116.93	"	"	...	1	8x2	28	7	1894	"
117.52	"	"	...	1	1½x2	24	3½	1894	"
117.83	Deck Bridge...	Stream...	97	3	15	62	14	1890	C. pile tres., w str. extrastr. 1905.
				1	16				
118.27	Con. pipe.....	Culvert...	...	1	12"	30	7	1898	Under track.
118.32	"	"	...	1	12"	26	6	1897	"
118.75	"	"	...	1	12"	33	9	1898	"
119.07	Stone arch.....	"	...	1	4x5	33	9	1883	"
119.26	Cedar box.....	"	...	1	1½x2	28	5	1894	"
119.62	Neustadt.								

22nd District—Harriston to Owen Sound.