

Mileage from Toronto.	STATIONS AND BUILDINGS	DESCRIPTION AND DIMENSIONS.	When Built.	REMARKS. (CONDITION).
35.96	Ops Station -----	SHI fdn, Fr., shgle roof 12½ x 14, ht 8½ 864 sq ft platform	1893	Fair
38.96	Section tool house-- Addition -----	Fr., shingle roof 12'x22', ht 7' 5'x20', ht 6'	1893	Good Poor

Mileage from Lindsay

LINDSAY to HALIBURTON--10th District.

1.65	Section tool house--	Fr., shingle roof 12'x22', ht 12'	1895	Fair
7.30	Section tool house-- Addition -----	Fr., shingle roof 10'x22', ht 7' 7'x12', ht 6'	1886	Poor
7.33	Cameron Staffn & dwelling	SHI fdn, concrete fdn under kitchen, fr. shingle roof 20'x32', ht 12' 18'x34', ht 12' 14'x17', ht 8' 2450 sq ft platform	1905	Good
11.05	Halls Station ----- Stable frame --	Fr., board roof 10'x20', ht 6'		Poor Closet
13.08	Stock yards (2) -----	462 sq ft platform 38'x40' 40'x49'	1898	Good. One chute
13.99	Freight house -----	SHI fdn, Fr., shgle roof 20'x31', ht 9'	1897	Fair
14.01	Fenelon Falls Station -----	SHI fd, fr., shgle roof 19'x41', ht 12' 2235 sq ft platform	1882	Fair
14.16	Section tool house--	Fr., shingle roof 14'x27', ht 8'	1876	Closet Poor
14.50	Bridge signal house	Fr., shingle roof 10½'x12½', ht 14'	1893	Good
19.08	Section tool house-- Addition -----	Fr., shingle roof 12'x16', ht 7' 7'x9', ht 4'	1887	Fair Poor
19.09	Falls Staffn & dwelling	Stone fdn, fr., shingle roof 16'x38', ht 14' Stone cellar 11'x12', ht 6'	1888	Fair

Mileage from Lindsay	STATIONS AND BUILDINGS	DESCRIPTION AND DIMENSIONS.	When Built.	REMARKS. (CONDITION).
	Fells--Cont.			
	Addition -----	Sill fdn fr., shgle roof 12'x15', ht 9' -----		
	Shed -----	12'x14', ht 7' ----- 1996 sq ft platform		Fair. Closet
19.14	Section dwelling --	Sill fdn, fr., shgle roof 12'x41', ht 11' -----	1893	Fair
	Addition -----	12'x16', ht 11' -----	1897	Good
	Shed addition --	12'x12', ht 7' -----		Closet
24.60	Section tool house--	Fr., shingle roof 12'x16' ht 7' -----	1888	Fair
24.65	Burnt River			
	Stat'n & dwelling	Sill fdn, fr., shgle roof 20'x41', ht 12' ---- 13'x22', ht 8' -----	1885	Poor
	Addition -----	1356 sq ft platform		Closet
33.03	Section tool house--	Fr., shingle roof 12'x16', ht 7' ----- 26'x36' -----	1889	Fair
33.22	Kinmount			
	Station -----	Sill fdn, fr., shgle roof 22'x44', ht 16' -----	1904	Rebuilt. Good
	Freight house fr.	Sill fdn, fr., shgle roof 22'x44', ht 13' ----- 1936 sq ft platform	1902	Fair
	Pump house ----	Sill fdn, fr., metallic shingle roof ----- 16'x32', ht 8' ----- 1542 sq ft platform	1905	Good
35.64	Kinmount Jct.	Fr., shingle roof 10'x16', ht 7' -----	1882	Poor
40.11	Section dwelling --	Stone fdn & cellar, fr., shingle roof ----- 18'x27', ht 16' -----	1889	Fair
40.11	Addition -----	Stone fdn, fr., shgle roof ----- 14'x14', ht 8' ----- 12'x16', ht 5' -----	1839	Fair
	Log shed -----			Poor. Closet
42.72	Gelert			
	Stat'n & dwelling	Sill fdn, fr., shgle roof 22'x78', ht 13' ----- 6'x12', ht 8' -----	1878	Poor
	Addition -----	1604 sq ft platform		Poor Closet
	Stock yard (2) --	33'x36' 32'x40' -----	1903	Good. Dou- ble chute
42.75	Section dwelling --	Sill fdn, fr., shgle roof 21'x27' ht 13' ----- 13'x13', ht 13' ----- 10'x12' ht 8' -----		Fair
	Addition -----			Closet
	Addition (shed)---	Fr., shingle roof 10'x16', ht 12' -----		Poor
	Stable -----	10'x10', ht 8' -----		Poor
42.80	Section tool house--	Fr., shingle roof 12'x22', ht 8' -----	1895	Fair
47.12	Locklin			
	Station -----	Sill fdn, fr., shgle roof 12'x14', ht 8' -----	1895	Fair