

Mileage from Lindsay	STATIONS AND BUILDINGS	DESCRIPTION AND DIMENSIONS.	When Built.	REMARKS. (CONDITION).
	<b>Locklin--Cont.</b> Freight house ---	Sill fdn, fr., shgle roof 16'x24', ht 10' ----- 888 sq ft platform.		Good
49.03	<b>Dysats</b>	582 sq ft platform.		
53.11	<b>Goulds</b>	582 sq ft platform.		
55.60	<b>Haliburton</b>	Sill fdn, fr., shgle roof 22½'x97', ht 13½' ---- 3318 sq ft platform	1895	Good. Remod- elled 1904
55.67	Section tool house	Fr., shingle roof ----- 10'x16', ht 7' -----	1884	Poor
	Stock yards (2)---	24'x36' -----	1903	Good. Double chute
	Section dwelling	Sill fdn, fr., shgle roof 18'x26' ht 13½' ----	1885	Poor
	Shed -----	Fr., shingle roof ----- 10'x12', ht 10' -----		Poor
	Stable -----	Fr., shingle roof ----- 12'x24', ht 11' -----		Fair. Plank cellar 10'x12'
	Shed -----	12'x14', ht 8' -----		Fair. Closet

Mileage from  
Whitby Libr.

## WHITBY to MANILLA JCT.--10th District.

0.00	<b>Whitby Harbor</b> Dock -----	11'x210' -----	1870	Poor
2.29	<b>Whitby</b> Freight -----	Sill fdn, fr., shgle roof 25'x70', ht 12' ----- 1125 sq ft platform	1870	Fair 36' added 1905
	Station -----	Cattlechute ----- Stone fdn, brick, shgle roof ----- 24'x40½' ht 25' ----	1871	Good Closet
	Addition -----	Brick vault ----- 11'x12'8", ht 11' ---- 2854 sq ft platform	1871	Good
2.47	Section tool house--	Fr., shingle roof ----- 10'x15', ht 7' ----- 7'x15', ht 6' -----	1889	Poor
5.99	Operators shelter --	Fr., shingle roof ----- 6'x12' ht 9' -----	1894	Fair
7.56	<b>Brooklin</b> Freight house ---	Sill fdn, fr., shgle roof 18'x30½', ht 12' ---- 560 sq ft platform.	1886	Good
	Stock yard (2) --	33'x56' -----	1903	Good. Single & double chute
	Section tool house	Fr., shingle roof ----- 10'x15½', ht 7' ----- 7'x11', ht 6' -----	1886	Fair
	Addition -----			

Mileage from Whitby Hb	STATIONS AND BUILDINGS	DESCRIPTION AND DIMENSIONS.	When Built.	REMARKS. (CONDITION).
	<b>Brooklin--Cont.</b>	Fr., shingle roof -----	1891	Good
	Coal shed -----	9'x11', ht 8' -----		Closet
	Station -----	Sill fdn, fr., shgle roof 21'x51', ht 14' ----- 1393 sq ft platform 27'x39', 31½'x39' ---		Good. Re- built 1900
11.35	Stock yards (2) ---		1895	Fair. Sin- gle & dou- ble chutes
11.39	<b>Myrtle</b>	Sill fdn, fr., shgle roof	1871	Good. Remod- elled 1888
	Stat'n & dwelling	19'x31', ht 11' -----  12'x17', ht 8½' ----- 1003 sq ft platform		Closet
	Addition -----	Sill fdn, fr., shgle roof	1894	Good
	Freight house ---	12'x17', ht 8' -----		
14.39	Section tool house---	Fr., board roof -----	1888	Poor
		10'x12', ht 8' -----		
14.41	<b>High Point</b>	Fr., shingle roof -----	1890	Fair
	Shelter -----	12'x14', ht 8' ----- 324 sq ft platform---		
16.21	<b>Manchester</b>	Sill fdn, fr., shgle roof	1871	Fair. Remod- elled 1895
	Stat'n & dwelling	31'x31', ht 13½' ---- 18'x18', ht 12' ----- 8'x12', ht 6' -----	1891	Fair
	Addition -----	Sill fdn, fr., shgle roof	1891	Poor
	Addition (shed)---	14'x16', ht 10' ----- 1386 sq ft platform 8'x12', ht 4' -----		Good
	Freight house ---	Fr., shingle roof -----	1894	Fair
	Oil platform ---	10'x14', ht 6½' -----		Fair
	Section tool house	Fr., board roof -----	1894	Poor
	Stable -----	10'x14', ht 7' ----- 14'x19', ht 7' -----		Closet
	Addition -----	Fr., shingle roof -----	1895	Fair
18.53	Section tool house---	12'x22', ht 7½' -----		
18.53	<b>Prince Albert</b>	Sill fnd, fr., shgle roof	1871	Fair. Remod- elled 1895
		28'x51', ht 13' ----- 16½'x30', ht 12' ----- 1728 sq ft platform		Closet
	Addition -----	Fr., shingle roof -----	1890	Poor
	Shed -----	10'x18', ht 8½' ----- 8'x9', ht 6½' -----		Poor
	Stable -----		1890	
19.95	<b>Port Perry</b>	27'x54', 32'x52½' ---		Closet
	Stockyards (2) --	Sill fdn, fr., shgle roof	1871	Fair
	Freight house ---	24½'x95½', ht 13' ----- 1020 sq ft platform Sill fdn, fr., shgle roof		35' added 1905
	Stat'n & dwelling	24½'x31½', ht 19½' -- 15'x24½', ht 13' ----- 4'x16', ht 10' -----	1890	Fair
	Addition -----	Fr., shingle roof -----	1890	Fair
	Addition -----	14'x28½' ht 12' ----- 5216 sq ft platform		
	Baggage room ---			