





Photo Album for Hyannis MA Job 30261 March 17, 2017

This week the cab finished on the cab line and has been merged with the chassis along with the pump house. The body was nearing completion in paint. Next week the chassis should continue assembly and testing. The aerial torque box may begin assembly. The body may have harnessing and trim added.



DSC00012



DSC00013



DSC00014



DSC00015



DSC00016



DSC00017



DSC00018



DSC00019



DSC00020



DSC00021



DSC00022



DSC00023



DSC00024



DSC00025



DSC00026



DSC00027



DSC00028



DSC00029



DSC00030



DSC00031



DSC00032



DSC00033



DSC00034



DSC00035



DSC00036



DSC00037



DSC00038



DSC00039



DSC00040



DSC00041



DSC00042



DSC00042a



DSC00043



DSC00095



DSC00096



DSC00097



DSC00098



DSC00099