
Photo Album for Marblehead, MA Job 30642 March 17, 2017

This week the cab was nearing completion in paint.
The pump house and body began fabrication. Next week the cab is scheduled to begin on the cab line where cab related content is added while the chassis may begin assembly. The pump house and body may begin the paint process.



DSC00295



DSC00297



DSC00296



DSC00298






DSC00299



DSC07106



DSC07105



DSC07107



DSC07108




DSC07110

Find us on Facebook



DSC07109



DSC07048



DSC07049



DSC07051



DSC07050



DSC07052





DSC07053

