


Photo Album for Attleboro, MA Job 30334 January 6, 2017


This week the cab began on the cab line where cab related content is added. The chassis was offsite for protective coating (no photos). The body began the paint process in metal finishing. Next week the cab and chassis should continue assembly. The pump house may have trim added. The body should be nearing completion in paint.



DSC04218



DSC04219



DSC04220



DSC04221



DSC04222



DSC07181



DSC07182




DSC07183



DSC07184



DSC07185



DSC00254



DSC00255



DSC00256



DSC00257



DSC00258