


# Photo Album for Attleboro, MA Job 30334 December 16, 2016

This week the cab began the paint process. The pump house began initial plumbing while the body began fabrication. Next week the cab should finish in paint. The pump house should finish plumbing while the body may begin the paint process at metal finishing.



DSC00306



DSC00307



DSC00308



DSC00309






DSC00310



DSC07324



DSC07325



DSC07326






DSC07327



DSC07328



DSC07101



DSC07102





DSC07103



DSC07104



DSC07105



DSC07106