

Photo Album for Benson, VT

Job # 30361

W/O # 20978428

February 24, 2017

Your new Pierce apparatus is now in production at the Bradenton, FL facility. This week the chassis arrived and is in staging. The main fire pump has arrived and the pump house structure was fabricated. The lower body modules were fabricated and are staged to begin the paint process. In the next report the chassis could begin preparations for fire service use. The fire pump should have valves and plumbing added and the body modules should begin the paint process.



QUALITY SYSTEM FORM
 Title: Window Sheet

QSF10-0836
 Effective Date: 12/01/14
 Page 1 of 1

PWO #: 20978428 Job #: 30361
 Chassis Color: 90RED Top Color: (Two Tone) 90RED
 VIN #: HHHF9512
 Customer: BENSON F.D.
 Contract Manager: Nathan Schwanger
 RFP Date: _____
 Rework Number: 20979641

CONFIGURATION
☐ PUMPER
☒ TANKER
☐ RESPONDER
☐ RESCUE
☐ BRUSH TRUCK
☐ OTHER: _____

Yes ☐ No ☒

DSC06125



DSC06126



DSC06127



DSC06128



DSC06129



DSC06130



DSC06131



DSC06132



DSC06133



DSC06134




DSC06135



DSC06136



DSC06137



DSC06138



DSC06139



DSC06140



DSC06141



DSC06142



DSC06143



DSC06144



DSC06145



DSC06146



DSC06147



DSC06148



DSC06149



DSC06150



DSC06151



DSC06152



DSC06153



DSC06154



DSC06155



DSC06156




DSC06228



DSC06229



DSC06230



DSC06288



DSC06289



DSC06290



DSC06291



DSC06292



DSC06293



DSC06294