

Photo Album for Benson, VT

Job # 30361

W/O # 20978428

March 10, 2017

Since the last report, the chassis, fire pump and pump house structure remained in staging. The lower body modules and water tank side sheets began the paint process. Next week the chassis should remain in staging, the pump may begin having valves and plumbing added and the lower body should continue with the paint process.



DSC06235



DSC06236



DSC06237



DSC06238



DSC06239



DSC06240



DSC06241



DSC06242



DSC06243