





Photo Album for Cambridge, MA Job 29084 April 15, 2016

This week the cab was merged with the chassis along with the cooling structure. The body continued in fabrication. Next week the chassis should continue assembly and testing. The body may begin the paint process in metal finishing.



DSC07250



DSC07251




DSC07252



DSC07253



DSC07254



DSC07255



DSC07256



DSC07257



DSC07258



DSC07259



DSC07260



DSC07261



DSC07262



DSC07263



DSC07264



DSC07265



DSC07266



DSC07267



DSC07268



DSC07269



DSC07270



DSC07271



DSC07272



DSC07273



DSC07274



DSC07275



DSC07276



DSC07277



DSC07278



DSC07279



DSC07280



DSC07281



DSC07282



DSC07283



DSC07284



DSC07285



DSC07286



DSC07287



DSC07288



DSC07289



DSC07290



DSC07291



DSC07292




DSC07293



DSC07294



DSC07295



DSC07296



DSC04077



DSC04078



DSC04079



DSC04080



DSC04081



DSC04082



DSC04083