


Photo Album for Cambridge, MA Job 29084 May 6, 2016

This week the body finished in paint and has been merged with the chassis at the Pierce rescue facility where your apparatus will remain until complete. Some wire harnessing has been installed along with the battery charger and auxiliary compressor. Next week work should continue on installation of body components.



DSC07424



DSC07425



DSC07426



DSC07427



DSC07428



DSC07429



DSC07430



DSC07431



DSC07432



DSC07433



DSC07434



DSC07435




DSC07436



DSC07437



DSC07438



DSC07439



DSC07440



DSC07441