


# Photo Album for Cambridge, MA Job 29085 January 22, 2016

This week the cab began on the cab line where cab related content is added while the chassis began assembly. The pump had valves installed. The body was fabricated and began the paint process in metal finishing. Next week the cab is scheduled to be merged with the chassis and pump. The body should finish in paint.



DSC07232



DSC07233



DSC07234




DSC07235





DSC07236



DSC00277



DSC00278



DSC00279





DSC00280



DSC00281



DSC00282



DSC00283





DSC00284



DSC02379




DSC02380



DSC02381





DSC00229



DSC00230



DSC00231



DSC00232



DSC00233