




Photo Album for Cambridge, MA Job 29085 January 29, 2016

This week the cab finished on the cab line and has been merged with the chassis along with the pump house. The body finished in paint and began on the line where harnessing and trim are added. Next week the chassis is scheduled to begin on the main assembly line where the body and water tank may be merged with the chassis.



DSC00111



DSC00112



DSC00113



DSC00114



DSC00115



DSC00116



DSC00117



DSC00118



DSC00119



DSC00120



DSC00121



DSC00122



DSC00123



DSC00124



DSC00125



DSC00126




DSC00127



DSC00128



DSC00129



DSC00130



DSC00131



DSC00132



DSC00133



DSC00134



DSC00135



DSC00136



DSC00137



DSC00138



DSC00139



DSC00140



DSC00141



DSC00142



DSC00143



DSC00144



DSC00487



DSC00488



DSC00489



DSC00490



DSC00491