




Photo Album for Cambridge, MA Job 29085 February 19, 2016

This week your apparatus finished on the main assembly line and was staged to finish assembly in an offline area. In the next few days, your apparatus should be released to alignment and initial testing. Next week your apparatus is scheduled to finish initial testing and may be back on the line where reflective striping and/or remaining content is added.



DSC07656



DSC07657



DSC07658



DSC07659



DSC07660



DSC07661



DSC07662



DSC07663



DSC07664




DSC07665



DSC07666



DSC07667



DSC07668



DSC07669



DSC07670



DSC07671




DSC07672



DSC07673



DSC07674



DSC07675



DSC07676



DSC07677



DSC07678



DSC07679



DSC07680



DSC07681




DSC07682



DSC07683




DSC07684



DSC07685



DSC07686



DSC07687



DSC07688



DSC07689



DSC07690



DSC07691



DSC07692



DSC07693



DSC07694



DSC07695



DSC07696




DSC07697



DSC07698



DSC07699



DSC07700



DSC07701



DSC07702



DSC07703



DSC07704



DSC07705



DSC07706



DSC07707



DSC07708



DSC07709



DSC07710



DSC07711



DSC07712



DSC07713