


Photo Album for Cambridge, MA Job 30239 October 07, 2016

This week the cab began the paint process. Pump plumbing was fabricated and installed in the body when panels were joined in fabrication. Next week the cab may finish in paint and is scheduled to begin on the cab line where cab related content is added while the chassis may begin assembly. The body should begin the paint process.



DSC00016



DSC00017



DSC00018



DSC00019



DSC00020



DSC07085



DSC07086



DSC07087



DSC07088



DSC07089



DSC07090



DSC07091