





Photo Album for Cambridge, MA Job 30239 October 28, 2016

This week the body and water tank were being merged with the chassis on the main assembly line where a majority of the components will be added. Next week your apparatus should be nearing completion on the main assembly line.



DSC05294



DSC05295



DSC05296



DSC05297



DSC05298



DSC05299



DSC05300



DSC05301




DSC05302



DSC05303



DSC05304



DSC05305




DSC05306



DSC05307



DSC05308



DSC05309



DSC05310



DSC05311



DSC05312



DSC05313



DSC05314



DSC05315



DSC05316



DSC05317



DSC05318



DSC05319



DSC05320



DSC05321



DSC05322



DSC05323



DSC05324



DSC05325



DSC05326



DSC05327



DSC05328



DSC05329