





Photo Album for Cambridge, MA Job 30239 November 18, 2016

This week your apparatus completed alignment and initial pump testing and had reflective striping applied. In the next few days your apparatus should complete 3rd party pump testing and be released to final product evaluation which is part of the quality process. This is your last scheduled report.



DSC05281



DSC05282



DSC05283




DSC05284



DSC05289



DSC05290



DSC05291



DSC05292



DSC05293



DSC05294



DSC05295



DSC05296



DSC05297



DSC05298



DSC05299



DSC05300



DSC05301




DSC05302



DSC05303



DSC05304



DSC05305



DSC05306



DSC05307



DSC05308



DSC05309



DSC05310



DSC05311



DSC05312



DSC05313



DSC05314



DSC05315



DSC05316



DSC05317



DSC05318



DSC05319



DSC05320



DSC05321



DSC05322



DSC05323



DSC05324



DSC05325



DSC05326



DSC05327



DSC05328