


Photo Album for Carver, MA Job 29258-02 March 4, 2016

This week the cab was nearing completion in paint. The pump plumbing began fabrication. Next week the cab should finish in paint. The pump plumbing should be installed in the body when panels are joined in fabrication. The body is scheduled to begin fabrication.



DSC00630



DSC00631




DSC00632



DSC00633



DSC00634



DSC04188



DSC04189



DSC04190



DSC04191