


# Photo Album for Carver, MA Job 29258-02 March 11, 2016

This week the cab began on the cab line where cab related content is added while the chassis began assembly. The plumbing was installed when body panels were joined in fabrication. Next week the cab and chassis should be nearing completion in assembly. The pump should arrive and have valves installed. The body should begin the paint process.





DSC08157



DSC08158



DSC08159




DSC08160





DSC08161



DSC02455



DSC02456



DSC02457






DSC02458



DSC02459



DSC04021



DSC04022





DSC04023



DSC04024




DSC04025



DSC04026



DSC04027



DSC04028